
Appendix H – Work Zones and Tree Management Plans

Victoria Park-Canning Level Crossing Removal

TREE MANAGEMENT PLAN SUMMARY

September 2022



1.1 ARBORIST SURVEY

The project arborist has provided a 'Preliminary Arboricultural Report' report including advice on particular trees of value, retention advice and tree protection advice during construction.

The survey includes 3000+ trees captured in & outside rail corridor (PTA, ToVP, CoC & CoG).

Data provided:

- → Species
- → Health
- → Size (height, canopy width, TPZ + RPZ)
- → Structure
- → Useful life expectancy
- → Habitat value
- → Black cockatoo foraging species
- → Native / exotic
- → Arborist notes, comments

WESTWORKS CONSULTANCY

Preliminary Tree Survey

Excerpt



Cook Pine Tree ID #116

Tree Details	
Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	3
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Notes:	
Foraging species:	

Tree Location	
Longitude:	115.918219
Latitude:	-31.990519
Land Use:	Street Verge
Land Type:	Public Area

Photos Street View Map View



1.2 MODELLING, COORDINATION & DOCUMENTATION

Arborist survey data imported to shared BIM model. Existing trees geolocated and modelled in 3D for coordination + clash detection with all design disciplines including canopies, RPZs + TPZs.

Trees assessed for protection based on:

- → Species
- → Health
- → Size (height, canopy width, TPZ + RPZ)
- → Structure
- → Useful life expectancy
- → Habitat value
- → Black cockatoo foraging species
- → Native / exotic
- → Valuable / weed species

Extensive design review & coordination has been undertaken and is ongoing with the construction team and all design discplines against:


- → Design & constructability - new station buildings, viaduct, retaining walls, car parks etc.
- → CPTED, sightlines + safety
- → Gantry crane operations
- → Earthworks
- → Access + laydown areas
- → Utility modification works
- → Road & intersection upgrades
- → Temporary works

The tree retention plans form part of the Landscape and Urban Design Package. This is a working drawing, subject to change as design progresses. Any departures from these drawings must be approved by the project landscape architect. ALUA will continue to aim to retain as many trees as possible.


The project arborist is to provide 'Arboricultural Impact Report' & 'Construction Specification' as per AS4970 prior to works on site commencing.



Overview of Tree Management Plans Layout



Station plaza (example extract)




Green Corridor (example extract)

1.3 CONSTRUCTION PHASE

The project arborist is to provide Updated Tree Protection Plan including 'Construction Specification' as per AS4970 prior to works on site commencing.


Protection measures throughout the construction phase include but are not limited to:

- → Tree Protection Fencing as per AS4970
- → Formative pruning (by qualified arborist) as per AS4373
- → Supplimental watering, fertilizing or other treatments as advised by project arborist and as per AS 4970
- → Arborist present on site during works within TPZs or SRZs as per AS4970
- → Any additional measures outlined in the 'Arboricultural Impact Report'
- → Regular site visits by project arborist as per AS4970, 2009 and as set out in the Tree Protection Construction Specification



LEGEND:
1 Chain wire mesh panels with shade cloth (if required) attached, held in place with concrete feet.
2 Alternative plywood or wooden paling fence panels. This fencing material also prevents building materials or soil entering the TPZ.
3 Mulch installation across surface of TPZ (at the discretion of the project arborist). No excavation, construction activity, grade changes, surface treatment or storage of materials of any kind is permitted within the TPZ.
4 Bracing is permissible within the TPZ. Installation of supports should avoid damaging roots.

FIGURE 3 PROTECTIVE FENCING



PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1

0 10 20 30 40 50 100mm

AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE

Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20200

VALIDATION

SIGNATURE

DATE

DATE APPROVED

REFERENCES

SCALE 1 : 5000

DATUM

HORIZONTAL: PCG20

VERTICAL: AHD71

DESIGNED HASSELL

DRAWN HASSELL

CHECKED H. GALLOWAY

APPROVED K. MELING

DATE 30.08.22

Government of Western Australia
Public Transport Authority

VICTORIA PARK TO CANNING LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT - SHEET LAYOUT PACKAGE 2

PTA Drawing No: 04-C-19-0310 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt

LA20301

NOTE: ANYTHING SHOWN BEYOND MATCHLINE SHOULD NOT BE USED AS PART OF THIS DRAWING.

FOR CONTINUATION REFER TO DWG No. ---

PRUNING REQUIRED AS PER ARBORIST REPORT

ALREADY REMOVED BY BRIDGE WORKS


AA165 CORfic

AA163 CORfic

AA166 CORfic

NOTE: ANYTHING SHOWN BEYOND MATCHLINE SHOULD NOT BE USED AS PART OF THIS DRAWING.

FOR CONTINUATION REFER TO DWG No. 0312



NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED
A00 — TREE ID - REFER ARBORIST REPORT
AGOfle — TREE SPECIES CODE
CANOPY
TPZ (TREE PROTECTION ZONE)
RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE TO BE RELOCATED ON SITE REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3)
0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1

0 10 20 30 40 50 100mm
AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20201

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 30.08.22


Government of Western Australia
Public Transport Authority


VICTORIA PARK TO CANNING LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 1

PTA Drawing No: 04-C-19-0311 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt





NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED

A00 — TREE ID - REFER ARBORIST REPORT
AGOFIc — TREE SPECIES CODE
CANOPY
TPZ (TREE PROTECTION ZONE)
RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE
TO BE RELOCATED ON SITE
REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3) 0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1 — 0 10 20 30 40 50 100mm AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20202

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500
DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 30.08.22

Government of Western Australia
Public Transport Authority

VICTORIA PARK TO CANNING
LEVEL CROSSING REMOVAL


ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 2

PTA Drawing No: 04-C-19-0312 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt

POTENTIAL LAYDOWN AREA.
CONSTRUCTION TEAM TO
CONFIRM WHICH LAYDOWN
AREAS REQUIRE TREE SURVEY

POTENTIAL LAYDOWN AREA.
CONSTRUCTION TEAM TO
CONFIRM ACCESS AND
LAYDOWN PLANS



NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

HAMILTON 104 TECcap
HAMILTON 101 ACMsmi
HAMILTON 100 ACMsmi
HAMILTON 103 ACMsmi
HAMILTON 102 ACMsmi
HAMILTON 98 FICmac
HAMILTON 99 ZOPcon
BB155 EUCteu
AA152 CORric
AA151 CORric
AA150 CORric
AA149 CORric
AA148 CORric
AA147 CORric
AA146 CORric
HAMILTON 62 CITspi
HAMILTON 65 JACmim
HAMILTON 61 ERYsyk
HAMILTON 60 ERYsyk
HAMILTON 59 MELaze
HAMILTON 58 ERYsyk
HAMILTON 57 CORcal
HAMILTON 56 MELrha
HAMILTON 7 MELrha
HAMILTON 16 MELrha

ARBORIST TO PROVIDE ADVICE ON VIABILITY FO JACARANDA FOR TRANSPLANT

POTENTIAL LAYDOWN AREA.
CONSTRUCTION TEAM TO
CONFIRM ACCESS AND
LAYDOWN PLANS

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED
A00 — TREE ID - REFER ARBORIST REPORT
AGOfle — TREE SPECIES CODE
CANOPY
TPZ (TREE PROTECTION ZONE)
RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE TO BE RELOCATED ON SITE REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

FOR CONTINUATION REFER TO DWG No. 0312

NOTE: ANYTHING SHOWN BEYOND MATCHLINE SHOULD NOT BE USED AS PART OF THIS DRAWING.

FOR CONTINUATION REFER TO DWG No. 0314

NOTE: ANYTHING SHOWN BEYOND MATCHLINE SHOULD NOT BE USED AS PART OF THIS DRAWING.

1:500 (A1) / 1:1000 (A3)
0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT				
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1 — 0 10 20 30 40 50 100mm — AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20203

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED	HASSELL
DRAWN	HASSELL
CHECKED	H. GALLOWAY
APPROVED	K. MELING
DATE	30.08.22

Government of Western Australia
Public Transport Authority

VICTORIA PARK TO CANNING
LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 3

PTA Drawing No: 04-C-19-0313 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt

POTENTIAL LAYDOWN AREA. CONSTRUCTION TEAM TO CONFIRM ACCESS AND LAYDOWN PLANS

POTENTIAL LAYDOWN AREA. CONSTRUCTION TEAM TO CONFIRM ACCESS AND LAYDOWN PLANS

ARBORIST ADVICE REQUIRED - POTENTIAL CLASH WITH BEAM INSTALL

ARBORIST SURVEY REQUIRED

ARBORIST TO PROVIDE ADVICE ON VIABILITY FO JACARANDA FOR TRANSPLANT


POTENTIAL LAYDOWN AREA. CONSTRUCTION TEAM TO CONFIRM ACCESS AND LAYDOWN PLANS

FOR CONTINUATION REFER TO DWG No. 0313

NOTE: ANYTHING SHOWN BEYOND MATCHLINE SHOULD NOT BE USED AS PART OF THIS DRAWING.

FOR CONTINUATION REFER TO DWG No. 0315

NOTE: ANYTHING SHOWN BEYOND MATCHLINE SHOULD NOT BE USED AS PART OF THIS DRAWING.



NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED
- A00 — TREE ID - REFER ARBORIST REPORT
- AGOfle — TREE SPECIES CODE
- CANOPY
- TPZ (TREE PROTECTION ZONE)
- RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE
TO BE RELOCATED ON SITE
REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3)

0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	HAS	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	DRN	HG	JPD

ORIG SIZE A1

0 10 20 30 40 50 100mm

AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20204

VALIDATION	REFERENCES
SIGNATURE	
DATE	
DATE APPROVED	

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED	HASSELL
DRAWN	HASSELL
CHECKED	H. GALLOWAY
APPROVED	K. MELING
DATE	30.08.22


Government of Western Australia Public Transport Authority

VICTORIA PARK TO CANNING LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 4

PTA Drawing No: 04-C-19-0314 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt



NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED
A00 — TREE ID - REFER ARBORIST REPORT
AGOfle — TREE SPECIES CODE
CANOPY
TPZ (TREE PROTECTION ZONE)
RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE
TO BE RELOCATED ON SITE
REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3) 0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1 — 0 10 20 30 40 50 100mm — AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20205

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 30.08.22


Government of Western Australia Public Transport Authority


VICTORIA PARK TO CANNING LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 5

PTA Drawing No: 04-C-19-0315 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt





NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED

A00 – TREE ID - REFER ARBORIST REPORT
AGOfle – TREE SPECIES CODE
CANOPY
TPZ (TREE PROTECTION ZONE)
RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE
TO BE RELOCATED ON SITE
REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3)
0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT				
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1
0 10 20 30 40 50 100mm
AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20206

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 30.08.22


Government of Western Australia
Public Transport Authority


VICTORIA PARK TO CANNING
LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 6

PTA Drawing No: 04-C-19-0316 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt





NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED



- TREE ID - REFER ARBORIST REPORT
- TREE SPECIES CODE
- EXISTING TREE TO BE REMOVED NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE
- EXISTING GRASS TREE TO BE RELOCATED ON SITE REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3) 0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1 — 0 10 20 30 40 50 100mm — AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20207

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 30.08.22


Government of Western Australia Public Transport Authority


VICTORIA PARK TO CANNING LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 7

PTA Drawing No: 04-C-19-0317 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt





NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED
A00 — TREE ID - REFER ARBORIST REPORT
AGOfle — TREE SPECIES CODE
CANOPY
TPZ (TREE PROTECTION ZONE)
RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE TO BE RELOCATED ON SITE REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3)
0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1

0 10 20 30 40 50 100mm
AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20208

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 30.08.22


Government of Western Australia
Public Transport Authority

VICTORIA PARK TO CANNING
LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 8

PTA Drawing No: 04-C-19-0318 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt



NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED
A00 — TREE ID - REFER ARBORIST REPORT
AGOfle — TREE SPECIES CODE
CANOPY
TPZ (TREE PROTECTION ZONE)
RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE TO BE RELOCATED ON SITE REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3)
0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
B	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD
A	05.08.22	15% REFERENCE DESIGN	HAS	HAS	HG	JPD

ORIG SIZE A1 — 0 10 20 30 40 50 100mm — AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20209

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 30.08.22


Government of Western Australia Public Transport Authority


VICTORIA PARK TO CANNING LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 9

PTA Drawing No: 04-C-19-0319 Rev: B

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt





NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED
A00 — TREE ID - REFER ARBORIST REPORT
AGDFle — TREE SPECIES CODE
CANOPY
TPZ (TREE PROTECTION ZONE)
RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE TO BE RELOCATED ON SITE REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3) 0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1 — 0 10 20 30 40 50 100mm AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20210

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 30.08.22


Government of Western Australia Public Transport Authority


VICTORIA PARK TO CANNING LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 10

PTA Drawing No: 04-C-19-0320 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt





NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

TREE PROTECTION PLANS

- PROPOSED TREE PROTECTION FENCING
- GANTRY CRANE IMPACT ZONE
- ROADS, ACCESS, LAYDOWN AND TEMPORARY WORKS IMPACT ZONE
- TEMPORARY ROAD RESERVE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE
- TEMPORARY CONSTRUCTION WORKS IMPACT ZONE

EXISTING TREE TO BE RETAINED



- TREE ID - REFER ARBORIST REPORT
- TREE SPECIES CODE
- CANOPY
- TPZ (TREE PROTECTION ZONE)
- RPZ (ROOT PROTECTION ZONE)

EXISTING TREE TO BE REMOVED
NOTE: SIGNIFICANT TRUNKS + BRANCHES TO BE STOCKPILED FOR RE-USE

EXISTING GRASS TREE
TO BE RELOCATED ON SITE
REQUIRES EXTRACTION, STORAGE AND CARE DURING CONSTRUCTION

1:500 (A1) / 1:1000 (A3)
0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

FOR INFORMATION

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	30.08.22	EARLY WORKS DEVELOPMENT APPLICATION	HAS	HAS	HG	JPD

ORIG SIZE A1
0 10 20 30 40 50 100mm
AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20211

VALIDATION	REFERENCES
SIGNATURE	
DATE	
DATE APPROVED	

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED	HASSELL
DRAWN	HASSELL
CHECKED	H. GALLOWAY
APPROVED	K. MELING
DATE	30.08.22

Government of Western Australia
Public Transport Authority


VICTORIA PARK TO CANNING
LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 11

PTA Drawing No: 04-C-19-0321 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt

POTENTIAL LAYDOWN AREA.
CONSTRUCTION TEAM TO
CONFIRM WHICH LAYDOWN
AREAS REQUIRE TREE SURVEY



NOTE:
THE TREE MANAGEMENT PLANS ARE A WORKING DRAWING. THE DRAWINGS MUST BE READ IN CONJUNCTION WITH THE ARBORIST'S REPORT AND TREE PROTECTION PLAN.
ARBORIST SURVEY AND REPORT IS NOT COMPLETE AT TIME OF ISSUE.
ARBORIST'S ADVICE & INPUT IS ONGOING.
THE PROJECT WILL MAKE EVERY EFFORT TO RETAIN AND PROTECT AS MANY TREES AS POSSIBLE.
TREES MARKED FOR REMOVAL CAN BE RETAINED IF THE DESIGN & CONSTRUCTION TEAM DETERMINE IT IS PRACTICAL TO DO SO.
TREES IDENTIFIED TO BE RETAINED OR REMOVED ARE SUBJECT TO CHANGE AS DESIGN PROGRESSES AND CONSTRUCTION METHODOLOGY IS REFINED.
ANY DEVIATION FROM THE TREE PROTECTION PLANS MUST BE APPROVED BY THE PROJECT LANDSCAPE ARCHITECT AND SUPERINTENDENT PRIOR TO WORKS COMMENCING.
CONSTRUCTION TEAM TO CONFIRM LAYDOWN AREAS OUTSIDE CORRIDOR PENDING FURTHER INVESTIGATION.
ALL TREES WITHIN LAYDOWN AREAS TO BE PROTECTED

POTENTIAL LAYDOWN AREA.
CONSTRUCTION TEAM TO
CONFIRM WHICH LAYDOWN
AREAS REQUIRE TREE SURVEY

1:500 (A1) / 1:1000 (A3)
0 5m 10 15 20 25 30 35 40 45 50 55 60 65 70 75

PRINT IN COLOUR

REFERENCE DESIGN

REV	DATE	AMENDMENT	DSN	DRN	CHK	APP
A	05.08.22	15% REFERENCE DESIGN	HAS	HAS	HG	JPD

ORIG SIZE A1
0 10 20 30 40 50 100mm
AT ORIGINAL PLOT SIZE

This document must not be copied without PTA's written permission, and the contents thereof must not be imparted to a third party nor be used for any unauthorised purpose.

ARMADALE LINE UPGRADE ALLIANCE
Innovation to Reality

Contractor No: LXR-P2-Z0-GN-CI-DL-DWG-20212

VALIDATION
SIGNATURE
DATE
DATE APPROVED

REFERENCES

SCALE 1 : 500

DATUM
HORIZONTAL: PCG20
VERTICAL: AHD71

DESIGNED HASSELL
DRAWN HASSELL
CHECKED H. GALLOWAY
APPROVED K. MELING
DATE 05.08.22

Government of Western Australia
Public Transport Authority

VICTORIA PARK TO CANNING
LEVEL CROSSING REMOVAL

ZONE 0 - URBAN DESIGN & LANDSCAPE
PACKAGE 2 - WHARF STREET
TREE MANAGEMENT PLAN - SHEET 12

PTA Drawing No: 04-C-19-0322 Rev: A

CAD DRAWING PATHNAME Autodesk Docs://AU-PS129931 - Inner Armadale Line Level Crossing - R22 - C22/LXR-P2-Z0-GN-CI-DL-M3D-00001.rvt

Preliminary Tree Survey

Location: Armadale Line Upgrade; Beckenham Train Station to Leach Highway

Report Prepared for: ALUA

Date: 18 August 2022

Mark Short
Grad Cert Arboriculture

Arboricultural Consultant
Westworks Consultancy
PO Box 173
Mundijong WA 6121
Mobile: 0417 011 426
mark@westworksconsultancy.com.au

Contents

1.0 Introduction 2
2.0 Methodology 2
2.1 Methodology – Tree Measurements 2
2.2 Methodology – Tree Health 3
2.3 Methodology - Structure 3
2.4 Methodology – Age Assessment 4
2.5 Useful Life Expectancy 5
2.6 Origin of species 5
2.7 Habitat (Nesting) Value 6
2.8 Foraging Species 6
3.0 Location of Subject Trees – Part A 7
3.1 Location of Subject Trees – Part A 8
3.2 Location of Subject Trees – Part A 9
3.3 Location of Subject Trees – Part A 10
3.4 Location of Subject Trees – Part A 11
3.5 Location of Subject Trees – Part A 12
3.6 Location of Subject Trees – Part A 13
3.7 Location of Subject Trees – Part A 14
4.0 Tree Assessments- Part A 15
5.0 Location of Subject Trees – Part B 279
5.2 Location of Subject Trees – Part B 281
5.3 Location of Subject Trees – Part B 282
5.4 Location of Subject Trees – Part B 283
5.5 Location of Subject Trees – Part B 284
5.6 Location of Subject Trees – Part B 285
5.7 Location of Subject Trees – Part B 286
5.8 Location of Subject Trees – Part B 287
5.9 Location of Subject Trees – Part B 288
5.10 Location of Subject Trees – Part B 289
5.11 Location of Subject Trees – Part B 290
5.12 Location of Subject Trees – Part B 291
5.13 Location of Subject Trees – Part B 292
5.14 Location of Subject Trees – Part B 293
5.15 Location of Subject Trees – Part B 294
5.16 Location of Subject Trees – Part B 295
5.17 Location of Subject Trees – Part B 296
6.0 Tree Assessments – Part B 297
7.0 Conclusion 609
8.0 Glossary of Arboricultural Terminology 612
9.0 Appendices – QTRA Risk Thresholds 615
10.0 References 616
11.0 Disclaimer and Limitations 617

1.0 Introduction

A tree survey was undertaken to pick up the details of trees on the verge and within the Rail corridor along the Armadale Train line from Beckenham Train Station, Beckenham to Leach Highway, Welshpool (Package 2). The purpose of this tree survey is to inform the design process for the raising of the train line and creation of new public areas.
The survey area has been divided into two sections, with the rail being the divide. “Part A,” is the western half of the Rail Corridor and verge and “Part B,” being the Eastern half of the rail corridor and adjacent verge. Trees have been number from 1 onwards for each portion

This portion of Track has been surveyed at different times, due to changing requirements of the project, as such the tree numbering is not necessarily concurrent on the map.

2.0 Methodology

This tree survey consisted of a walk-through assessment to collect the following details of nominated trees within the site:

- Age
- Height (in meters),
- Canopy spread
- Diameter of the trunk at breast height and ground level (for determining TPZ and SRZ)
- Health and structure,
- Useful Life Expectancy
- Origin of species
- Habitat Value.
- Foraging – this is noted by exception with a “Yes,” otherwise left blank

An aerial assessment and Soil or tissue sampling was not undertaken during this assessment.

2.1 Methodology – Tree Measurements

The height of the tree is an approximate height taken in meters (m)

The canopy spread gives an indication of the general spread of the canopy in meters

The Diameter of the trunk is measures at 1.4m above ground level and at ground level with a DBH tape. This allows for the calculation of the Tree Protection Zone (TPZ) and the Structural Root Zone (SRZ() in line with the Australian Standard for Protection of Trees on Development Sites (AS 497 – 2009) The TPZ and SRZ information is provided with each tree.

2.2 Methodology – Tree Health

- **Good:** The tree will show good to excellent vigour throughout the tree for the species. The tree will exhibit a full and healthy canopy of foliage with only minimal pest or diseases evident.
- **Fair:** The tree is growing in a reasonable condition and shape with adequate canopy foliage for the species. Minor dead wood may be present throughout the crown, with reasonable colour and density when compared to a typical healthy specimen of that species.
- **Poor:** The tree appears to not be growing to its full capability with the canopy potentially visibly showing signs of openness and thinning with excessive amounts of dead or dying limbs. Evidence of established pest and disease issues will be evident or symptoms of stress indicating the tree is in decline.
- **Dead:** No living tissue was found; the tree is dead and should be removed. Unless it is otherwise noted as holding potential as a habitat tree.

2.3 Methodology - Structure

- **Good:** The tree will show good to excellent vigour throughout the tree for the species. The tree will exhibit a full and healthy canopy of foliage with only minimal pest or diseases evident.
- **Fair:** The tree is growing in a reasonable condition and shape with adequate canopy foliage for the species. Minor dead wood may be present throughout the crown, with reasonable colour and density when compared to a typical healthy specimen of that species.
- **Poor:** The tree appears stunted and not growing to its full capability with the canopy potentially visibly showing signs of openness and thinning with excessive amounts of dead or dying limbs. Evidence of established pest and disease issues will be evident or symptoms of stress indicating the tree is in decline.
- **Very poor:** The tree is in a state of decline with the canopy visibly open with considerable deadwood with pest and diseases being present throughout the tree as it enters the final stages of senescing.
- H**as Failed:** The tree is of a significantly poor structural integrity that a failure event was present at time of inspection.

***Determining removal versus retention**


All trees are typically advocated for retention if they are recorded as fair or good in wither the Health or structure category.

Where a tree required removal on the ground pf poor health or poor structural integrity it will be expressly noted in the Comments section.

In terms of guidance for the removal of trees due to design constraints, where trees are recorded as Poor in terms of Health or Poor or Very Poor in the structure category, should be considered over and above those that rate fair/good in both categories. With the design being altered to retain as many trees as possible.

2.4 Methodology – Age Assessment

The age of the subject trees was assessed against the following categories.



2.5 Useful Life Expectancy

Very Long (Greater than 40 + years)
Very high quality and high value, these trees would hold such a condition that make them a valuable part of the environment/ landscape, would be considered to hold a Useful Life Expectancy (ULE) of greater than 40 years, thus allowing them to make a substantial contribution for a long period of time.

Long (Greater than 20 to 40 years)
High quality and high value, these trees would hold such a condition that make them a valuable part of the environment/ landscape, thus allowing them to make a substantial contribution to for at least 20 years from the time of inspection.

Medium (Between 11 to 20 years)
Medium quality and medium value, trees of this category are thought of as making a good contribution to the area they dwell in and would be considered to hold a ULE of a minimum of 11 years.

Short (Between 6 to 10 years)
Low quality and low value. These trees would be regarded as being in an adequate condition that would see them being retained for a period that would allow new plantings to establish.

Transient (1 to 5 years)
Very Low quality and very low value, these trees would be regarded as having a poor form, displaying a low vitality, and may be exhibiting initial signs of structural decline. They would be considered to have a ULE of less than 5 years and are to be included replacement plan.

Dead or hazardous (no remaining ULE).
Trees in this category would be considered to hold such a condition that would potentially hold no value or in their current state it would be reasonable to undertake their removal for reasons of sound Arboricultural management, due to a high level of risk.

2.6 Origin of species

Native – The definition below is as it is stipulated in the Environmental Protections Act 1986

3(1). native vegetation means indigenous aquatic or terrestrial vegetation and includes dead vegetation unless that dead vegetation is of a class declared by regulation to be excluded from this definition but does not include vegetation in a plantation.

51A. native vegetation has the meaning given by section 3(1) but does not include vegetation that was intentionally sown, planted or propagated unless —

(a) that vegetation was sown, planted, or propagated as required under this Act or another written law; or

(b) that vegetation is of a class declared by regulation to be included in this definition.

Exotic – A species of plant that is not indigenous to the Project area, and/or has been planted

2.7 Habitat (Nesting) Value

High value - Trees in this category will have a DBH of 500mm or greater, and/or has hollows of 150mm in diameter or greater.

Medium value. - Trees with a DBH of up to 500mm but not greater then 300mm with hollows of up to 140mm in diameter this also relates to the potential for future significant nesting hollows.

Low Value - Trees with no hollows, holding low nesting values.

2.8 Foraging Species

Trees in the project area have been assessed in regards to their suitability as foraging trees for Forest red-tailed black cockatoo (calyptorhynchus banksii naso); - Baudin's cockatoo (calyptorhynchus baudinii); - Carnaby's cockatoo (calyptorhynchus latirostris); - Peregrine falcon (falco peregrinus).


Yes. – Are a suitable tree species for foraging

No – Not a suitable species for foraging

Black Cockatoo foraging tree means native plant species known to be utilised by black cockatoo species for foraging and includes Corymbia calophylla (marri), Eucalyptus marginata(jarrah), Eucalyptus spp., Banksia spp., Allocasuarina spp., and Xanthorrhoea spp

3.0 Location of Subject Trees – Part A

Subject tree marked coloured dots in relation to species.



3.1 Location of Subject Trees – Part A



3.2 Location of Subject Trees – Part A



3.3 Location of Subject Trees – Part A



3.4 Location of Subject Trees – Part A




3.5 Location of Subject Trees – Part A



3.6 Location of Subject Trees – Part A



3.7 Location of Subject Trees – Part A



Swamp Mallet Tree ID #1

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5.5
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.951507
Latitude:	-32.020148

Photos Street View Map View



Common Sheoak Tree ID #2

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	11
DBH [cm]:	51.48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.74
Tree Protection Zone (TPZ) [m]:	6.18
Structural Root Zone (SRZ) [m]:	2.92
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No pruning required
Foraging species:	No

Tree Location

Longitude:	115.947101
Latitude:	-32.015904

Photos Street View Map View



Broad-leaved Paperbark Tree ID #3

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	28.68
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.512
Tree Protection Zone (TPZ) [m]:	3.44
Structural Root Zone (SRZ) [m]:	2.5
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.946678
Latitude:	-32.015493

Photos Street View Map View



Broad-leaved Paperbark Tree ID #4

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	26.25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	3.15
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.946635
Latitude:	-32.015464

Photos Street View Map View



Tuart Tree ID #5

Tree Details

Latin Name:	Eucalyptus gomphocephala
Common Name:	Tuart
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	74.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.78
Tree Protection Zone (TPZ) [m]:	8.94
Structural Root Zone (SRZ) [m]:	2.98
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No pruning required
Foraging species:	Yes

Tree Location

Longitude:	115.946609
Latitude:	-32.015429

Photos Street View Map View



Broad-leaved Paperbark Tree ID #6

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	14.8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.325
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.06
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.946586
Latitude:	-32.015412

Photos Street View Map View



Tuart Tree ID #7

Tree Details

Latin Name:	Eucalyptus gomphocephala
Common Name:	Tuart
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	11
DBH [cm]:	74.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.83
Tree Protection Zone (TPZ) [m]:	8.94
Structural Root Zone (SRZ) [m]:	3.06
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No pruning required
Foraging species:	Yes

Tree Location

Longitude:	115.946424
Latitude:	-32.015240

Photos Street View Map View



Broad-leaved Paperbark Tree ID #8

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.946403
Latitude:	-32.015226

Photos Street View Map View



Broad-leaved Paperbark Tree ID #9

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	6
DBH [cm]:	36.68
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	4.4
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.946365
Latitude:	-32.015162

Photos Street View Map View



Broad-leaved Paperbark Tree ID #10

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	2
DBH [cm]:	18.19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.275
Tree Protection Zone (TPZ) [m]:	2.18
Structural Root Zone (SRZ) [m]:	1.92
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.946340
Latitude:	-32.015137

Photos Street View Map View



Swamp Mahogany Tree ID #11

Tree Details

Latin Name:	Eucalyptus robusta
Common Name:	Swamp Mahogany
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	8
DBH [cm]:	65
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.98
Tree Protection Zone (TPZ) [m]:	7.8
Structural Root Zone (SRZ) [m]:	3.28
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.946298
Latitude:	-32.015119

Photos Street View Map View



Broad-leaved Paperbark Tree ID #12

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	2
DBH [cm]:	16.37
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.245
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.83
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.946274
Latitude:	-32.015103

Photos Street View Map View



Broad-leaved Paperbark Tree ID #13

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	2
DBH [cm]:	31.85
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	3.82
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor lifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.946254
Latitude:	-32.015088

Photos Street View Map View



Broad-leaved Paperbark Tree ID #14

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.946268
Latitude:	-32.014959

Photos Street View Map View



Common Sheoak Tree ID #15

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	7
DBH [cm]:	39.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.595
Tree Protection Zone (TPZ) [m]:	4.78
Structural Root Zone (SRZ) [m]:	2.66
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 4.6m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.945705
Latitude:	-32.014570

Photos Street View Map View



Grass Tree Tree ID #16

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Fully Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Suitable for transplanting
Foraging species:	No

Tree Location

Longitude:	115.936315
Latitude:	-32.005300

Photos Street View Map View



Jacaranda Tree ID #17

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.295
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	1.98
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.946028
Latitude:	-32.014882

Photos Street View Map View



Jacaranda Tree ID #18

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	25.4
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.05
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945981
Latitude:	-32.014811

Photos Street View Map View



Jacaranda Tree ID #19

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	25.3
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.285
Tree Protection Zone (TPZ) [m]:	3.04
Structural Root Zone (SRZ) [m]:	1.95
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945919
Latitude:	-32.014756

Photos Street View Map View



Jacaranda Tree ID #20

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945873
Latitude:	-32.014707

Photos Street View Map View



Jacaranda Tree ID #21

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5.5
DBH [cm]:	20.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2.46
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945820
Latitude:	-32.014657

Photos Street View Map View



Jacaranda Tree ID #22

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5.5
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.198
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945773
Latitude:	-32.014609

Photos Street View Map View



Jacaranda Tree ID #23

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	21.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.58
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945708
Latitude:	-32.014541

Photos Street View Map View



Jacaranda Tree ID #24

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	23.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.78
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945471
Latitude:	-32.014306

Photos Street View Map View



Jacaranda Tree ID #25

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	24.3
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.288
Tree Protection Zone (TPZ) [m]:	2.92
Structural Root Zone (SRZ) [m]:	1.96
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945421
Latitude:	-32.014261

Photos Street View Map View



Jacaranda Tree ID #26

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	22.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.242
Tree Protection Zone (TPZ) [m]:	2.74
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945359
Latitude:	-32.014202

Photos Street View Map View



Jacaranda Tree ID #27

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	23.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.272
Tree Protection Zone (TPZ) [m]:	2.78
Structural Root Zone (SRZ) [m]:	1.92
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945296
Latitude:	-32.014150

Photos Street View Map View



Jacaranda Tree ID #28

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.328
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	2.07
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945240
Latitude:	-32.014081

Photos Street View Map View



Jacaranda Tree ID #29

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	19.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.298
Tree Protection Zone (TPZ) [m]:	2.3
Structural Root Zone (SRZ) [m]:	1.99
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945184
Latitude:	-32.014041

Photos Street View Map View



Jacaranda Tree ID #30

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	22.3
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.275
Tree Protection Zone (TPZ) [m]:	2.68
Structural Root Zone (SRZ) [m]:	1.92
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945129
Latitude:	-32.013986

Photos Street View Map View



Jacaranda Tree ID #31

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	25.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.295
Tree Protection Zone (TPZ) [m]:	3.1
Structural Root Zone (SRZ) [m]:	1.98
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945077
Latitude:	-32.013933

Photos Street View Map View



Jacaranda Tree ID #32

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	21.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.58
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.944961
Latitude:	-32.013822

Photos Street View Map View



Jacaranda Tree ID #33

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	19.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.242
Tree Protection Zone (TPZ) [m]:	2.38
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.944915
Latitude:	-32.013790

Photos Street View Map View



Jacaranda Tree ID #34

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	23.4
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.268
Tree Protection Zone (TPZ) [m]:	2.81
Structural Root Zone (SRZ) [m]:	1.9
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.944859
Latitude:	-32.013722

Photos Street View Map View



Jacaranda Tree ID #35

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	20.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.254
Tree Protection Zone (TPZ) [m]:	2.46
Structural Root Zone (SRZ) [m]:	1.86
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.944776
Latitude:	-32.013661

Photos Street View Map View



Jacaranda Tree ID #36

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	19.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.236
Tree Protection Zone (TPZ) [m]:	2.3
Structural Root Zone (SRZ) [m]:	1.8
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.944741
Latitude:	-32.013614

Photos Street View Map View



River Red Gum Tree ID #37

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	82.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.96
Tree Protection Zone (TPZ) [m]:	9.9
Structural Root Zone (SRZ) [m]:	3.25
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.955982
Latitude:	-32.024384

Photos Street View Map View



River Red Gum Tree ID #38

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	15
DBH [cm]:	121.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.23
Tree Protection Zone (TPZ) [m]:	14.58
Structural Root Zone (SRZ) [m]:	3.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.955819
Latitude:	-32.024232

Photos Street View Map View



River Red Gum Tree ID #39

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	4
DBH [cm]:	54.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.76
Tree Protection Zone (TPZ) [m]:	6.54
Structural Root Zone (SRZ) [m]:	2.95
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal Deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.955638
Latitude:	-32.024048

Photos Street View Map View



River Red Gum Tree ID #40

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	4
DBH [cm]:	38.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.54
Tree Protection Zone (TPZ) [m]:	4.61
Structural Root Zone (SRZ) [m]:	2.55
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.955588
Latitude:	-32.024033

Photos Street View Map View



River Red Gum Tree ID #41

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	4
DBH [cm]:	36.42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	4.37
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.955563
Latitude:	-32.024011

Photos Street View Map View



River Red Gum Tree ID #42

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	9
DBH [cm]:	46.8
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	5.62
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.955534
Latitude:	-32.023958

Photos Street View Map View



River Red Gum Tree ID #43

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	14
DBH [cm]:	100
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.235
Tree Protection Zone (TPZ) [m]:	12
Structural Root Zone (SRZ) [m]:	3.62
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.955489
Latitude:	-32.023921

Photos Street View Map View



River Red Gum Tree ID #44

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	19
DBH [cm]:	108
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.29
Tree Protection Zone (TPZ) [m]:	12.96
Structural Root Zone (SRZ) [m]:	3.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.955338
Latitude:	-32.023778

Photos Street View Map View



River Red Gum Tree ID #45

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	43.67
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.85
Tree Protection Zone (TPZ) [m]:	5.24
Structural Root Zone (SRZ) [m]:	3.09
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal recommended, as the union of the trunks has included bark, and there is fungal activity within the trunk, these conditions will degrade the overall structure of the tree in time
Foraging species:	No

Tree Location

Longitude:	115.955150
Latitude:	-32.023622

Photos Street View Map View



River Red Gum Tree ID #46

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	24
DBH [cm]:	109.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.18
Tree Protection Zone (TPZ) [m]:	13.14
Structural Root Zone (SRZ) [m]:	3.55
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Target pruning to uplift the canopy will be required to provide clearance of of ground level
Foraging species:	No

Tree Location

Longitude:	115.954959
Latitude:	-32.023449

Photos Street View Map View



Marri Tree ID #47

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	13
DBH [cm]:	65.4
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.61
Tree Protection Zone (TPZ) [m]:	7.85
Structural Root Zone (SRZ) [m]:	2.69
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	Yes

Tree Location

Longitude:	115.953905
Latitude:	-32.023482

Photos Street View Map View



Marri Tree ID #48

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	9
DBH [cm]:	46.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.474
Tree Protection Zone (TPZ) [m]:	5.54
Structural Root Zone (SRZ) [m]:	2.42
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter and uplift canopy to provide 2m clearance above ground level. Early signs of Marri Canker evident.
Foraging species:	Yes

Tree Location

Longitude:	115.953330
Latitude:	-32.021979

Photos Street View Map View



Marri Tree ID #49

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	4.5
DBH [cm]:	31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.72
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter and uplift canopy to provide 2m clearance above ground level. Early signs of Marri Canker evident.
Foraging species:	Yes

Tree Location

Longitude:	115.953299
Latitude:	-32.021964

Photos Street View Map View



Marri Tree ID #50

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4
DBH [cm]:	23
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.76
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter and uplift canopy to provide 2m clearance above ground level. Early signs of Marri Canker evident.
Foraging species:	Yes

Tree Location

Longitude:	115.953328
Latitude:	-32.021948

Photos Street View Map View



Marri Tree ID #51

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4
DBH [cm]:	23.86
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.59
Tree Protection Zone (TPZ) [m]:	2.86
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter and uplift canopy to provide 2m clearance above ground level.
Foraging species:	Yes

Tree Location

Longitude:	115.953273
Latitude:	-32.021921

Photos Street View Map View



Marri Tree ID #52

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	8
DBH [cm]:	41.82
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	5.02
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter and remove basal sucker by path. Early signs of Marri Canker evident.
Foraging species:	Yes

Tree Location

Longitude:	115.953190
Latitude:	-32.021852

Photos Street View Map View



Marri Tree ID #53

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	8
DBH [cm]:	0.35
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter. Early signs of Marri Canker evident.
Foraging species:	Yes

Tree Location

Longitude:	115.953199
Latitude:	-32.021842

Photos Street View Map View



Desert Fan Palm Tree ID #54

Tree Details

Latin Name:	Washingtonia filifera
Common Name:	Desert Fan Palm
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal recommended as it is an exotic species
Foraging species:	No

Tree Location

Longitude:	115.953187
Latitude:	-32.021834

Photos Street View Map View



Scarlet Bottlebrush Tree ID #55

Tree Details

Latin Name:	Callistemon phoeniceus
Common Name:	Scarlet Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	11-20 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Blue sprawling shrub speciesLow sprawling shrub species
Foraging species:	No

Tree Location

Longitude:	115.953048
Latitude:	-32.021669

Photos Street View Map View



Swamp Mallet Tree ID #56

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	10
DBH [cm]:	43.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	5.22
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.952919
Latitude:	-32.021557

Photos Street View Map View



Swamp Mallet Tree ID #57

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.952965
Latitude:	-32.021513

Photos Street View Map View



Grey Stinkwood Tree ID #58

Tree Details

Latin Name:	Jacksonia furcellata
Common Name:	Grey Stinkwood
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic shrub species
Foraging species:	No

Tree Location

Longitude:	115.952905
Latitude:	-32.021542

Photos Street View Map View



Scarlet Bottlebrush Tree ID #59

Tree Details

Latin Name:	Callistemon phoeniceus
Common Name:	Scarlet Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	9
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic low sprawling shrub species. Remove Arundo (Bamboo) from around it.
Foraging species:	No

Tree Location

Longitude:	115.952847
Latitude:	-32.021479

Photos Street View Map View



Scarlet Bottlebrush Tree ID #60

Tree Details

Latin Name:	Callistemon phoeniceus
Common Name:	Scarlet Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic low sprawling shrub species. Remove Arundo (Bamboo) from around it.
Foraging species:	No

Tree Location

Longitude:	115.952823
Latitude:	-32.021461

Photos Street View Map View



Scarlet Bottlebrush Tree ID #61

Tree Details

Latin Name:	Callistemon phoeniceus
Common Name:	Scarlet Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic low sprawling shrub species. it.
Foraging species:	No

Tree Location

Longitude:	115.952754
Latitude:	-32.021398

Photos Street View Map View



Mahogany Gum Tree ID #62

Tree Details

Latin Name:	Eucalyptus botryoides
Common Name:	Mahogany Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	13
DBH [cm]:	58
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	6.96
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove epicormic shoots on trunk.botry
Foraging species:	No

Tree Location

Longitude:	115.952847
Latitude:	-32.021427

Photos Street View Map View



Swamp Mallet Tree ID #63

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	16
DBH [cm]:	71
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.94
Tree Protection Zone (TPZ) [m]:	8.52
Structural Root Zone (SRZ) [m]:	3.22
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove low branches to uplift canopy and remove all Deadwood over the footpath
Foraging species:	No

Tree Location

Longitude:	115.952637
Latitude:	-32.021291

Photos Street View Map View



Spotted Gum Tree ID #64

Tree Details

Latin Name:	Corymbia maculata
Common Name:	Spotted Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	14
DBH [cm]:	79
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.9
Tree Protection Zone (TPZ) [m]:	9.48
Structural Root Zone (SRZ) [m]:	3.17
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.952669
Latitude:	-32.021262

Photos Street View Map View



Swamp Mallet Tree ID #65

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.952587
Latitude:	-32.021258

Photos Street View Map View



Scarlet Bottlebrush Tree ID #66

Tree Details

Latin Name:	Callistemon phoeniceus
Common Name:	Scarlet Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic low sprawling shrub species. it.
Foraging species:	No

Tree Location

Longitude:	115.952601
Latitude:	-32.021277

Photos Street View Map View



Scarlet Bottlebrush Tree ID #67

Tree Details

Latin Name:	Callistemon phoeniceus
Common Name:	Scarlet Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic low sprawling shrub species. it.
Foraging species:	No

Tree Location

Longitude:	115.952420
Latitude:	-32.021082

Photos Street View Map View



Oleander Tree ID #68

Tree Details

Latin Name:	Nerium Oleander
Common Name:	Oleander
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Exotic weed species, removal is recommended.
Foraging species:	No

Tree Location

Longitude:	115.952502
Latitude:	-32.021148

Photos Street View Map View



Oleander Tree ID #69

Tree Details

Latin Name:	Nerium Oleander
Common Name:	Oleander
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Exotic weed species, removal is recommended.
Foraging species:	No

Tree Location

Longitude:	115.952446
Latitude:	-32.021101

Photos Street View Map View



Flinders Ranges Wattle Tree ID #70

Tree Details

Latin Name:	Acacia iteaphylla
Common Name:	Flinders Ranges Wattle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	4
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal is recommended as is has a low useful life expectancy
Foraging species:	No

Tree Location

Longitude:	115.952414
Latitude:	-32.021063

Photos Street View Map View



Marri Tree ID #71

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.84
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	Yes

Tree Location

Longitude:	115.952379
Latitude:	-32.021038

Photos Street View Map View



Oleander Tree ID #72

Tree Details

Latin Name:	Nerium Oleander
Common Name:	Oleander
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	4
DBH [cm]:	4.8
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Exotic weed species, removal is recommended.
Foraging species:	No

Tree Location

Longitude:	115.952366
Latitude:	-32.021027

Photos Street View Map View



Swamp Mallet Tree ID #73

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift low hanging branches by footpath.
Foraging species:	No

Tree Location

Longitude:	115.952218
Latitude:	-32.020890

Photos Street View Map View



Swamp Mallet Tree ID #74

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	13.96
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in poor condition removal is recommended.
Foraging species:	No

Tree Location

Longitude:	115.951976
Latitude:	-32.020650

Photos Street View Map View



Jacaranda Tree ID #75

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Poor
Structure:	Very Poor
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	0.236
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	1.8
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Tree recently removed, stump remains
Foraging species:	No

Tree Location

Longitude:	115.944420
Latitude:	-32.013312

Photos Street View Map View



Jacaranda Tree ID #76

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Poor
Structure:	Very Poor
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	0.236
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	1.8
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Tree recently removed, stump remains
Foraging species:	No

Tree Location

Longitude:	115.944354
Latitude:	-32.013271

Photos Street View Map View



Jacaranda Tree ID #77

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	37
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	4.44
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.944310
Latitude:	-32.013226

Photos Street View Map View



Jacaranda Tree ID #78

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	0.52
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.54
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.55
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.944275
Latitude:	-32.013166

Photos Street View Map View



Queensland Box Tree ID #79

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	71
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.68
Tree Protection Zone (TPZ) [m]:	8.52
Structural Root Zone (SRZ) [m]:	2.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940051
Latitude:	-32.009243

Photos Street View Map View



Queensland Box Tree ID #80

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	59
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.68
Tree Protection Zone (TPZ) [m]:	7.08
Structural Root Zone (SRZ) [m]:	2.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939933
Latitude:	-32.009113

Photos Street View Map View



Queensland Box Tree ID #81

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	0.52
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939832
Latitude:	-32.009018

Photos Street View Map View



Crepe Myrtle Tree ID #82

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.06
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.02
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940173
Latitude:	-32.009345

Photos Street View Map View



Crepe Myrtle Tree ID #83

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.06
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.02
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940449
Latitude:	-32.009275

Photos Street View Map View



Crepe Myrtle Tree ID #84

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.06
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.02
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940405
Latitude:	-32.009230

Photos Street View Map View



Crepe Myrtle Tree ID #85

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.06
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.02
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940367
Latitude:	-32.009182

Photos Street View Map View



Callery Pear Tree ID #86

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1.5
DBH [cm]:	3
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.08
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940313
Latitude:	-32.009122

Photos Street View Map View



Callery Pear Tree ID #87

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.13
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.4
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940147
Latitude:	-32.008991

Photos Street View Map View



Callery Pear Tree ID #88

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940126
Latitude:	-32.008961

Photos Street View Map View



Callery Pear Tree ID #89

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940155
Latitude:	-32.008893

Photos Street View Map View



Callery Pear Tree ID #90

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940131
Latitude:	-32.008880

Photos Street View Map View



Callery Pear Tree ID #91

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1.5
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939848
Latitude:	-32.008715

Photos Street View Map View



Callery Pear Tree ID #92

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1.5
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939821
Latitude:	-32.008693

Photos Street View Map View



Callery Pear Tree ID #93

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	1.5
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939795
Latitude:	-32.008664

Photos Street View Map View



Callery Pear Tree ID #94

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	1.5
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939761
Latitude:	-32.008639

Photos Street View Map View



Callery Pear Tree ID #95

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	1
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939731
Latitude:	-32.008617

Photos Street View Map View



Callery Pear Tree ID #96

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939702
Latitude:	-32.008590

Photos Street View Map View



Callery Pear Tree ID #97

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939618
Latitude:	-32.008525

Photos Street View Map View



Callery Pear Tree ID #98

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939596
Latitude:	-32.008507

Photos Street View Map View



Callery Pear Tree ID #99

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939564
Latitude:	-32.008473

Photos Street View Map View



Callery Pear Tree ID #100

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939530
Latitude:	-32.008444

Photos Street View Map View



Callery Pear Tree ID #101

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939486
Latitude:	-32.008402

Photos Street View Map View



Callery Pear Tree ID #102

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939465
Latitude:	-32.008293

Photos Street View Map View



Callery Pear Tree ID #103

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939400
Latitude:	-32.008322

Photos Street View Map View



Callery Pear Tree ID #104

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939309
Latitude:	-32.008359

Photos Street View Map View



Callery Pear Tree ID #105

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939332
Latitude:	-32.008263

Photos Street View Map View



Callery Pear Tree ID #106

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939280
Latitude:	-32.008210

Photos Street View Map View



Callery Pear Tree ID #107

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4.5
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939198
Latitude:	-32.008132

Photos Street View Map View



Callery Pear Tree ID #108

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4.5
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939143
Latitude:	-32.008065

Photos Street View Map View



Callery Pear Tree ID #109

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939084
Latitude:	-32.008010

Photos Street View Map View



Callery Pear Tree ID #110

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.939174
Latitude:	-32.007986

Photos Street View Map View



Callery Pear Tree ID #111

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938918
Latitude:	-32.007827

Photos Street View Map View



Callery Pear Tree ID #113

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4.5
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938792
Latitude:	-32.007708

Photos Street View Map View



Callery Pear Tree ID #114

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938750
Latitude:	-32.007658

Photos Street View Map View



Callery Pear Tree ID #115

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938543
Latitude:	-32.007610

Photos Street View Map View



Callery Pear Tree ID #116

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938450
Latitude:	-32.007381

Photos Street View Map View



Callery Pear Tree ID #117

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938350
Latitude:	-32.007282

Photos Street View Map View



Callery Pear Tree ID #118

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938266
Latitude:	-32.007210

Photos Street View Map View



Callery Pear Tree ID #119

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938197
Latitude:	-32.007151

Photos Street View Map View



Callery Pear Tree ID #120

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938148
Latitude:	-32.007101

Photos Street View Map View



Callery Pear Tree ID #121

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.938050
Latitude:	-32.007000

Photos Street View Map View



Callery Pear Tree ID #122


Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.937991
Latitude:	-32.006946

Photos Street View Map View



Callery Pear Tree ID #123

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.937950
Latitude:	-32.006884

Photos Street View Map View



Callery Pear Tree ID #124

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.937034
Latitude:	-32.006124

Photos Street View Map View



Callery Pear Tree ID #125

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.937004
Latitude:	-32.006096

Photos Street View Map View



Claret ash Tree ID #126

Tree Details

Latin Name:	Fraxinus excelsior raywood
Common Name:	Claret ash
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.12
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.36
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.941239
Latitude:	-32.010403

Photos Street View Map View



Claret ash Tree ID #127

Tree Details

Latin Name:	Fraxinus excelsior raywood
Common Name:	Claret ash
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.12
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.36
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.941165
Latitude:	-32.010328

Photos Street View Map View



Claret ash Tree ID #128

Tree Details

Latin Name:	Fraxinus excelsior raywood
Common Name:	Claret ash
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.941079
Latitude:	-32.010254

Photos Street View Map View



Claret ash Tree ID #129

Tree Details

Latin Name:	Fraxinus excelsior raywood
Common Name:	Claret ash
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.940996
Latitude:	-32.010183

Photos Street View Map View



Callery Pear Tree ID #130

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.936162
Latitude:	-32.005401

Photos Street View Map View



Callery Pear Tree ID #131

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.936102
Latitude:	-32.005344

Photos Street View Map View



Callery Pear Tree ID #132

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.936068
Latitude:	-32.005314

Photos Street View Map View



Crepe Myrtle Tree ID #133

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.08
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.936014
Latitude:	-32.005258

Photos Street View Map View



Crepe Myrtle Tree ID #134

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.08
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935954
Latitude:	-32.005212

Photos Street View Map View



Crepe Myrtle Tree ID #135

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.08
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935896
Latitude:	-32.005165

Photos Street View Map View



Crepe Myrtle Tree ID #136

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.08
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935839
Latitude:	-32.005117

Photos Street View Map View



Crepe Myrtle Tree ID #137

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.08
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935766
Latitude:	-32.005069

Photos Street View Map View



Crepe Myrtle Tree ID #138

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.08
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935699
Latitude:	-32.005022

Photos Street View Map View



Crepe Myrtle Tree ID #139

Tree Details

Latin Name:	Lagerstroemia indica
Common Name:	Crepe Myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	3
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935812
Latitude:	-32.005251

Photos Street View Map View



Callery Pear Tree ID #140

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.09
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.2
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935624
Latitude:	-32.005094

Photos Street View Map View



Callery Pear Tree ID #141

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.09
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.2
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935491
Latitude:	-32.004999

Photos Street View Map View



Callery Pear Tree ID #142

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.09
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.2
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935380
Latitude:	-32.004918

Photos Street View Map View



Callery Pear Tree ID #143

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	0.5
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.09
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.2
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	The main leader has been snapped off.
Foraging species:	No

Tree Location

Longitude:	115.935346
Latitude:	-32.004888

Photos Street View Map View



Callery Pear Tree ID #144

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	1
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.09
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.2
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935201
Latitude:	-32.004772

Photos Street View Map View



Callery Pear Tree ID #145

Tree Details

Latin Name:	Pyrus calleryana
Common Name:	Callery Pear
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	45.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.91
Tree Protection Zone (TPZ) [m]:	5.46
Structural Root Zone (SRZ) [m]:	3.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.934987
Latitude:	-32.004622

Photos Street View Map View



Flowering Gum Tree ID #146

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	50
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.57
Tree Protection Zone (TPZ) [m]:	6
Structural Root Zone (SRZ) [m]:	2.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933911
Latitude:	-32.003626

Photos Street View Map View



Flowering Gum Tree ID #147

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	50
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.57
Tree Protection Zone (TPZ) [m]:	6
Structural Root Zone (SRZ) [m]:	2.61
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead removal and replacement recommended.
Foraging species:	No

Tree Location

Longitude:	115.933849
Latitude:	-32.003563

Photos Street View Map View



Flowering Gum Tree ID #148

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	55
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	6.6
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is suffering nutrient deficiencies is recommended to apply 1000l of water with 1% bioprime.
Foraging species:	No

Tree Location

Longitude:	115.933778
Latitude:	-32.003508

Photos Street View Map View



Flowering Gum Tree ID #149

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	30.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.62
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is suffering nutrient deficiencies is recommended to apply 1000l of water with 1% bioprime.
Foraging species:	No

Tree Location

Longitude:	115.933683
Latitude:	-32.003439

Photos Street View Map View



Flowering Gum Tree ID #150

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	5.64
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933548
Latitude:	-32.003330

Photos Street View Map View



Flowering Gum Tree ID #151

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	40
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead removal and replacement recommended.
Foraging species:	No

Tree Location

Longitude:	115.933475
Latitude:	-32.003272

Photos Street View Map View



Flowering Gum Tree ID #152

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	35.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	4.25
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.932923
Latitude:	-32.002832

Photos Street View Map View



Flowering Gum Tree ID #153

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.931606
Latitude:	-32.001827

Photos Street View Map View



Flowering Gum Tree ID #154

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	This tree is dead removal and replacement recommended.
Foraging species:	No

Tree Location

Longitude:	115.931483
Latitude:	-32.001721

Photos Street View Map View



Flowering Gum Tree ID #155

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	83
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.83
Tree Protection Zone (TPZ) [m]:	9.96
Structural Root Zone (SRZ) [m]:	3.06
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Marri Canker evident remove all Deadwood mulch root zone and treat with 1000 litres of water with 1% bioprime
Foraging species:	No

Tree Location

Longitude:	115.931401
Latitude:	-32.001673

Photos Street View Map View



Flowering Gum Tree ID #156

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	81
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	9.72
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Marri Canker evident remove all Deadwood mulch root zone and treat with 1000 litres of water with 1% bioprime
Foraging species:	No

Tree Location

Longitude:	115.931321
Latitude:	-32.001612

Photos Street View Map View



Flowering Gum Tree ID #157

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	5.04
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.931076
Latitude:	-32.001418

Photos Street View Map View



Flowering Gum Tree ID #158

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	40.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.43
Tree Protection Zone (TPZ) [m]:	4.86
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.930921
Latitude:	-32.001299

Photos Street View Map View



Flowering Gum Tree ID #159

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	46.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	5.58
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.930834
Latitude:	-32.001234

Photos Street View Map View



Flowering Gum Tree ID #160

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	50
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.415
Tree Protection Zone (TPZ) [m]:	6
Structural Root Zone (SRZ) [m]:	2.29
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.930762
Latitude:	-32.001178

Photos Street View Map View



Flowering Gum Tree ID #161

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	53.12
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	6.37
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to improve sightlines around tree
Foraging species:	No

Tree Location

Longitude:	115.930689
Latitude:	-32.001113

Photos Street View Map View



Flowering Gum Tree ID #162

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	40
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead removal and replacement recommended.
Foraging species:	No

Tree Location

Longitude:	115.930617
Latitude:	-32.001057

Photos Street View Map View



Flowering Gum Tree ID #163

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	69
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	8.28
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is suffering with Marri Canker, It is recommended to apply 1000l of water with 1% bioprime.
Foraging species:	No

Tree Location

Longitude:	115.929030
Latitude:	-31.999838

Photos Street View Map View



Flowering Gum Tree ID #164

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead, removal and replacement recommended
Foraging species:	No

Tree Location

Longitude:	115.929179
Latitude:	-31.999943

Photos Street View Map View



Flowering Gum Tree ID #165

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.928336
Latitude:	-31.999286

Photos Street View Map View



River Red Gum Tree ID #166

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	104.01
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.82
Tree Protection Zone (TPZ) [m]:	12.48
Structural Root Zone (SRZ) [m]:	3.04
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.958891
Latitude:	-32.026959

Photos Street View Map View



River Red Gum Tree ID #167

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	17
DBH [cm]:	128.35
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.465
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	3.89
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.958761
Latitude:	-32.026863

Photos Street View Map View



River Red Gum Tree ID #170

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	11
DBH [cm]:	94
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.095
Tree Protection Zone (TPZ) [m]:	11.28
Structural Root Zone (SRZ) [m]:	3.44
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.958604
Latitude:	-32.026728

Photos Street View Map View



Swamp Mahogany Tree ID #171

Tree Details

Latin Name:	Eucalyptus robusta
Common Name:	Swamp Mahogany
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	11
DBH [cm]:	67
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.88
Tree Protection Zone (TPZ) [m]:	8.04
Structural Root Zone (SRZ) [m]:	3.14
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958508
Latitude:	-32.026641

Photos Street View Map View



River Red Gum Tree ID #172

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	11
DBH [cm]:	50.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	6.06
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958473
Latitude:	-32.026601

Photos Street View Map View



River Red Gum Tree ID #173

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	13
DBH [cm]:	47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	5.64
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958448
Latitude:	-32.026573

Photos Street View Map View



River Red Gum Tree ID #174

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	13
DBH [cm]:	26.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.335
Tree Protection Zone (TPZ) [m]:	3.18
Structural Root Zone (SRZ) [m]:	2.09
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958416
Latitude:	-32.026552

Photos Street View Map View



River Red Gum Tree ID #175

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	16
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.62
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.71
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958381
Latitude:	-32.026539

Photos Street View Map View



River Red Gum Tree ID #176

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	14
DBH [cm]:	24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	2.88
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958397
Latitude:	-32.026520

Photos Street View Map View



River Red Gum Tree ID #177

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	14
DBH [cm]:	35.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.435
Tree Protection Zone (TPZ) [m]:	4.26
Structural Root Zone (SRZ) [m]:	2.33
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958342
Latitude:	-32.026520

Photos Street View Map View



River Red Gum Tree ID #178

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	3
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958371
Latitude:	-32.026506

Photos Street View Map View



River Red Gum Tree ID #179

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	16
DBH [cm]:	81
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.985
Tree Protection Zone (TPZ) [m]:	9.72
Structural Root Zone (SRZ) [m]:	3.29
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958342
Latitude:	-32.026489

Photos Street View Map View



River Red Gum Tree ID #180

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	11
DBH [cm]:	89.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.87
Tree Protection Zone (TPZ) [m]:	10.74
Structural Root Zone (SRZ) [m]:	3.12
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.958243
Latitude:	-32.026381

Photos Street View Map View



River Red Gum Tree ID #181

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	13
DBH [cm]:	75
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.87
Tree Protection Zone (TPZ) [m]:	9
Structural Root Zone (SRZ) [m]:	3.12
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.958075
Latitude:	-32.026246

Photos Street View Map View



River Red Gum Tree ID #182

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	16
DBH [cm]:	69.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.925
Tree Protection Zone (TPZ) [m]:	8.34
Structural Root Zone (SRZ) [m]:	3.2
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957953
Latitude:	-32.026123

Photos Street View Map View



River Red Gum Tree ID #183

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	56
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.64
Tree Protection Zone (TPZ) [m]:	6.72
Structural Root Zone (SRZ) [m]:	2.74
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957787
Latitude:	-32.025989

Photos Street View Map View



River Red Gum Tree ID #184

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	13
DBH [cm]:	73.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.9
Tree Protection Zone (TPZ) [m]:	8.82
Structural Root Zone (SRZ) [m]:	3.17
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957634
Latitude:	-32.025873

Photos Street View Map View



River Red Gum Tree ID #185

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	15
DBH [cm]:	77.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.945
Tree Protection Zone (TPZ) [m]:	9.3
Structural Root Zone (SRZ) [m]:	3.23
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957594
Latitude:	-32.025833

Photos Street View Map View



River Red Gum Tree ID #186

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	15
DBH [cm]:	108.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.05
Tree Protection Zone (TPZ) [m]:	13.02
Structural Root Zone (SRZ) [m]:	3.38
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter and uplift canopy to 2m above ground level
Foraging species:	No

Tree Location

Longitude:	115.957474
Latitude:	-32.025688

Photos Street View Map View



River Red Gum Tree ID #187

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	15
DBH [cm]:	111
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.18
Tree Protection Zone (TPZ) [m]:	13.32
Structural Root Zone (SRZ) [m]:	3.55
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter and uplift canopy to 2m above ground level
Foraging species:	No

Tree Location

Longitude:	115.957311
Latitude:	-32.025559

Photos Street View Map View



River Red Gum Tree ID #188

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	15
DBH [cm]:	82
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.35
Tree Protection Zone (TPZ) [m]:	9.84
Structural Root Zone (SRZ) [m]:	3.75
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter and uplift canopy to 2m above ground level and remove the two smaller rear leaders to form one main leader.
Foraging species:	No

Tree Location

Longitude:	115.957140
Latitude:	-32.025411

Photos Street View Map View



River Red Gum Tree ID #189

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	16
DBH [cm]:	79
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.99
Tree Protection Zone (TPZ) [m]:	9.48
Structural Root Zone (SRZ) [m]:	3.3
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter and uplift canopy to 2m above ground level.
Foraging species:	No

Tree Location

Longitude:	115.956983
Latitude:	-32.025274

Photos Street View Map View



River Red Gum Tree ID #190

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	18
DBH [cm]:	112
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.265
Tree Protection Zone (TPZ) [m]:	13.44
Structural Root Zone (SRZ) [m]:	3.65
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.956876
Latitude:	-32.025176

Photos Street View Map View



River Red Gum Tree ID #191

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	18
DBH [cm]:	116
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.41
Tree Protection Zone (TPZ) [m]:	13.92
Structural Root Zone (SRZ) [m]:	3.82
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter and uplift to provide 2 m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.956753
Latitude:	-32.025034

Photos Street View Map View



River Red Gum Tree ID #192

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	13
DBH [cm]:	65.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.805
Tree Protection Zone (TPZ) [m]:	7.86
Structural Root Zone (SRZ) [m]:	3.02
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.956595
Latitude:	-32.024910

Photos Street View Map View



River Red Gum Tree ID #193

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	15
DBH [cm]:	96.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.16
Tree Protection Zone (TPZ) [m]:	11.58
Structural Root Zone (SRZ) [m]:	3.52
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.956457
Latitude:	-32.024789

Photos Street View Map View



River Red Gum Tree ID #194

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.295
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	1.98
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956407
Latitude:	-32.024741

Photos Street View Map View



River Red Gum Tree ID #195

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	10
DBH [cm]:	45.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	5.46
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead northern leader
Foraging species:	No

Tree Location

Longitude:	115.956376
Latitude:	-32.024717

Photos Street View Map View



River Red Gum Tree ID #196

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	6
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956333
Latitude:	-32.024681

Photos Street View Map View



River Red Gum Tree ID #197

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	4
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956303
Latitude:	-32.024652

Photos Street View Map View



River Red Gum Tree ID #198

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	13
DBH [cm]:	89
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.07
Tree Protection Zone (TPZ) [m]:	10.68
Structural Root Zone (SRZ) [m]:	3.4
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956267
Latitude:	-32.024619

Photos Street View Map View



River Red Gum Tree ID #199

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	12
DBH [cm]:	45
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.59
Tree Protection Zone (TPZ) [m]:	5.4
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956246
Latitude:	-32.024593

Photos Street View Map View



River Red Gum Tree ID #200

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	2
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead removal recommended.
Foraging species:	No

Tree Location

Longitude:	115.956228
Latitude:	-32.024563

Photos Street View Map View



WA Peppermint Tree ID #201

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5.5
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933364
Latitude:	-32.005376

Photos Street View Map View



WA Peppermint Tree ID #202

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	65
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.83
Tree Protection Zone (TPZ) [m]:	7.8
Structural Root Zone (SRZ) [m]:	3.06
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933447
Latitude:	-32.005456

Photos Street View Map View



Oleander Tree ID #203

Tree Details

Latin Name:	Nerium Oleander
Common Name:	Oleander
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	9
DBH [cm]:	6.56
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	4.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a weed species and is poisonous
Foraging species:	No

Tree Location

Longitude:	115.933438
Latitude:	-32.005248

Photos Street View Map View



WA Peppermint Tree ID #204

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	52
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	6.24
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933583
Latitude:	-32.005332

Photos Street View Map View



Flowering Gum Tree ID #205

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	56
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	6.72
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933679
Latitude:	-32.005329

Photos Street View Map View



WA Peppermint Tree ID #206

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	75
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.77
Tree Protection Zone (TPZ) [m]:	9
Structural Root Zone (SRZ) [m]:	2.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933721
Latitude:	-32.005204

Photos Street View Map View



WA Peppermint Tree ID #207

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Very Poor
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	45
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	5.4
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933590
Latitude:	-32.005161

Photos Street View Map View



Swamp Paperbark Tree ID #208

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	4.5
DBH [cm]:	40.3
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.475
Tree Protection Zone (TPZ) [m]:	4.84
Structural Root Zone (SRZ) [m]:	2.42
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933715
Latitude:	-32.005014

Photos Street View Map View



Swamp Paperbark Tree ID #209

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4.5
DBH [cm]:	78.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.56
Tree Protection Zone (TPZ) [m]:	9.42
Structural Root Zone (SRZ) [m]:	2.59
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933681
Latitude:	-32.005005

Photos Street View Map View



WA Peppermint Tree ID #210

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	38.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	4.66
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933826
Latitude:	-32.004979

Photos Street View Map View



WA Peppermint Tree ID #211

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	45
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	5.4
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933866
Latitude:	-32.005082

Photos Street View Map View



Tuart Tree ID #212

Tree Details

Latin Name:	Eucalyptus gomphocephala
Common Name:	Tuart
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	14
DBH [cm]:	83.3
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.96
Tree Protection Zone (TPZ) [m]:	10
Structural Root Zone (SRZ) [m]:	3.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter, remove basal shoots and uplift to provide 2m clearance above ground level.
Foraging species:	Yes

Tree Location

Longitude:	115.933958
Latitude:	-32.005038

Photos Street View Map View



White Cedar Tree ID #213

Tree Details

Latin Name:	Melia azedarach
Common Name:	White Cedar
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	12
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.933925
Latitude:	-32.005123

Photos Street View Map View



Marri Tree ID #214

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Poor
Structure:	Very Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4
DBH [cm]:	46
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.73
Tree Protection Zone (TPZ) [m]:	5.52
Structural Root Zone (SRZ) [m]:	2.9
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in very poor condition removal is recommended
Foraging species:	Yes

Tree Location

Longitude:	115.933983
Latitude:	-32.005071

Photos Street View Map View



White Cedar Tree ID #215

Tree Details

Latin Name:	Melia azedarach
Common Name:	White Cedar
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	14
DBH [cm]:	93
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.02
Tree Protection Zone (TPZ) [m]:	11.16
Structural Root Zone (SRZ) [m]:	3.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.934071
Latitude:	-32.005204

Photos Street View Map View



Swamp Paperbark Tree ID #216

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	39
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	4.68
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.933932
Latitude:	-32.004822

Photos Street View Map View



Swamp Paperbark Tree ID #217

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	34.67
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.16
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.933959
Latitude:	-32.004797

Photos Street View Map View



Swamp Paperbark Tree ID #218

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.44
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934080
Latitude:	-32.004953

Photos Street View Map View



Swamp Paperbark Tree ID #219

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead removal recommended with only shallow stump grinding so that it does not cause root damage to the adjacent trees
Foraging species:	No

Tree Location

Longitude:	115.934102
Latitude:	-32.004940

Photos Street View Map View



Swamp Paperbark Tree ID #220

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.72
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934144
Latitude:	-32.004999

Photos Street View Map View



Marri Tree ID #221

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Dead
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	10
DBH [cm]:	40
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	Yes

Tree Location

Longitude:	115.934189
Latitude:	-32.005011

Photos Street View Map View



River Red Gum Tree ID #222

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	10
DBH [cm]:	53.15
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	6.38
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934222
Latitude:	-32.005071

Photos Street View Map View



Marri Tree ID #223

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	10
DBH [cm]:	29.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	3.54
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934313
Latitude:	-32.005023

Photos Street View Map View



Marri Tree ID #224

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	10
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934263
Latitude:	-32.005013

Photos Street View Map View



River Red Gum Tree ID #225

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	10
DBH [cm]:	46
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	5.52
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934235
Latitude:	-32.005004

Photos Street View Map View



Marri Tree ID #226

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	10
DBH [cm]:	53
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.78
Tree Protection Zone (TPZ) [m]:	6.36
Structural Root Zone (SRZ) [m]:	2.98
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934204
Latitude:	-32.004981

Photos Street View Map View



Swamp Paperbark Tree ID #227

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.36
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2.15
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934190
Latitude:	-32.004949

Photos Street View Map View



Swamp Paperbark Tree ID #228

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	88
Canopy Spread [m]:	6
DBH [cm]:	58.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.95
Tree Protection Zone (TPZ) [m]:	7.02
Structural Root Zone (SRZ) [m]:	3.24
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934159
Latitude:	-32.004918

Photos Street View Map View



Swamp Paperbark Tree ID #229

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	51
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.44
Tree Protection Zone (TPZ) [m]:	6.12
Structural Root Zone (SRZ) [m]:	2.34
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934122
Latitude:	-32.004906

Photos Street View Map View



Swamp Paperbark Tree ID #230

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	61
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	7.32
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934167
Latitude:	-32.004869

Photos Street View Map View



Marri Tree ID #231

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	6
DBH [cm]:	23
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	2.76
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934285
Latitude:	-32.004968

Photos Street View Map View



Marri Tree ID #232

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	1
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead
Foraging species:	Yes

Tree Location

Longitude:	115.934327
Latitude:	-32.004951

Photos Street View Map View



Swamp Paperbark Tree ID #233

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	23
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.76
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934369
Latitude:	-32.004935

Photos Street View Map View



Marri Tree ID #234

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.11
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.31
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934284
Latitude:	-32.004935

Photos Street View Map View



Marri Tree ID #235

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	11
DBH [cm]:	49.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.64
Tree Protection Zone (TPZ) [m]:	5.9
Structural Root Zone (SRZ) [m]:	2.74
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter.
Foraging species:	Yes

Tree Location

Longitude:	115.934256
Latitude:	-32.004922

Photos Street View Map View



Marri Tree ID #236

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	11
DBH [cm]:	49.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.11
Tree Protection Zone (TPZ) [m]:	5.9
Structural Root Zone (SRZ) [m]:	1.31
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter.
Foraging species:	Yes

Tree Location

Longitude:	115.934261
Latitude:	-32.004913

Photos Street View Map View



Marri Tree ID #237

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	1
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead
Foraging species:	Yes

Tree Location

Longitude:	115.934304
Latitude:	-32.004925

Photos Street View Map View



Marri Tree ID #238

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	1
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead
Foraging species:	Yes

Tree Location

Longitude:	115.934348
Latitude:	-32.004914

Photos Street View Map View



Marri Tree ID #239

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	1
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead
Foraging species:	Yes

Tree Location

Longitude:	115.934324
Latitude:	-32.004903

Photos Street View Map View



Marri Tree ID #240

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	.
Foraging species:	Yes

Tree Location

Longitude:	115.934290
Latitude:	-32.004891

Photos Street View Map View



Marri Tree ID #241

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934325
Latitude:	-32.004868

Photos Street View Map View



Marri Tree ID #242

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934346
Latitude:	-32.004849

Photos Street View Map View



Swamp Paperbark Tree ID #243

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	51
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	6.12
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level and remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.934407
Latitude:	-32.004897

Photos Street View Map View



Marri Tree ID #244

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	11
DBH [cm]:	55
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	6.6
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter.
Foraging species:	Yes

Tree Location

Longitude:	115.934425
Latitude:	-32.004873

Photos Street View Map View



Marri Tree ID #245

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	11
DBH [cm]:	47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.86
Tree Protection Zone (TPZ) [m]:	5.64
Structural Root Zone (SRZ) [m]:	3.11
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	The main leader has died, remove this leader to ground level end keep smaller side shoot.
Foraging species:	Yes

Tree Location

Longitude:	115.934378
Latitude:	-32.004842

Photos Street View Map View



Marri Tree ID #246

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead
Foraging species:	Yes

Tree Location

Longitude:	115.934366
Latitude:	-32.004876

Photos Street View Map View



Marri Tree ID #247

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	27.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.34
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	Yes

Tree Location

Longitude:	115.934439
Latitude:	-32.004839

Photos Street View Map View



Marri Tree ID #248

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	60
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	7.2
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	Yes

Tree Location

Longitude:	115.934395
Latitude:	-32.004816

Photos Street View Map View



Marri Tree ID #249

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	10
DBH [cm]:	63.2
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	7.58
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	Yes

Tree Location

Longitude:	115.934428
Latitude:	-32.004813

Photos Street View Map View



Jarrah Tree ID #250

Tree Details

Latin Name:	Eucalyptus marginata
Common Name:	Jarrah
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	35.48
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.43
Tree Protection Zone (TPZ) [m]:	4.26
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934458
Latitude:	-32.004797

Photos Street View Map View



Marri Tree ID #251

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	14
DBH [cm]:	80
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1
Tree Protection Zone (TPZ) [m]:	9.6
Structural Root Zone (SRZ) [m]:	3.31
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level and remove all Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.934373
Latitude:	-32.004736

Photos Street View Map View



Marri Tree ID #252

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	14
DBH [cm]:	65
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1
Tree Protection Zone (TPZ) [m]:	7.8
Structural Root Zone (SRZ) [m]:	3.31
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level and remove all Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.934390
Latitude:	-32.004687

Photos Street View Map View



Jarrah Tree ID #253

Tree Details

Latin Name:	Eucalyptus marginata
Common Name:	Jarrah
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	11
DBH [cm]:	78
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.89
Tree Protection Zone (TPZ) [m]:	9.36
Structural Root Zone (SRZ) [m]:	3.15
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.934481
Latitude:	-32.004598

Photos Street View Map View



Hibiscus Tree ID #254

Tree Details

Latin Name:	Hibiscus cultivar
Common Name:	Hibiscus
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	29.98
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	1.5
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	3.92
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.934594
Latitude:	-32.004578

Photos Street View Map View



Swamp Paperbark Tree ID #255

Tree Details

Latin Name:	Melaleuca rhaphiophylla
Common Name:	Swamp Paperbark
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	9
DBH [cm]:	54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	6.48
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934069
Latitude:	-32.004688

Photos Street View Map View



Coral Tree Tree ID #256

Tree Details

Latin Name:	Erythrina sykesii
Common Name:	Coral Tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	61
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.2
Tree Protection Zone (TPZ) [m]:	7.32
Structural Root Zone (SRZ) [m]:	3.57
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all lower epicormic shoots in monitor the attachment points of shoots that make up the canopy
Foraging species:	No

Tree Location

Longitude:	115.934164
Latitude:	-32.004614

Photos Street View Map View



Marri Tree ID #257

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Poor
Structure:	Very Poor
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	12
DBH [cm]:	69
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	8.28
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	11-20 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline
Foraging species:	Yes

Tree Location

Longitude:	115.934082
Latitude:	-32.004584

Photos Street View Map View



White Cedar Tree ID #258

Tree Details

Latin Name:	Melia azedarach
Common Name:	White Cedar
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	12
DBH [cm]:	0.9
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	1.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	3.69
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.934145
Latitude:	-32.004498

Photos Street View Map View



WA Peppermint Tree ID #259

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3.5
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.934293
Latitude:	-32.004572

Photos Street View Map View



Fiddlewood Tree ID #260

Tree Details

Latin Name:	Citharexylum spinosum
Common Name:	Fiddlewood
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	40.31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	4.84
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934372
Latitude:	-32.004455

Photos Street View Map View



Hibiscus Tree ID #261

Tree Details

Latin Name:	Hibiscus cultivar
Common Name:	Hibiscus
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	18.65
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	2.24
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.934419
Latitude:	-32.004414

Photos Street View Map View



Jacaranda Tree ID #262

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	8
DBH [cm]:	38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934416
Latitude:	-32.004375

Photos Street View Map View



Coral Tree Tree ID #263

Tree Details

Latin Name:	Erythrina sykesii
Common Name:	Coral Tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	12
DBH [cm]:	62
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.89
Tree Protection Zone (TPZ) [m]:	7.44
Structural Root Zone (SRZ) [m]:	3.15
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934207
Latitude:	-32.004391

Photos Street View Map View



Coral Tree Tree ID #264

Tree Details

Latin Name:	Erythrina sykesii
Common Name:	Coral Tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	15
DBH [cm]:	118.73
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.46
Tree Protection Zone (TPZ) [m]:	14.25
Structural Root Zone (SRZ) [m]:	3.88
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.934166
Latitude:	-32.004368

Photos Street View Map View



Fiddlewood Tree ID #265

Tree Details

Latin Name:	Citharexylum spinosum
Common Name:	Fiddlewood
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	43
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	5.16
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location


Longitude:	115.934363
Latitude:	-32.004294

Photos Street View Map View



5.0 Location of Subject Trees – Part B

Subject tree marked coloured dots in relation to species



5.1 Location of Subject Trees – Part B



5.2 Location of Subject Trees – Part B



5.3 Location of Subject Trees – Part B



5.4 Location of Subject Trees – Part B



5.5 Location of Subject Trees – Part B





5.6 Location of Subject Trees – Part B



5.7 Location of Subject Trees – Part B



5.8 Location of Subject Trees – Part B



5.9 Location of Subject Trees – Part B



5.10 Location of Subject Trees – Part B



5.11 Location of Subject Trees – Part B



5.12 Location of Subject Trees – Part B



5.13 Location of Subject Trees – Part B



5.14 Location of Subject Trees – Part B



5.15 Location of Subject Trees – Part B



5.16 Location of Subject Trees – Part B





5.17 Location of Subject Trees – Part B



Marri Tree ID #1

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	11
DBH [cm]:	67
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.76
Tree Protection Zone (TPZ) [m]:	8.04
Structural Root Zone (SRZ) [m]:	2.95
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2 m clearance above ground level and remove all deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.951550
Latitude:	-32.019792

Photos Street View Map View



Scarlet Bottlebrush Tree ID #2

Tree Details

Latin Name:	Callistemon phoeniceus
Common Name:	Scarlet Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	5
DBH [cm]:	3
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.951622
Latitude:	-32.019794

Photos Street View Map View



Spotted Gum Tree ID #3

Tree Details

Latin Name:	Corymbia maculata
Common Name:	Spotted Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.574
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	2.62
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.951440
Latitude:	-32.019635

Photos Street View Map View



Spotted Gum Tree ID #4

Tree Details

Latin Name:	Corymbia maculata
Common Name:	Spotted Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	47.8
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	5.74
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.951340
Latitude:	-32.019595

Photos Street View Map View



Marri Tree ID #5

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	51.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.624
Tree Protection Zone (TPZ) [m]:	6.18
Structural Root Zone (SRZ) [m]:	2.71
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.951304
Latitude:	-32.019571

Photos Street View Map View



River Red Gum Tree ID #6

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	8.1
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is regrowth from a pre-existing stump, removal and stump grinding is recommended
Foraging species:	No

Tree Location

Longitude:	115.949765
Latitude:	-32.018062

Photos Street View Map View



River Red Gum Tree ID #7

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	8.1
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.13
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.4
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is regrowth from a pre-existing stump, removal and stump grinding is recommended
Foraging species:	No

Tree Location

Longitude:	115.949133
Latitude:	-32.017457

Photos Street View Map View



Flooded Gum Tree ID #8

Tree Details

Latin Name:	Eucalyptus rudis subsp. rudis
Common Name:	Flooded Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	19
DBH [cm]:	92
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.3
Tree Protection Zone (TPZ) [m]:	11.04
Structural Root Zone (SRZ) [m]:	3.69
Useful Life Expectancy:	11-20 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all basil shoots and uplift canopy to provide 2m clearance of the canopy above ground level
Foraging species:	No

Tree Location

Longitude:	115.948073
Latitude:	-32.016383

Photos Street View Map View



Poplar Tree ID #9

Tree Details

Latin Name:	Populus nigra
Common Name:	Poplar
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	No

Tree Location

Longitude:	115.948006
Latitude:	-32.016288

Photos Street View Map View



Poplar Tree ID #10

Tree Details

Latin Name:	Populus nigra
Common Name:	Poplar
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is a poor specimen and does not suit the landscape, it is recemented to remove and stump grind. (Poison to kill it before removal to prevent suckering.)
Foraging species:	No

Tree Location

Longitude:	115.947982
Latitude:	-32.016249

Photos Street View Map View



Flooded Gum Tree ID #11

Tree Details

Latin Name:	Eucalyptus rudis subsp. rudis
Common Name:	Flooded Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	15
DBH [cm]:	95
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.19
Tree Protection Zone (TPZ) [m]:	11.4
Structural Root Zone (SRZ) [m]:	3.56
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.947482
Latitude:	-32.015859

Photos Street View Map View



Common Sheoak Tree ID #12

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	15
DBH [cm]:	89
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.25
Tree Protection Zone (TPZ) [m]:	10.68
Structural Root Zone (SRZ) [m]:	3.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.946828
Latitude:	-32.015123

Photos Street View Map View



Common Sheoak Tree ID #13

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	15
DBH [cm]:	92
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.4
Tree Protection Zone (TPZ) [m]:	11.04
Structural Root Zone (SRZ) [m]:	3.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.946720
Latitude:	-32.015077

Photos Street View Map View



Geraldton Wax Tree ID #14

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	5
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.942352
Latitude:	-32.010767

Photos Street View Map View



Swamp Mallet Tree ID #15

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	39.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.64
Tree Protection Zone (TPZ) [m]:	4.74
Structural Root Zone (SRZ) [m]:	2.74
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead limp to the east and all of the deadwood over 25 mm in diameter, uplift canopy to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.941876
Latitude:	-32.010321

Photos Street View Map View



Acacia Tree ID #16

Tree Details

Latin Name:	Acacia sp
Common Name:	Acacia
Tree Age:	Post Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal is recommended as this tree has reached maturity and would likely only have a couple of years of life left
Foraging species:	No

Tree Location

Longitude:	115.941495
Latitude:	-32.009958

Photos Street View Map View



Acacia Tree ID #17

Tree Details

Latin Name:	Acacia sp
Common Name:	Acacia
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	No

Tree Location

Longitude:	115.941529
Latitude:	-32.009936

Photos Street View Map View



Swamp Mallet Tree ID #18

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	28.7
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.435
Tree Protection Zone (TPZ) [m]:	3.44
Structural Root Zone (SRZ) [m]:	2.33
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.941474
Latitude:	-32.009942

Photos Street View Map View



Eurabbie Tree ID #19

Tree Details

Latin Name:	Eucalyptus bicostata
Common Name:	Eurabbie
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	9
DBH [cm]:	107
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.99
Tree Protection Zone (TPZ) [m]:	12.84
Structural Root Zone (SRZ) [m]:	3.3
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.940491
Latitude:	-32.008916

Photos Street View Map View



Flinders Ranges Wattle Tree ID #20

Tree Details

Latin Name:	Acacia iteaphylla
Common Name:	Flinders Ranges Wattle
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	22.79
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.73
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.940498
Latitude:	-32.008850

Photos Street View Map View



Flinders Ranges Wattle Tree ID #21

Tree Details

Latin Name:	Acacia iteaphylla
Common Name:	Flinders Ranges Wattle
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	17.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	2.14
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline, removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.940484
Latitude:	-32.008837

Photos Street View Map View



Swamp Mahogany Tree ID #22

Tree Details

Latin Name:	Eucalyptus robusta
Common Name:	Swamp Mahogany
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	9
DBH [cm]:	75.3
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.86
Tree Protection Zone (TPZ) [m]:	9.04
Structural Root Zone (SRZ) [m]:	3.11
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.940334
Latitude:	-32.008798

Photos Street View Map View



Swamp Mahogany Tree ID #23

Tree Details

Latin Name:	Eucalyptus robusta
Common Name:	Swamp Mahogany
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	6
DBH [cm]:	75.3
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.86
Tree Protection Zone (TPZ) [m]:	9.04
Structural Root Zone (SRZ) [m]:	3.11
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.940245
Latitude:	-32.008693

Photos Street View Map View



Flowering Gum Tree ID #24

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	67
DBH [cm]:	43.01
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.695
Tree Protection Zone (TPZ) [m]:	5.16
Structural Root Zone (SRZ) [m]:	2.84
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.940056
Latitude:	-32.008422

Photos Street View Map View



Yellow Gum Tree ID #25

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	33.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	4.01
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all low branches to uplift canopy to 2m above ground level and removal deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.939899
Latitude:	-32.008275

Photos Street View Map View



Yellow Gum Tree ID #26

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5.5
DBH [cm]:	19.24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.335
Tree Protection Zone (TPZ) [m]:	2.31
Structural Root Zone (SRZ) [m]:	2.09
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all low branches to uplift canopy to 2m above ground level and removal deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.939861
Latitude:	-32.008246

Photos Street View Map View



Yellow Gum Tree ID #27

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	12
DBH [cm]:	48.21
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	5.79
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift low canopies to provide 2m clearance above ground level and remove all deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.939822
Latitude:	-32.008197

Photos Street View Map View



WA Peppermint Tree ID #28

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6.5
DBH [cm]:	47.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.655
Tree Protection Zone (TPZ) [m]:	5.7
Structural Root Zone (SRZ) [m]:	2.77
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required, good specimen, despite some missing bark.
Foraging species:	No

Tree Location

Longitude:	115.931865
Latitude:	-32.001570

Photos Street View Map View



Swamp Mallet Tree ID #29

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5.5
DBH [cm]:	11.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.43
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift tree to provide 2M clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.931794
Latitude:	-32.001465

Photos Street View Map View



Swamp Mallet Tree ID #30

Tree Details

Latin Name:	Eucalyptus spathulata
Common Name:	Swamp Mallet
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5.5
DBH [cm]:	29.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.313
Tree Protection Zone (TPZ) [m]:	3.5
Structural Root Zone (SRZ) [m]:	2.03
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift tree to provide 2M clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.931745
Latitude:	-32.001438

Photos Street View Map View



Illawarra Flame Tree Tree ID #31

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Mature
Health:	Good
Structure:	Good
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	39.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	45.5
Tree Protection Zone (TPZ) [m]:	4.73
Structural Root Zone (SRZ) [m]:	16.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Good specimen
Foraging species:	No

Tree Location

Longitude:	115.945705
Latitude:	-32.014062

Photos Street View Map View



Kurrajong Tree ID #32

Tree Details

Latin Name:	Brachychiton populneus
Common Name:	Kurrajong
Tree Age:	Mature
Health:	Good
Structure:	Good
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4.5
DBH [cm]:	14.2
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.205
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.7
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Good specimen
Foraging species:	No

Tree Location

Longitude:	115.945672
Latitude:	-32.013950

Photos Street View Map View



Kurrajong Tree ID #33

Tree Details

Latin Name:	Brachychiton populneus
Common Name:	Kurrajong
Tree Age:	Mature
Health:	Good
Structure:	Good
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8.5
DBH [cm]:	41.3
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.478
Tree Protection Zone (TPZ) [m]:	4.96
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Good specimen
Foraging species:	No

Tree Location

Longitude:	115.945632
Latitude:	-32.013899

Photos Street View Map View



Kurrajong Tree ID #34

Tree Details

Latin Name:	Brachychiton populneus
Common Name:	Kurrajong
Tree Age:	Mature
Health:	Good
Structure:	Good
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4.5
DBH [cm]:	27.7
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.36
Tree Protection Zone (TPZ) [m]:	3.32
Structural Root Zone (SRZ) [m]:	2.15
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Good specimen
Foraging species:	No

Tree Location

Longitude:	115.945517
Latitude:	-32.013881

Photos Street View Map View



Illawarra Flame Tree Tree ID #35

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Mature
Health:	Good
Structure:	Good
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8.5
DBH [cm]:	31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	3.72
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Good specimen
Foraging species:	No

Tree Location

Longitude:	115.945102
Latitude:	-32.013467

Photos Street View Map View



Illawarra Flame Tree Tree ID #36

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8.5
DBH [cm]:	23.6
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.294
Tree Protection Zone (TPZ) [m]:	2.83
Structural Root Zone (SRZ) [m]:	1.98
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required.
Foraging species:	No

Tree Location

Longitude:	115.945078
Latitude:	-32.013426

Photos Street View Map View



Bracelet Honey-myrtle Tree ID #37

Tree Details

Latin Name:	Melaleuca armillaris
Common Name:	Bracelet Honey-myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	6
DBH [cm]:	29
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	3.48
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide clearance over the past
Foraging species:	No

Tree Location

Longitude:	115.945036
Latitude:	-32.013422

Photos Street View Map View



Bracelet Honey-myrtle Tree ID #38

Tree Details

Latin Name:	Melaleuca armillaris
Common Name:	Bracelet Honey-myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	6
DBH [cm]:	108.42
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.435
Tree Protection Zone (TPZ) [m]:	13.01
Structural Root Zone (SRZ) [m]:	2.33
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide clearance over the past
Foraging species:	No

Tree Location

Longitude:	115.945015
Latitude:	-32.013405

Photos Street View Map View



Illawarra Flame Tree Tree ID #39

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8.5
DBH [cm]:	21.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.266
Tree Protection Zone (TPZ) [m]:	2.62
Structural Root Zone (SRZ) [m]:	1.9
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	History would benefit from application of 500L by prime at 1%
Foraging species:	No

Tree Location

Longitude:	115.945002
Latitude:	-32.013375

Photos Street View Map View



Kurrajong Tree ID #40

Tree Details

Latin Name:	Brachychiton populneus
Common Name:	Kurrajong
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5.5
DBH [cm]:	33.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.438
Tree Protection Zone (TPZ) [m]:	4.06
Structural Root Zone (SRZ) [m]:	2.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree would benefit from an application of 500L of water with Bioprime at 1%. It is advisable that no further pruning be undertaken on this tree as previous poor pruning has resulted in a loss of canopy on its western side. It needs to be left to fill in the western side of its canopy.
Foraging species:	No

Tree Location

Longitude:	115.945082
Latitude:	-32.013323

Photos Street View Map View



Illawarra Flame Tree Tree ID #41

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2.8
DBH [cm]:	17.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.238
Tree Protection Zone (TPZ) [m]:	2.1
Structural Root Zone (SRZ) [m]:	1.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree would benefit from an application of 500L Bioprime mixed at 1%
Foraging species:	No

Tree Location

Longitude:	115.945048
Latitude:	-32.013299

Photos Street View Map View



Bracelet Honey-myrtle Tree ID #42

Tree Details

Latin Name:	Melaleuca armillaris
Common Name:	Bracelet Honey-myrtle
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	27.99
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.398
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.945168
Latitude:	-32.013386

Photos Street View Map View



Weeping Bottlebrush Tree ID #43

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6.5
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	45.5
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	16.45
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is reaching the end of its useful life.
Foraging species:	No

Tree Location

Longitude:	115.955745
Latitude:	-32.023378

Photos Street View Map View



Marri Tree ID #44

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	44.49
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	5.34
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	.
Foraging species:	Yes

Tree Location

Longitude:	115.956348
Latitude:	-32.024252

Photos Street View Map View



Marri Tree ID #45

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	19.21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	2.31
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	.
Foraging species:	Yes

Tree Location

Longitude:	115.956334
Latitude:	-32.024247

Photos Street View Map View



Marri Tree ID #46

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	12
DBH [cm]:	45
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	5.4
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.956370
Latitude:	-32.024191

Photos Street View Map View



Marri Tree ID #47

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	18
DBH [cm]:	80.61
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.985
Tree Protection Zone (TPZ) [m]:	9.67
Structural Root Zone (SRZ) [m]:	3.29
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.956302
Latitude:	-32.024128

Photos Street View Map View



Marri Tree ID #48

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956299
Latitude:	-32.024194

Photos Street View Map View



Marri Tree ID #49

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.12
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.36
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956273
Latitude:	-32.024186

Photos Street View Map View



Marri Tree ID #50

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956280
Latitude:	-32.024190

Photos Street View Map View



Marri Tree ID #51

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	26.4
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	3.17
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956190
Latitude:	-32.024113

Photos Street View Map View



Marri Tree ID #52

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	41.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.515
Tree Protection Zone (TPZ) [m]:	4.98
Structural Root Zone (SRZ) [m]:	2.5
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.956152
Latitude:	-32.024086

Photos Street View Map View



Marri Tree ID #53

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	39
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	4.68
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.956136
Latitude:	-32.024097

Photos Street View Map View



Marri Tree ID #54

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	7
DBH [cm]:	37
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.44
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.956122
Latitude:	-32.024066

Photos Street View Map View



Grey Stinkwood Tree ID #55

Tree Details

Latin Name:	Jacksonia furcellata
Common Name:	Grey Stinkwood
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	7.07
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic shrub species
Foraging species:	No

Tree Location

Longitude:	115.956261
Latitude:	-32.024164

Photos Street View Map View



Grey Stinkwood Tree ID #56

Tree Details

Latin Name:	Jacksonia furcellata
Common Name:	Grey Stinkwood
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	5.83
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic shrub species
Foraging species:	No

Tree Location

Longitude:	115.956233
Latitude:	-32.024149

Photos Street View Map View



Grey Stinkwood Tree ID #57

Tree Details

Latin Name:	Jacksonia furcellata
Common Name:	Grey Stinkwood
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	8.6
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic shrub species
Foraging species:	No

Tree Location

Longitude:	115.956210
Latitude:	-32.024132

Photos Street View Map View



Marri Tree ID #58

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	10
DBH [cm]:	28.22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	3.39
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.956200
Latitude:	-32.024054

Photos Street View Map View



Marri Tree ID #59

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	12
DBH [cm]:	54.67
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	6.56
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident. Remove dead wood stubs over footpath.
Foraging species:	Yes

Tree Location

Longitude:	115.956169
Latitude:	-32.024029

Photos Street View Map View



Marri Tree ID #60

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	7
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.956109
Latitude:	-32.024057

Photos Street View Map View



Marri Tree ID #61

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	5
DBH [cm]:	40.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.9
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.956101
Latitude:	-32.024042

Photos Street View Map View



Marri Tree ID #62

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956076
Latitude:	-32.024042

Photos Street View Map View



Marri Tree ID #63

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956063
Latitude:	-32.024029

Photos Street View Map View



Marri Tree ID #64

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	10
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956067
Latitude:	-32.023997

Photos Street View Map View



Marri Tree ID #65

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	15
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956049
Latitude:	-32.024009

Photos Street View Map View



Marri Tree ID #66

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956045
Latitude:	-32.023992

Photos Street View Map View



Marri Tree ID #67

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	85
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.75
Tree Protection Zone (TPZ) [m]:	10.2
Structural Root Zone (SRZ) [m]:	2.93
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Marri canker evident on trunk.
Foraging species:	Yes

Tree Location

Longitude:	115.956102
Latitude:	-32.023953

Photos Street View Map View



Marri Tree ID #68

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	67.42
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.85
Tree Protection Zone (TPZ) [m]:	8.09
Structural Root Zone (SRZ) [m]:	3.09
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Signs of Marri canker evidence. Minor uplifting required adjacent to footpath .
Foraging species:	Yes

Tree Location

Longitude:	115.955996
Latitude:	-32.023952

Photos Street View Map View



River Red Gum Tree ID #69

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	11
DBH [cm]:	59
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.76
Tree Protection Zone (TPZ) [m]:	7.08
Structural Root Zone (SRZ) [m]:	2.95
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.955891
Latitude:	-32.023819

Photos Street View Map View



Marri Tree ID #70

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	13
DBH [cm]:	74
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.71
Tree Protection Zone (TPZ) [m]:	8.88
Structural Root Zone (SRZ) [m]:	2.87
Useful Life Expectancy:	11-20 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline likely as a result of adjacent roadworks that may have affected it's root zone.
Foraging species:	Yes

Tree Location

Longitude:	115.955907
Latitude:	-32.023737

Photos Street View Map View



Marri Tree ID #71

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	4
DBH [cm]:	34.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	4.14
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Included bark at the bifurcation 4 m above ground level.
Foraging species:	Yes

Tree Location

Longitude:	115.955806
Latitude:	-32.023760

Photos Street View Map View



Marri Tree ID #72

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	6
DBH [cm]:	28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.955766
Latitude:	-32.023738

Photos Street View Map View



Marri Tree ID #73

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Poor
Structure:	Very Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	13.93
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	11-20 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.955754
Latitude:	-32.023721

Photos Street View Map View



Marri Tree ID #74

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	6
DBH [cm]:	43
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	5.16
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.955735
Latitude:	-32.023696

Photos Street View Map View



Marri Tree ID #76

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	2.88
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.955798
Latitude:	-32.023686

Photos Street View Map View



Marri Tree ID #77

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	9
DBH [cm]:	55.38
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.735
Tree Protection Zone (TPZ) [m]:	6.65
Structural Root Zone (SRZ) [m]:	2.91
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident
Foraging species:	Yes

Tree Location

Longitude:	115.955774
Latitude:	-32.023668

Photos Street View Map View



Marri Tree ID #78

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	45.45
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1
Tree Protection Zone (TPZ) [m]:	5.45
Structural Root Zone (SRZ) [m]:	3.31
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Early signs of Marri Canker evident. This tree has failed many years earlier and fallen on its side, as a result assign branch has now become the main leader and another shoot has emerged from the original based of also formed as a leader.
Foraging species:	Yes

Tree Location

Longitude:	115.955701
Latitude:	-32.023671

Photos Street View Map View



Marri Tree ID #79

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.955737
Latitude:	-32.023638

Photos Street View Map View



Marri Tree ID #80

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	26.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	3.18
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.955686
Latitude:	-32.023655

Photos Street View Map View



Marri Tree ID #81

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.955666
Latitude:	-32.023623

Photos Street View Map View



Marri Tree ID #82

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Fully Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	18
DBH [cm]:	153
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.65
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	4.08
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Marri Canker evident on trunk.
Foraging species:	Yes

Tree Location

Longitude:	115.955764
Latitude:	-32.023552

Photos Street View Map View



Marri Tree ID #83

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	18
DBH [cm]:	108
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.23
Tree Protection Zone (TPZ) [m]:	12.96
Structural Root Zone (SRZ) [m]:	3.61
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Marri Canker evident on trunk.
Foraging species:	Yes

Tree Location

Longitude:	115.955623
Latitude:	-32.023448

Photos Street View Map View



Marri Tree ID #84

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	15
DBH [cm]:	57.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	6.86
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Marri Canker evident on trunk.
Foraging species:	Yes

Tree Location

Longitude:	115.955141
Latitude:	-32.023014

Photos Street View Map View



Marri Tree ID #85

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	15
DBH [cm]:	42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.54
Tree Protection Zone (TPZ) [m]:	5.04
Structural Root Zone (SRZ) [m]:	2.55
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Marri Canker evident on trunk. Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	Yes

Tree Location

Longitude:	115.955116
Latitude:	-32.022985

Photos Street View Map View



Common Sheoak Tree ID #86

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	8
DBH [cm]:	48.72
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	5.85
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.954857
Latitude:	-32.022779

Photos Street View Map View



Common Sheoak Tree ID #87

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	4.5
DBH [cm]:	37.21
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.47
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.954803
Latitude:	-32.022753

Photos Street View Map View



Marri Tree ID #88

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	13
DBH [cm]:	0
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.83
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	3.06
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	There is some canopy decline. Mulching around it's root zone and application of 1000 litres of water with 1% bioprime would be advantageous in improving its health.
Foraging species:	Yes

Tree Location

Longitude:	115.952786
Latitude:	-32.020950

Photos Street View Map View



Yellow Gum Tree ID #89

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	9
DBH [cm]:	29
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	3.48
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.950603
Latitude:	-32.018648

Photos Street View Map View



Yellow Gum Tree ID #90

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	9
DBH [cm]:	29
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	3.48
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.950496
Latitude:	-32.018633

Photos Street View Map View



Yellow Gum Tree ID #91

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.950219
Latitude:	-32.018351

Photos Street View Map View



Yellow Gum Tree ID #92

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.950197
Latitude:	-32.018294

Photos Street View Map View



Marri Tree ID #93

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	8
DBH [cm]:	43.28
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	5.19
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	Remove easternmost trunk dick to source as it is heavily infected with Marri canker. Uplift low hanging branches on the western side.
Foraging species:	Yes

Tree Location

Longitude:	115.950380
Latitude:	-32.018349

Photos Street View Map View



Marri Tree ID #94

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	11
DBH [cm]:	59.52
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.93
Tree Protection Zone (TPZ) [m]:	7.14
Structural Root Zone (SRZ) [m]:	3.21
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.950117
Latitude:	-32.018329

Photos Street View Map View



Silver Princess Tree ID #95

Tree Details

Latin Name:	Eucalyptus caesia
Common Name:	Silver Princess
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.950177
Latitude:	-32.018260

Photos Street View Map View



Silver Princess Tree ID #96

Tree Details

Latin Name:	Eucalyptus caesia
Common Name:	Silver Princess
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	3.84
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.950190
Latitude:	-32.018276

Photos Street View Map View



Yellow Gum Tree ID #97

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.950265
Latitude:	-32.018194

Photos Street View Map View



Red Cap Gum Tree ID #98

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	9
DBH [cm]:	33.56
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.585
Tree Protection Zone (TPZ) [m]:	4.03
Structural Root Zone (SRZ) [m]:	2.64
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.950187
Latitude:	-32.018070

Photos Street View Map View



Red Cap Gum Tree ID #99

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.950144
Latitude:	-32.018045

Photos Street View Map View



Red Cap Gum Tree ID #100

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.950106
Latitude:	-32.017987

Photos Street View Map View



Red Cap Gum Tree ID #101

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	23.54
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	2.82
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.950056
Latitude:	-32.017941

Photos Street View Map View



Red Cap Gum Tree ID #102

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	37.83
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	4.54
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.950017
Latitude:	-32.017903

Photos Street View Map View



Red Cap Gum Tree ID #103

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	23.43
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	2.81
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949972
Latitude:	-32.017863

Photos Street View Map View



Red Cap Gum Tree ID #104

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949860
Latitude:	-32.017752

Photos Street View Map View



Red Cap Gum Tree ID #105

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	14
DBH [cm]:	81.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.915
Tree Protection Zone (TPZ) [m]:	9.78
Structural Root Zone (SRZ) [m]:	3.19
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter, mulch around root zone and treat with 1000L of water with 1% bioprime
Foraging species:	No

Tree Location

Longitude:	115.949625
Latitude:	-32.017531

Photos Street View Map View



Red Cap Gum Tree ID #106

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.949570
Latitude:	-32.017469

Photos Street View Map View



Red Cap Gum Tree ID #107

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	18
DBH [cm]:	96
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.29
Tree Protection Zone (TPZ) [m]:	11.52
Structural Root Zone (SRZ) [m]:	3.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter, mulch around root zone and treat with 1000L of water with 1% bioprime
Foraging species:	No

Tree Location

Longitude:	115.949383
Latitude:	-32.017386

Photos Street View Map View



Red Cap Gum Tree ID #108

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	18
DBH [cm]:	113
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.28
Tree Protection Zone (TPZ) [m]:	13.56
Structural Root Zone (SRZ) [m]:	3.67
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Medium
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter, mulch around root zone and treat with 1000L of water with 1% bioprime
Foraging species:	No

Tree Location

Longitude:	115.949320
Latitude:	-32.017267

Photos Street View Map View



Red Cap Gum Tree ID #109

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	17
DBH [cm]:	71
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.99
Tree Protection Zone (TPZ) [m]:	8.52
Structural Root Zone (SRZ) [m]:	3.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Medium
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter, mulch around root zone.
Foraging species:	No

Tree Location

Longitude:	115.949233
Latitude:	-32.017176

Photos Street View Map View



Red Cap Gum Tree ID #110

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	17
DBH [cm]:	77.65
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.96
Tree Protection Zone (TPZ) [m]:	9.32
Structural Root Zone (SRZ) [m]:	3.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter, mulch around root zone.
Foraging species:	No

Tree Location

Longitude:	115.949201
Latitude:	-32.017300

Photos Street View Map View



River Red Gum Tree ID #111

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	17
DBH [cm]:	53
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.96
Tree Protection Zone (TPZ) [m]:	6.36
Structural Root Zone (SRZ) [m]:	3.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949393
Latitude:	-32.017599

Photos Street View Map View



River Red Gum Tree ID #112

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	5
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949382
Latitude:	-32.017591

Photos Street View Map View



River Red Gum Tree ID #113

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	5
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949362
Latitude:	-32.017590

Photos Street View Map View



River Red Gum Tree ID #114

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	6
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949342
Latitude:	-32.017597

Photos Street View Map View



River Red Gum Tree ID #115

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949393
Latitude:	-32.017562

Photos Street View Map View



River Red Gum Tree ID #116

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949401
Latitude:	-32.017541

Photos Street View Map View



River Red Gum Tree ID #117

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	5
DBH [cm]:	15.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949299
Latitude:	-32.017515

Photos Street View Map View



River Red Gum Tree ID #118

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	3
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949276
Latitude:	-32.017528

Photos Street View Map View



River Red Gum Tree ID #119

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	3
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949247
Latitude:	-32.017509

Photos Street View Map View



River Red Gum Tree ID #120

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	17
DBH [cm]:	54.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	6.54
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949234
Latitude:	-32.017480

Photos Street View Map View



Coral Gum Tree ID #121

Tree Details

Latin Name:	Eucalyptus torquata
Common Name:	Coral Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	9.22
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.949262
Latitude:	-32.017462

Photos Street View Map View



Coral Gum Tree ID #122

Tree Details

Latin Name:	Eucalyptus torquata
Common Name:	Coral Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.949329
Latitude:	-32.017405

Photos Street View Map View



Coral Gum Tree ID #123

Tree Details

Latin Name:	Eucalyptus torquata
Common Name:	Coral Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.949293
Latitude:	-32.017481

Photos Street View Map View



Red Cap Gum Tree ID #124

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	34.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	4.1
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.949005
Latitude:	-32.017141

Photos Street View Map View



Red Cap Gum Tree ID #125

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.948975
Latitude:	-32.017122

Photos Street View Map View



Marri Tree ID #126

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	14
DBH [cm]:	75.59
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.91
Tree Protection Zone (TPZ) [m]:	9.07
Structural Root Zone (SRZ) [m]:	3.18
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Mulch over root zone and treat with 1000 l of water with 1% bioprime.
Foraging species:	Yes

Tree Location

Longitude:	115.948517
Latitude:	-32.016472

Photos Street View Map View



Marri Tree ID #127

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	52.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	6.3
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Mulch over root zone and treat with 1000 l of water with 1% bioprime.
Foraging species:	Yes

Tree Location

Longitude:	115.948143
Latitude:	-32.016099

Photos Street View Map View



Marri Tree ID #128

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	50.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	6.06
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Mulch over root zone and treat with 1000 l of water with 1% bioprime.
Foraging species:	Yes

Tree Location

Longitude:	115.948160
Latitude:	-32.016087

Photos Street View Map View



Common Sheoak Tree ID #129

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	18
DBH [cm]:	85
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.1
Tree Protection Zone (TPZ) [m]:	10.2
Structural Root Zone (SRZ) [m]:	3.44
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.944455
Latitude:	-32.012713

Photos Street View Map View



Jacaranda Tree ID #131

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.943613
Latitude:	-32.011882

Photos Street View Map View



Jacaranda Tree ID #132

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	28.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	3.42
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.943515
Latitude:	-32.011794

Photos Street View Map View



Jacaranda Tree ID #133

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.943401
Latitude:	-32.011683

Photos Street View Map View



Jacaranda Tree ID #134

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	18.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.22
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level and remove basal shoots.
Foraging species:	No

Tree Location

Longitude:	115.943296
Latitude:	-32.011580

Photos Street View Map View



Jacaranda Tree ID #135

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Consider replacing is a better structured tree
Foraging species:	No

Tree Location

Longitude:	115.943182
Latitude:	-32.011470

Photos Street View Map View



Jacaranda Tree ID #136

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	17.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.1
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.943065
Latitude:	-32.011354

Photos Street View Map View



Jacaranda Tree ID #137

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	17.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.1
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.943013
Latitude:	-32.011285

Photos Street View Map View



Yellow Gum Tree ID #138

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	52.59
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	6.31
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.942860
Latitude:	-32.011156

Photos Street View Map View



Yellow Gum Tree ID #139

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	27.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	3.34
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.942814
Latitude:	-32.011108

Photos Street View Map View



Yellow Gum Tree ID #140

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.942767
Latitude:	-32.011085

Photos Street View Map View



Yellow Gum Tree ID #141

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	22.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	2.7
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.942748
Latitude:	-32.011050

Photos Street View Map View



Acacia Tree ID #142

Tree Details

Latin Name:	Acacia saligna
Common Name:	Acacia
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	5
DBH [cm]:	4.47
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	Shrub species
Foraging species:	No

Tree Location

Longitude:	115.941189
Latitude:	-32.009482

Photos Street View Map View



Bracelet Honey-myrtle Tree ID #143

Tree Details

Latin Name:	Melaleuca armillaris
Common Name:	Bracelet Honey-myrtle
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	26.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.412
Tree Protection Zone (TPZ) [m]:	3.14
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	This tree is in generally poor condition
Foraging species:	No

Tree Location

Longitude:	115.954361
Latitude:	-32.022132

Photos Street View Map View



Common Sheoak Tree ID #145

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	14
DBH [cm]:	69
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	78
Tree Protection Zone (TPZ) [m]:	8.28
Structural Root Zone (SRZ) [m]:	20.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.944595
Latitude:	-32.012824

Photos Street View Map View



Common Sheoak Tree ID #146

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	18
DBH [cm]:	99.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.13
Tree Protection Zone (TPZ) [m]:	11.94
Structural Root Zone (SRZ) [m]:	3.48
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.944178
Latitude:	-32.012426

Photos Street View Map View



Jacaranda Tree ID #147

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7.5
DBH [cm]:	28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.943823
Latitude:	-32.012072

Photos Street View Map View



Jacaranda Tree ID #148

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7.5
DBH [cm]:	28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.943728
Latitude:	-32.011992

Photos Street View Map View



Yellow Gum Tree ID #149

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9.5
DBH [cm]:	38.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	4.61
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.936717
Latitude:	-32.005267

Photos Street View Map View



Jacaranda Tree ID #150

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4.5
DBH [cm]:	23
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	2.76
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.936674
Latitude:	-32.005215

Photos Street View Map View



Olive Tree ID #151

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3.5
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.936629
Latitude:	-32.005157

Photos Street View Map View



Jacaranda Tree ID #152

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.04
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.86
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.936551
Latitude:	-32.005107

Photos Street View Map View



River Red Gum Tree ID #153

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.04
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.86
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.936503
Latitude:	-32.005068

Photos Street View Map View



Coral Gum Tree ID #154

Tree Details

Latin Name:	Eucalyptus torquata
Common Name:	Coral Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.12
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.36
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.936335
Latitude:	-32.004945

Photos Street View Map View



Yellow Gum Tree ID #155

Tree Details

Latin Name:	Eucalyptus leucoxylon
Common Name:	Yellow Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	11
DBH [cm]:	39.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.74
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.934566
Latitude:	-32.003545

Photos Street View Map View



Marri Tree ID #156

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	33
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	36
Tree Protection Zone (TPZ) [m]:	3.96
Structural Root Zone (SRZ) [m]:	14.91
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basal shoots
Foraging species:	Yes

Tree Location

Longitude:	115.959141
Latitude:	-32.026610

Photos Street View Map View



Marri Tree ID #157

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	55
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	60
Tree Protection Zone (TPZ) [m]:	6.6
Structural Root Zone (SRZ) [m]:	18.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.959111
Latitude:	-32.026587

Photos Street View Map View



Marri Tree ID #158

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	37
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	4.44
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.959087
Latitude:	-32.026629

Photos Street View Map View



Marri Tree ID #159

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.959057
Latitude:	-32.026614

Photos Street View Map View



Marri Tree ID #160

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	29
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	3.48
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.959044
Latitude:	-32.026597

Photos Street View Map View



Marri Tree ID #161

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	21
Canopy Spread [m]:	10
DBH [cm]:	51
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.68
Tree Protection Zone (TPZ) [m]:	6.12
Structural Root Zone (SRZ) [m]:	2.81
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter , This tree has a minor cavity at its base, however it is producing suitable response growth to manage its structural integrity
Foraging species:	Yes

Tree Location

Longitude:	115.959075
Latitude:	-32.026560

Photos Street View Map View



Marri Tree ID #162

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	10
DBH [cm]:	38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.43
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.959017
Latitude:	-32.026577

Photos Street View Map View



Marri Tree ID #163

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.958994
Latitude:	-32.026577

Photos Street View Map View



Marri Tree ID #164

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	32.65
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	3.92
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.958973
Latitude:	-32.026576

Photos Street View Map View



Marri Tree ID #165

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	58
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.62
Tree Protection Zone (TPZ) [m]:	6.96
Structural Root Zone (SRZ) [m]:	2.71
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.958983
Latitude:	-32.026545

Photos Street View Map View



Marri Tree ID #166

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	56
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	6.72
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.959022
Latitude:	-32.026513

Photos Street View Map View



Marri Tree ID #167

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	3
DBH [cm]:	33.32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	4
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.958938
Latitude:	-32.026535

Photos Street View Map View



Marri Tree ID #168

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.958916
Latitude:	-32.026525

Photos Street View Map View



Marri Tree ID #169

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.958904
Latitude:	-32.026515

Photos Street View Map View



Marri Tree ID #170

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.958913
Latitude:	-32.026507

Photos Street View Map View



Marri Tree ID #171

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	21.26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.55
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter ,
Foraging species:	Yes

Tree Location

Longitude:	115.958887
Latitude:	-32.026507

Photos Street View Map View



Marri Tree ID #172

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	9
DBH [cm]:	76
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	9.12
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter , There is some minor canopy decline is Tree can be treated with 500 litres of water, mixed with 1% Bioprime to reduce stress and assist with regeneration of foliage
Foraging species:	Yes

Tree Location

Longitude:	115.958959
Latitude:	-32.026485

Photos Street View Map View



Marri Tree ID #173

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	9
DBH [cm]:	69
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	8.28
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter , There are signs of Marri Canker on the trunk, this Tree can be treated with There is some minor canopy decline is Tree can be treated with 500 litres of water, mixed with 1% Bioprime to reduce stress and assist with regeneration of foliage
Foraging species:	Yes

Tree Location

Longitude:	115.958920
Latitude:	-32.026452

Photos Street View Map View



Marri Tree ID #174

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	33
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.96
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dead removal is recommended
Foraging species:	Yes

Tree Location

Longitude:	115.958873
Latitude:	-32.026498

Photos Street View Map View



Marri Tree ID #175

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	2
DBH [cm]:	12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	1-5 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is dying, removal is recommended
Foraging species:	Yes

Tree Location

Longitude:	115.958885
Latitude:	-32.026481

Photos Street View Map View



Marri Tree ID #176

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958870
Latitude:	-32.026475

Photos Street View Map View



Marri Tree ID #177

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	21
Canopy Spread [m]:	10
DBH [cm]:	45
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	5.4
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958884
Latitude:	-32.026466

Photos Street View Map View



Marri Tree ID #178

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead leader and preserve other living leader
Foraging species:	Yes

Tree Location

Longitude:	115.958848
Latitude:	-32.026474

Photos Street View Map View



Marri Tree ID #179

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.145
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958858
Latitude:	-32.026457

Photos Street View Map View



Marri Tree ID #180

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	57.43
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1.07
Tree Protection Zone (TPZ) [m]:	6.89
Structural Root Zone (SRZ) [m]:	3.4
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958842
Latitude:	-32.026442

Photos Street View Map View



Marri Tree ID #181

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	41.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	1.07
Tree Protection Zone (TPZ) [m]:	4.97
Structural Root Zone (SRZ) [m]:	3.4
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	Yes

Tree Location

Longitude:	115.958856
Latitude:	-32.026433

Photos Street View Map View



Marri Tree ID #182

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958825
Latitude:	-32.026435

Photos Street View Map View



Marri Tree ID #183

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958889
Latitude:	-32.026432

Photos Street View Map View



Marri Tree ID #184

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958870
Latitude:	-32.026418

Photos Street View Map View



Marri Tree ID #185

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958865
Latitude:	-32.026405

Photos Street View Map View



Marri Tree ID #186

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958876
Latitude:	-32.026396

Photos Street View Map View



Marri Tree ID #187

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting over the PSP required
Foraging species:	Yes

Tree Location

Longitude:	115.958859
Latitude:	-32.026383

Photos Street View Map View



Marri Tree ID #188

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	10.97
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958809
Latitude:	-32.026427

Photos Street View Map View



Marri Tree ID #189


Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	35.78
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	4.29
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958817
Latitude:	-32.026417

Photos Street View Map View



Marri Tree ID #190

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.88
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958790
Latitude:	-32.026416

Photos Street View Map View



Marri Tree ID #191

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	Yes

Tree Location

Longitude:	115.958833
Latitude:	-32.026382

Photos Street View Map View



Marri Tree ID #192

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	Yes

Tree Location

Longitude:	115.958804
Latitude:	-32.026398

Photos Street View Map View



Marri Tree ID #193

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	10
DBH [cm]:	48.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.82
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958786
Latitude:	-32.026400

Photos Street View Map View



Marri Tree ID #194

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958769
Latitude:	-32.026394

Photos Street View Map View



Marri Tree ID #195

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	15.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958761
Latitude:	-32.026383

Photos Street View Map View



Marri Tree ID #196

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958812
Latitude:	-32.026359

Photos Street View Map View



Marri Tree ID #197


Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	7
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958802
Latitude:	-32.026340

Photos Street View Map View



Marri Tree ID #198

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	4
DBH [cm]:	33.42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.01
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958753
Latitude:	-32.026370

Photos Street View Map View



Marri Tree ID #199

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	4
DBH [cm]:	33.53
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	4.02
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958735
Latitude:	-32.026361

Photos Street View Map View



Marri Tree ID #200

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	4
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958737
Latitude:	-32.026352

Photos Street View Map View



Marri Tree ID #201

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	36.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.62
Tree Protection Zone (TPZ) [m]:	4.42
Structural Root Zone (SRZ) [m]:	2.71
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958717
Latitude:	-32.026346

Photos Street View Map View



Marri Tree ID #202

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.36
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.15
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958789
Latitude:	-32.026328

Photos Street View Map View



Marri Tree ID #203

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.36
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.15
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958774
Latitude:	-32.026319

Photos Street View Map View



Marri Tree ID #204

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	40
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958715
Latitude:	-32.026334

Photos Street View Map View



Marri Tree ID #205

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to Provide 2 m clearance above ground level for passive surveillance
Foraging species:	Yes

Tree Location

Longitude:	115.958762
Latitude:	-32.026300

Photos Street View Map View



Marri Tree ID #206

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to Provide 2 m clearance above ground level for passive surveillance
Foraging species:	Yes

Tree Location

Longitude:	115.958742
Latitude:	-32.026308

Photos Street View Map View



Marri Tree ID #207

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	38.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	4.62
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958671
Latitude:	-32.026299

Photos Street View Map View



Marri Tree ID #208

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	49.86
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	5.98
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter and dead leader
Foraging species:	Yes

Tree Location

Longitude:	115.958641
Latitude:	-32.026269

Photos Street View Map View



Marri Tree ID #209

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958625
Latitude:	-32.026257

Photos Street View Map View



Marri Tree ID #210

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.12
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.36
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958608
Latitude:	-32.026261

Photos Street View Map View



Marri Tree ID #211

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	12
DBH [cm]:	57
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	6.84
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is experiencing canopy decline possibly due to the presence of Mary canker treat is 500 L of water with 1% bio prime and monitor it's health
Foraging species:	Yes

Tree Location

Longitude:	115.958675
Latitude:	-32.026224

Photos Street View Map View



Marri Tree ID #212

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	13
DBH [cm]:	59
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	7.08
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is experiencing canopy decline possibly due to the presence of Mary canker treat is 500 L of water with 1% bio prime and monitor it's health
Foraging species:	Yes

Tree Location

Longitude:	115.958641
Latitude:	-32.026195

Photos Street View Map View



Marri Tree ID #213

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958582
Latitude:	-32.026241

Photos Street View Map View



Marri Tree ID #214

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958589
Latitude:	-32.026231

Photos Street View Map View



River Red Gum Tree ID #215

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	4
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.958543
Latitude:	-32.026204

Photos Street View Map View



Marri Tree ID #216

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	2
DBH [cm]:	43.19
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.67
Tree Protection Zone (TPZ) [m]:	5.18
Structural Root Zone (SRZ) [m]:	2.8
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958557
Latitude:	-32.026132

Photos Street View Map View



Marri Tree ID #217

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	15.23
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958505
Latitude:	-32.026175

Photos Street View Map View



Marri Tree ID #218

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	20.16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	2.42
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958490
Latitude:	-32.026163

Photos Street View Map View



Marri Tree ID #219

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	16.35
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958499
Latitude:	-32.026148

Photos Street View Map View



Marri Tree ID #220

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	32.53
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	3.9
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide clearance above ground level
Foraging species:	Yes

Tree Location

Longitude:	115.958456
Latitude:	-32.026126

Photos Street View Map View



River Red Gum Tree ID #221

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.958469
Latitude:	-32.026065

Photos Street View Map View



Marri Tree ID #222

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	28.84
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	3.46
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958469
Latitude:	-32.026032

Photos Street View Map View



Marri Tree ID #223

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.88
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958447
Latitude:	-32.026040

Photos Street View Map View



Marri Tree ID #224

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	11.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958385
Latitude:	-32.026037

Photos Street View Map View



Marri Tree ID #225

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	6
DBH [cm]:	24.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	2.94
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958388
Latitude:	-32.026026

Photos Street View Map View



Marri Tree ID #226

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	49.04
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	5.88
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958428
Latitude:	-32.026014

Photos Street View Map View



Marri Tree ID #227

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958413
Latitude:	-32.026003

Photos Street View Map View



Marri Tree ID #228

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958363
Latitude:	-32.026019

Photos Street View Map View



Marri Tree ID #229

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958373
Latitude:	-32.026009

Photos Street View Map View



Marri Tree ID #230

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	14.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.175
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.59
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958338
Latitude:	-32.026001

Photos Street View Map View



Marri Tree ID #231

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	8.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958314
Latitude:	-32.025981

Photos Street View Map View



Marri Tree ID #232

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	29
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.48
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958336
Latitude:	-32.025920

Photos Street View Map View



Marri Tree ID #233

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	13
DBH [cm]:	60.88
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	7.31
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958312
Latitude:	-32.025899

Photos Street View Map View



Marri Tree ID #234

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	15
DBH [cm]:	77
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.85
Tree Protection Zone (TPZ) [m]:	9.24
Structural Root Zone (SRZ) [m]:	3.09
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958316
Latitude:	-32.025859

Photos Street View Map View



Marri Tree ID #235

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958294
Latitude:	-32.025880

Photos Street View Map View



Marri Tree ID #236

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	16
DBH [cm]:	76.3
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	9.16
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958275
Latitude:	-32.025868

Photos Street View Map View



Marri Tree ID #237

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	15
DBH [cm]:	41.18
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	4.94
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958285
Latitude:	-32.025945

Photos Street View Map View



Marri Tree ID #238

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.958273
Latitude:	-32.025921

Photos Street View Map View



Marri Tree ID #239

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	70.04
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.68
Tree Protection Zone (TPZ) [m]:	8.4
Structural Root Zone (SRZ) [m]:	2.81
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter. This tree it by Marri Canker on main trunk, monitor it's progress over the next 18 months
Foraging species:	Yes

Tree Location

Longitude:	115.958255
Latitude:	-32.025904

Photos Street View Map View



Marri Tree ID #240

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	14
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all deadwood over 25 mm in diameter.
Foraging species:	Yes

Tree Location

Longitude:	115.958234
Latitude:	-32.025886

Photos Street View Map View



Marri Tree ID #241

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	3
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958216
Latitude:	-32.025870

Photos Street View Map View



Marri Tree ID #242

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	Very Poor
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	3
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	Yes

Tree Location

Longitude:	115.958181
Latitude:	-32.025855

Photos Street View Map View



Marri Tree ID #243

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	3
DBH [cm]:	28.27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3.39
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958159
Latitude:	-32.025842

Photos Street View Map View



Marri Tree ID #244

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958137
Latitude:	-32.025825

Photos Street View Map View



Grey Stinkwood Tree ID #245

Tree Details

Latin Name:	Jacksonia furcellata
Common Name:	Grey Stinkwood
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	7.07
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Endemic shrub species
Foraging species:	No

Tree Location

Longitude:	115.958118
Latitude:	-32.025814

Photos Street View Map View



Marri Tree ID #246

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958104
Latitude:	-32.025805

Photos Street View Map View



Marri Tree ID #247

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958084
Latitude:	-32.025798

Photos Street View Map View



Marri Tree ID #248

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.215
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.74
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958074
Latitude:	-32.025789

Photos Street View Map View



Marri Tree ID #249

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	3
DBH [cm]:	43.76
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.82
Tree Protection Zone (TPZ) [m]:	5.25
Structural Root Zone (SRZ) [m]:	3.04
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958052
Latitude:	-32.025776

Photos Street View Map View



Marri Tree ID #250

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	3
DBH [cm]:	29.21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.78
Tree Protection Zone (TPZ) [m]:	3.51
Structural Root Zone (SRZ) [m]:	2.98
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958040
Latitude:	-32.025761

Photos Street View Map View



Marri Tree ID #251

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	5
DBH [cm]:	44.52
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	5.34
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.958008
Latitude:	-32.025731

Photos Street View Map View



Marri Tree ID #252

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	59.51
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1.21
Tree Protection Zone (TPZ) [m]:	7.14
Structural Root Zone (SRZ) [m]:	3.59
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.957968
Latitude:	-32.025708

Photos Street View Map View



Marri Tree ID #253

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	Yes

Tree Location

Longitude:	115.957847
Latitude:	-32.025620

Photos Street View Map View



Marri Tree ID #254

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	14
DBH [cm]:	70
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.95
Tree Protection Zone (TPZ) [m]:	8.4
Structural Root Zone (SRZ) [m]:	3.24
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.957924
Latitude:	-32.025570

Photos Street View Map View



Marri Tree ID #255

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	33
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.96
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.957807
Latitude:	-32.025454

Photos Street View Map View



Marri Tree ID #256

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	62.94
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	7.55
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.957750
Latitude:	-32.025500

Photos Street View Map View



Marri Tree ID #257

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957756
Latitude:	-32.025431

Photos Street View Map View



Marri Tree ID #258

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	5.04
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957683
Latitude:	-32.025445

Photos Street View Map View



Marri Tree ID #259

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	29
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.36
Tree Protection Zone (TPZ) [m]:	3.48
Structural Root Zone (SRZ) [m]:	2.15
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957654
Latitude:	-32.025427

Photos Street View Map View



Marri Tree ID #260

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	12
DBH [cm]:	55
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	6.6
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957699
Latitude:	-32.025370

Photos Street View Map View



Marri Tree ID #261


Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957667
Latitude:	-32.025350

Photos Street View Map View



Marri Tree ID #262

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	33
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	3.96
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957627
Latitude:	-32.025379

Photos Street View Map View



Marri Tree ID #263

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	41.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	4.97
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957597
Latitude:	-32.025356

Photos Street View Map View



Marri Tree ID #264

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	37.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.44
Tree Protection Zone (TPZ) [m]:	4.5
Structural Root Zone (SRZ) [m]:	2.34
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957571
Latitude:	-32.025331

Photos Street View Map View



Marri Tree ID #265

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	13.04
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957603
Latitude:	-32.025284

Photos Street View Map View



Marri Tree ID #266

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	21.93
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.63
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957600
Latitude:	-32.025254

Photos Street View Map View



Marri Tree ID #267

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	10
DBH [cm]:	38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is experiencing canopy decline treat leaves 500 L of water with 1% bio prime and monitor
Foraging species:	Yes

Tree Location

Longitude:	115.957589
Latitude:	-32.025240

Photos Street View Map View



Marri Tree ID #268

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	7
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957557
Latitude:	-32.025227

Photos Street View Map View



Marri Tree ID #269

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	42.07
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	5.05
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.957522
Latitude:	-32.025199

Photos Street View Map View



Marri Tree ID #270

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	12
DBH [cm]:	47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.64
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.957528
Latitude:	-32.025129

Photos Street View Map View



Marri Tree ID #271

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	7
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957469
Latitude:	-32.025102

Photos Street View Map View



Marri Tree ID #272

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	7
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957466
Latitude:	-32.025138

Photos Street View Map View



Marri Tree ID #273

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957412
Latitude:	-32.025122

Photos Street View Map View



Marri Tree ID #274

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957383
Latitude:	-32.025104

Photos Street View Map View



Marri Tree ID #275

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	12
DBH [cm]:	73.68
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.26
Tree Protection Zone (TPZ) [m]:	8.84
Structural Root Zone (SRZ) [m]:	3.65
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957332
Latitude:	-32.025104

Photos Street View Map View



River Red Gum Tree ID #276

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	24.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.98
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.957361
Latitude:	-32.025069

Photos Street View Map View



River Red Gum Tree ID #277

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	No

Tree Location

Longitude:	115.957348
Latitude:	-32.025047

Photos Street View Map View



Marri Tree ID #278

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	5
DBH [cm]:	48.92
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.87
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957285
Latitude:	-32.025063

Photos Street View Map View



Marri Tree ID #279

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	37.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.5
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957263
Latitude:	-32.025059

Photos Street View Map View



River Red Gum Tree ID #280

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	14.42
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is comprised of to epicormic shoots as a result of losing is the original main leader removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.957248
Latitude:	-32.025048

Photos Street View Map View



River Red Gum Tree ID #281

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.957237
Latitude:	-32.025036

Photos Street View Map View



River Red Gum Tree ID #282

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.13
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.4
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.957245
Latitude:	-32.025029

Photos Street View Map View



Marri Tree ID #283

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	5
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.957333
Latitude:	-32.024978

Photos Street View Map View



River Red Gum Tree ID #284

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	6
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.957179
Latitude:	-32.024982

Photos Street View Map View



River Red Gum Tree ID #285

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	13
DBH [cm]:	63
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.72
Tree Protection Zone (TPZ) [m]:	7.56
Structural Root Zone (SRZ) [m]:	2.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957158
Latitude:	-32.024965

Photos Street View Map View



River Red Gum Tree ID #286

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	10
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957166
Latitude:	-32.024947

Photos Street View Map View



River Red Gum Tree ID #287

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	7
DBH [cm]:	25.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	3.06
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957140
Latitude:	-32.024949

Photos Street View Map View



River Red Gum Tree ID #288

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	7
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957124
Latitude:	-32.024937

Photos Street View Map View



River Red Gum Tree ID #289

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957105
Latitude:	-32.024925

Photos Street View Map View



River Red Gum Tree ID #290

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	8
DBH [cm]:	24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.88
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957081
Latitude:	-32.024910

Photos Street View Map View



River Red Gum Tree ID #291

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	8
DBH [cm]:	27.46
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	3.3
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.957070
Latitude:	-32.024900

Photos Street View Map View



Marri Tree ID #292

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.957037
Latitude:	-32.024829

Photos Street View Map View



Marri Tree ID #293

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4
DBH [cm]:	24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	2.88
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	0 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	Yes

Tree Location

Longitude:	115.957005
Latitude:	-32.024831

Photos Street View Map View



Marri Tree ID #294

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956988
Latitude:	-32.024818

Photos Street View Map View



Marri Tree ID #295

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	26.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.18
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956974
Latitude:	-32.024805

Photos Street View Map View



Marri Tree ID #296

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956961
Latitude:	-32.024797

Photos Street View Map View



Marri Tree ID #297

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	11
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956973
Latitude:	-32.024739

Photos Street View Map View



Marri Tree ID #298

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	7
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956966
Latitude:	-32.024712

Photos Street View Map View



Marri Tree ID #299

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	7
DBH [cm]:	37
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	4.44
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956898
Latitude:	-32.024728

Photos Street View Map View



Marri Tree ID #300

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	21.26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	2.55
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956901
Latitude:	-32.024746

Photos Street View Map View



Marri Tree ID #301

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	8
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956918
Latitude:	-32.024682

Photos Street View Map View



Marri Tree ID #302

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	8
DBH [cm]:	38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956851
Latitude:	-32.024697

Photos Street View Map View



WA Peppermint Tree ID #303

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956848
Latitude:	-32.024630

Photos Street View Map View



WA Peppermint Tree ID #304

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	33.3
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	1
Tree Protection Zone (TPZ) [m]:	4
Structural Root Zone (SRZ) [m]:	3.31
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to improve passive surveillance
Foraging species:	No

Tree Location

Longitude:	115.956800
Latitude:	-32.024642

Photos Street View Map View



WA Peppermint Tree ID #305

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	32.9
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.77
Tree Protection Zone (TPZ) [m]:	3.95
Structural Root Zone (SRZ) [m]:	2.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to improve passive surveillance
Foraging species:	No

Tree Location

Longitude:	115.956778
Latitude:	-32.024636

Photos Street View Map View



Marri Tree ID #306

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956799
Latitude:	-32.024657

Photos Street View Map View



WA Peppermint Tree ID #307

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956799
Latitude:	-32.024608

Photos Street View Map View



WA Peppermint Tree ID #308

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	36.51
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.75
Tree Protection Zone (TPZ) [m]:	4.38
Structural Root Zone (SRZ) [m]:	2.93
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.956743
Latitude:	-32.024606

Photos Street View Map View



WA Peppermint Tree ID #309

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	12.9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.365
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.17
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.956750
Latitude:	-32.024595

Photos Street View Map View



WA Peppermint Tree ID #310

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	11.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956754
Latitude:	-32.024585

Photos Street View Map View



Coastal Tea Tree Tree ID #311

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	8.12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This shrub can be regarded as a weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.956736
Latitude:	-32.024581

Photos Street View Map View



Marri Tree ID #312

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	8
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956790
Latitude:	-32.024576

Photos Street View Map View



Marri Tree ID #313

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	8
DBH [cm]:	30.23
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	3.63
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956773
Latitude:	-32.024561

Photos Street View Map View



WA Peppermint Tree ID #314

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4
DBH [cm]:	21.02
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956710
Latitude:	-32.024576

Photos Street View Map View



WA Peppermint Tree ID #315

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956681
Latitude:	-32.024573

Photos Street View Map View



WA Peppermint Tree ID #316

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	0
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	No

Tree Location

Longitude:	115.956663
Latitude:	-32.024565

Photos Street View Map View



WA Peppermint Tree ID #317

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	25.1
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.43
Tree Protection Zone (TPZ) [m]:	3.01
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.956667
Latitude:	-32.024553

Photos Street View Map View



WA Peppermint Tree ID #318

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	9
DBH [cm]:	45
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1
Tree Protection Zone (TPZ) [m]:	5.4
Structural Root Zone (SRZ) [m]:	3.31
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplift canopy to provide 2 m clearance and improve passive surveillance
Foraging species:	No

Tree Location

Longitude:	115.956621
Latitude:	-32.024541

Photos Street View Map View



Marri Tree ID #319

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	8
DBH [cm]:	23
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	2.76
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956648
Latitude:	-32.024513

Photos Street View Map View



WA Peppermint Tree ID #320

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	9
DBH [cm]:	24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.88
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead tree
Foraging species:	No

Tree Location

Longitude:	115.956605
Latitude:	-32.024542

Photos Street View Map View



Coastal Tea Tree Tree ID #321

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	8.12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This shrub can be regarded as a weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.956578
Latitude:	-32.024427

Photos Street View Map View



Coastal Tea Tree Tree ID #322

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	8.12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This shrub can be regarded as a weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.956535
Latitude:	-32.024389

Photos Street View Map View



Coastal Tea Tree Tree ID #323

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	8.12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This shrub can be regarded as a weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.956488
Latitude:	-32.024365

Photos Street View Map View



Coastal Tea Tree Tree ID #324

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Has Failed
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	8.12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This shrub can be regarded as a weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.956472
Latitude:	-32.024326

Photos Street View Map View



Coastal Tea Tree Tree ID #325

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Has Failed
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	65
DBH [cm]:	8.12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This shrub can be regarded as a weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.956404
Latitude:	-32.024297

Photos Street View Map View



Marri Tree ID #326

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956546
Latitude:	-32.024431

Photos Street View Map View



Marri Tree ID #327

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	Yes

Tree Location

Longitude:	115.956510
Latitude:	-32.024399

Photos Street View Map View



Marri Tree ID #328

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	8
DBH [cm]:	51
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.61
Tree Protection Zone (TPZ) [m]:	6.12
Structural Root Zone (SRZ) [m]:	2.69
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956457
Latitude:	-32.024368

Photos Street View Map View



Marri Tree ID #329

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956563
Latitude:	-32.024387

Photos Street View Map View



Marri Tree ID #330

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	14
DBH [cm]:	61.73
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	7.41
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956531
Latitude:	-32.024348

Photos Street View Map View



Marri Tree ID #331

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	25.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	3.06
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956438
Latitude:	-32.024344

Photos Street View Map View



Marri Tree ID #332

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	36.95
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.59
Tree Protection Zone (TPZ) [m]:	4.43
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level to improve passive surveillance
Foraging species:	Yes

Tree Location

Longitude:	115.956424
Latitude:	-32.024320

Photos Street View Map View



Marri Tree ID #333

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	5.04
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level to improve passive surveillance
Foraging species:	Yes

Tree Location

Longitude:	115.956382
Latitude:	-32.024289

Photos | Street View | Map View



Marri Tree ID #334

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	66.88
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.74
Tree Protection Zone (TPZ) [m]:	8.03
Structural Root Zone (SRZ) [m]:	2.92
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level to improve passive surveillance
Foraging species:	Yes

Tree Location

Longitude:	115.956370
Latitude:	-32.024280

Photos Street View Map View



Marri Tree ID #335

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	12.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.16
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.53
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level to improve passive surveillance
Foraging species:	Yes

Tree Location

Longitude:	115.956383
Latitude:	-32.024272

Photos Street View Map View



Marri Tree ID #336

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	8.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.11
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.31
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.956365
Latitude:	-32.024251

Photos Street View Map View



Marri Tree ID #337

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	7
DBH [cm]:	26.44
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	3.17
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level to improve passive surveillance
Foraging species:	Yes

Tree Location

Longitude:	115.956364
Latitude:	-32.024262

Photos Street View Map View



Marri Tree ID #338

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	.no work required
Foraging species:	Yes

Tree Location

Longitude:	115.956389
Latitude:	-32.024235

Photos Street View Map View



Queensland Box Tree ID #339

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	38.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.62
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.934861
Latitude:	-32.003592

Photos Street View Map View



WA Peppermint Tree ID #340

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	3.72
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935596
Latitude:	-32.003435

Photos Street View Map View



WA Peppermint Tree ID #341

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	3.72
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935708
Latitude:	-32.003346

Photos Street View Map View



Moreton Bay Fig Tree ID #342

Tree Details

Latin Name:	Ficus macrophylla
Common Name:	Moreton Bay Fig
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	18
DBH [cm]:	1.25
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	1.4
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	3.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplift canopy to 2 m above ground level
Foraging species:	No

Tree Location

Longitude:	115.935091
Latitude:	-32.003654

Photos Street View Map View



Common Lilly Pilly Tree ID #343

Tree Details

Latin Name:	Acmena smithii
Common Name:	Common Lilly Pilly
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	16
DBH [cm]:	63.41
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.08
Tree Protection Zone (TPZ) [m]:	7.61
Structural Root Zone (SRZ) [m]:	3.42
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935330
Latitude:	-32.003491

Photos Street View Map View



River Red Gum Tree ID #344

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	21
Canopy Spread [m]:	16
DBH [cm]:	67
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.87
Tree Protection Zone (TPZ) [m]:	8.04
Structural Root Zone (SRZ) [m]:	3.12
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935420
Latitude:	-32.003435

Photos Street View Map View



Broad-leaved Paperbark Tree ID #345

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	8
DBH [cm]:	48.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.545
Tree Protection Zone (TPZ) [m]:	5.78
Structural Root Zone (SRZ) [m]:	2.56
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935119
Latitude:	-32.003498

Photos Street View Map View



Broad-leaved Paperbark Tree ID #346

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	8
DBH [cm]:	54.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.68
Tree Protection Zone (TPZ) [m]:	6.54
Structural Root Zone (SRZ) [m]:	2.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935142
Latitude:	-32.003480

Photos Street View Map View



Cape Honey suckle Tree ID #347

Tree Details

Latin Name:	Tecomaria capensis
Common Name:	Cape Honey suckle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	10
DBH [cm]:	65.25
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.99
Tree Protection Zone (TPZ) [m]:	7.83
Structural Root Zone (SRZ) [m]:	3.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935317
Latitude:	-32.003361

Photos Street View Map View



River Red Gum Tree ID #348

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	13
DBH [cm]:	78.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.9
Tree Protection Zone (TPZ) [m]:	9.42
Structural Root Zone (SRZ) [m]:	3.17
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Fungal fruiting body observed at base of the trunk, sonic tomography is recommended to determine wall thickness
Foraging species:	No

Tree Location

Longitude:	115.935355
Latitude:	-32.003872

Photos Street View Map View



River Red Gum Tree ID #349

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	13
DBH [cm]:	89
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.04
Tree Protection Zone (TPZ) [m]:	10.68
Structural Root Zone (SRZ) [m]:	3.36
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935375
Latitude:	-32.003829

Photos Street View Map View



Weeping Bottlebrush Tree ID #350

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	19.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.34
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935406
Latitude:	-32.003787

Photos Street View Map View



Weeping Bottlebrush Tree ID #351

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	34.68
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.51
Tree Protection Zone (TPZ) [m]:	4.16
Structural Root Zone (SRZ) [m]:	2.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935411
Latitude:	-32.003766

Photos Street View Map View



Swamp Mahogany Tree ID #352

Tree Details

Latin Name:	Eucalyptus robusta
Common Name:	Swamp Mahogany
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	7
DBH [cm]:	47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	5.64
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935445
Latitude:	-32.003725

Photos Street View Map View



Swamp Mahogany Tree ID #353

Tree Details

Latin Name:	Eucalyptus robusta
Common Name:	Swamp Mahogany
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	8
DBH [cm]:	64
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	7.68
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935498
Latitude:	-32.003683

Photos Street View Map View



Marri Tree ID #354

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance over verge.
Foraging species:	Yes

Tree Location

Longitude:	115.935566
Latitude:	-32.003627

Photos Street View Map View



Swamp Mahogany Tree ID #355

Tree Details

Latin Name:	Eucalyptus robusta
Common Name:	Swamp Mahogany
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	16
DBH [cm]:	66.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.75
Tree Protection Zone (TPZ) [m]:	7.98
Structural Root Zone (SRZ) [m]:	2.93
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935593
Latitude:	-32.003642

Photos Street View Map View



River Red Gum Tree ID #356

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	17
DBH [cm]:	75.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.98
Tree Protection Zone (TPZ) [m]:	9.06
Structural Root Zone (SRZ) [m]:	3.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935640
Latitude:	-32.003580

Photos Street View Map View



WA Peppermint Tree ID #357

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935647
Latitude:	-32.003532

Photos Street View Map View



Pepper Tree Tree ID #358

Tree Details

Latin Name:	Schinus molle
Common Name:	Pepper Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	0.49
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935775
Latitude:	-32.003498

Photos Street View Map View



Tasmanian Blue Gum Tree ID #359

Tree Details

Latin Name:	Eucalyptus globulus
Common Name:	Tasmanian Blue Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	8
DBH [cm]:	84
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.95
Tree Protection Zone (TPZ) [m]:	10.08
Structural Root Zone (SRZ) [m]:	3.24
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935817
Latitude:	-32.003513

Photos Street View Map View



River Red Gum Tree ID #360

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	8
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935831
Latitude:	-32.003528

Photos Street View Map View



Mahogany Gum Tree ID #361

Tree Details

Latin Name:	Eucalyptus botryoides
Common Name:	Mahogany Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	16
DBH [cm]:	88.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.98
Tree Protection Zone (TPZ) [m]:	10.62
Structural Root Zone (SRZ) [m]:	3.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935849
Latitude:	-32.003543

Photos Street View Map View



Spotted Gum Tree ID #362

Tree Details

Latin Name:	Corymbia maculata
Common Name:	Spotted Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	5
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935864
Latitude:	-32.003566

Photos Street View Map View



Tasmanian Blue Gum Tree ID #363

Tree Details

Latin Name:	Eucalyptus globulus
Common Name:	Tasmanian Blue Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	12
DBH [cm]:	72
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.05
Tree Protection Zone (TPZ) [m]:	8.64
Structural Root Zone (SRZ) [m]:	3.38
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935892
Latitude:	-32.003586

Photos Street View Map View



Tasmanian Blue Gum Tree ID #364

Tree Details

Latin Name:	Eucalyptus globulus
Common Name:	Tasmanian Blue Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	7
DBH [cm]:	31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	3.72
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935911
Latitude:	-32.003606

Photos Street View Map View



Olive Tree ID #365

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	14.76
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935903
Latitude:	-32.003629

Photos Street View Map View



Olive Tree ID #366

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	13.45
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935880
Latitude:	-32.003612

Photos Street View Map View



Olive Tree ID #367

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	16.88
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.03
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935854
Latitude:	-32.003594

Photos Street View Map View



Jacaranda Tree ID #368

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	8
DBH [cm]:	28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935777
Latitude:	-32.003596

Photos Street View Map View



Olive Tree ID #369

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	12.53
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935809
Latitude:	-32.003618

Photos Street View Map View



Olive Tree ID #370

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935828
Latitude:	-32.003636

Photos Street View Map View



Illawarra Plumb Tree ID #371

Tree Details

Latin Name:	Podocarpus elatus
Common Name:	Illawarra Plumb
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	12
DBH [cm]:	78
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	9.36
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935735
Latitude:	-32.003656

Photos Street View Map View



Spotted Gum Tree ID #372

Tree Details

Latin Name:	Corymbia maculata
Common Name:	Spotted Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	7
DBH [cm]:	31.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	3.78
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935680
Latitude:	-32.003686

Photos Street View Map View



Deodar Tree ID #373

Tree Details

Latin Name:	Cedrus deodara
Common Name:	Deodar
Tree Age:	Mature
Health:	Dead
Structure:	Very Poor
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	8
DBH [cm]:	35.16
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	4.22
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935632
Latitude:	-32.003694

Photos Street View Map View



Sydney Blue Gum Tree ID #374

Tree Details

Latin Name:	Eucalyptus saligna
Common Name:	Sydney Blue Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	18
DBH [cm]:	100
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.15
Tree Protection Zone (TPZ) [m]:	12
Structural Root Zone (SRZ) [m]:	3.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935911
Latitude:	-32.003710

Photos Street View Map View



Chinese Elm Tree ID #375

Tree Details

Latin Name:	Ulmus parvifolia
Common Name:	Chinese Elm
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	13
DBH [cm]:	43.06
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.75
Tree Protection Zone (TPZ) [m]:	5.17
Structural Root Zone (SRZ) [m]:	2.93
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935936
Latitude:	-32.003745

Photos Street View Map View



Flooded Gum Tree ID #376

Tree Details

Latin Name:	Eucalyptus rudis subsp. rudis
Common Name:	Flooded Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	8
DBH [cm]:	0.49
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.54
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.55
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935891
Latitude:	-32.003751

Photos Street View Map View



Fiddlewood Tree ID #377

Tree Details

Latin Name:	Citharexylum spinosum
Common Name:	Fiddlewood
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	2
DBH [cm]:	28.83
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	3.46
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935860
Latitude:	-32.003777

Photos Street View Map View



Tree ID #378

Tree Details

Latin Name:	Schinus polygamus
Common Name:	
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	8
DBH [cm]:	35.16
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	4.22
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935831
Latitude:	-32.003793

Photos Street View Map View



Fiddlewood Tree ID #379

Tree Details

Latin Name:	Citharexylum spinosum
Common Name:	Fiddlewood
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	8
DBH [cm]:	35.16
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	4.22
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.935810
Latitude:	-32.003813

Photos Street View Map View



7.0 Conclusion

265 Trees were picked up on the western side of the train tracks between Beckenham Street to Leach Highway, Labelled as Part A.

Trees 5, 7 and 11 are foraging species for Forest red-tailed black cockatoo (calyptorhynchus banksii naso); - Baudin's cockatoo (calyptorhynchus baudinii); - Carnaby's cockatoo (calyptorhynchus latirostris); - Peregrine falcon (falco peregrinus). No trees were observed to hold any Habitat value for these species of bird.

A Grass tree located within the trial corridor between Stockman Way and Hamilton street, labelled as Tree 16 would be suitable for transplanting. The Jacaranda within the Bus interchange area could be transplanted on the provision that the asphalt for the bush interchange area can be removed to allow for approximately 6months of preparation time.

Additional specimens identified on the western side of Beckenham Train Station were found to be all *Eucalyptus camaldulensis* which are not endemic to the area. One additional Marri (Tree 47) was identified on the verge of William Street and would be ideal for retention, as it is a naturally occurring species that provides a food source for various bird species. No other trees are suitable for transplanting due to their location, proximity to other trees and/or size.

With regards to Part B, which is the eastern portion of land from the train tracks to the verge, 379 trees were picked up, this is inclusive of areas around level crossings.

Trees 1, 5, 8, 12, 13, 19, and 24 were identified as being foraging species for Forest red-tailed black cockatoo (calyptorhynchus banksii naso); - Baudin's cockatoo (calyptorhynchus baudinii); - Carnaby's cockatoo (calyptorhynchus latirostris); - Peregrine falcon (falco peregrinus). No trees were observed to hold any Habitat value for these species of bird.

No trees are suitable for transplanting due to their location, proximity to other trees and/or size.

Tree 2 is a Callistemon phonecius, which is a dense shrub, as is Tree 14, which may hold some habitat value for ground based fauna.

Tree 14 is a Geraldton wax, which can be regarded as a weed species in the Perth region and should be considered for removal.

Trees 6 and 7 are Eucalyptus camaldulensis suckers from remanent stumps that should be removed as they will never form a structurally stable tree. Trees 9 and 10 are Poplars, which are exotic trees species, tree 9 is dead and tree 10 is in decline, both are recommended for removal due to their condition and because they do not suit the landscape. It is suggested to poison tree 10 before removal takes place to prevent the root material producing masses of suckers.

Trees 16, 17, 20, 21 and 23 are at the end of their useful life and are now either dead or in decline, these should also be removed.

The additional trees picked up around Beckenham Train Station are numbered from 156 to 338. These are Mostly Marri that ire in a suitable condition to Retain, a number of them will require the removal of deadwood, especially over the adjacent
PSP.

Tree 172, 173, 211, 212, 267, was found to be experiencing some decline in its canopy, as such it is recommended to apply 500 litres of water, mixed with 1% Bioprime to reduce stress and assist with regeneration of foliage

Tree 174, 181, 191, 192, 277, 193 and 320 is dead and removal is recommended to provide additional space for the adjacent trees

Tree 280 is an E. camaldulensis that is comprised of epicormic shoots, it will never form into a suitable tree with an adequate structure, as such, removal is recommended.

Tree 175 is mostly dead, and removal is recommended to provide additional space for the adjacent trees to develop fuller canopies.

Trees 311, 321, 322, 323, 324, 325 and 326, are Leptospermum laevigatum (Coastal Tree Tree), this can be regarded as a weed species and removal is recommended.

106 trees were picked up as part of a supplementary survey around Hamilton street on the 7 July 2022.

27 are Marri, which are regarded as a foraging species for Forest red-tailed black cockatoo (calyptorhynchus banksii naso); - Baudin's cockatoo (calyptorhynchus baudinii); - Carnaby's cockatoo (calyptorhynchus latirostris); - Peregrine falcon (falco peregrinus).

Tree 45 has fungal fruiting bodies at the base of its trunk, it is recommended to undertake a single point sonic tomogram (PiCUS) at ground level to ensure that the tree is retaining a suitable wall thickness and that the fungus has not degraded it to an unacceptable level.

Should this area be used as a temporary Depot and material holding area, it is important that the tree protection zones for all trees are implemented utilising steel mesh temporary fencing to protect the canopies of the trees and to prevent compaction occurring around the rootzones of the trees. This step will ensure that the trees survive for the long term, following demobilisation from the area.

Across the site referred to as "Package 2: the following trees were found to have a DBH 500mm in diameter or greater that have the potential (in the long term) to provide nesting habitat for the bird species listed above. As such, these have been noted as holding a "High" Habitat Value.

- Part A, there were 8 Marri, 3 Tuarts and 1 Jarrah (Numbered: 5, 7, 47, 212, 226, 244, 248, 249, 251, 252, 253, 257)
- Part B there were 36 Marri (Numbered: 1, 5, 47, 59, 67, 68, 70, 77, 82, 83, 84, 94, 126, 127, 128, 157, 161, 165, 166, 172, 173, 180, 211, 212, 233, 234, 236, 239, 252, 254, 256, 260, 275, 328, 330 and 334)

There are no trees that were found to suitable for transplanting based upon available space to undertake appropriate preparation works.

No Rare or Priority Flora was identified in the area of Package 2 (Beckenham Train Station to Leach Highway

8.0 Glossary of Arboricultural Terminology

Abscission - The shedding of a leaf or other short-lived part of a woody plant, involving the formation of a corky layer across its base; in some tree species twigs can be shed in this way.

Abiotic - Pertaining to non-living agents, e.g., environmental factors.

Absorptive roots - non-woody, short-lived roots, generally having a diameter of less than one millimetre, the primary function of which is uptake of water and nutrients.

Adaptive growth - In tree biomechanics, the process whereby the rate of wood formation in the cambial zone, as well as wood quality, responds to gravity and other forces acting on the cambium. This helps to maintain a uniform distribution of mechanical stress.

Adaptive roots - The adaptive growth of existing roots; or the production of new roots in response to damage, decay or altered mechanical loading.

Adventitious shoots - Shoots that develop other than from apical, axillary, or dormant buds; see also 'epicormic'

Anchorage - The system whereby a tree is fixed within the soil, involving cohesion between roots and soil and the development of a branched system of roots which withstands wind and gravitational forces transmitted from the aerial parts of the tree.

Axil - The place where a bud is borne between a leaf and its parent shoot.

Bacteria - Microscopic single-celled organisms, many species of which break down dead organic matter, and some of which cause diseases in other organisms.

Bark - A term usually applied to all the tissues of a woody plant lying outside the vascular cambium, thus including the phloem, cortex, and periderm; occasionally applied only to the periderm or the phellem.

Basidiomycotina (Basidiomycetes) - One of the major taxonomic groups of fungi.

Bolling - A term sometimes used to describe pollard heads.

Bottle-butt - A broadening of the stem base and buttresses of a tree, in excess of normal and sometimes denoting a growth response to weakening in that region, especially due to decay.

Bracing - The use of rods or cables to restrain the movement between parts of a tree.

Branch:

- **Primary** - A first order branch arising from a trunk or stem
- **Lateral** - A second order branch, subordinate to a primary branch
- **Sub-lateral** - A third order branch, originating from lateral branch

Branch bark ridge - The raised arc of bark tissues that forms within the acute angle between a branch and its parent stem.

Branch-collar - A visible swelling formed at the base of a branch.

Brown-rot - A type of wood decay in which cellulose is degraded, while lignin is only modified.

Buckling - An irreversible deformation of a structure subjected to a bending load.

Buttress zone - The region at the base of a tree where the major lateral roots join the stem, with buttress-like formations on the upper side of the junctions.

Cambium - Layer of dividing cells producing xylem (woody) tissue internally and phloem (bark) tissue externally.

Canker - A persistent lesion formed by the death of bark and cambium due to colonisation by fungi or bacteria.

Canopy species - Tree species that mature to form a closed forest canopy.

Cleaning out - The removal of dead, crossing, weak, and damaged branches, where this will not damage or spoil the overall appearance of the tree.

Compartmentalisation - The chemical confinement of disease, decay, or other dysfunction within a trees tissue, due to passive and/or active defences operating at the boundaries of the affected region.

Compression fork - An acute angled fork that is mechanically optimised for the growth pressure that two or more adjacent stems exert on each other.

Compression strength - The ability of a material or structure to resist failure when subjected to compressive loading, measurable in trees with special drilling devices.

Compressive loading - Mechanical loading which exerts a positive pressure, the opposite to tensile loading.

Tree Protection Zone - Area from which access is prohibited for the duration of the project to prevent damage to a tree.

Crown/Canopy - The main foliage bearing section of the tree.

Crown lifting - The removal of limbs and small branches to a specified height above ground level.

Crown thinning - The removal of a proportion of secondary branch growth throughout the crown to produce an even density of foliage around a well-balanced branch structure.

Crown reduction/shaping - A specified reduction in crown size whilst preserving, as far as possible, the natural tree shape.

Crown reduction/thinning - Reduction of the canopy volume by thinning to remove selected branches whilst preserving the natural tree shape.

Deadwood - Branch or stem wood bearing no live tissues.

Decurrent - A system of branching in which the crown is borne on a number of major widely spreading limbs of similar size.

Defect - In relation to tree hazards, any feature of a tree which detracts from the uniform distribution of mechanical stress, or which makes the tree mechanically unsuited to its environment.

Delamination - The separation of wood layers along their length, visible as longitudinal splitting.

Dieback - The death of parts of a woody plant, starting at shoot-tips or root-tips.

Disease - A malfunction in or destruction of tissues within a living organism, usually excluding mechanical damage; in trees, usually caused pathogens.

Distal - In the direction away from the main body of a tree or subject organism (cf. proximal)

Dominance - In trees, the tendency for a leading shoot to grow faster or more vigorously than the lateral shoots; also, the tendency of a tree to maintain a taller crown than its neighbours.

Dormant bud - An axial bud which does not develop into a shoot until after the formation of two or more annual wood increments; many such buds persist through the life of a tree and develop only if stimulated to do so.

Dysfunction - In woody tissues, the loss of physiological function, especially water conduction, in sapwood.

DBH (Diameter at Breast Height) - Stem diameter measured at a height of 1.4 metres or the nearest measurable point. Where measurement at a height of 1.4 metres is not possible, another height may be specified.

Endophytes - Micro-organisms that live inside plant tissues without causing overt disease, but in some cases capable of causing disease if the tissues become physiologically stressed.

Epicormic shoot - A shoot having developed from a dormant or adventitious bud and not having developed from a first-year shoot.

Excrescence - Any abnormal outgrowth on the surface of tree or other organism.

Excurrent - In trees, a system of branching in which there is a well-defined central main stem, bearing branches which are limited in their length, diameter, and secondary branching (cf. decurrent).

Fastigiate - Having upright, often clustered branches.

Flush cut - A pruning cut which removes part of the branch bark ridge and or branch-collar.

Girdling root - A root which circles and constricts the stem or roots possibly causing death of phloem and/or cambial tissue.

Habit - The overall growth characteristics, shape of the tree and branch structure.

Haloing - Removing or pruning trees from around the crown of another (usually mature or post-mature) tree to prevent it becoming supressed.

Hazard beam - An upwardly curved part of a tree in which strong internal stresses may occur without being reduced by adaptive growth, prone to longitudinal splitting.

Heartwood/false-heartwood - The dead central wood that has become dysfunctional as part of the aging processes and being distinct from the sapwood.

Heave - The lifting of pavements and other structures by root diameter expansion; also, the lifting of one side of a wind-rocked root-plate.

High canopy tree species - Tree species having potential to contribute to the closed canopy of a mature forest.

Incipient failure - In wood tissues, a mechanical failure which results only in deformation or cracking, and not in the fall or detachment of the affected part.

Included bark (ingrown bark) - Bark of adjacent parts of a tree (usually forks, acutely joined branches or basal flutes) which is in face-to-face contact.

Infection - The establishment of a parasitic micro-organism in the tissues of a tree or other organism.

Internode - The part of a stem between two nodes; not to be confused with a length of stem which bear nodes but no branches.

Lever arm - A mechanical term denoting the length of the lever represented by a structure that is free to move at one end, such as a tree or individual branch.

Lignin - The hard, cement-like constituent of wood cells; deposition of lignin within the matrix of cellulose microfibrils in the cell wall is termed Lignification.

Lions tailing - When a branch of a tree that has few if any side branches except at its end and is thus liable to snap due to end-loading.

Loading - A mechanical term describing the force acting on a structure from a particular source, e.g., the weight of the structure itself or wind pressure.

Longitudinal - Along the length (of a stem, root, or branch).

Lopping - A term often used to describe the removal of large branches from a tree, but also used to describe other forms of cutting

Minor deadwood - Deadwood of a diameter less than 25mm and or unlikely to cause significant harm or damage upon impact with a target.

Mulch - Material laid down over the rooting area of plants to help conserve moisture; mulch may consist of organic matter, or artificial material.

Mycelium - The body of a fungus, consisting of branched filaments (hyphae).

Occlusion - The process whereby a wound is progressively closed by the formation of new wood and bark around it.

Pathogen - A micro-organism which causes disease in another organism.

Photosynthesis - The process whereby plants use light energy to split hydrogen from water molecules and combine it with carbon dioxide to form the molecular building blocks for synthesizing carbohydrates and other biochemical products.

Phytotoxic - Toxic to plants.

Pollarding - The removal of the tree canopy, back to the stem or primary branches, usually to a point just outside that of the previous cutting.

Primary branch - A major branch, generally having a basal diameter greater than 0.25 x stem diameter.

Probability - A statistical measure of the likelihood that a particular event might occur.

Pruning - The removal or cutting back tree parts to growth points.

Rams-horn - In connection with wounds on trees, a roll of occluding tissues which has a spiral structure as seen in cross section.

Reactive Growth/Reaction Wood - Production of woody tissue in response to altered mechanical or external loading.

Residual wall - The amount of non-decayed wood remaining following decay of internal wood

Rib - A ridge of wood that has usually developed because of locally increased mechanical loading. Often associated with internal cracking in the wood of the stem, branch, or root.

Ringbarking (girdling) - The removal of a ring of bark and phloem around the circumference of a stem or branch, normally resulting in an inability to transport photosynthetic assimilates above or below the area of damage.

Ripewood - The older central wood of those tree species in which sapwood gradually ages without being converted to heartwood.

Root-collar - The transitional area between the stem/s and roots.

Root zone - Area of soils containing absorptive roots of the tree/s described. The Primary root zone is that which we consider of primary importance to the physiological well-being of the tree.

Sapwood - Living xylem tissues.

Selective delignification - A kind of wood decay (white-rot) in which lignin is degraded faster than cellulose.

Shedding - In woody plants, the normal abscission, rotting off or sloughing of leaves, floral parts, twigs, fine roots, and bark scales.

Shrub species - Woody perennial species forming the lowest level of woody plants in a forest or garden and not normally considered to be trees.

Simultaneous white rot - A kind of wood decay in which lignin and cellulose are degraded at about the same rate.

Soft-rot - A kind of wood decay in which a fungus degrades cellulose within the cells,

Spores - Propagules of fungi; most spores are microscopic and dispersed in air or water.

Sporophore - The spore bearing structure of fungi.

Stem/s - Principle above-ground structural component(s) of a tree that supports its branches.

Stress - In plant physiology, a condition under which one or more physiological functions are not operating within their optimum range, for example due to lack of water, inadequate nutrition, or extremes of temperature: In mechanics, the application of an external force to an object.

Stringy white-rot - The kind of wood decay produced by selective delignification.

Structural roots - Roots, generally having a diameter greater than 50 millimetres, and contributing significantly to the structural support and stability of the tree.

Structural root zone (ZRZ) - The zone of the root plate most likely to contain roots that are critical for anchorage and the stability of the tree.

Subsidence - In relation to soil or structures resting in or on soil, a sinking due to shrinkage when certain types of clay soil dry out, sometimes due to extraction of moisture by tree roots.

Subsidence - In relation to branches of trees, a term that can be used to describe a progressive downward bending due to increasing weight.

Taper - In stems and branches, the degree of change in girth along a given length.

Targets - In tree risk assessment persons or property or other things of value which might be harmed or damaged by falling parts of a tree

Topping/ Lopping - In arboriculture, the removal of the crown of a tree, or of a major proportion of it.

Torsional stress - Mechanical stress applied by a twisting force.

Translocation - In plant physiology, the movement of water and dissolved materials through the body of the plant.

Transpiration - The evaporation of moisture from the surface of a plant, especially via the stomata of leaves; it exerts a suction which draws water up from the roots and through the intervening xylem cells.

Tree Protection Zone (TRZ) - This is an area left around a tree to ensure protection of the above and below ground parts of the tree during construction works. It will usually include the SRZ and is usually recommended to be fenced off for the period of the works.

Understorey - A layer of vegetation consisting of younger or smaller trees and shrubs which are adapted to grow under lower light conditions.

Understorey tree species - Tree species not having potential to attain a size at which they can contribute to the closed high canopy of a forest or garden.

Vascular wilt - A type of plant disease in which water-conducting cells become dysfunctional.

Vessels - Water-conducting cells in plants, usually wide and long for hydraulic efficiency; generally, not present in coniferous trees.

Vigour - The expression of carbohydrate expenditure to growth (in trees).

Vitality - A measure of physiological condition.


White-rot - A range of kinds of wood decay in which lignin, usually together with cellulose and other wood constituents, is degraded.

Wind exposure - The degree to which a tree or other object is exposed to wind, both in terms of duration and velocity.

Windthrow - The blowing over of a tree at its roots.

Woundwood - Wood with atypical anatomical features, formed in the vicinity of a wound.

9.0 Appendices – QTRA Risk Thresholds



10.0 References

Mattheck, C. and Breloer, H. 1994. The body language of trees - a handbook for failure analysis. The Stationery Office, London England. p 11- 21, 22 – 27, 39, 60 – 65, 130 – 136, 171 – 172.

Harris, R, H. Clark, J, R. Matheny, N, P. 2004 Arboriculture, Integrated management of Trees, Shrubs, and vines. Pearson education, Upper Saddle River, New Jersey, USA. p 162, 351.

Lonsdale, D. 1999, 2010 Principles of Tree Hazard Assessment and Management. The Stationary Office, London England. PG: 149-150.

Shigo, A, L. 1979. Tree Decay; An expanded Concept. USDA Forest Service Agricultural Information. Bulletin No 419.

Duiker, S, W. 2002. Diagnosing Soil Compaction using a Penetrometer. Penn State College of Agricultural Science Research. Pennsylvania, USA.

Day, S.D. and Bassuk, N.L. 1994. Soil Compaction: A Review of the effects of soil compaction and amelioration treatments on landscape trees. Journal of Arboriculture. Vol 20 No 1 p 9-17.

Ganesson, S. 1995 Plant Pathology 202. Challenger Institute of Technology, Murdoch. Perth, Western Australia, Pg: 81 to 93.

Dunster, J, A, A. Smiley, T. Matheny, N. Lilly, S. (2013) Tree Risk Assessment Manual. International society of Arboriculture. Champaign Illinois, USA. p 29, 67 – 71, 74 – 84, 88 – 95.

Fay, N. 2007 Defining and Surveying Veteran and Ancient Trees, UK Biodiversity Action plan. England.

Smith, K, D. May, P, B. Moore, G, M. 2001. The Influence of Compaction and soil Strength on the Establishment of four Australian Landscape Trees, Journal of Arboriculture Vol 27 No 1.

Ellison, M. (2010). Quantified Tree Risk Assessment – Licensed User Manual, Quantified Tree Risk Assessment Ltd, Poynton, England.

Standards Australia. AS 4373 – 2007 Pruning of amenity Trees, Sydney, Australia.

Standards Australia. AS 4970 – 2009 Protection of Trees on Development Sites.

11.0 Disclaimer and Limitations

a. References in this report to the “Consultant” means the person listed on the cover page as an employee of Westworks Consultancy.
b. References in this report to Westworks Consultancy means Westworks Group Pty Ltd as trustee for Ussheridan Trust trading as Westworks Consultancy (ACN 156 131 010 ABN 46 156 131 010).
c. In this report a reference to a group of persons includes a reference to all of them collectively, any two or more collectively and each of them individually.
d. The releases and limitations in this report apply to the Arborist, Westworks Consultancy and any employees, directors, contractors, and agents of the Arborist and/or Westworks Consultancy.
e. This report only covers identifiable defects present at the time of inspection. The Arborist and Westworks Consultancy accept no responsibility and cannot be held liable for any structural defect or unforeseen event/situation that may occur after the time of inspection.
f. The Arborist and Westworks Consultancy cannot and do not guarantee trees contained within this report will be structurally sound under all circumstances and cannot and do not guarantee that the recommendations made will categorically result in the tree being made “safe.” Unless specifically mentioned this report will only be concerned with above ground inspections, that will be undertaken visually from ground level.
g. Trees are living organisms and as such cannot be classified as “safe” under any circumstances.
h. Failure events can occur for any number of reasons at any time and cannot always reasonably be foreseen, as any number of circumstances can come about at any time before or after an inspection that the Arborist and Westworks Consultancy may not be aware of.
i. All recommendations are made based on what can be reasonably identified at the time of inspection therefore the author accepts no liability for any recommendations made.
j. Care has been taken to obtain all information from reliable sources. All data has been verified or as much as possible; however, the Arborist and Westworks Consultancy can neither guarantee nor be responsible for the accuracy of information provided by others.
k. Booking of re-assessment after the prescribed period is the responsibility of the land manager/owner only. The Arborist and Westworks Consultancy are not responsible for providing reminders or notification that re assessment may be due and will not be held responsible to reinspect the listed trees until requested.
l. The Arborist and Westworks Consultancy make no express warranties under this report.
m. Except as the report specifically states, or as contained in any express warranty provided in relation to any goods or services provided or to be provided, the report does not include by implication any other term, condition, or warranty in respect of the quality, merchantability, acceptability, fitness for purpose, condition, description, assembly, manufacture, design or performance of the goods or services or any contractual remedy for their failure.
n. If the client is a consumer nothing in the Repot restricts, limits, or modifies the client's rights or remedies against Westworks Consultancy for failure of a statutory guarantee under the ACL save to the extent lawfully permissible.
o. To the greatest extent permitted under law the Arborist and Westworks Consultancy are not liable to the client or any third party in any way under or in connection with the Report or in connection with the goods or services provided by them to the client or any third party.
p. To the greatest extent permitted under law the Arborist and Westworks Consultancy are not liable for any indirect or consequential losses or expenses suffered by the client or any third party, howsoever caused, including but not limited to loss of turnover, profits, business or goodwill or any liability to any other party.
q. The client expressly acknowledges and agrees that:
    i. it has not relied upon, any service involving skill and judgement, or on any advice, recommendation, information, or assistance given by the Arborist or Westworks Consultancy, their agents, contractors, or employees in relation to any goods or services or their use or purpose.
    ii. it has not made known, whether expressly or by implication, to the Arborist and Westworks Consultancy any purpose for which it requires the goods or services and it has the sole responsibility of satisfying itself that any goods or services as suitable for the use of the client.
    iii. nothing in this Report is to be interpreted as excluding, restricting, or modifying the application of any non-excludable State or Federal legislation applicable to the sale of goods or supply of service.
    iv. Any reinspection is the responsibility of the tree owner to arrange as required.
    v.

Preliminary Tree Survey

Location: Armadale Line Upgrade; Leach Highway to Miller Street

Report Prepared for: ALUA

Date: 18 August 2022

Mark Short
Grad Cert Arboriculture

Arboricultural Consultant
Westworks Consultancy
PO Box 173
Mundijong WA 6121
Mobile: 0417 011 426
mark@westworksconsultancy.com.au
www.westworksconsultancy.com.au

Contents

1.0 Introduction 2
2.0 Methodology 2
2.1 Methodology – Tree Measurements 2
2.2 Methodology – Tree Health 3
2.3 Methodology - Structure 3
2.4 Methodology – Age Assessment 4
2.5 Useful Life Expectancy 5
2.6 Origin of species 5
2.7 Habitat (Nesting) Value 6
2.8 Foraging Species 6
3.0 Location of Subject Trees – Part C 7
3.1 Location of Subject Trees – Part C 8
3.2 Location of Subject Trees – Part C 9
3.3 Location of Subject Trees – Part C 10
3.4 Location of Subject Trees – Part C 11
3.5 Location of Subject Trees – Part C 12
3.6 Location of Subject Trees – Part C 13
3.7 Location of Subject Trees – Part C 14
3.8 Location of Subject Trees – Part C 15
3.9 Location of Subject Trees – Part C 16
3.10 Location of Subject Trees – Part C 17
3.11 Location of Subject Trees – Part C 18
3.12 Location of Subject Trees – Part C 19
3.13 Location of Subject Trees – Part C 20
3.14 Location of Subject Trees – Part C 21
3.15 Location of Subject Trees – Part C 22
3.16 Location of Subject Trees – Part C 23
3.17 Location of Subject Trees – Part C 24
4.0 Tree Assessments- Part C 25
5.0 Location of Subject Trees – Part D 534
5.1 Location of Subject Trees – Part D 535
5.2 Location of Subject Trees – Part D 536
5.3 Location of Subject Trees – Part D 537
5.4 Location of Subject Trees – Part D 538
5.5 Location of Subject Trees – Part D 539
5.6 Location of Subject Trees – Part D 540
5.7 Location of Subject Trees – Part D 541
5.8 Location of Subject Trees – Part D 542
5.9 Location of Subject Trees – Part D 543
5.10 Location of Subject Trees – Part D 544
5.11 Location of Subject Trees – Part D 545
5.12 Location of Subject Trees – Part D 546
5.13 Location of Subject Trees – Part D 547
5.14 Location of Subject Trees – Part D 548
6.0 Tree Assessments – Part D 549
9.0 Conclusion 1063
10.0 Glossary of Arboricultural Terminology 1065
11.0 Appendices – QTRA Risk Thresholds 1068
12.0 References 1069
13.0 Disclaimer and Limitations 1070

1.0 Introduction

A tree survey was undertaken to pick up the details of trees on the verge and within the Rail corridor along the Armadale Train line from Leach Highway, Welshpool to Miller Street, East Victoria Park (Package 1). The purpose of this tree survey is to inform the design process for the raising of the train line and creation of new public areas.
The survey area has been divided into two sections, with the rail being the divide. “Part C,” is the western half of the Rail Corridor and verge and “Part D,” being the Eastern half of the rail corridor and adjacent verge. Trees have been number from 1 onwards for each portion

This portion of Track has been surveyed at different times, due to changing requirements of the project, as such the tree numbering is not necessarily concurrent on the map.

This also includes trees around Welshpool Train Station, which are in section 7 and 8, with the trees being numbered 1 to 49.

This report is a combined report of those previously provided on the 6 May, 12 May, and 7 July 2022

2.0 Methodology

This tree survey consisted of a walk-through assessment to collect the following details of trees within 5m of the Rail Corridor Fence from Leach Highway to Miller Street (East and West Verges):

- Age
- Height (in meters),
- Canopy spread
- Diameter of the trunk at breast height and ground level (for determining TPZ and SRZ)
- Health and structure,
- Useful Life Expectancy
- Origin of species
- Habitat Value.
- Foraging – this is noted by exception with a “Yes,” otherwise left blank

An aerial assessment and Soil or tissue sampling was not undertaken during this assessment.

2.1 Methodology – Tree Measurements

The height of the tree is an approximate height taken in meters (m)

The canopy spread gives an indication of the general spread of the canopy in meters

The Diameter of the trunk is measures at 1.4m above ground level and at ground level with a DBH tape. This allows for the calculation of the Tree Protection Zone (TPZ) and the Structural Root Zone (SRZ() in line with the Australian Standard for Protection of Trees on Development Sites (AS 497 – 2009) The TPZ and SRZ information is provided with each tree.

2.2 Methodology – Tree Health

- **Good:** The tree will show good to excellent vigour throughout the tree for the species. The tree will exhibit a full and healthy canopy of foliage with only minimal pest or diseases evident.
- **Fair:** The tree is growing in a reasonable condition and shape with adequate canopy foliage for the species. Minor dead wood may be present throughout the crown, with reasonable colour and density when compared to a typical healthy specimen of that species.
- **Poor:** The tree appears to not be growing to its full capability with the canopy potentially visibly showing signs of openness and thinning with excessive amounts of dead or dying limbs. Evidence of established pest and disease issues will be evident or symptoms of stress indicating the tree is in decline.
- **Dead:** No living tissue was found; the tree is dead and should be removed. Unless it is otherwise noted as holding potential as a habitat tree.

2.3 Methodology - Structure

- **Good:** The tree will show good to excellent vigour throughout the tree for the species. The tree will exhibit a full and healthy canopy of foliage with only minimal pest or diseases evident.
- **Fair:** The tree is growing in a reasonable condition and shape with adequate canopy foliage for the species. Minor dead wood may be present throughout the crown, with reasonable colour and density when compared to a typical healthy specimen of that species.
- **Poor:** The tree appears stunted and not growing to its full capability with the canopy potentially visibly showing signs of openness and thinning with excessive amounts of dead or dying limbs. Evidence of established pest and disease issues will be evident or symptoms of stress indicating the tree is in decline.
- **Very poor:** The tree is in a state of decline with the canopy visibly open with considerable deadwood with pest and diseases being present throughout the tree as it enters the final stages of senescing.
- H**as Failed:** The tree is of a significantly poor structural integrity that a failure event was present at time of inspection.

***Determining removal versus retention**


All trees are typically advocated for retention if they are recorded as fair or good in wither the Health or structure category.

Where a tree required removal on the ground pf poor health or poor structural integrity it will be expressly noted in the Comments section.

In terms of guidance for the removal of trees due to design constraints, where trees are recorded as Poor in terms of Health or Poor or Very Poor in the structure category, should be considered over and above those that rate fair/good in both categories. With the design being altered to retain as many trees as possible.

2.4 Methodology – Age Assessment

The age of the subject trees was assessed against the following categories.



2.5 Useful Life Expectancy

Very Long (Greater than 40 + years)
Very high quality and high value, these trees would hold such a condition that make them a valuable part of the environment/ landscape, would be considered to hold a Useful Life Expectancy (ULE) of greater than 40 years, thus allowing them to make a substantial contribution for a long period of time.

Long (Greater than 20 to 40 years)
High quality and high value, these trees would hold such a condition that make them a valuable part of the environment/ landscape, thus allowing them to make a substantial contribution to for at least 20 years from the time of inspection.

Medium (Between 11 to 20 years)
Medium quality and medium value, trees of this category are thought of as making a good contribution to the area they dwell in and would be considered to hold a ULE of a minimum of 11 years.

Short (Between 6 to 10 years)
Low quality and low value. These trees would be regarded as being in an adequate condition that would see them being retained for a period that would allow new plantings to establish.

Transient (1 to 5 years)
Very Low quality and very low value, these trees would be regarded as having a poor form, displaying a low vitality, and may be exhibiting initial signs of structural decline. They would be considered to have a ULE of less than 5 years and are to be included replacement plan.

Dead or hazardous (no remaining ULE).
Trees in this category would be considered to hold such a condition that would potentially hold no value or in their current state it would be reasonable to undertake their removal for reasons of sound Arboricultural management, due to a high level of risk.

2.6 Origin of species

Native – The definition below is as it is stipulated in the Environmental Protections Act 1986

3(1). native vegetation means indigenous aquatic or terrestrial vegetation, and includes dead vegetation unless that dead vegetation is of a class declared by regulation to be excluded from this definition but does not include vegetation in a plantation;

51A. native vegetation has the meaning given by section 3(1) but does not include vegetation that was intentionally sown, planted or propagated unless —

(a) that vegetation was sown, planted or propagated as required under this Act or another written law; or

(b) that vegetation is of a class declared by regulation to be included in this definition;

Exotic – A species of plant that is not indigenous to the Project area, and/or has been planted

2.7 Habitat (Nesting) Value

High value - Trees in this category will have a DBH of 500mm or greater, and/or has hollows of 150mm in diameter or greater.

Medium value. - Trees with a DBH of up to 500mm but not greater then 300mm with hollows of up to 140mm in diameter this also relates to the potential for future significant nesting hollows.

Low Value - Trees with no hollows, holding low nesting values.

2.8 Foraging Species

Trees in the project area have been assessed in regards to their suitability as foraging trees for Forest red-tailed black cockatoo (calyptorhynchus banksii naso); - Baudin's cockatoo (calyptorhynchus baudinii); - Carnaby's cockatoo (calyptorhynchus latirostris); - Peregrine falcon (falco peregrinus).

Yes. – Are a suitable tree species for foraging

No – Not a suitable species for foraging

Black Cockatoo foraging tree means native plant species known to be utilised by black cockatoo species for foraging and includes Corymbia calophylla (marri), Eucalyptus marginata(jarrah), Eucalyptus spp., Banksia spp., Allocasuarina spp., and Xanthorrhoea spp

3.0 Location of Subject Trees – Part C


Subject tree marked coloured dots in relation to species.



3.1 Location of Subject Trees – Part C



3.2 Location of Subject Trees – Part C



3.3 Location of Subject Trees – Part C



3.4 Location of Subject Trees – Part C



3.5 Location of Subject Trees – Part C



3.6 Location of Subject Trees – Part C



3.7 Location of Subject Trees – Part C



3.8 Location of Subject Trees – Part C



3.9 Location of Subject Trees – Part C



3.10 Location of Subject Trees – Part C



3.11 Location of Subject Trees – Part C



3.12 Location of Subject Trees – Part C



3.13 Location of Subject Trees – Part C



3.14 Location of Subject Trees – Part C




3.15 Location of Subject Trees – Part C



3.16 Location of Subject Trees – Part C



3.17 Location of Subject Trees – Part C



Flowering Gum Tree ID #1

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	37
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.462
Tree Protection Zone (TPZ) [m]:	4.44
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in poor condition, likely due to compacted soil around it remove all grass for radius of 3 m and replace with mulch Myer prime at 1% and remove all dead wood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.927255
Latitude:	-31.998454

Photos Street View Map View



Flowering Gum Tree ID #2

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.556
Tree Protection Zone (TPZ) [m]:	6.48
Structural Root Zone (SRZ) [m]:	2.59
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in poor condition likely due to compacted soil around it remove all grass for radius of 3 m and replace with mulch Myer prime at 1% and remove all dead wood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.927179
Latitude:	-31.998397

Photos Street View Map View



Flowering Gum Tree ID #3

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	44.7
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.535
Tree Protection Zone (TPZ) [m]:	5.36
Structural Root Zone (SRZ) [m]:	2.54
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in poor condition likely due to compacted soil around it remove all grass for radius of 3 m and replace with mulch Bioprime at 1%. Remove all dead wood over 25 mm in diameter, basal suckers and uplift the canopy to 2m above ground level.
Foraging species:	No

Tree Location

Longitude:	115.927030
Latitude:	-31.998282

Photos Street View Map View



Flowering Gum Tree ID #4

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	
Health:	Dead
Structure:	
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	0 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	This tree is dead remove to ground level and stump grind.
Foraging species:	No

Tree Location

Longitude:	115.926867
Latitude:	-31.998156

Photos Street View Map View



Flowering Gum Tree ID #5

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in poor condition likely due to compacted soil around it remove all grass for radius of 3 m and replace with mulch Bioprime at 1%. Remove all dead wood over 25 mm in diameter, basal suckers and uplift the canopy to 2m above ground level.
Foraging species:	No

Tree Location

Longitude:	115.926699
Latitude:	-31.998033

Photos Street View Map View



Flowering Gum Tree ID #6

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	41.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	4.94
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in poor condition likely due to compacted soil around it remove all grass for radius of 3 m and replace with mulch Myer prime at 1% and remove all dead wood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.926632
Latitude:	-31.997980

Photos Street View Map View



Flowering Gum Tree ID #8

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Poor
Structure:	Very Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	41.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	4.94
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in poor condition likely due to compacted soil around it remove all grass for radius of 3 m and replace with mulch Myer prime at 1% and remove all dead wood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.926552
Latitude:	-31.997919

Photos Street View Map View



Zamia Tree ID #9

Tree Details

Latin Name:	Macrozamia riedlei
Common Name:	Zamia
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	0.1
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead fronds
Foraging species:	No

Tree Location

Longitude:	115.926769
Latitude:	-31.997989

Photos Street View Map View



Jarrah Tree ID #10

Tree Details

Latin Name:	Eucalyptus marginata
Common Name:	Jarrah
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	12
DBH [cm]:	65.72
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.85
Tree Protection Zone (TPZ) [m]:	7.89
Structural Root Zone (SRZ) [m]:	3.09
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline, likely due to compacted soil around it remove all grass for radius of 3 m and replace with mulch Myer prime at 1% and remove all dead wood over 25 mm in diameter.
Foraging species:	Yes

Tree Location

Longitude:	115.926105
Latitude:	-31.997577

Photos Street View Map View



Marri Tree ID #11

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	15
DBH [cm]:	75.2
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.05
Tree Protection Zone (TPZ) [m]:	9.02
Structural Root Zone (SRZ) [m]:	3.38
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	Yes

Tree Location

Longitude:	115.926049
Latitude:	-31.997540

Photos Street View Map View



Flowering Gum Tree ID #12

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	21.4
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.285
Tree Protection Zone (TPZ) [m]:	2.57
Structural Root Zone (SRZ) [m]:	1.95
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.925994
Latitude:	-31.997489

Photos Street View Map View



Flowering Gum Tree ID #13

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	52
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	6.24
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to 2 m above ground level
Foraging species:	No

Tree Location

Longitude:	115.925922
Latitude:	-31.997425

Photos Street View Map View



Marri Tree ID #14

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	19
DBH [cm]:	120.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.3
Tree Protection Zone (TPZ) [m]:	14.46
Structural Root Zone (SRZ) [m]:	3.69
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter and uplift to 4.6m over the road.
Foraging species:	Yes

Tree Location

Longitude:	115.925715
Latitude:	-31.997282

Photos Street View Map View



Flowering Gum Tree ID #15

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2.5
DBH [cm]:	192
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter and treat with 300 l of water with 1% bioprime trace.
Foraging species:	No

Tree Location

Longitude:	115.925220
Latitude:	-31.996879

Photos Street View Map View



Flowering Gum Tree ID #16

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	98.2
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.98
Tree Protection Zone (TPZ) [m]:	11.78
Structural Root Zone (SRZ) [m]:	3.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.925069
Latitude:	-31.996759

Photos Street View Map View



Flowering Gum Tree ID #17

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline, remove or grass for 3M around trunk and replace with mulch apply 500L of water with bioprime trace at 1% and remove all dead wood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.924594
Latitude:	-31.996382

Photos Street View Map View



WA Peppermint Tree ID #18

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	12.5
DBH [cm]:	234.61
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.0251
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	3.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.920579
Latitude:	-31.993200

Photos Street View Map View



WA Peppermint Tree ID #19

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	12
DBH [cm]:	97
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.93
Tree Protection Zone (TPZ) [m]:	11.64
Structural Root Zone (SRZ) [m]:	3.21
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.920446
Latitude:	-31.993188

Photos Street View Map View



WA Peppermint Tree ID #20

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	9
DBH [cm]:	63.25
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.93
Tree Protection Zone (TPZ) [m]:	7.59
Structural Root Zone (SRZ) [m]:	3.21
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920420
Latitude:	-31.993060

Photos Street View Map View



WA Peppermint Tree ID #21

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	36.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	4.38
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920366
Latitude:	-31.993052

Photos Street View Map View



Geraldton Wax Tree ID #22

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.920331
Latitude:	-31.993017

Photos Street View Map View



WA Peppermint Tree ID #23

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	59.29
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.695
Tree Protection Zone (TPZ) [m]:	7.11
Structural Root Zone (SRZ) [m]:	2.84
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920236
Latitude:	-31.993026

Photos Street View Map View



WA Peppermint Tree ID #24

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	59.29
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.695
Tree Protection Zone (TPZ) [m]:	7.11
Structural Root Zone (SRZ) [m]:	2.84
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level, remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.920118
Latitude:	-31.992937

Photos Street View Map View



WA Peppermint Tree ID #25

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	10
DBH [cm]:	51.91
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	92
Tree Protection Zone (TPZ) [m]:	6.23
Structural Root Zone (SRZ) [m]:	22.11
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920261
Latitude:	-31.992939

Photos Street View Map View



WA Peppermint Tree ID #26

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	56.6
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1.02
Tree Protection Zone (TPZ) [m]:	6.79
Structural Root Zone (SRZ) [m]:	3.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920221
Latitude:	-31.992915

Photos Street View Map View



WA Peppermint Tree ID #27

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	44.09
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.98
Tree Protection Zone (TPZ) [m]:	5.29
Structural Root Zone (SRZ) [m]:	3.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920153
Latitude:	-31.992860

Photos Street View Map View



WA Peppermint Tree ID #28

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	22.76
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	2.73
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920075
Latitude:	-31.992826

Photos Street View Map View



WA Peppermint Tree ID #29

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	16.52
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920127
Latitude:	-31.992817

Photos Street View Map View



WA Peppermint Tree ID #30

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	38.67
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	4.64
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920051
Latitude:	-31.992761

Photos Street View Map View



Geraldton Wax Tree ID #31


Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2.5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919982
Latitude:	-31.992719

Photos Street View Map View



Geraldton Wax Tree ID #32

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	0
Canopy Spread [m]:	2.5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919939
Latitude:	-31.992683

Photos Street View Map View



Geraldton Wax Tree ID #33

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	2.5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919879
Latitude:	-31.992639

Photos Street View Map View



Geraldton Wax Tree ID #34

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2.5
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919782
Latitude:	-31.992582

Photos Street View Map View



Geraldton Wax Tree ID #35

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919704
Latitude:	-31.992429

Photos Street View Map View



WA Peppermint Tree ID #36

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2.5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is growing as a low dent shrub beware of possible habitat value
Foraging species:	No

Tree Location

Longitude:	115.919602
Latitude:	-31.992452

Photos Street View Map View



Geraldton Wax Tree ID #37

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2.5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919509
Latitude:	-31.992439

Photos Street View Map View



Lantana Tree ID #38

Tree Details

Latin Name:	Lantana sp
Common Name:	Lantana
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	2
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919548
Latitude:	-31.992307

Photos Street View Map View



Coastal Tea Tree Tree ID #39

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3.5
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919461
Latitude:	-31.992234

Photos Street View Map View



Wooly Bush Tree ID #40

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.919450
Latitude:	-31.992259

Photos Street View Map View



Wooly Bush Tree ID #41

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	4
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.919318
Latitude:	-31.992177

Photos Street View Map View



Flowering Gum Tree ID #42

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	50.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.56
Tree Protection Zone (TPZ) [m]:	6.06
Structural Root Zone (SRZ) [m]:	2.59
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2.5 m clearance above ground level and remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.919359
Latitude:	-31.992353

Photos Street View Map View



Red Cap Gum Tree ID #43

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	25.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	3.06
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2.5 m clearance above ground level and remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.919281
Latitude:	-31.992268

Photos Street View Map View



Red Cap Gum Tree ID #44

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	7
DBH [cm]:	25.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	3.06
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2.5 m clearance above ground level and remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.919277
Latitude:	-31.992248

Photos Street View Map View



Coastal Tea Tree Tree ID #45

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a weed species
Foraging species:	No

Tree Location

Longitude:	115.919243
Latitude:	-31.992275

Photos Street View Map View



Coastal Tea Tree Tree ID #46

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a weed species
Foraging species:	No

Tree Location

Longitude:	115.919201
Latitude:	-31.992242

Photos Street View Map View



Red Cap Gum Tree ID #47

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	30.78
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.325
Tree Protection Zone (TPZ) [m]:	3.69
Structural Root Zone (SRZ) [m]:	2.06
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2.5 m clearance above ground level and remove all deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.919231
Latitude:	-31.992220

Photos Street View Map View



Coastal Tea Tree Tree ID #48

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a weed species
Foraging species:	No

Tree Location

Longitude:	115.919196
Latitude:	-31.992189

Photos Street View Map View



Wooly Bush Tree ID #49

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is low and sprawling
Foraging species:	No

Tree Location

Longitude:	115.919190
Latitude:	-31.992219

Photos Street View Map View



Wooly Bush Tree ID #50

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is low and sprawling
Foraging species:	No

Tree Location

Longitude:	115.919156
Latitude:	-31.992156

Photos Street View Map View



Wooly Bush Tree ID #51

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is low and sprawling
Foraging species:	No

Tree Location

Longitude:	115.919059
Latitude:	-31.992066

Photos Street View Map View



Wooly Bush Tree ID #52

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is low and sprawling
Foraging species:	No

Tree Location

Longitude:	115.918990
Latitude:	-31.992008

Photos Street View Map View



Flowering Gum Tree ID #53

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	35.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	4.26
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.919067
Latitude:	-31.992118

Photos Street View Map View



Grass Tree Tree ID #54

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.919021
Latitude:	-31.992059

Photos Street View Map View



Grass Tree Tree ID #55

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.919010
Latitude:	-31.992048

Photos Street View Map View



Geraldton Wax Tree ID #56

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	3
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919374
Latitude:	-31.992174

Photos Street View Map View



Geraldton Wax Tree ID #57

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	-1
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919279
Latitude:	-31.992111

Photos Street View Map View



Wooly Bush Tree ID #58

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	8
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.919222
Latitude:	-31.992057

Photos Street View Map View



Geraldton Wax Tree ID #59

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2.5
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.919201
Latitude:	-31.992025

Photos Street View Map View



Wooly Bush Tree ID #60

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.919083
Latitude:	-31.991921

Photos Street View Map View



Wooly Bush Tree ID #61

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.919019
Latitude:	-31.991865

Photos Street View Map View



Geraldton Wax Tree ID #62

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.918927
Latitude:	-31.991891

Photos Street View Map View



Wooly Bush Tree ID #63

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	8
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.918888
Latitude:	-31.991857

Photos Street View Map View



Broad-leaved Paperbark Tree ID #64

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	62.03
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.93
Tree Protection Zone (TPZ) [m]:	7.44
Structural Root Zone (SRZ) [m]:	3.21
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide team leaders clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918735
Latitude:	-31.991845

Photos Street View Map View



Broad-leaved Paperbark Tree ID #65

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	62.03
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.93
Tree Protection Zone (TPZ) [m]:	7.44
Structural Root Zone (SRZ) [m]:	3.21
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide team leaders clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918640
Latitude:	-31.991772

Photos Street View Map View



Jarrah Tree ID #66

Tree Details

Latin Name:	Eucalyptus marginata
Common Name:	Jarrah
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	8
DBH [cm]:	81.78
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	3
Tree Protection Zone (TPZ) [m]:	9.81
Structural Root Zone (SRZ) [m]:	5.25
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.918352
Latitude:	-31.991301

Photos Street View Map View



Grass Tree Tree ID #67

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	82
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.918371
Latitude:	-31.991220

Photos Street View Map View



Grass Tree Tree ID #68

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.918402
Latitude:	-31.991220

Photos Street View Map View



Grass Tree Tree ID #69

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.918390
Latitude:	-31.991208

Photos Street View Map View



Grass Tree Tree ID #70

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.918378
Latitude:	-31.991200

Photos Street View Map View



Flowering Gum Tree ID #71

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	50
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	6
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.918090
Latitude:	-31.991214

Photos Street View Map View



Marri Tree ID #72

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	7.5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.09
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is a sucker from a remnant stump removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.918063
Latitude:	-31.991143

Photos Street View Map View



Marri Tree ID #73

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	19
DBH [cm]:	133.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	2.33
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	4.72
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Good mature specimen Minor uplifting required to provide 2m clearance above ground level
Foraging species:	Yes

Tree Location

Longitude:	115.918167
Latitude:	-31.991085

Photos Street View Map View



Marri Tree ID #74

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	18.3
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	22.8
Tree Protection Zone (TPZ) [m]:	2.2
Structural Root Zone (SRZ) [m]:	12.3
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918099
Latitude:	-31.991007

Photos Street View Map View



Broad-leaved Paperbark Tree ID #75

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	33
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.44
Tree Protection Zone (TPZ) [m]:	3.96
Structural Root Zone (SRZ) [m]:	2.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918032
Latitude:	-31.991120

Photos Street View Map View



Geraldton Wax Tree ID #76

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.918098
Latitude:	-31.990963

Photos Street View Map View



Wooly Bush Tree ID #77

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.918055
Latitude:	-31.990965

Photos Street View Map View



Wooly Bush Tree ID #78

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.918027
Latitude:	-31.990914

Photos Street View Map View



Geraldton Wax Tree ID #79

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917964
Latitude:	-31.990844

Photos Street View Map View



Olive Tree ID #80

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8.5
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	All basil epicormic shoots recommended to be removed and the tree uplifted to 2 m above ground level along with the removal of deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.918153
Latitude:	-31.991282

Photos Street View Map View



Flowering Gum Tree ID #81

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7.5
DBH [cm]:	34.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	4.14
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917841
Latitude:	-31.990890

Photos Street View Map View



Wooly Bush Tree ID #82

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove the vegetation around this shrub
Foraging species:	No

Tree Location

Longitude:	115.917899
Latitude:	-31.990854

Photos Street View Map View



Olive Tree ID #83

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917799
Latitude:	-31.990824

Photos Street View Map View



Broad-leaved Paperbark Tree ID #84

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8.5
DBH [cm]:	40
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Lifting required to provide 2 m of clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917764
Latitude:	-31.990768

Photos Street View Map View



Olive Tree ID #85

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917730
Latitude:	-31.990703

Photos Street View Map View



Olive Tree ID #86

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	57.79
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1.54
Tree Protection Zone (TPZ) [m]:	6.93
Structural Root Zone (SRZ) [m]:	3.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917647
Latitude:	-31.990579

Photos Street View Map View



Wooly Bush Tree ID #87

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	3
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917881
Latitude:	-31.990736

Photos Street View Map View



Geraldton Wax Tree ID #88

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917956
Latitude:	-31.990675

Photos Street View Map View



Zamia Tree ID #89

Tree Details

Latin Name:	Macrozamia riedlei
Common Name:	Zamia
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917928
Latitude:	-31.990696

Photos Street View Map View



Grass Tree Tree ID #90

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917869
Latitude:	-31.990573

Photos Street View Map View



Grass Tree Tree ID #91

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917848
Latitude:	-31.990551

Photos Street View Map View



Grass Tree Tree ID #92

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917840
Latitude:	-31.990540

Photos Street View Map View



Grass Tree Tree ID #93

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	8
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917814
Latitude:	-31.990485

Photos Street View Map View



Marri Tree ID #94

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5.5
DBH [cm]:	26.7
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.374
Tree Protection Zone (TPZ) [m]:	3.2
Structural Root Zone (SRZ) [m]:	2.19
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917803
Latitude:	-31.990624

Photos Street View Map View



Marri Tree ID #95

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	12
DBH [cm]:	71
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	8.52
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level
Foraging species:	Yes

Tree Location

Longitude:	115.917784
Latitude:	-31.990589

Photos Street View Map View



WA Peppermint Tree ID #96

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	57.65
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1
Tree Protection Zone (TPZ) [m]:	6.92
Structural Root Zone (SRZ) [m]:	3.31
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917700
Latitude:	-31.990479

Photos Street View Map View



Grass Tree Tree ID #97

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917660
Latitude:	-31.990406

Photos Street View Map View



Grass Tree Tree ID #98

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	20-40 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917646
Latitude:	-31.990396

Photos Street View Map View



Geraldton Wax Tree ID #99

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917643
Latitude:	-31.990368

Photos Street View Map View



Flowering Gum Tree ID #100

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	10
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	45.5
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	16.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Medium
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917615
Latitude:	-31.990524

Photos Street View Map View



Olive Tree ID #101

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	18.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.325
Tree Protection Zone (TPZ) [m]:	2.22
Structural Root Zone (SRZ) [m]:	2.06
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2 metres clearance from level and remove basil shoots
Foraging species:	No

Tree Location

Longitude:	115.917585
Latitude:	-31.990473

Photos Street View Map View



Olive Tree ID #102

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	172.13
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917518
Latitude:	-31.990327

Photos Street View Map View



Grass Tree Tree ID #103

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917516
Latitude:	-31.990212

Photos Street View Map View



Grass Tree Tree ID #104

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917505
Latitude:	-31.990201

Photos Street View Map View



Grass Tree Tree ID #105

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917467
Latitude:	-31.990242

Photos Street View Map View



Geraldton Wax Tree ID #106

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	3
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917481
Latitude:	-31.990272

Photos Street View Map View



Grass Tree Tree ID #107

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917465
Latitude:	-31.990174

Photos Street View Map View



Grass Tree Tree ID #108

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917458
Latitude:	-31.990133

Photos Street View Map View



Grass Tree Tree ID #109

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917444
Latitude:	-31.990127

Photos Street View Map View



Flowering Gum Tree ID #110

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	8
DBH [cm]:	30.92
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	3.71
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide metres above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917429
Latitude:	-31.990172

Photos Street View Map View



Grass Tree Tree ID #111

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917426
Latitude:	-31.990134

Photos Street View Map View



Grass Tree Tree ID #112

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917422
Latitude:	-31.990114

Photos Street View Map View



Grass Tree Tree ID #113

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917413
Latitude:	-31.990111

Photos Street View Map View



Grass Tree Tree ID #114

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917395
Latitude:	-31.990115

Photos Street View Map View



Grass Tree Tree ID #115

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917393
Latitude:	-31.990126

Photos Street View Map View



Grass Tree Tree ID #116

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917382
Latitude:	-31.990120

Photos Street View Map View



Grass Tree Tree ID #117

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917445
Latitude:	-31.990066

Photos Street View Map View



Grass Tree Tree ID #118

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917451
Latitude:	-31.990071

Photos Street View Map View



Geraldton Wax Tree ID #119

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2.5
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917464
Latitude:	-31.990051

Photos Street View Map View



WA Peppermint Tree ID #120

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	8
DBH [cm]:	50.54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.63
Tree Protection Zone (TPZ) [m]:	6.06
Structural Root Zone (SRZ) [m]:	2.73
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level and remove all basil shoots
Foraging species:	No

Tree Location

Longitude:	115.917427
Latitude:	-31.989992

Photos Street View Map View



Grass Tree Tree ID #121

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917371
Latitude:	-31.990049

Photos Street View Map View



Grass Tree Tree ID #122

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917379
Latitude:	-31.990045

Photos Street View Map View



Grass Tree Tree ID #123

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917366
Latitude:	-31.990038

Photos Street View Map View



Grass Tree Tree ID #124

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917375
Latitude:	-31.990029

Photos Street View Map View

Grass Tree Tree ID #125

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917350
Latitude:	-31.990032

Photos Street View Map View



Grass Tree Tree ID #126

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917359
Latitude:	-31.990024

Photos Street View Map View



Grass Tree Tree ID #127

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917339
Latitude:	-31.990019

Photos Street View Map View



Grass Tree Tree ID #128

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917381
Latitude:	-31.989935

Photos Street View Map View



Grass Tree Tree ID #129

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917387
Latitude:	-31.989928

Photos Street View Map View



Grass Tree Tree ID #130

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917413
Latitude:	-31.989918

Photos Street View Map View



Grass Tree Tree ID #131

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917401
Latitude:	-31.989896

Photos Street View Map View

WA Peppermint Tree ID #132

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	39.07
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.635
Tree Protection Zone (TPZ) [m]:	4.69
Structural Root Zone (SRZ) [m]:	2.73
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917389
Latitude:	-31.989858

Photos Street View Map View



WA Peppermint Tree ID #133

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	17.93
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	2.15
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917334
Latitude:	-31.989807

Photos Street View Map View



Geraldton Wax Tree ID #134

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	3
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917294
Latitude:	-31.989912

Photos Street View Map View



Broad-leaved Paperbark Tree ID #135

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4.5
DBH [cm]:	0.35
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917273
Latitude:	-31.989881

Photos Street View Map View



Olive Tree ID #136

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	121.81
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	14.62
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.917235
Latitude:	-31.989843

Photos Street View Map View



Grass Tree Tree ID #137

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917337
Latitude:	-31.989900

Photos Street View Map View



Grass Tree Tree ID #138

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917354
Latitude:	-31.989900

Photos Street View Map View



Grass Tree Tree ID #139

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917367
Latitude:	-31.989898

Photos Street View Map View



Grass Tree Tree ID #140

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917333
Latitude:	-31.989894

Photos Street View Map View



Grass Tree Tree ID #141

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917341
Latitude:	-31.989891

Photos Street View Map View



Grass Tree Tree ID #142

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917334
Latitude:	-31.989883

Photos Street View Map View



Grass Tree Tree ID #143

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917317
Latitude:	-31.989889

Photos Street View Map View



Grass Tree Tree ID #144

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917326
Latitude:	-31.989874

Photos Street View Map View



Grass Tree Tree ID #145

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917317
Latitude:	-31.989870

Photos Street View Map View



Grass Tree Tree ID #146

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917313
Latitude:	-31.989864

Photos Street View Map View



Grass Tree Tree ID #147

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917322
Latitude:	-31.989870

Photos Street View Map View



Grass Tree Tree ID #148

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917315
Latitude:	-31.989859

Photos Street View Map View



Grass Tree Tree ID #149

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917329
Latitude:	-31.989857

Photos Street View Map View



Grass Tree Tree ID #150

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917318
Latitude:	-31.989851

Photos Street View Map View



Grass Tree Tree ID #151

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917308
Latitude:	-31.989841

Photos Street View Map View



Grass Tree Tree ID #152

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917302
Latitude:	-31.989834

Photos Street View Map View



Grass Tree Tree ID #153

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917291
Latitude:	-31.989821

Photos Street View Map View



Grass Tree Tree ID #154

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917289
Latitude:	-31.989816

Photos Street View Map View



Grass Tree Tree ID #155

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917223
Latitude:	-31.989826

Photos Street View Map View



Grass Tree Tree ID #156

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917276
Latitude:	-31.989781

Photos Street View Map View



Grass Tree Tree ID #157

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917284
Latitude:	-31.989782

Photos Street View Map View



Grass Tree Tree ID #158

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917266
Latitude:	-31.989774

Photos Street View Map View



Grass Tree Tree ID #159

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917335
Latitude:	-31.989775

Photos Street View Map View



Grass Tree Tree ID #160

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917321
Latitude:	-31.989764

Photos Street View Map View



Grass Tree Tree ID #161

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917295
Latitude:	-31.989756

Photos Street View Map View



Grass Tree Tree ID #162

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917261
Latitude:	-31.989764

Photos Street View Map View



Grass Tree Tree ID #163

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917248
Latitude:	-31.989765

Photos Street View Map View



Broad-leaved Paperbark Tree ID #164

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	20.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.42
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting will be required to lift a canopy 2 m above ground level clearance around a tree
Foraging species:	No

Tree Location

Longitude:	115.917200
Latitude:	-31.989783

Photos Street View Map View



Grass Tree Tree ID #165

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1.5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917260
Latitude:	-31.989766

Photos Street View Map View



Grass Tree Tree ID #166

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917308
Latitude:	-31.989749

Photos Street View Map View



Grass Tree Tree ID #167

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917255
Latitude:	-31.989739

Photos Street View Map View



Grass Tree Tree ID #168

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917244
Latitude:	-31.989732

Photos Street View Map View



Grass Tree Tree ID #169

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917280
Latitude:	-31.989729

Photos Street View Map View



Grass Tree Tree ID #170

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917262
Latitude:	-31.989733

Photos Street View Map View



Grass Tree Tree ID #171

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917354
Latitude:	-31.989660

Photos Street View Map View



Grass Tree Tree ID #172

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917341
Latitude:	-31.989644

Photos Street View Map View



Grass Tree Tree ID #173

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917295
Latitude:	-31.989727

Photos Street View Map View



Grass Tree Tree ID #174

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917283
Latitude:	-31.989701

Photos Street View Map View



Grass Tree Tree ID #175

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917238
Latitude:	-31.989714

Photos Street View Map View



Grass Tree Tree ID #176

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917243
Latitude:	-31.989713

Photos Street View Map View



Grass Tree Tree ID #177

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917239
Latitude:	-31.989695

Photos Street View Map View



Grass Tree Tree ID #178

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917276
Latitude:	-31.989669

Photos Street View Map View



Grass Tree Tree ID #179

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917247
Latitude:	-31.989647

Photos Street View Map View



Grass Tree Tree ID #180

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917255
Latitude:	-31.989661

Photos Street View Map View



Grass Tree Tree ID #181

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917252
Latitude:	-31.989642

Photos Street View Map View



Grass Tree Tree ID #182

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917256
Latitude:	-31.989656

Photos Street View Map View



Grass Tree Tree ID #183

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917181
Latitude:	-31.989719

Photos Street View Map View



Geraldton Wax Tree ID #184

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917207
Latitude:	-31.989605

Photos Street View Map View



WA Peppermint Tree ID #185

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	6
DBH [cm]:	21.69
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	52
Tree Protection Zone (TPZ) [m]:	2.6
Structural Root Zone (SRZ) [m]:	17.4
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting may be required to improve clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917170
Latitude:	-31.989588

Photos Street View Map View



Geraldton Wax Tree ID #186

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917128
Latitude:	-31.989476

Photos Street View Map View



Olive Tree ID #187

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2.5
DBH [cm]:	12.8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.16
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917073
Latitude:	-31.989552

Photos Street View Map View



Red Cap Gum Tree ID #188

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	27.99
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917051
Latitude:	-31.989507

Photos Street View Map View



Olive Tree ID #189

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2.5
DBH [cm]:	8.06
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917030
Latitude:	-31.989461

Photos Street View Map View



Red Cap Gum Tree ID #190

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	23.6
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.262
Tree Protection Zone (TPZ) [m]:	2.83
Structural Root Zone (SRZ) [m]:	1.89
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917010
Latitude:	-31.989424

Photos Street View Map View



Olive Tree ID #191

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	22.66
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2.72
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplift to provide 2 metres clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916962
Latitude:	-31.989344

Photos Street View Map View



Geraldton Wax Tree ID #192

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917067
Latitude:	-31.989391

Photos Street View Map View



Geraldton Wax Tree ID #193

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	6
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917044
Latitude:	-31.989335

Photos Street View Map View



Wooly Bush Tree ID #194

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917083
Latitude:	-31.989344

Photos Street View Map View



Grass Tree Tree ID #195

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917015
Latitude:	-31.989332

Photos Street View Map View



Grass Tree Tree ID #196

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917016
Latitude:	-31.989399

Photos Street View Map View



Grass Tree Tree ID #197

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917002
Latitude:	-31.989336

Photos Street View Map View



Grass Tree Tree ID #198

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916975
Latitude:	-31.989351

Photos Street View Map View



Grass Tree Tree ID #199

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916982
Latitude:	-31.989341

Photos Street View Map View



Grass Tree Tree ID #200

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916967
Latitude:	-31.989332

Photos Street View Map View



Grass Tree Tree ID #201

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916947
Latitude:	-31.989336

Photos Street View Map View



Grass Tree Tree ID #202

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916956
Latitude:	-31.989321

Photos Street View Map View



Grass Tree Tree ID #203

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916976
Latitude:	-31.989319

Photos Street View Map View



Grass Tree Tree ID #204

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917125
Latitude:	-31.989260

Photos Street View Map View



Grass Tree Tree ID #205

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916968
Latitude:	-31.989269

Photos Street View Map View



Broad-leaved Paperbark Tree ID #206

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove small broken limb and stub uplifts ground-level
Foraging species:	No

Tree Location

Longitude:	115.916922
Latitude:	-31.989277

Photos Street View Map View



Olive Tree ID #207

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	19.12
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2.29
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove small broken limb and stub uplifts ground-level
Foraging species:	No

Tree Location

Longitude:	115.916896
Latitude:	-31.989221

Photos Street View Map View



Wooly Bush Tree ID #208

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916928
Latitude:	-31.989031

Photos Street View Map View



Grass Tree Tree ID #209

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This Grass Tree is in decline, and will likely due in the next 12 months
Foraging species:	No

Tree Location

Longitude:	115.916876
Latitude:	-31.988934

Photos Street View Map View



Wooly Bush Tree ID #210

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916814
Latitude:	-31.988906

Photos Street View Map View



Flowering Gum Tree ID #211

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	12
DBH [cm]:	32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.62
Tree Protection Zone (TPZ) [m]:	3.84
Structural Root Zone (SRZ) [m]:	2.71
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove small broken limb and stub uplift to 2m above ground level
Foraging species:	No

Tree Location

Longitude:	115.916796
Latitude:	-31.989032

Photos Street View Map View



Olive Tree ID #212

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	24.69
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.96
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basal shoots and all Deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.916760
Latitude:	-31.988984

Photos Street View Map View



Broad-leaved Paperbark Tree ID #213

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	24.69
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.96
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basal shoots and all Deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.916733
Latitude:	-31.988892

Photos Street View Map View



Broad-leaved Paperbark Tree ID #214

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	11.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.162
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.54
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.916724
Latitude:	-31.988872

Photos Street View Map View



Weeping Paperbark Tree ID #215

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	16.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.363
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.16
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.916698
Latitude:	-31.988881

Photos Street View Map View



Olive Tree ID #216

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	39
DBH [cm]:	7.25
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basal shoots and all Deadwood over 25 mm in diameter.
Foraging species:	No

Tree Location

Longitude:	115.916680
Latitude:	-31.988869

Photos Street View Map View

Broad-leaved Paperbark Tree ID #217

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	13.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.135
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.916705
Latitude:	-31.988846

Photos Street View Map View



Broad-leaved Paperbark Tree ID #218

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	13.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.135
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.916691
Latitude:	-31.988827

Photos Street View Map View



Weeping Paperbark Tree ID #219

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	16.8
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.02
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.916676
Latitude:	-31.988796

Photos Street View Map View



Weeping Paperbark Tree ID #220

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	29
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	3.48
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance from ground level
Foraging species:	No

Tree Location

Longitude:	115.916634
Latitude:	-31.988790

Photos Street View Map View



Weeping Paperbark Tree ID #221

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	17.9
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.15
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance from ground level
Foraging species:	No

Tree Location

Longitude:	115.916618
Latitude:	-31.988739

Photos Street View Map View



Grass Tree Tree ID #222

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916675
Latitude:	-31.988815

Photos Street View Map View



Grass Tree Tree ID #223

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916743
Latitude:	-31.988835

Photos Street View Map View



Grass Tree Tree ID #224

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916756
Latitude:	-31.988830

Photos Street View Map View



Grass Tree Tree ID #225

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916807
Latitude:	-31.988848

Photos Street View Map View



Grass Tree Tree ID #226

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916801
Latitude:	-31.988836

Photos Street View Map View



Grass Tree Tree ID #227

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916772
Latitude:	-31.988819

Photos Street View Map View



Grass Tree Tree ID #228

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916781
Latitude:	-31.988823

Photos Street View Map View



Grass Tree Tree ID #229

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916881
Latitude:	-31.988834

Photos Street View Map View



Grass Tree Tree ID #230

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916872
Latitude:	-31.988818

Photos Street View Map View



Grass Tree Tree ID #231

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916846
Latitude:	-31.988782

Photos Street View Map View



Grass Tree Tree ID #232

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916793
Latitude:	-31.988808

Photos Street View Map View



Grass Tree Tree ID #233

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916798
Latitude:	-31.988822

Photos Street View Map View



Grass Tree Tree ID #234

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916770
Latitude:	-31.988791

Photos Street View Map View



Grass Tree Tree ID #235

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916819
Latitude:	-31.988746

Photos Street View Map View



Grass Tree Tree ID #236

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916810
Latitude:	-31.988761

Photos Street View Map View



Grass Tree Tree ID #237

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916807
Latitude:	-31.988739

Photos Street View Map View



Grass Tree Tree ID #238

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916805
Latitude:	-31.988714

Photos Street View Map View



Grass Tree Tree ID #239

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916788
Latitude:	-31.988683

Photos Street View Map View



Wooly Bush Tree ID #240

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916727
Latitude:	-31.988769

Photos Street View Map View



Grass Tree Tree ID #241

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916773
Latitude:	-31.988655

Photos Street View Map View



Grass Tree Tree ID #242

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916759
Latitude:	-31.988633

Photos Street View Map View



Grass Tree Tree ID #243

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916751
Latitude:	-31.988624

Photos Street View Map View



Grass Tree Tree ID #244

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916728
Latitude:	-31.988628

Photos Street View Map View



Grass Tree Tree ID #245

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916719
Latitude:	-31.988594

Photos Street View Map View



Grass Tree Tree ID #246

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916629
Latitude:	-31.988654

Photos Street View Map View



Grass Tree Tree ID #247

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916643
Latitude:	-31.988658

Photos Street View Map View



Grass Tree Tree ID #248

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916631
Latitude:	-31.988646

Photos Street View Map View



Grass Tree Tree ID #249

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916643
Latitude:	-31.988719

Photos Street View Map View



Grass Tree Tree ID #250

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916635
Latitude:	-31.988710

Photos Street View Map View



Grass Tree Tree ID #251

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916611
Latitude:	-31.988713

Photos Street View Map View



Olive Tree ID #252

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	22.52
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	2.7
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplift to provide 2m canopy clearance over the verge
Foraging species:	No

Tree Location

Longitude:	115.916601
Latitude:	-31.988723

Photos Street View Map View



Weeping Paperbark Tree ID #253

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	27.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	3.26
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplift to provide 2m canopy clearance over the verge
Foraging species:	No

Tree Location

Longitude:	115.916600
Latitude:	-31.988699

Photos Street View Map View



Geraldton Wax Tree ID #254

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.916651
Latitude:	-31.988593

Photos Street View Map View



Wooly Bush Tree ID #255

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916707
Latitude:	-31.988560

Photos Street View Map View



Wooly Bush Tree ID #256

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916701
Latitude:	-31.988529

Photos Street View Map View



Geraldton Wax Tree ID #257

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916609
Latitude:	-31.988536

Photos Street View Map View



Wooly Bush Tree ID #258

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916573
Latitude:	-31.988484

Photos Street View Map View



Olive Tree ID #259

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Mature
Health:	Fair
Structure:	Very Poor
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	10.58
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Clump of olives that are from multiple suckers
Foraging species:	No

Tree Location

Longitude:	115.916539
Latitude:	-31.988401

Photos Street View Map View



Grass Tree Tree ID #260

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916509
Latitude:	-31.988376

Photos Street View Map View



Grass Tree Tree ID #261

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916512
Latitude:	-31.988356

Photos Street View Map View



Grass Tree Tree ID #262

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	3
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916505
Latitude:	-31.988347

Photos Street View Map View



Wooly Bush Tree ID #263

Tree Details

Latin Name:	Adenanthis cygnorum
Common Name:	Wooly Bush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	8
DBH [cm]:	3
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916490
Latitude:	-31.988319

Photos Street View Map View



Olive Tree ID #264

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	14.71
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplifting provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916543
Latitude:	-31.988608

Photos Street View Map View



Weeping Paperbark Tree ID #265


Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	14.7
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916557
Latitude:	-31.988570

Photos Street View Map View



Broad-leaved Paperbark Tree ID #266

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	25.95
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	3.11
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916526
Latitude:	-31.988577

Photos Street View Map View



Weeping Paperbark Tree ID #267

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	20.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	2.46
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.916544
Latitude:	-31.988546

Photos Street View Map View



Weeping Paperbark Tree ID #268

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	18.3
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	237
Tree Protection Zone (TPZ) [m]:	2.2
Structural Root Zone (SRZ) [m]:	32.9
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916505
Latitude:	-31.988539

Photos Street View Map View



Broad-leaved Paperbark Tree ID #269

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	15.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916533
Latitude:	-31.988505

Photos Street View Map View



Broad-leaved Paperbark Tree ID #270

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916503
Latitude:	-31.988483

Photos Street View Map View



Broad-leaved Paperbark Tree ID #271

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916469
Latitude:	-31.988463

Photos Street View Map View



Weeping Paperbark Tree ID #272

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	13.8
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	9.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916491
Latitude:	-31.988431

Photos Street View Map View



Weeping Paperbark Tree ID #273

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3.5
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.276
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.93
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916434
Latitude:	-31.988427

Photos Street View Map View



River Red Gum Tree ID #274

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	23.65
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.86
Tree Protection Zone (TPZ) [m]:	2.84
Structural Root Zone (SRZ) [m]:	3.11
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is comprised of multiple suckers from a remnant stump removal and stump grinding is recommended as it will never form a stable tree
Foraging species:	No

Tree Location

Longitude:	115.916463
Latitude:	-31.988406

Photos Street View Map View



Broad-leaved Paperbark Tree ID #275

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	14.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.212
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.73
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916462
Latitude:	-31.988381

Photos Street View Map View



Olive Tree ID #276

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	24.95
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2.99
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916425
Latitude:	-31.988374

Photos Street View Map View



Weeping Paperbark Tree ID #277

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	21.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2.54
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916387
Latitude:	-31.988326

Photos Street View Map View



Weeping Paperbark Tree ID #278

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916367
Latitude:	-31.988300

Photos Street View Map View



Broad-leaved Paperbark Tree ID #279

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	15.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916409
Latitude:	-31.988305

Photos Street View Map View



Olive Tree ID #280

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	9.06
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level. Remove basal shoots
Foraging species:	No

Tree Location

Longitude:	115.916344
Latitude:	-31.988236

Photos Street View Map View



Weeping Paperbark Tree ID #281

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	33.6
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	4.03
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916320
Latitude:	-31.988191

Photos Street View Map View



Broad-leaved Paperbark Tree ID #282

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	22.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.228
Tree Protection Zone (TPZ) [m]:	2.7
Structural Root Zone (SRZ) [m]:	1.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916345
Latitude:	-31.988187

Photos Street View Map View



Broad-leaved Paperbark Tree ID #283

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	15.8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.206
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.7
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916326
Latitude:	-31.988172

Photos Street View Map View



Broad-leaved Paperbark Tree ID #284

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916294
Latitude:	-31.988182

Photos Street View Map View



Broad-leaved Paperbark Tree ID #285

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2.5
DBH [cm]:	13.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.228
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916310
Latitude:	-31.988144

Photos Street View Map View



Weeping Paperbark Tree ID #286

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	24.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.388
Tree Protection Zone (TPZ) [m]:	2.94
Structural Root Zone (SRZ) [m]:	2.22
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916274
Latitude:	-31.988126

Photos Street View Map View



Olive Tree ID #287

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	15.31
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916261
Latitude:	-31.988106

Photos Street View Map View



Weeping Paperbark Tree ID #288

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	37
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.388
Tree Protection Zone (TPZ) [m]:	4.44
Structural Root Zone (SRZ) [m]:	2.22
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916258
Latitude:	-31.988076

Photos Street View Map View



Weeping Paperbark Tree ID #289

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	42.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	5.1
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916269
Latitude:	-31.988063

Photos Street View Map View



Broad-leaved Paperbark Tree ID #290

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	27.79
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.332
Tree Protection Zone (TPZ) [m]:	3.33
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916220
Latitude:	-31.988045

Photos Street View Map View



Broad-leaved Paperbark Tree ID #291

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	19.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.3
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916241
Latitude:	-31.988010

Photos Street View Map View



Weeping Paperbark Tree ID #292

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3.5
DBH [cm]:	47.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	5.66
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916193
Latitude:	-31.987937

Photos Street View Map View



Snow Gum Tree ID #293

Tree Details

Latin Name:	Eucalyptus pauciflora
Common Name:	Snow Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	40.18
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.72
Tree Protection Zone (TPZ) [m]:	4.82
Structural Root Zone (SRZ) [m]:	2.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2m clearance above ground level and remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.916074
Latitude:	-31.987455

Photos Street View Map View



Snow Gum Tree ID #294

Tree Details

Latin Name:	Eucalyptus pauciflora
Common Name:	Snow Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.262
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	1.89
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2m clearance above ground level and remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.916044
Latitude:	-31.987393

Photos Street View Map View



Red Cap Gum Tree ID #295

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	23.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	2.82
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy to provide 2m clearance above ground level and remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915984
Latitude:	-31.987420

Photos Street View Map View



Geraldton Wax Tree ID #296

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	8
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.914600
Latitude:	-31.984946

Photos Street View Map View



Flowering Gum Tree ID #297

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	34.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	4.1
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.914473
Latitude:	-31.984966

Photos Street View Map View



Weeping Bottlebrush Tree ID #298

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	13.57
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914381
Latitude:	-31.984851

Photos Street View Map View



Broad-leaved Paperbark Tree ID #299

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	87
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.92
Tree Protection Zone (TPZ) [m]:	10.44
Structural Root Zone (SRZ) [m]:	3.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914352
Latitude:	-31.984744

Photos Street View Map View



WA Peppermint Tree ID #300

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	75.17
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1
Tree Protection Zone (TPZ) [m]:	9.02
Structural Root Zone (SRZ) [m]:	3.31
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914319
Latitude:	-31.984667

Photos Street View Map View



Broad-leaved Paperbark Tree ID #301

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	2
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.198
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.914327
Latitude:	-31.984721

Photos Street View Map View



WA Peppermint Tree ID #302

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	37.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	4.49
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914161
Latitude:	-31.984404

Photos Street View Map View



Blue Gum Tree ID #303

Tree Details

Latin Name:	Eucalyptus tereticornis
Common Name:	Blue Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	3
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is effectively rootstock material where the grafted tree has died and a rootstock has taken over it is recommended to remove this as it will never have a good structure
Foraging species:	No

Tree Location

Longitude:	115.914264
Latitude:	-31.984652

Photos Street View Map View



Olive Tree ID #304

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Very Poor
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	7.5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.375
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.19
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree has a very poor structure removal recommended
Foraging species:	No

Tree Location

Longitude:	115.914234
Latitude:	-31.984599

Photos Street View Map View



WA Peppermint Tree ID #305

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	45.22
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.72
Tree Protection Zone (TPZ) [m]:	5.43
Structural Root Zone (SRZ) [m]:	2.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914131
Latitude:	-31.984350

Photos Street View Map View



WA Peppermint Tree ID #306

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	
DBH [cm]:	76.32
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.09
Tree Protection Zone (TPZ) [m]:	9.16
Structural Root Zone (SRZ) [m]:	3.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914131
Latitude:	-31.984305

Photos Street View Map View



Broad-leaved Paperbark Tree ID #307

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	68.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.765
Tree Protection Zone (TPZ) [m]:	8.22
Structural Root Zone (SRZ) [m]:	2.96
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914116
Latitude:	-31.984431

Photos Street View Map View



Weeping Paperbark Tree ID #308

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	18.12
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.252
Tree Protection Zone (TPZ) [m]:	2.17
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914048
Latitude:	-31.984348

Photos Street View Map View



Weeping Paperbark Tree ID #309

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	9.86
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.16
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914073
Latitude:	-31.984364

Photos Street View Map View



Red Cap Gum Tree ID #310

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove lower shoots to uplift canopy by 2 m above ground level and remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.914013
Latitude:	-31.984335

Photos Street View Map View



Broad-leaved Paperbark Tree ID #311

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	2
DBH [cm]:	12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.914031
Latitude:	-31.984308

Photos Street View Map View



Olive Tree ID #312

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	15.66
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove lower shoots to uplift canopy by 2 m above ground level and remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.914007
Latitude:	-31.984288

Photos Street View Map View



Weeping Paperbark Tree ID #313

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	33.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.51
Tree Protection Zone (TPZ) [m]:	4.02
Structural Root Zone (SRZ) [m]:	2.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913966
Latitude:	-31.984246

Photos Street View Map View



Weeping Paperbark Tree ID #314

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	67
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	8.04
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913889
Latitude:	-31.984152

Photos Street View Map View



Blue Gum Tree ID #315

Tree Details

Latin Name:	Eucalyptus tereticornis
Common Name:	Blue Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	3
DBH [cm]:	22.39
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	2.69
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is effectively rootstock material where the grafted tree has died and a rootstock has taken over it is recommended to remove this as it will never have a good structure
Foraging species:	No

Tree Location

Longitude:	115.913832
Latitude:	-31.984084

Photos Street View Map View



WA Peppermint Tree ID #316

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	45.69
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	76.5
Tree Protection Zone (TPZ) [m]:	5.48
Structural Root Zone (SRZ) [m]:	20.46
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913901
Latitude:	-31.984062

Photos Street View Map View



WA Peppermint Tree ID #317

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	51.7
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	6.2
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913886
Latitude:	-31.984013

Photos Street View Map View



WA Peppermint Tree ID #318

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	56.44
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	80.6
Tree Protection Zone (TPZ) [m]:	6.77
Structural Root Zone (SRZ) [m]:	20.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913848
Latitude:	-31.984018

Photos Street View Map View



WA Peppermint Tree ID #319

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	34.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.68
Tree Protection Zone (TPZ) [m]:	4.18
Structural Root Zone (SRZ) [m]:	2.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913806
Latitude:	-31.983941

Photos Street View Map View



Weeping Bottlebrush Tree ID #320

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913790
Latitude:	-31.984032

Photos Street View Map View



Olive Tree ID #321

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	14.97
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a large sprawling olive canopy cleaning required
Foraging species:	No

Tree Location

Longitude:	115.913752
Latitude:	-31.983984

Photos Street View Map View



Flowering Gum Tree ID #322

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	32.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.9
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level and remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.913725
Latitude:	-31.983938

Photos Street View Map View



Weeping Bottlebrush Tree ID #323

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913685
Latitude:	-31.983926

Photos Street View Map View



Broad-leaved Paperbark Tree ID #324

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	9
DBH [cm]:	50
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	6
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level, and remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.913636
Latitude:	-31.983830

Photos Street View Map View



Broad-leaved Paperbark Tree ID #325

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	15.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.285
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.95
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level, and remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.913563
Latitude:	-31.983777

Photos Street View Map View



Geraldton Wax Tree ID #326

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913733
Latitude:	-31.983742

Photos Street View Map View



Geraldton Wax Tree ID #327

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913589
Latitude:	-31.983597

Photos Street View Map View



Geraldton Wax Tree ID #328

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913437
Latitude:	-31.983393

Photos Street View Map View



Geraldton Wax Tree ID #329

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913328
Latitude:	-31.983267

Photos Street View Map View



Geraldton Wax Tree ID #330

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913216
Latitude:	-31.983156

Photos Street View Map View



On Sided Bottlebrush Tree ID #331

Tree Details

Latin Name:	Calothamnus quadrifidus
Common Name:	On Sided Bottlebrush
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	15
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This shrub is in decline and 50% dead
Foraging species:	No

Tree Location

Longitude:	115.913378
Latitude:	-31.983410

Photos Street View Map View



Broad-leaved Paperbark Tree ID #332

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.61
Tree Protection Zone (TPZ) [m]:	5.64
Structural Root Zone (SRZ) [m]:	2.69
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level, and remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.913532
Latitude:	-31.983725

Photos Street View Map View



Olive Tree ID #333

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	14.97
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a large sprawling olive canopy cleaning required
Foraging species:	No

Tree Location

Longitude:	115.913457
Latitude:	-31.983643

Photos Street View Map View



Red Cap Gum Tree ID #334

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	18.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.22
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level, and remove all deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.913438
Latitude:	-31.983622

Photos Street View Map View



Red Cap Gum Tree ID #335

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	10.2
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.174
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.59
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913423
Latitude:	-31.983585

Photos Street View Map View



Broad-leaved Paperbark Tree ID #336

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	47.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	5.7
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913348
Latitude:	-31.983522

Photos Street View Map View



Broad-leaved Paperbark Tree ID #337

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913291
Latitude:	-31.983471

Photos Street View Map View



Broad-leaved Paperbark Tree ID #338

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	25.78
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	3.09
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913255
Latitude:	-31.983433

Photos Street View Map View



Olive Tree ID #339

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	14.97
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a large sprawling olive canopy cleaning required
Foraging species:	No

Tree Location

Longitude:	115.913214
Latitude:	-31.983381

Photos Street View Map View



Flowering Gum Tree ID #340

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	66
Canopy Spread [m]:	
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.913133
Latitude:	-31.983316

Photos Street View Map View



Flowering Gum Tree ID #341

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	66
Canopy Spread [m]:	
DBH [cm]:	56
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	6.72
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.913094
Latitude:	-31.983281

Photos Street View Map View



Weeping Bottlebrush Tree ID #342

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	14.02
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to start providing clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913054
Latitude:	-31.983228

Photos Street View Map View



Geraldton Wax Tree ID #343

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.912962
Latitude:	-31.983118

Photos Street View Map View



Flowering Gum Tree ID #344

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	10.2
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912888
Latitude:	-31.983060

Photos Street View Map View



Weeping Paperbark Tree ID #345

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	17.56
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.11
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912890
Latitude:	-31.983022

Photos Street View Map View



Weeping Bottlebrush Tree ID #346

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	12.87
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912829
Latitude:	-31.982974

Photos Street View Map View



Weeping Bottlebrush Tree ID #347

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	10.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912807
Latitude:	-31.982959

Photos Street View Map View



Broad-leaved Paperbark Tree ID #348

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	82.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.705
Tree Protection Zone (TPZ) [m]:	9.9
Structural Root Zone (SRZ) [m]:	2.86
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912752
Latitude:	-31.982900

Photos Street View Map View



Weeping Paperbark Tree ID #349

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	8.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.135
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.43
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912725
Latitude:	-31.982841

Photos Street View Map View



WA Peppermint Tree ID #350

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	25.96
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal recommended due to decline of the specimen
Foraging species:	No

Tree Location

Longitude:	115.912767
Latitude:	-31.982820

Photos Street View Map View



River Red Gum Tree ID #351

Tree Details

Latin Name:	Eucalyptus camaldulensis var. obtusa
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	71
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.545777
Tree Protection Zone (TPZ) [m]:	8.52
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level and remove stubs from previous locking
Foraging species:	No

Tree Location

Longitude:	115.912658
Latitude:	-31.982786

Photos Street View Map View



Grevillea sp Tree ID #352

Tree Details

Latin Name:	Grevillea sp
Common Name:	Grevillea sp
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	5
DBH [cm]:	11.36
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level and remove stubs from previous locking
Foraging species:	No

Tree Location

Longitude:	115.912601
Latitude:	-31.982754

Photos Street View Map View



Sydney Blue Gum Tree ID #353

Tree Details

Latin Name:	Eucalyptus saligna
Common Name:	Sydney Blue Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	11
DBH [cm]:	85.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	10.26
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level and remove stubs from previous locking
Foraging species:	No

Tree Location

Longitude:	115.912581
Latitude:	-31.982719

Photos Street View Map View



Weeping Paperbark Tree ID #354

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	19.73
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.245
Tree Protection Zone (TPZ) [m]:	2.37
Structural Root Zone (SRZ) [m]:	1.83
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912512
Latitude:	-31.982657

Photos Street View Map View



Weeping Paperbark Tree ID #355

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	22.4
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	2.69
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912517
Latitude:	-31.982614

Photos Street View Map View



Weeping Paperbark Tree ID #356

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912502
Latitude:	-31.982600

Photos Street View Map View



Broad-leaved Paperbark Tree ID #357

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912461
Latitude:	-31.982608

Photos Street View Map View



Weeping Paperbark Tree ID #358

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912392
Latitude:	-31.982550

Photos Street View Map View



Sydney Blue Gum Tree ID #359

Tree Details

Latin Name:	Eucalyptus saligna
Common Name:	Sydney Blue Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	2
DBH [cm]:	41.31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.96
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree has been heavily lopped due to over power lines is recommended to remove
Foraging species:	No

Tree Location

Longitude:	115.912359
Latitude:	-31.982482

Photos Street View Map View



Weeping Paperbark Tree ID #360

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912307
Latitude:	-31.982467

Photos Street View Map View



Paperbark Tree ID #361

Tree Details

Latin Name:	Melaleuca sp.
Common Name:	Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	13.22
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.182
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.62
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide at least 2 m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912282
Latitude:	-31.982446

Photos Street View Map View



Broad-leaved Paperbark Tree ID #362

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	42.7
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.575
Tree Protection Zone (TPZ) [m]:	5.12
Structural Root Zone (SRZ) [m]:	2.62
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.912244
Latitude:	-31.982409

Photos Street View Map View



Broad-leaved Paperbark Tree ID #363

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	5.04
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.912226
Latitude:	-31.982359

Photos Street View Map View



Flowering Gum Tree ID #364

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	43.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	5.22
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.912214
Latitude:	-31.982341

Photos Street View Map View



Flowering Gum Tree ID #365

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.395
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.24
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.912199
Latitude:	-31.982308

Photos Street View Map View



Flowering Gum Tree ID #366

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	40.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	4.82
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove low branch to the Northwest clearance around clearance around the tree
Foraging species:	No

Tree Location

Longitude:	115.912172
Latitude:	-31.982295

Photos Street View Map View



Weeping Bottlebrush Tree ID #367

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.185
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.63
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove low branches to start uplifting this tree
Foraging species:	No

Tree Location

Longitude:	115.912137
Latitude:	-31.982281

Photos Street View Map View



Grass Tree Tree ID #368

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916868
Latitude:	-31.988900

Photos Street View Map View



Common Sheoak Tree ID #369

Tree Details

Latin Name:	Allocasuarina fraseriana
Common Name:	Common Sheoak
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	39.35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.67
Tree Protection Zone (TPZ) [m]:	4.72
Structural Root Zone (SRZ) [m]:	2.8
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2M clearance above ground level, Remove all dead wood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.917691
Latitude:	-31.990445

Photos Street View Map View



Broad-leaved Paperbark Tree ID #370

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	14.87
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove low branches to start uplifting this tree
Foraging species:	No

Tree Location

Longitude:	115.912128
Latitude:	-31.982255

Photos Street View Map View



Silver Princess Tree ID #371


Tree Details

Latin Name:	Eucalyptus caesia
Common Name:	Silver Princess
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.165
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.55
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.912095
Latitude:	-31.982234

Photos Street View Map View



Showy honey myrtle Tree ID #372

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.395
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	2.24
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912091
Latitude:	-31.982189

Photos Street View Map View



Broad-leaved Paperbark Tree ID #373

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	16.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912064
Latitude:	-31.982183

Photos Street View Map View



Russian Olive Tree ID #374

Tree Details

Latin Name:	Elaeagnus angustifolia
Common Name:	Russian Olive
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	31.7
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.59
Tree Protection Zone (TPZ) [m]:	3.8
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level and remove all Deadwood over 25 mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.912039
Latitude:	-31.982178

Photos Street View Map View



Weeping Paperbark Tree ID #375

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911971
Latitude:	-31.982116

Photos Street View Map View



Broad-leaved Paperbark Tree ID #376

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	11.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911956
Latitude:	-31.982106

Photos Street View Map View



Red Cap Gum Tree ID #377

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	12.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level, remove dead leader back to source
Foraging species:	No

Tree Location

Longitude:	115.911977
Latitude:	-31.982094

Photos Street View Map View



Red Cap Gum Tree ID #378

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	26.91
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.36
Tree Protection Zone (TPZ) [m]:	3.23
Structural Root Zone (SRZ) [m]:	2.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level, remove deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.911930
Latitude:	-31.982087

Photos Street View Map View



Weeping Bottlebrush Tree ID #379

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	8.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.16
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.53
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level and remove stubs left from poor pruning
Foraging species:	No

Tree Location

Longitude:	115.911915
Latitude:	-31.982076

Photos Street View Map View



Weeping Bottlebrush Tree ID #380

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	8.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.16
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.53
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level and remove stubs left from poor pruning
Foraging species:	No

Tree Location

Longitude:	115.911894
Latitude:	-31.982065

Photos Street View Map View



Broad-leaved Paperbark Tree ID #381

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.265
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	1.89
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove low branches to start uplifting this tree
Foraging species:	No

Tree Location

Longitude:	115.911939
Latitude:	-31.982071

Photos Street View Map View



Broad-leaved Paperbark Tree ID #382

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	73.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.745
Tree Protection Zone (TPZ) [m]:	8.82
Structural Root Zone (SRZ) [m]:	2.92
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove low branches that have been left as result of poor pruning
Foraging species:	No

Tree Location

Longitude:	115.911898
Latitude:	-31.982037

Photos Street View Map View



Broad-leaved Paperbark Tree ID #383

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	21.22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.235
Tree Protection Zone (TPZ) [m]:	2.55
Structural Root Zone (SRZ) [m]:	1.8
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911867
Latitude:	-31.981980

Photos Street View Map View



Broad-leaved Paperbark Tree ID #384

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	67
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.605
Tree Protection Zone (TPZ) [m]:	8.04
Structural Root Zone (SRZ) [m]:	2.68
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911827
Latitude:	-31.981954

Photos Street View Map View



Broad-leaved Paperbark Tree ID #385

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	13.83
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911829
Latitude:	-31.981985

Photos Street View Map View



Weeping Bottlebrush Tree ID #386

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	7.81
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.152
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.5
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911794
Latitude:	-31.981954

Photos Street View Map View



Russian Olive Tree ID #387

Tree Details

Latin Name:	Elaeagnus angustifolia
Common Name:	Russian Olive
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	31.23
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	3.75
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Call specimen removal recommended
Foraging species:	No

Tree Location

Longitude:	115.911800
Latitude:	-31.981915

Photos Street View Map View



Broad-leaved Paperbark Tree ID #388

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	31.89
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	3.83
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911725
Latitude:	-31.981824

Photos Street View Map View



Broad-leaved Paperbark Tree ID #389

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	65.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	7.86
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911659
Latitude:	-31.981799

Photos Street View Map View



Weeping Paperbark Tree ID #390

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911621
Latitude:	-31.981782

Photos Street View Map View



Weeping Paperbark Tree ID #391

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	14.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.245
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.83
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911643
Latitude:	-31.981754

Photos Street View Map View



Weeping Paperbark Tree ID #392

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911624
Latitude:	-31.981740

Photos Street View Map View



Flowering Gum Tree ID #393

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	15.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911582
Latitude:	-31.981676

Photos Street View Map View



Flowering Gum Tree ID #394

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	83.4
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.695
Tree Protection Zone (TPZ) [m]:	10.01
Structural Root Zone (SRZ) [m]:	2.84
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.911571
Latitude:	-31.981715

Photos Street View Map View



Russian Olive Tree ID #395

Tree Details

Latin Name:	Elaeagnus angustifolia
Common Name:	Russian Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift tree to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911551
Latitude:	-31.981664

Photos Street View Map View



Weeping Bottlebrush Tree ID #396

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift tree to start providing 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911511
Latitude:	-31.981664

Photos Street View Map View



Weeping Paperbark Tree ID #397

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	23
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2.76
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift tree to start providing 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911462
Latitude:	-31.981606

Photos Street View Map View



Flowering Gum Tree ID #398

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	49.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.555
Tree Protection Zone (TPZ) [m]:	5.94
Structural Root Zone (SRZ) [m]:	2.58
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911465
Latitude:	-31.981580

Photos Street View Map View



Broad-leaved Paperbark Tree ID #399

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	71
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.73
Tree Protection Zone (TPZ) [m]:	8.52
Structural Root Zone (SRZ) [m]:	2.9
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911404
Latitude:	-31.981524

Photos Street View Map View



Broad-leaved Paperbark Tree ID #400

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	38.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	4.62
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.911361
Latitude:	-31.981482

Photos Street View Map View



Broad-leaved Paperbark Tree ID #401

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.337
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.911332
Latitude:	-31.981452

Photos Street View Map View



Broad-leaved Paperbark Tree ID #402

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	4.5
DBH [cm]:	25.7
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.08
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911273
Latitude:	-31.981427

Photos Street View Map View



Broad-leaved Paperbark Tree ID #403

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.168
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.56
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.911254
Latitude:	-31.981394

Photos Street View Map View



Red Cap Gum Tree ID #404

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.36
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.15
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911275
Latitude:	-31.981371

Photos Street View Map View



Broad-leaved Paperbark Tree ID #405

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	73
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.77
Tree Protection Zone (TPZ) [m]:	8.76
Structural Root Zone (SRZ) [m]:	2.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.911166
Latitude:	-31.981268

Photos Street View Map View



Weeping Paperbark Tree ID #406

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	3
DBH [cm]:	23.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	2.82
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.911118
Latitude:	-31.981227

Photos Street View Map View



Grass Tree Tree ID #407

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916859
Latitude:	-31.988912

Photos Street View Map View



Grass Tree Tree ID #408

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916762
Latitude:	-31.988752

Photos Street View Map View



Grass Tree Tree ID #409

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916754
Latitude:	-31.988765

Photos Street View Map View



Grass Tree Tree ID #410

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916758
Latitude:	-31.988775

Photos Street View Map View



Grass Tree Tree ID #411

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916794
Latitude:	-31.988700

Photos Street View Map View



Grass Tree Tree ID #412

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916808
Latitude:	-31.988698

Photos Street View Map View



Grass Tree Tree ID #413

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916833
Latitude:	-31.988738

Photos Street View Map View



Grass Tree Tree ID #414

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916817
Latitude:	-31.988710

Photos Street View Map View



Geraldton Wax Tree ID #415

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.916667
Latitude:	-31.988474

Photos Street View Map View



Broad-leaved Paperbark Tree ID #416

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	45.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.57
Tree Protection Zone (TPZ) [m]:	5.46
Structural Root Zone (SRZ) [m]:	2.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915790
Latitude:	-31.987224

Photos Street View Map View



Broad-leaved Paperbark Tree ID #417

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915660
Latitude:	-31.986992

Photos Street View Map View



Broad-leaved Paperbark Tree ID #418

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	49
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.59
Tree Protection Zone (TPZ) [m]:	5.88
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915613
Latitude:	-31.986913

Photos Street View Map View



Broad-leaved Paperbark Tree ID #419

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	46.8
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	5.62
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915429
Latitude:	-31.986589

Photos Street View Map View



Pixie Mops Tree ID #420

Tree Details

Latin Name:	Petrophile liniaris
Common Name:	Pixie Mops
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	3
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	6-10 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.913557
Latitude:	-31.983547

Photos Street View Map View



Pixie Mops Tree ID #421

Tree Details

Latin Name:	Petrophile liniaris
Common Name:	Pixie Mops
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	3
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	6-10 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.913425
Latitude:	-31.983356

Photos Street View Map View



Pixie Mops Tree ID #422

Tree Details

Latin Name:	Petrophile liniaris
Common Name:	Pixie Mops
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	13
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	11-20 years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.913181
Latitude:	-31.983128

Photos Street View Map View



Weeping Paperbark Tree ID #423

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Poor
Structure:	Very Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	46.7
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.75
Tree Protection Zone (TPZ) [m]:	5.6
Structural Root Zone (SRZ) [m]:	2.93
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is 90% dead, removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.912554
Latitude:	-31.982583

Photos Street View Map View



Geraldton Wax Tree ID #424


Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	25
DBH [cm]:	52
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	6.24
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.909138
Latitude:	-31.978930

Photos Street View Map View



Panjang Tree ID #425

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907286
Latitude:	-31.976964

Photos Street View Map View



Panjang Tree ID #426

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907244
Latitude:	-31.976860

Photos Street View Map View



Panjang Tree ID #427

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907206
Latitude:	-31.976817

Photos Street View Map View



Panjang Tree ID #428

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907154
Latitude:	-31.976803

Photos Street View Map View



Panjang Tree ID #429

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907182
Latitude:	-31.976779

Photos Street View Map View

Panjang Tree ID #430

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907136
Latitude:	-31.976735

Photos Street View Map View



Panjang Tree ID #431

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907036
Latitude:	-31.976636

Photos Street View Map View



Panjang Tree ID #432

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.906954
Latitude:	-31.976625

Photos Street View Map View



Panjang Tree ID #433


Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.906987
Latitude:	-31.976683

Photos Street View Map View



Panjang Tree ID #434

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.906944
Latitude:	-31.976724

Photos Street View Map View



Panjang Tree ID #435

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907015
Latitude:	-31.976800

Photos Street View Map View

Panjang Tree ID #436

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907153
Latitude:	-31.976862

Photos Street View Map View

Panjang Tree ID #437

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907099
Latitude:	-31.976888

Photos Street View Map View

Panjang Tree ID #438

Tree Details

Latin Name:	Acacia lasiocaroa
Common Name:	Panjang
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Native shrub
Foraging species:	No

Tree Location

Longitude:	115.907199
Latitude:	-31.976966

Photos Street View Map View

Geraldton Wax Tree ID #439

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	4
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.05
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	0.94
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.907275
Latitude:	-31.977012

Photos Street View Map View

Weeping Bottlebrush Tree ID #440

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	14
DBH [cm]:	11.79
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.172
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.58
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911089
Latitude:	-31.981200

Photos Street View Map View

Weeping Bottlebrush Tree ID #441

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	14
DBH [cm]:	12.98
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911044
Latitude:	-31.981169

Photos Street View Map View

Weeping Paperbark Tree ID #442

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4.5
DBH [cm]:	23.64
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2.84
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911081
Latitude:	-31.981158

Photos Street View Map View



Olive Tree ID #443

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	29.1
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.428
Tree Protection Zone (TPZ) [m]:	3.49
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.911053
Latitude:	-31.981138

Photos Street View Map View



Broad-leaved Paperbark Tree ID #444

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	46.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.683
Tree Protection Zone (TPZ) [m]:	5.54
Structural Root Zone (SRZ) [m]:	2.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.911012
Latitude:	-31.981075

Photos Street View Map View



Red Cap Gum Tree ID #445

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.195
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.67
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910977
Latitude:	-31.981084

Photos Street View Map View



Broad-leaved Paperbark Tree ID #446

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	50.87
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.625
Tree Protection Zone (TPZ) [m]:	6.1
Structural Root Zone (SRZ) [m]:	2.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910972
Latitude:	-31.981055

Photos Street View Map View



Broad-leaved Paperbark Tree ID #447

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	10
DBH [cm]:	67
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.645
Tree Protection Zone (TPZ) [m]:	8.04
Structural Root Zone (SRZ) [m]:	2.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910905
Latitude:	-31.981007

Photos Street View Map View



Flowering Gum Tree ID #448

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	10
DBH [cm]:	65.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.645
Tree Protection Zone (TPZ) [m]:	7.86
Structural Root Zone (SRZ) [m]:	2.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910835
Latitude:	-31.980929

Photos Street View Map View



Weeping Paperbark Tree ID #449

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910826
Latitude:	-31.980890

Photos Street View Map View



Olive Tree ID #450

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	36.41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.523
Tree Protection Zone (TPZ) [m]:	4.37
Structural Root Zone (SRZ) [m]:	2.52
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.910802
Latitude:	-31.980880

Photos Street View Map View



Costal Mort Tree ID #451

Tree Details

Latin Name:	Eucalyptus utilis
Common Name:	Costal Mort
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	40.94
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.92
Tree Protection Zone (TPZ) [m]:	4.91
Structural Root Zone (SRZ) [m]:	3.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.910666
Latitude:	-31.980747

Photos Street View Map View



Costal Mort Tree ID #452

Tree Details

Latin Name:	Eucalyptus utilis
Common Name:	Costal Mort
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	77.66
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.033
Tree Protection Zone (TPZ) [m]:	9.32
Structural Root Zone (SRZ) [m]:	3.35
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.910607
Latitude:	-31.980680

Photos Street View Map View



Weeping Paperbark Tree ID #453

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.346
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.12
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910495
Latitude:	-31.980596

Photos Street View Map View



Broad-leaved Paperbark Tree ID #454

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910479
Latitude:	-31.980563

Photos Street View Map View



Broad-leaved Paperbark Tree ID #455

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	22.6
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.355
Tree Protection Zone (TPZ) [m]:	2.71
Structural Root Zone (SRZ) [m]:	2.14
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910396
Latitude:	-31.980487

Photos Street View Map View



Weeping Paperbark Tree ID #456

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.225
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	1.77
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.910358
Latitude:	-31.980475

Photos Street View Map View



Weeping Paperbark Tree ID #457

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	17.56
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.11
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910329
Latitude:	-31.980455

Photos Street View Map View



Broad-leaved Paperbark Tree ID #458

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	11
DBH [cm]:	69.8
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.727
Tree Protection Zone (TPZ) [m]:	8.38
Structural Root Zone (SRZ) [m]:	2.89
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level and to provide clearance around adjacent Melaleuca
Foraging species:	No

Tree Location

Longitude:	115.910347
Latitude:	-31.980430

Photos Street View Map View



Broad-leaved Paperbark Tree ID #459

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	20.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2.46
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.910312
Latitude:	-31.980429

Photos Street View Map View



Weeping Paperbark Tree ID #460

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5.5
DBH [cm]:	35.81
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.388
Tree Protection Zone (TPZ) [m]:	4.3
Structural Root Zone (SRZ) [m]:	2.22
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.910274
Latitude:	-31.980343

Photos Street View Map View



Weeping Paperbark Tree ID #461

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	39.77
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.472
Tree Protection Zone (TPZ) [m]:	4.77
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.910209
Latitude:	-31.980257

Photos Street View Map View



Broad-leaved Paperbark Tree ID #462

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	49
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.625
Tree Protection Zone (TPZ) [m]:	5.88
Structural Root Zone (SRZ) [m]:	2.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.910140
Latitude:	-31.980244

Photos Street View Map View



Broad-leaved Paperbark Tree ID #463

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8.5
DBH [cm]:	57.63
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	6.92
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.910132
Latitude:	-31.980194

Photos Street View Map View



Weeping Bottlebrush Tree ID #464

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	7.5
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.095
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.23
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basal shoots
Foraging species:	No

Tree Location

Longitude:	115.910129
Latitude:	-31.980160

Photos Street View Map View



Flowering Gum Tree ID #465

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7.5
DBH [cm]:	65.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.615
Tree Protection Zone (TPZ) [m]:	7.86
Structural Root Zone (SRZ) [m]:	2.7
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.910037
Latitude:	-31.980114

Photos Street View Map View



Weeping Paperbark Tree ID #466

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.252
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.910012
Latitude:	-31.980087

Photos Street View Map View



Weeping Paperbark Tree ID #467

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.909985
Latitude:	-31.980053

Photos Street View Map View



Weeping Paperbark Tree ID #468

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	60
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.63
Tree Protection Zone (TPZ) [m]:	7.2
Structural Root Zone (SRZ) [m]:	2.73
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level and remove basal shoot. This tree could be considered for removal due to the lopping that has destroyed it's form
Foraging species:	No

Tree Location

Longitude:	115.909913
Latitude:	-31.979993

Photos Street View Map View



Red Cap Gum Tree ID #469

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	34.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.59
Tree Protection Zone (TPZ) [m]:	4.14
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.909900
Latitude:	-31.979967

Photos Street View Map View



Broad-leaved Paperbark Tree ID #470

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	60
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	7.2
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.909859
Latitude:	-31.979917

Photos Street View Map View



Broad-leaved Paperbark Tree ID #471

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	3
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.295
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	1.98
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.909815
Latitude:	-31.979862

Photos Street View Map View



Broad-leaved Paperbark Tree ID #472

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	40.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.495
Tree Protection Zone (TPZ) [m]:	4.82
Structural Root Zone (SRZ) [m]:	2.46
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.909783
Latitude:	-31.979839

Photos Street View Map View



Broad-leaved Paperbark Tree ID #473

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	57
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.655
Tree Protection Zone (TPZ) [m]:	6.84
Structural Root Zone (SRZ) [m]:	2.77
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.909753
Latitude:	-31.979806

Photos Street View Map View



Weeping Paperbark Tree ID #474

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	37
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	4.44
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.909720
Latitude:	-31.979763

Photos Street View Map View



Dryland Tea-tree Tree ID #475

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4.5
DBH [cm]:	22.44
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2.69
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	11-20 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.909710
Latitude:	-31.979746

Photos Street View Map View



Red Cap Gum Tree ID #476

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	5
DBH [cm]:	21.66
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.6
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917888
Latitude:	-31.990935

Photos Street View Map View



Olive Tree ID #477

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	0
Canopy Spread [m]:	3
DBH [cm]:	17.46
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	2.1
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917974
Latitude:	-31.991049

Photos Street View Map View



Red Cap Gum Tree ID #478

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	42.43
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	5.09
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917933
Latitude:	-31.990991

Photos Street View Map View



Hills Fig Tree ID #479

Tree Details

Latin Name:	Ficus microcarpa var hilli
Common Name:	Hills Fig
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	26
DBH [cm]:	111
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.15
Tree Protection Zone (TPZ) [m]:	13.32
Structural Root Zone (SRZ) [m]:	3.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.915509
Latitude:	-31.988026

Photos Street View Map View



Flowering Gum Tree ID #480

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	8
DBH [cm]:	77.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.05
Tree Protection Zone (TPZ) [m]:	9.3
Structural Root Zone (SRZ) [m]:	3.38
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.915728
Latitude:	-31.987802

Photos Street View Map View



WA Peppermint Tree ID #481

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	8
DBH [cm]:	129
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.36
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	3.77
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.915816
Latitude:	-31.987735

Photos Street View Map View



Gum-topped Bloodwood Tree ID #482


Tree Details

Latin Name:	Corymbia erythrophloia
Common Name:	Gum-topped Bloodwood
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.915039
Latitude:	-31.985941

Photos Street View Map View



Olive Tree ID #483

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	20.66
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.48
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.915024
Latitude:	-31.985892

Photos Street View Map View



Olive Tree ID #484

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	22.93
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.75
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.914866
Latitude:	-31.985558

Photos Street View Map View



Broad-leaved Paperbark Tree ID #485

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	11
DBH [cm]:	64.82
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	7.78
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.914782
Latitude:	-31.985428

Photos Street View Map View



Olive Tree ID #486

Tree Details

Latin Name:	Olea europaea
Common Name:	Olive
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	9
DBH [cm]:	39.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	4.7
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.914677
Latitude:	-31.985254

Photos Street View Map View



Red Cap Gum Tree ID #487

Tree Details

Latin Name:	Eucalyptus erythrocorys
Common Name:	Red Cap Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.914606
Latitude:	-31.985184

Photos Street View Map View



Hills Fig Tree ID #488

Tree Details

Latin Name:	Ficus microcarpa var hilli
Common Name:	Hills Fig
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	16
DBH [cm]:	100
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.27
Tree Protection Zone (TPZ) [m]:	12
Structural Root Zone (SRZ) [m]:	3.66
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.909258
Latitude:	-31.979962

Photos Street View Map View



Hills Fig Tree ID #489

Tree Details

Latin Name:	Ficus microcarpa var hilli
Common Name:	Hills Fig
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	16
DBH [cm]:	110.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.23
Tree Protection Zone (TPZ) [m]:	13.26
Structural Root Zone (SRZ) [m]:	3.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.909002
Latitude:	-31.980150

Photos Street View Map View



Broad-leaved Paperbark Tree ID #490

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	36.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	4.38
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	20-40 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide continued clearancece over the verge
Foraging species:	No

Tree Location

Longitude:	115.915896
Latitude:	-31.987413

Photos Street View Map View



Jacaranda Tree ID #491

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5.5
DBH [cm]:	26.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.315
Tree Protection Zone (TPZ) [m]:	3.18
Structural Root Zone (SRZ) [m]:	2.04
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.924073
Latitude:	-31.995990

Photos Street View Map View



Jacaranda Tree ID #492

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.924016
Latitude:	-31.995940

Photos Street View Map View



Jacaranda Tree ID #493

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923954
Latitude:	-31.995883

Photos Street View Map View



Jacaranda Tree ID #494

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923879
Latitude:	-31.995834

Photos Street View Map View



Jacaranda Tree ID #495

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basal shoots
Foraging species:	No

Tree Location

Longitude:	115.923823
Latitude:	-31.995798

Photos Street View Map View



Jacaranda Tree ID #496

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	46
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	5.52
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923763
Latitude:	-31.995736

Photos Street View Map View



Jacaranda Tree ID #497

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	46
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	5.52
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923688
Latitude:	-31.995687

Photos Street View Map View



Jacaranda Tree ID #498

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923641
Latitude:	-31.995644

Photos Street View Map View



Jacaranda Tree ID #499

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.44
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	2.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923573
Latitude:	-31.995597

Photos Street View Map View



Jacaranda Tree ID #500

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	9
DBH [cm]:	59.29
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.63
Tree Protection Zone (TPZ) [m]:	7.11
Structural Root Zone (SRZ) [m]:	2.73
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923496
Latitude:	-31.995540

Photos Street View Map View



Jacaranda Tree ID #501

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	9
DBH [cm]:	50.06
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	6.01
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923439
Latitude:	-31.995497

Photos Street View Map View



Jacaranda Tree ID #502

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.61
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.69
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923388
Latitude:	-31.995449

Photos Street View Map View



Jacaranda Tree ID #503

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.61
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.69
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923333
Latitude:	-31.995410

Photos Street View Map View



Jacaranda Tree ID #504

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	8
DBH [cm]:	48.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.515
Tree Protection Zone (TPZ) [m]:	5.82
Structural Root Zone (SRZ) [m]:	2.5
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923200
Latitude:	-31.995297

Photos Street View Map View



Jacaranda Tree ID #505

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	11
DBH [cm]:	38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.59
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923154
Latitude:	-31.995248

Photos Street View Map View



Jacaranda Tree ID #506

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	11
DBH [cm]:	52.3
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	6.28
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.923030
Latitude:	-31.995167

Photos Street View Map View



Jacaranda Tree ID #507

Tree Details

Latin Name:	Jacaranda mimosifolia
Common Name:	Jacaranda
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	11
DBH [cm]:	46.8
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.56
Tree Protection Zone (TPZ) [m]:	5.62
Structural Root Zone (SRZ) [m]:	2.59
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.922959
Latitude:	-31.995111

Photos Street View Map View



Flowering Gum Tree ID #508

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	72
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	8.64
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.922470
Latitude:	-31.994751

Photos Street View Map View



Flowering Gum Tree ID #509

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	72
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	8.64
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.922141
Latitude:	-31.994505

Photos Street View Map View



Flowering Gum Tree ID #510

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	10
DBH [cm]:	72
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	8.64
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.922074
Latitude:	-31.994458

Photos Street View Map View



5.0 Location of Subject Trees – Part D


Subject tree marked coloured dots in relation to species



5.1 Location of Subject Trees – Part D



5.2 Location of Subject Trees – Part D




5.3 Location of Subject Trees – Part D



5.4 Location of Subject Trees – Part D



5.5 Location of Subject Trees – Part D



5.6 Location of Subject Trees – Part D




5.7 Location of Subject Trees – Part D




5.8 Location of Subject Trees – Part D




5.9 Location of Subject Trees – Part D



5.10 Location of Subject Trees – Part D



5.11 Location of Subject Trees – Part D



5.12 Location of Subject Trees – Part D



5.13 Location of Subject Trees – Part D



5.14 Location of Subject Trees – Part D



Grey Stinkwood Tree ID #1

Tree Details

Latin Name:	Jacksonia furcellata
Common Name:	Grey Stinkwood
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Shrub in decline - consider removal
Foraging species:	No

Tree Location

Longitude:	115.927342
Latitude:	-31.998031

Photos Street View Map View



Grey Stinkwood Tree ID #2

Tree Details

Latin Name:	Jacksonia furcellata
Common Name:	Grey Stinkwood
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Shrub in decline - consider removal
Foraging species:	No

Tree Location

Longitude:	115.927244
Latitude:	-31.997975

Photos Street View Map View



Grey Stinkwood Tree ID #3

Tree Details

Latin Name:	Jacksonia furcellata
Common Name:	Grey Stinkwood
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	3
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Shrub in decline - consider removal
Foraging species:	No

Tree Location

Longitude:	115.927215
Latitude:	-31.997957

Photos Street View Map View



Weeping Paperbark Tree ID #4

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	30
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.922025
Latitude:	-31.993857

Photos Street View Map View



Weeping Bottlebrush Tree ID #5

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	23.11
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.77
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921980
Latitude:	-31.993818

Photos Street View Map View



Weeping Paperbark Tree ID #6

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	42.26
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	5.07
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921904
Latitude:	-31.993766

Photos Street View Map View



Weeping Paperbark Tree ID #7

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	41.59
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.99
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921856
Latitude:	-31.993725

Photos Street View Map View



Showy honey myrtle Tree ID #8

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	10.3
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to start achieving 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921811
Latitude:	-31.993692

Photos Street View Map View



Weeping Paperbark Tree ID #9

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	27.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	3.26
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921769
Latitude:	-31.993657

Photos Street View Map View



Showy honey myrtle Tree ID #10

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	11.75
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921727
Latitude:	-31.993627

Photos Street View Map View



Weeping Paperbark Tree ID #11

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	2
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.12
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.36
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	no work required
Foraging species:	No

Tree Location

Longitude:	115.921700
Latitude:	-31.993607

Photos Street View Map View



Weeping Bottlebrush Tree ID #12

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	8.43
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.13
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.4
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline, removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.921669
Latitude:	-31.993577

Photos Street View Map View



Showy honey myrtle Tree ID #13

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	9.95
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921650
Latitude:	-31.993570

Photos Street View Map View



Weeping Paperbark Tree ID #14

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	30.28
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	3.63
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921636
Latitude:	-31.993555

Photos Street View Map View



Weeping Bottlebrush Tree ID #15

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	8.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921615
Latitude:	-31.993544

Photos Street View Map View



Weeping Paperbark Tree ID #16

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	36.4
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.37
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921589
Latitude:	-31.993506

Photos Street View Map View



Weeping Bottlebrush Tree ID #17

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	10.54
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921554
Latitude:	-31.993489

Photos Street View Map View



Showy honey myrtle Tree ID #18

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	15.1
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	None
Foraging species:	No

Tree Location

Longitude:	115.921531
Latitude:	-31.993471

Photos Street View Map View



Weeping Paperbark Tree ID #19

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921509
Latitude:	-31.993457

Photos Street View Map View



Weeping Bottlebrush Tree ID #20

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	8.66
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921491
Latitude:	-31.993438

Photos Street View Map View



Weeping Paperbark Tree ID #21

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921441
Latitude:	-31.993402

Photos Street View Map View



Weeping Bottlebrush Tree ID #22

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	7.55
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921414
Latitude:	-31.993386

Photos Street View Map View



Showy honey myrtle Tree ID #23


Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	8.66
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921318
Latitude:	-31.993310

Photos Street View Map View



Weeping Paperbark Tree ID #24

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	7
DBH [cm]:	47.63
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.72
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921298
Latitude:	-31.993285

Photos Street View Map View



Weeping Bottlebrush Tree ID #25

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	11.27
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921275
Latitude:	-31.993270

Photos Street View Map View



Showy honey myrtle Tree ID #26

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921240
Latitude:	-31.993248

Photos Street View Map View



Weeping Paperbark Tree ID #27

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	15.26
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921224
Latitude:	-31.993230

Photos Street View Map View



Weeping Bottlebrush Tree ID #28

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	12.04
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921204
Latitude:	-31.993213

Photos Street View Map View



Weeping Paperbark Tree ID #29

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	7
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.921174
Latitude:	-31.993191

Photos Street View Map View



Weeping Paperbark Tree ID #30

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	5
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921149
Latitude:	-31.993173

Photos Street View Map View



Cook Pine Tree ID #31

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	14
DBH [cm]:	91
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.95
Tree Protection Zone (TPZ) [m]:	10.92
Structural Root Zone (SRZ) [m]:	3.24
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove lower branches to uplift tree to 2m above ground level
Foraging species:	No

Tree Location

Longitude:	115.921056
Latitude:	-31.993108

Photos Street View Map View



Weeping Paperbark Tree ID #32

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	17.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2.06
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.921006
Latitude:	-31.993060

Photos Street View Map View



Flinders Ranges Wattle Tree ID #33

Tree Details

Latin Name:	Acacia iteaphylla
Common Name:	Flinders Ranges Wattle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	16.31
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	6-10 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a short lived shrub species, removal can be considered
Foraging species:	No

Tree Location

Longitude:	115.920825
Latitude:	-31.992939

Photos Street View Map View



Weeping Paperbark Tree ID #34

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	6
DBH [cm]:	40
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920827
Latitude:	-31.992905

Photos Street View Map View



Weeping Paperbark Tree ID #35

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	6
DBH [cm]:	54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	6.48
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920810
Latitude:	-31.992895

Photos Street View Map View



Weeping Bottlebrush Tree ID #36

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	5.64
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920785
Latitude:	-31.992884

Photos Street View Map View



Weeping Bottlebrush Tree ID #37

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	10.63
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920756
Latitude:	-31.992861

Photos Street View Map View



Weeping Bottlebrush Tree ID #38

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	12.81
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920675
Latitude:	-31.992799

Photos Street View Map View



Showy honey myrtle Tree ID #39

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	21.95
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	2.63
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920662
Latitude:	-31.992785

Photos Street View Map View



Cook Pine Tree ID #40

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	11
DBH [cm]:	86
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.88
Tree Protection Zone (TPZ) [m]:	10.32
Structural Root Zone (SRZ) [m]:	3.14
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920617
Latitude:	-31.992767

Photos Street View Map View



Weeping Paperbark Tree ID #41

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	35.69
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.28
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920494
Latitude:	-31.992677

Photos Street View Map View



Coastal Tea Tree Tree ID #42

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	11.22
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.920476
Latitude:	-31.992642

Photos Street View Map View



Coastal Tea Tree Tree ID #43

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.920410
Latitude:	-31.992617

Photos Street View Map View



Weeping Bottlebrush Tree ID #44

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.44
Tree Protection Zone (TPZ) [m]:	5.04
Structural Root Zone (SRZ) [m]:	2.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920369
Latitude:	-31.992579

Photos Street View Map View



Coastal Tea Tree Tree ID #45

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	20.59
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	2.47
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.920335
Latitude:	-31.992549

Photos Street View Map View



Weeping Bottlebrush Tree ID #46

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	24.08
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	2.89
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920298
Latitude:	-31.992516

Photos Street View Map View



Coastal Tea Tree Tree ID #47

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	7
DBH [cm]:	20.66
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	2.48
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.920217
Latitude:	-31.992475

Photos Street View Map View



Weeping Bottlebrush Tree ID #48

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	3.84
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920166
Latitude:	-31.992451

Photos Street View Map View



Showy honey myrtle Tree ID #49

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	16.46
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.920092
Latitude:	-31.992358

Photos Street View Map View



Coastal Tea Tree Tree ID #50

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.920005
Latitude:	-31.992303

Photos Street View Map View



Coastal Tea Tree Tree ID #51

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919964
Latitude:	-31.992281

Photos Street View Map View



Coastal Tea Tree Tree ID #52

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919890
Latitude:	-31.992214

Photos Street View Map View



Coastal Tea Tree Tree ID #53

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919846
Latitude:	-31.992173

Photos Street View Map View



Coastal Tea Tree Tree ID #54

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919868
Latitude:	-31.992311

Photos Street View Map View



Coastal Tea Tree Tree ID #55

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919814
Latitude:	-31.992269

Photos Street View Map View



Coastal Tea Tree Tree ID #56

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919763
Latitude:	-31.992229

Photos Street View Map View



Coastal Tea Tree Tree ID #57

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919621
Latitude:	-31.992120

Photos Street View Map View



Coastal Tea Tree Tree ID #58

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919590
Latitude:	-31.992095

Photos Street View Map View



Coastal Tea Tree Tree ID #59

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919514
Latitude:	-31.992037

Photos Street View Map View



Coastal Tea Tree Tree ID #60

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919445
Latitude:	-31.991983

Photos Street View Map View



Coastal Tea Tree Tree ID #61

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	10
DBH [cm]:	13.19
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Can be regarded as a Weed species, removal recommended
Foraging species:	No

Tree Location

Longitude:	115.919305
Latitude:	-31.991880

Photos Street View Map View



Showy honey myrtle Tree ID #62

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	58.57
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	7.03
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a low sprawling shrub uplifting will be required
Foraging species:	No

Tree Location

Longitude:	115.919057
Latitude:	-31.991504

Photos Street View Map View



WA Peppermint Tree ID #63

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	95.42
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.218
Tree Protection Zone (TPZ) [m]:	11.45
Structural Root Zone (SRZ) [m]:	3.6
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918964
Latitude:	-31.991528

Photos Street View Map View



WA Peppermint Tree ID #64

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	49.69
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	5.96
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918985
Latitude:	-31.991442

Photos Street View Map View



WA Peppermint Tree ID #65

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	83.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.08
Tree Protection Zone (TPZ) [m]:	10.02
Structural Root Zone (SRZ) [m]:	3.42
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918919
Latitude:	-31.991375

Photos Street View Map View



Showy honey myrtle Tree ID #66

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	34.38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	4.13
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918898
Latitude:	-31.991361

Photos Street View Map View



Norfolk Island Pine Tree ID #67

Tree Details

Latin Name:	Araucaria heterophylla
Common Name:	Norfolk Island Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	11
DBH [cm]:	54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.56
Tree Protection Zone (TPZ) [m]:	6.48
Structural Root Zone (SRZ) [m]:	2.59
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918877
Latitude:	-31.991333

Photos Street View Map View



Showy honey myrtle Tree ID #68

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	34.48
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	4.14
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918825
Latitude:	-31.991266

Photos Street View Map View



Weeping Paperbark Tree ID #69

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	32.56
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	3.91
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918802
Latitude:	-31.991241

Photos Street View Map View



Weeping Paperbark Tree ID #70

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	4
DBH [cm]:	26.1
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	3.13
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918759
Latitude:	-31.991186

Photos Street View Map View



Showy honey myrtle Tree ID #71

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	10.54
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918719
Latitude:	-31.991133

Photos Street View Map View



Norfolk Island Pine Tree ID #72

Tree Details

Latin Name:	Araucaria heterophylla
Common Name:	Norfolk Island Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	35.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.39
Tree Protection Zone (TPZ) [m]:	4.3
Structural Root Zone (SRZ) [m]:	2.23
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918871
Latitude:	-31.991334

Photos Street View Map View



Showy honey myrtle Tree ID #73

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	15.33
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918634
Latitude:	-31.991051

Photos Street View Map View



WA Peppermint Tree ID #74

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	69.2
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.894
Tree Protection Zone (TPZ) [m]:	8.3
Structural Root Zone (SRZ) [m]:	3.16
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918666
Latitude:	-31.991192

Photos Street View Map View



WA Peppermint Tree ID #75

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	37.43
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.845
Tree Protection Zone (TPZ) [m]:	4.49
Structural Root Zone (SRZ) [m]:	3.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918627
Latitude:	-31.991146

Photos Street View Map View



WA Peppermint Tree ID #76

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918594
Latitude:	-31.991090

Photos Street View Map View



Grass Tree Tree ID #77

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918659
Latitude:	-31.991139

Photos Street View Map View



Grass Tree Tree ID #78

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918619
Latitude:	-31.991103

Photos Street View Map View



Grass Tree Tree ID #79

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918621
Latitude:	-31.991087

Photos Street View Map View



Grass Tree Tree ID #80

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918611
Latitude:	-31.991079

Photos Street View Map View



Grass Tree Tree ID #81

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918595
Latitude:	-31.991058

Photos Street View Map View



Grass Tree Tree ID #82

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918590
Latitude:	-31.991049

Photos Street View Map View



Grass Tree Tree ID #83

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918577
Latitude:	-31.991061

Photos Street View Map View



Grass Tree Tree ID #84

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918593
Latitude:	-31.991043

Photos Street View Map View



Grass Tree Tree ID #85

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918544
Latitude:	-31.991038

Photos Street View Map View



Grass Tree Tree ID #86

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918536
Latitude:	-31.991030

Photos Street View Map View



Grass Tree Tree ID #87

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918524
Latitude:	-31.991020

Photos Street View Map View



Grass Tree Tree ID #88

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918507
Latitude:	-31.991021

Photos Street View Map View



Grass Tree Tree ID #89

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918508
Latitude:	-31.991008

Photos Street View Map View



Grass Tree Tree ID #90

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918519
Latitude:	-31.991014

Photos Street View Map View



Grass Tree Tree ID #91

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918512
Latitude:	-31.991004

Photos Street View Map View



Grass Tree Tree ID #92

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918412
Latitude:	-31.990885

Photos Street View Map View



Norfolk Island Pine Tree ID #93

Tree Details

Latin Name:	Araucaria heterophylla
Common Name:	Norfolk Island Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	0
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	1.218
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	3.6
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918651
Latitude:	-31.991074

Photos Street View Map View



Weeping Bottlebrush Tree ID #94

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Poor
Structure:	Very Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	0
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	1.218
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	3.6
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline and is recommended for removal
Foraging species:	No

Tree Location

Longitude:	115.918577
Latitude:	-31.990989

Photos Street View Map View



Weeping Paperbark Tree ID #95

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	20.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2.46
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918507
Latitude:	-31.990912

Photos Street View Map View



Showy honey myrtle Tree ID #96

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	11.05
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918476
Latitude:	-31.990860

Photos Street View Map View



Weeping Paperbark Tree ID #97

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	2
DBH [cm]:	17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918460
Latitude:	-31.990841

Photos Street View Map View



Cook Pine Tree ID #98

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	3
DBH [cm]:	0.43
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basal shoots and uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918418
Latitude:	-31.990798

Photos Street View Map View



Showy honey myrtle Tree ID #99

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	18.17
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.18
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918405
Latitude:	-31.990762

Photos Street View Map View



Weeping Paperbark Tree ID #100

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	16.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918387
Latitude:	-31.990743

Photos Street View Map View



Tree Summary Report

September 27, 2022 |
Total Tree Count: 50

Filters Applied

Tree Filter:
Tree Id>=101 and Tree Id<=1685
Client Site Filter:
(Client Site=ALUA - Part D)

Showy honey myrtle Tree ID #101

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	10.68
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918372
Latitude:	-31.990721

Photos Street View Map View



Weeping Bottlebrush Tree ID #102

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	30.01
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	3.6
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	1-5 years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal is recommended due to its poor condition
Foraging species:	No

Tree Location

Longitude:	115.918323
Latitude:	-31.990658

Photos Street View Map View



Weeping Paperbark Tree ID #103

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	17.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	23.5
Tree Protection Zone (TPZ) [m]:	2.1
Structural Root Zone (SRZ) [m]:	12.46
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918358
Latitude:	-31.990697

Photos Street View Map View



Grass Tree Tree ID #104

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918402
Latitude:	-31.990869

Photos Street View Map View



Grass Tree Tree ID #105

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918210
Latitude:	-31.990595

Photos Street View Map View



Grass Tree Tree ID #106

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918189
Latitude:	-31.990592

Photos Street View Map View



Grass Tree Tree ID #107

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918178
Latitude:	-31.990582

Photos Street View Map View



Grass Tree Tree ID #108

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918152
Latitude:	-31.990511

Photos Street View Map View



Grass Tree Tree ID #109

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918111
Latitude:	-31.990468

Photos Street View Map View



Grass Tree Tree ID #110

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918104
Latitude:	-31.990457

Photos Street View Map View



Grass Tree Tree ID #111

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918083
Latitude:	-31.990456

Photos Street View Map View



Grass Tree Tree ID #112

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918064
Latitude:	-31.990402

Photos Street View Map View



WA Peppermint Tree ID #113

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	32.72
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.442
Tree Protection Zone (TPZ) [m]:	3.93
Structural Root Zone (SRZ) [m]:	2.35
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918111
Latitude:	-31.990555

Photos Street View Map View



WA Peppermint Tree ID #114

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	40.02
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918086
Latitude:	-31.990539

Photos Street View Map View



WA Peppermint Tree ID #115

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	9
DBH [cm]:	50.47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	6.06
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918075
Latitude:	-31.990503

Photos Street View Map View



Cook Pine Tree ID #116

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	3
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918219
Latitude:	-31.990519

Photos Street View Map View



Showy honey myrtle Tree ID #117

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	18.14
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.18
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918118
Latitude:	-31.990387

Photos Street View Map View



Weeping Paperbark Tree ID #118

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	1
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.09
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918085
Latitude:	-31.990344

Photos Street View Map View



Showy honey myrtle Tree ID #119

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	1
DBH [cm]:	10.74
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918052
Latitude:	-31.990289

Photos Street View Map View



WA Peppermint Tree ID #120

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	1
DBH [cm]:	60.01
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.845
Tree Protection Zone (TPZ) [m]:	7.2
Structural Root Zone (SRZ) [m]:	3.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917961
Latitude:	-31.990322

Photos Street View Map View



Cook Pine Tree ID #121

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	3
DBH [cm]:	49.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	5.9
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918009
Latitude:	-31.990226

Photos Street View Map View



Showy honey myrtle Tree ID #122

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	14.66
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917976
Latitude:	-31.990173

Photos Street View Map View



Weeping Paperbark Tree ID #123

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	21.63
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.6
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917961
Latitude:	-31.990149

Photos Street View Map View



Weeping Paperbark Tree ID #124

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.224
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.77
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917903
Latitude:	-31.990040

Photos Street View Map View



WA Peppermint Tree ID #125

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	1
DBH [cm]:	36.2
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	4.34
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917812
Latitude:	-31.990086

Photos Street View Map View



WA Peppermint Tree ID #126

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	1
DBH [cm]:	59.57
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1.1
Tree Protection Zone (TPZ) [m]:	7.15
Structural Root Zone (SRZ) [m]:	3.44
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917722
Latitude:	-31.989983

Photos Street View Map View



WA Peppermint Tree ID #127

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	50.35
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.94
Tree Protection Zone (TPZ) [m]:	6.04
Structural Root Zone (SRZ) [m]:	3.22
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917684
Latitude:	-31.989925

Photos Street View Map View



Showy honey myrtle Tree ID #128

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	12.61
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917876
Latitude:	-31.990013

Photos Street View Map View



Weeping Paperbark Tree ID #129

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	12.65
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917869
Latitude:	-31.989985

Photos Street View Map View



Cook Pine Tree ID #130

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	11
DBH [cm]:	62
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.64
Tree Protection Zone (TPZ) [m]:	7.44
Structural Root Zone (SRZ) [m]:	2.74
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917845
Latitude:	-31.989943

Photos Street View Map View



Showy honey myrtle Tree ID #131

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	15.56
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917827
Latitude:	-31.989905

Photos Street View Map View



Showy honey myrtle Tree ID #132

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	14.66
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917796
Latitude:	-31.989850

Photos Street View Map View



Weeping Paperbark Tree ID #133

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	16.97
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.258
Tree Protection Zone (TPZ) [m]:	2.04
Structural Root Zone (SRZ) [m]:	1.87
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917770
Latitude:	-31.989807

Photos Street View Map View



Showy honey myrtle Tree ID #134

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	7.35
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917755
Latitude:	-31.989766

Photos Street View Map View



Weeping Paperbark Tree ID #135

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	3.36
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917730
Latitude:	-31.989744

Photos Street View Map View



Showy honey myrtle Tree ID #136

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	12.29
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917712
Latitude:	-31.989698

Photos Street View Map View



Cook Pine Tree ID #137

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	9
DBH [cm]:	69
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.72
Tree Protection Zone (TPZ) [m]:	8.28
Structural Root Zone (SRZ) [m]:	2.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917675
Latitude:	-31.989643

Photos Street View Map View



WA Peppermint Tree ID #138

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	41.92
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.3628
Tree Protection Zone (TPZ) [m]:	5.03
Structural Root Zone (SRZ) [m]:	2.16
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917633
Latitude:	-31.989756

Photos Street View Map View



WA Peppermint Tree ID #139

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	57.84
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.94
Tree Protection Zone (TPZ) [m]:	6.94
Structural Root Zone (SRZ) [m]:	3.22
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917591
Latitude:	-31.989715

Photos Street View Map View



WA Peppermint Tree ID #140

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	62
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.675
Tree Protection Zone (TPZ) [m]:	7.44
Structural Root Zone (SRZ) [m]:	2.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917560
Latitude:	-31.989623

Photos Street View Map View



Zamia Tree ID #141

Tree Details

Latin Name:	Macrozamia riedlei
Common Name:	Zamia
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove dead fronds
Foraging species:	No

Tree Location

Longitude:	115.917626
Latitude:	-31.989700

Photos Street View Map View



Geraldton Wax Tree ID #142

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.917547
Latitude:	-31.989561

Photos Street View Map View



Geraldton Wax Tree ID #143


Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.917512
Latitude:	-31.989496

Photos Street View Map View



Geraldton Wax Tree ID #144

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.917478
Latitude:	-31.989435

Photos Street View Map View



WA Peppermint Tree ID #145

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	5692
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.82
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	3.04
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917371
Latitude:	-31.989312

Photos Street View Map View



Weeping Paperbark Tree ID #146

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.405
Tree Protection Zone (TPZ) [m]:	3.84
Structural Root Zone (SRZ) [m]:	2.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917632
Latitude:	-31.989578

Photos Street View Map View



Weeping Paperbark Tree ID #147

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.84
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917575
Latitude:	-31.989487

Photos Street View Map View



Weeping Paperbark Tree ID #148

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	13.61
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917544
Latitude:	-31.989413

Photos Street View Map View



Weeping Paperbark Tree ID #149

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	14.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level. Some photopic influence is evident due to the pine, but it is otherwise ook
Foraging species:	No

Tree Location

Longitude:	115.917516
Latitude:	-31.989382

Photos Street View Map View



Cook Pine Tree ID #150

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	62.4
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	7.49
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917518
Latitude:	-31.989339

Photos Street View Map View



Showy honey myrtle Tree ID #151

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Has Failed
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	20.59
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.47
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree has had a main leader fail and the rail side of its trunk removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.917487
Latitude:	-31.989295

Photos Street View Map View



Weeping Paperbark Tree ID #152

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	22
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.255
Tree Protection Zone (TPZ) [m]:	2.64
Structural Root Zone (SRZ) [m]:	1.86
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917458
Latitude:	-31.989262

Photos Street View Map View



Grass Tree Tree ID #153

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917438
Latitude:	-31.989321

Photos Street View Map View



Grass Tree Tree ID #154

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917366
Latitude:	-31.989197

Photos Street View Map View



Grass Tree Tree ID #155

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917367
Latitude:	-31.989184

Photos Street View Map View



Grass Tree Tree ID #156

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917350
Latitude:	-31.989190

Photos Street View Map View



Grass Tree Tree ID #157

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917344
Latitude:	-31.989141

Photos Street View Map View



Grass Tree Tree ID #158

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917324
Latitude:	-31.989124

Photos Street View Map View



Grass Tree Tree ID #159

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917308
Latitude:	-31.989131

Photos Street View Map View



Weeping Bottlebrush Tree ID #160

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	23
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.32
Tree Protection Zone (TPZ) [m]:	2.76
Structural Root Zone (SRZ) [m]:	2.05
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917403
Latitude:	-31.989146

Photos Street View Map View



Grass Tree Tree ID #161

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917320
Latitude:	-31.989153

Photos Street View Map View



Showy honey myrtle Tree ID #162

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	12.73
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917389
Latitude:	-31.989120

Photos Street View Map View



Cook Pine Tree ID #163

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	81
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	834
Tree Protection Zone (TPZ) [m]:	9.72
Structural Root Zone (SRZ) [m]:	55.8
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917347
Latitude:	-31.989053

Photos Street View Map View



Weeping Paperbark Tree ID #164

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917303
Latitude:	-31.988979

Photos Street View Map View



Weeping Bottlebrush Tree ID #165

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	27.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.305
Tree Protection Zone (TPZ) [m]:	3.26
Structural Root Zone (SRZ) [m]:	2.01
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917256
Latitude:	-31.988909

Photos Street View Map View



Showy honey myrtle Tree ID #166

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	9.64
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917253
Latitude:	-31.988877

Photos Street View Map View



Weeping Bottlebrush Tree ID #167

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	11.14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.154
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917238
Latitude:	-31.988856

Photos Street View Map View



Grass Tree Tree ID #168

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917209
Latitude:	-31.988892

Photos Street View Map View



WA Peppermint Tree ID #169

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	276.52
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.548
Tree Protection Zone (TPZ) [m]:	15
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917186
Latitude:	-31.988867

Photos Street View Map View



WA Peppermint Tree ID #170

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	44.76
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	5.37
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917141
Latitude:	-31.988867

Photos Street View Map View



WA Peppermint Tree ID #171

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	26.72
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.43
Tree Protection Zone (TPZ) [m]:	3.21
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917127
Latitude:	-31.988838

Photos Street View Map View



Grass Tree Tree ID #172

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917116
Latitude:	-31.988859

Photos Street View Map View



Grass Tree Tree ID #173

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917126
Latitude:	-31.988812

Photos Street View Map View



Grass Tree Tree ID #174

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917119
Latitude:	-31.988798

Photos Street View Map View



Grass Tree Tree ID #175

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917120
Latitude:	-31.988790

Photos Street View Map View



Grass Tree Tree ID #176

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917122
Latitude:	-31.988783

Photos Street View Map View



Grass Tree Tree ID #177

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917112
Latitude:	-31.988790

Photos Street View Map View



Grass Tree Tree ID #178

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	
Canopy Spread [m]:	2
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917111
Latitude:	-31.988776

Photos Street View Map View



WA Peppermint Tree ID #179

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	40
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.653
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.77
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917092
Latitude:	-31.988815

Photos Street View Map View



WA Peppermint Tree ID #180

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	37
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.758
Tree Protection Zone (TPZ) [m]:	4.44
Structural Root Zone (SRZ) [m]:	2.95
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917050
Latitude:	-31.988771

Photos Street View Map View



WA Peppermint Tree ID #181

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	47.33
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.665
Tree Protection Zone (TPZ) [m]:	5.68
Structural Root Zone (SRZ) [m]:	2.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917063
Latitude:	-31.988712

Photos Street View Map View



WA Peppermint Tree ID #182

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	34.69
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	4.16
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917014
Latitude:	-31.988697

Photos Street View Map View



WA Peppermint Tree ID #183

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	24.08
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.422
Tree Protection Zone (TPZ) [m]:	2.89
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917032
Latitude:	-31.988648

Photos Street View Map View



WA Peppermint Tree ID #184

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	66.44
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.137
Tree Protection Zone (TPZ) [m]:	7.97
Structural Root Zone (SRZ) [m]:	1.44
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916994
Latitude:	-31.988618

Photos Street View Map View



Grass Tree Tree ID #185

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917100
Latitude:	-31.988786

Photos Street View Map View



Grass Tree Tree ID #186

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	
DBH Range:	N/A
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917064
Latitude:	-31.988727

Photos Street View Map View



Grass Tree Tree ID #187

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917026
Latitude:	-31.988738

Photos Street View Map View



Grass Tree Tree ID #188

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917080
Latitude:	-31.988691

Photos Street View Map View



Weeping Bottlebrush Tree ID #189

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	12.1
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917208
Latitude:	-31.988813

Photos Street View Map View



Cook Pine Tree ID #190

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917189
Latitude:	-31.988755

Photos Street View Map View



Showy honey myrtle Tree ID #191

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917159
Latitude:	-31.988703

Photos Street View Map View



Showy honey myrtle Tree ID #192

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	10.05
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917132
Latitude:	-31.988648

Photos Street View Map View



Grass Tree Tree ID #193

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917055
Latitude:	-31.988619

Photos Street View Map View



Weeping Bottlebrush Tree ID #194

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	26.78
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.385
Tree Protection Zone (TPZ) [m]:	3.21
Structural Root Zone (SRZ) [m]:	2.22
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917099
Latitude:	-31.988599

Photos Street View Map View



Weeping Bottlebrush Tree ID #195

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	18.82
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.26
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917071
Latitude:	-31.988558

Photos Street View Map View



Showy honey myrtle Tree ID #196

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	20.35
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.44
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917037
Latitude:	-31.988484

Photos Street View Map View



Weeping Paperbark Tree ID #197

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	2
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917023
Latitude:	-31.988474

Photos Street View Map View



Cook Pine Tree ID #198

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	11
DBH [cm]:	55
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	6.6
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.917002
Latitude:	-31.988446

Photos Street View Map View



Showy honey myrtle Tree ID #199

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	19.54
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2.34
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916977
Latitude:	-31.988409

Photos Street View Map View



Weeping Paperbark Tree ID #200

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916952
Latitude:	-31.988369

Photos Street View Map View



Showy honey myrtle Tree ID #201

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	16.88
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.03
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.916931
Latitude:	-31.988325

Photos Street View Map View



Showy honey myrtle Tree ID #202

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	8.89
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916899
Latitude:	-31.988246

Photos Street View Map View



Grass Tree Tree ID #203

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916771
Latitude:	-31.988195

Photos Street View Map View



WA Peppermint Tree ID #204

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	7
DBH [cm]:	42.66
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	5.12
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This is a poor specimen removal is recommended stump grinding Sydney very silly so it does not disturb the roots of the adjacent cook pine
Foraging species:	No

Tree Location

Longitude:	115.916867
Latitude:	-31.988190

Photos Street View Map View



WA Peppermint Tree ID #205

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	7
DBH [cm]:	75
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	9
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916855
Latitude:	-31.988161

Photos Street View Map View



Showy honey myrtle Tree ID #206

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	16.71
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.01
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916813
Latitude:	-31.988111

Photos Street View Map View



Showy honey myrtle Tree ID #207

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	15.72
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916776
Latitude:	-31.988033

Photos Street View Map View



Grass Tree Tree ID #208

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918031
Latitude:	-31.990355

Photos Street View Map View



Grass Tree Tree ID #209

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.918027
Latitude:	-31.990331

Photos Street View Map View



Grass Tree Tree ID #210

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917785
Latitude:	-31.989955

Photos Street View Map View



WA Peppermint Tree ID #211

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	11
DBH [cm]:	82.13
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.95
Tree Protection Zone (TPZ) [m]:	9.86
Structural Root Zone (SRZ) [m]:	3.24
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.917765
Latitude:	-31.989903

Photos Street View Map View



Grass Tree Tree ID #212

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917603
Latitude:	-31.989795

Photos Street View Map View



Grass Tree Tree ID #213

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917407
Latitude:	-31.989470

Photos Street View Map View



Geraldton Wax Tree ID #214

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.917285
Latitude:	-31.989074

Photos Street View Map View



Grass Tree Tree ID #215

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917244
Latitude:	-31.989037

Photos Street View Map View



Grass Tree Tree ID #216

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917281
Latitude:	-31.989042

Photos Street View Map View



Grass Tree Tree ID #217

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917269
Latitude:	-31.989027

Photos Street View Map View



Grass Tree Tree ID #218

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917273
Latitude:	-31.989018

Photos Street View Map View



Grass Tree Tree ID #219

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917260
Latitude:	-31.989013

Photos Street View Map View



Grass Tree Tree ID #220

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917246
Latitude:	-31.989021

Photos Street View Map View



Grass Tree Tree ID #221

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917261
Latitude:	-31.988996

Photos Street View Map View



Grass Tree Tree ID #222

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917233
Latitude:	-31.988984

Photos Street View Map View



Grass Tree Tree ID #223

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917241
Latitude:	-31.988966

Photos Street View Map View



Grass Tree Tree ID #224

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917217
Latitude:	-31.988969

Photos Street View Map View



Grass Tree Tree ID #225

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917229
Latitude:	-31.988956

Photos Street View Map View



Grass Tree Tree ID #226

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917097
Latitude:	-31.988775

Photos Street View Map View



Grass Tree Tree ID #227

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917042
Latitude:	-31.988615

Photos Street View Map View



Grass Tree Tree ID #228

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917029
Latitude:	-31.988609

Photos Street View Map View



Grass Tree Tree ID #229

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917017
Latitude:	-31.988608

Photos Street View Map View



Grass Tree Tree ID #230

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917026
Latitude:	-31.988601

Photos Street View Map View



Grass Tree Tree ID #231

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917024
Latitude:	-31.988591

Photos Street View Map View



Grass Tree Tree ID #232

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917025
Latitude:	-31.988582

Photos Street View Map View



Grass Tree Tree ID #233

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.917005
Latitude:	-31.988587

Photos Street View Map View



Grass Tree Tree ID #234

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916993
Latitude:	-31.988533

Photos Street View Map View



Grass Tree Tree ID #235

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916990
Latitude:	-31.988527

Photos Street View Map View



Grass Tree Tree ID #236

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916986
Latitude:	-31.988521

Photos Street View Map View



Grass Tree Tree ID #237

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916982
Latitude:	-31.988514

Photos Street View Map View



Grass Tree Tree ID #238

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916978
Latitude:	-31.988499

Photos Street View Map View



Grass Tree Tree ID #239

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916964
Latitude:	-31.988503

Photos Street View Map View



Grass Tree Tree ID #240

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916964
Latitude:	-31.988511

Photos Street View Map View



Grass Tree Tree ID #241

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916963
Latitude:	-31.988525

Photos Street View Map View



Grass Tree Tree ID #242

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916908
Latitude:	-31.988567

Photos Street View Map View



Grass Tree Tree ID #243

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916827
Latitude:	-31.988370



Grass Tree Tree ID #244

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916809
Latitude:	-31.988359

Photos Street View Map View



Grass Tree Tree ID #245

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916828
Latitude:	-31.988352

Photos Street View Map View



Grass Tree Tree ID #246

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916800
Latitude:	-31.988343

Photos Street View Map View



Grass Tree Tree ID #247

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916808
Latitude:	-31.988329

Photos Street View Map View



Grass Tree Tree ID #248

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916781
Latitude:	-31.988317

Photos Street View Map View



Grass Tree Tree ID #249

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	1
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916786
Latitude:	-31.988335

Photos Street View Map View



Grass Tree Tree ID #250

Tree Details

Latin Name:	Xanthorrhoea. Sp
Common Name:	Grass Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.916802
Latitude:	-31.988297

Photos Street View Map View



Geraldton Wax Tree ID #251

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	6
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.916789
Latitude:	-31.988290

Photos Street View Map View



Grevillea sp Tree ID #252

Tree Details

Latin Name:	Grevillea sp
Common Name:	Grevillea sp
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	6
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Landscape species
Foraging species:	No

Tree Location

Longitude:	115.915716
Latitude:	-31.986276

Photos Street View Map View



WA Peppermint Tree ID #253

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	35.36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.472
Tree Protection Zone (TPZ) [m]:	4.24
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915612
Latitude:	-31.986144

Photos Street View Map View



WA Peppermint Tree ID #254

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	80
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.71
Tree Protection Zone (TPZ) [m]:	9.6
Structural Root Zone (SRZ) [m]:	2.87
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915601
Latitude:	-31.986101

Photos Street View Map View



WA Peppermint Tree ID #255

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	61.77
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.13
Tree Protection Zone (TPZ) [m]:	7.41
Structural Root Zone (SRZ) [m]:	3.48
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915515
Latitude:	-31.985953

Photos Street View Map View



Costal Mort Tree ID #256

Tree Details

Latin Name:	Eucalyptus utilis
Common Name:	Costal Mort
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	31
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.61
Tree Protection Zone (TPZ) [m]:	3.72
Structural Root Zone (SRZ) [m]:	2.69
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915418
Latitude:	-31.985752

Photos Street View Map View



WA Peppermint Tree ID #257

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	43.53
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	1.13
Tree Protection Zone (TPZ) [m]:	5.22
Structural Root Zone (SRZ) [m]:	3.48
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915273
Latitude:	-31.985555

Photos Street View Map View



WA Peppermint Tree ID #258

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	60.92
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	7.31
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915242
Latitude:	-31.985490



WA Peppermint Tree ID #259

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	33.3
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	4
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915212
Latitude:	-31.985400

Photos Street View Map View



WA Peppermint Tree ID #260

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	70
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.06
Tree Protection Zone (TPZ) [m]:	8.4
Structural Root Zone (SRZ) [m]:	3.39
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915157
Latitude:	-31.985337

Photos Street View Map View



Geraldton Wax Tree ID #261

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	6
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.915150
Latitude:	-31.985250

Photos Street View Map View



WA Peppermint Tree ID #262

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	33.65
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.04
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914581
Latitude:	-31.984446

Photos Street View Map View



WA Peppermint Tree ID #263

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	55.14
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	1.05
Tree Protection Zone (TPZ) [m]:	6.62
Structural Root Zone (SRZ) [m]:	3.38
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914555
Latitude:	-31.984386

Photos Street View Map View



WA Peppermint Tree ID #264

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	39
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.68
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914003
Latitude:	-31.983719

Photos Street View Map View



Geraldton Wax Tree ID #265

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	5
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913901
Latitude:	-31.983639

Photos Street View Map View



On Sided Bottlebrush Tree ID #266

Tree Details

Latin Name:	Calothamnus quadrifidus
Common Name:	On Sided Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	5
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.913863
Latitude:	-31.983564

Photos Street View Map View



On Sided Bottlebrush Tree ID #267

Tree Details

Latin Name:	Calothamnus quadrifidus
Common Name:	On Sided Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	5
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.913841
Latitude:	-31.983552

Photos Street View Map View



Geraldton Wax Tree ID #268

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	5
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913825
Latitude:	-31.983476

Photos Street View Map View



On Sided Bottlebrush Tree ID #269

Tree Details

Latin Name:	Calothamnus quadrifidus
Common Name:	On Sided Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	8
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.1
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.26
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.913751
Latitude:	-31.983441

Photos Street View Map View



Coastal Tea Tree Tree ID #270

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913716
Latitude:	-31.983400

Photos Street View Map View



Coastal Tea Tree Tree ID #271

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	15
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913627
Latitude:	-31.983302

Photos Street View Map View



On Sided Bottlebrush Tree ID #272

Tree Details

Latin Name:	Calothamnus quadrifidus
Common Name:	On Sided Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	5
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.913597
Latitude:	-31.983271

Photos Street View Map View



Geraldton Wax Tree ID #273

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913516
Latitude:	-31.983183

Photos Street View Map View



Geraldton Wax Tree ID #274

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913348
Latitude:	-31.983005

Photos Street View Map View



Geraldton Wax Tree ID #275

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913194
Latitude:	-31.982835

Photos Street View Map View



Geraldton Wax Tree ID #276

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	1
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.913070
Latitude:	-31.982722

Photos Street View Map View



Geraldton Wax Tree ID #277

Tree Details

Latin Name:	Chamelaucium uncinatum
Common Name:	Geraldton Wax
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	10
DBH [cm]:	2
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Weed species
Foraging species:	No

Tree Location

Longitude:	115.912822
Latitude:	-31.982472

Photos Street View Map View



WA Peppermint Tree ID #278

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	71
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	8.52
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912948
Latitude:	-31.982539

Photos Street View Map View



WA Peppermint Tree ID #279

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	38.04
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.89
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	3.15
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.912744
Latitude:	-31.982310

Photos Street View Map View



WA Peppermint Tree ID #280

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Poor
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	31.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	45.5
Tree Protection Zone (TPZ) [m]:	3.82
Structural Root Zone (SRZ) [m]:	16.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline, removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.908981
Latitude:	-31.978420

Photos Street View Map View



WA Peppermint Tree ID #281

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	29.62
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.56
Tree Protection Zone (TPZ) [m]:	3.55
Structural Root Zone (SRZ) [m]:	2.59
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree is in decline, removal is recommended
Foraging species:	No

Tree Location

Longitude:	115.908835
Latitude:	-31.978296

Photos Street View Map View



WA Peppermint Tree ID #282

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	10.8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.908812
Latitude:	-31.978273

Photos Street View Map View



WA Peppermint Tree ID #283

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	28.9
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.42
Tree Protection Zone (TPZ) [m]:	3.47
Structural Root Zone (SRZ) [m]:	2.3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.908763
Latitude:	-31.978225

Photos Street View Map View



Coastal Tea Tree Tree ID #284

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	10
DBH [cm]:	17.66
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.12
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Invasive species- Recommendation to remove - multiple trees
Foraging species:	No

Tree Location

Longitude:	115.920139
Latitude:	-31.992413

Photos Street View Map View



Weeping Paperbark Tree ID #285

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.16
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.919016
Latitude:	-31.991476

Photos Street View Map View



WA Peppermint Tree ID #286

Tree Details

Latin Name:	Agonis flexuosa
Common Name:	WA Peppermint
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	49.69
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	5.96
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.918949
Latitude:	-31.991409

Photos Street View Map View



Showy honey myrtle Tree ID #287

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	16.73
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.26
Tree Protection Zone (TPZ) [m]:	2.01
Structural Root Zone (SRZ) [m]:	1.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916732
Latitude:	-31.987961

Photos Street View Map View



Showy honey myrtle Tree ID #288

Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	4
DBH [cm]:	21.63
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	2.6
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916697
Latitude:	-31.987914

Photos Street View Map View



Weeping Bottlebrush Tree ID #289

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	4.9
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.28
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.94
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916677
Latitude:	-31.987881

Photos Street View Map View



Showy honey myrtle Tree ID #290


Tree Details

Latin Name:	Melaleuca nesophila
Common Name:	Showy honey myrtle
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	19.13
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.3
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.916660
Latitude:	-31.987859

Photos Street View Map View



Marri Tree ID #291

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	13
DBH [cm]:	64.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.76
Tree Protection Zone (TPZ) [m]:	7.74
Structural Root Zone (SRZ) [m]:	2.95
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	High
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.916137
Latitude:	-31.986999

Photos Street View Map View



Marri Tree ID #292

Tree Details

Latin Name:	Corymbia calophylla
Common Name:	Marri
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	10
DBH [cm]:	39.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	4.78
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Native
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	Yes

Tree Location

Longitude:	115.916060
Latitude:	-31.986787

Photos Street View Map View



River Red Gum Tree ID #293

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	12
DBH [cm]:	52.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.76
Tree Protection Zone (TPZ) [m]:	6.3
Structural Root Zone (SRZ) [m]:	2.95
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915926
Latitude:	-31.986685

Photos Street View Map View



River Red Gum Tree ID #294

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	35.8
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	4.3
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.916004
Latitude:	-31.986658

Photos Street View Map View



River Red Gum Tree ID #295

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	15
DBH [cm]:	49.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.63
Tree Protection Zone (TPZ) [m]:	5.94
Structural Root Zone (SRZ) [m]:	2.73
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915921
Latitude:	-31.986579

Photos Street View Map View



Cook Pine Tree ID #296

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	11
DBH [cm]:	59.8
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.705
Tree Protection Zone (TPZ) [m]:	7.18
Structural Root Zone (SRZ) [m]:	2.86
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915881
Latitude:	-31.986458

Photos Street View Map View



River Red Gum Tree ID #297

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	5
DBH [cm]:	19.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.275
Tree Protection Zone (TPZ) [m]:	2.3
Structural Root Zone (SRZ) [m]:	1.92
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915847
Latitude:	-31.986459

Photos Street View Map View



River Red Gum Tree ID #298

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	6
DBH [cm]:	27.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.36
Tree Protection Zone (TPZ) [m]:	3.26
Structural Root Zone (SRZ) [m]:	2.15
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915803
Latitude:	-31.986454

Photos Street View Map View



River Red Gum Tree ID #299

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	15
DBH [cm]:	74
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.86
Tree Protection Zone (TPZ) [m]:	8.88
Structural Root Zone (SRZ) [m]:	3.11
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915773
Latitude:	-31.986443

Photos Street View Map View



Weeping Red Paperbark Tree ID #300

Tree Details

Latin Name:	Melaleuca viridiflora
Common Name:	Weeping Red Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	3
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915745
Latitude:	-31.986427

Photos Street View Map View



Weeping Red Paperbark Tree ID #301

Tree Details

Latin Name:	Melaleuca viridiflora
Common Name:	Weeping Red Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	21
Canopy Spread [m]:	14
DBH [cm]:	35.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.43
Tree Protection Zone (TPZ) [m]:	4.26
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915730
Latitude:	-31.986411

Photos Street View Map View



Weeping Red Paperbark Tree ID #302

Tree Details

Latin Name:	Melaleuca viridiflora
Common Name:	Weeping Red Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	21
Canopy Spread [m]:	13
DBH [cm]:	57.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.77
Tree Protection Zone (TPZ) [m]:	6.86
Structural Root Zone (SRZ) [m]:	2.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915712
Latitude:	-31.986388

Photos Street View Map View



River Red Gum Tree ID #303

Tree Details

Latin Name:	Eucalyptus camaldulensis
Common Name:	River Red Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	12
DBH [cm]:	62.6
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.775
Tree Protection Zone (TPZ) [m]:	7.51
Structural Root Zone (SRZ) [m]:	2.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915670
Latitude:	-31.986336

Photos Street View Map View



Eurabbie Tree ID #304

Tree Details

Latin Name:	Eucalyptus bicostata
Common Name:	Eurabbie
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	12
DBH [cm]:	61.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	7.38
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove all Deadwood over 25mm in diameter
Foraging species:	No

Tree Location

Longitude:	115.915773
Latitude:	-31.986378

Photos Street View Map View



Weeping Red Paperbark Tree ID #305

Tree Details

Latin Name:	Melaleuca viridiflora
Common Name:	Weeping Red Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	7
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.11
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.31
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915669
Latitude:	-31.986361

Photos Street View Map View



Broad-leaved Paperbark Tree ID #306

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	10
DBH [cm]:	53.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.54
Tree Protection Zone (TPZ) [m]:	6.38
Structural Root Zone (SRZ) [m]:	2.55
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove stubs on lower portion of trunk
Foraging species:	No

Tree Location

Longitude:	115.915821
Latitude:	-31.986355

Photos Street View Map View



Cook Pine Tree ID #307

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	5
DBH [cm]:	49.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	5.94
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915730
Latitude:	-31.986171

Photos Street View Map View



Broad-leaved Paperbark Tree ID #308

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.59
Tree Protection Zone (TPZ) [m]:	6.48
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915658
Latitude:	-31.986009

Photos Street View Map View



Cook Pine Tree ID #309

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	9
DBH [cm]:	58
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	6.96
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915561
Latitude:	-31.985840

Photos Street View Map View



Lemon-scented Gum Tree ID #310

Tree Details

Latin Name:	Corymbia citriodora
Common Name:	Lemon-scented Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	23
Canopy Spread [m]:	19
DBH [cm]:	64.4
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.88
Tree Protection Zone (TPZ) [m]:	7.73
Structural Root Zone (SRZ) [m]:	3.14
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915521
Latitude:	-31.985785

Photos Street View Map View



Broad-leaved Paperbark Tree ID #311

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	8
DBH [cm]:	50.6
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	6.07
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915494
Latitude:	-31.985746

Photos Street View Map View



Lemon-scented Gum Tree ID #312

Tree Details

Latin Name:	Corymbia citriodora
Common Name:	Lemon-scented Gum
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	21
Canopy Spread [m]:	18
DBH [cm]:	77.5
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1
Tree Protection Zone (TPZ) [m]:	9.3
Structural Root Zone (SRZ) [m]:	3.31
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.915436
Latitude:	-31.985675

Photos Street View Map View



Acacia Tree ID #313

Tree Details

Latin Name:	Acacia saligna
Common Name:	Acacia
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal recommended due to short lifespan of this species
Foraging species:	No

Tree Location

Longitude:	115.915420
Latitude:	-31.985624

Photos Street View Map View



Acacia Tree ID #314

Tree Details

Latin Name:	Acacia saligna
Common Name:	Acacia
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	13.3
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal recommended due to short lifespan of this species
Foraging species:	No

Tree Location

Longitude:	115.915405
Latitude:	-31.985611

Photos Street View Map View



Cook Pine Tree ID #315

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	8
DBH [cm]:	54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.588
Tree Protection Zone (TPZ) [m]:	6.48
Structural Root Zone (SRZ) [m]:	2.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove basil shoots and uplift to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915188
Latitude:	-31.985238

Photos Street View Map View



Dryland Tea-tree Tree ID #316

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.29
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915151
Latitude:	-31.985173

Photos Street View Map View



Broad-leaved Paperbark Tree ID #317

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	9
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.93
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	3.21
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915061
Latitude:	-31.984979

Photos Street View Map View



Cook Pine Tree ID #318

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	10
DBH [cm]:	55.6
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.917
Tree Protection Zone (TPZ) [m]:	6.67
Structural Root Zone (SRZ) [m]:	3.19
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.915022
Latitude:	-31.984938

Photos Street View Map View



Weeping Paperbark Tree ID #319

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	32.59
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.435
Tree Protection Zone (TPZ) [m]:	3.91
Structural Root Zone (SRZ) [m]:	2.33
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914996
Latitude:	-31.984905

Photos Street View Map View



Queensland Box Tree ID #320

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	16.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.186
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.914972
Latitude:	-31.984866

Photos Street View Map View



Broad-leaved Paperbark Tree ID #321

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	10
DBH [cm]:	62
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.76
Tree Protection Zone (TPZ) [m]:	7.44
Structural Root Zone (SRZ) [m]:	2.95
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level required
Foraging species:	No

Tree Location

Longitude:	115.914930
Latitude:	-31.984788

Photos Street View Map View



Weeping Paperbark Tree ID #322

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	12
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level required
Foraging species:	No

Tree Location

Longitude:	115.914894
Latitude:	-31.984728

Photos Street View Map View



Broad-leaved Paperbark Tree ID #323

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	10
DBH [cm]:	55.14
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.91
Tree Protection Zone (TPZ) [m]:	6.62
Structural Root Zone (SRZ) [m]:	3.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level required
Foraging species:	No

Tree Location

Longitude:	115.914879
Latitude:	-31.984702

Photos Street View Map View



Broad-leaved Paperbark Tree ID #324

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	12
DBH [cm]:	63.2
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.805
Tree Protection Zone (TPZ) [m]:	7.58
Structural Root Zone (SRZ) [m]:	3.02
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplifting required to provide 2m clearance above ground level required
Foraging species:	No

Tree Location

Longitude:	115.914826
Latitude:	-31.984641

Photos Street View Map View



Weeping Paperbark Tree ID #325

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	25.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.06
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level required
Foraging species:	No

Tree Location

Longitude:	115.914805
Latitude:	-31.984590

Photos Street View Map View



Dryland Tea-tree Tree ID #326

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Mature
Health:	Good
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	6
DBH [cm]:	20.45
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	2.45
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level required
Foraging species:	No

Tree Location

Longitude:	115.914789
Latitude:	-31.984559

Photos Street View Map View



Weeping Bottlebrush Tree ID #327

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	8.12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.12
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.36
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914757
Latitude:	-31.984540

Photos Street View Map View



Broad-leaved Paperbark Tree ID #328

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5
DBH [cm]:	47.2
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	5.66
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914728
Latitude:	-31.984497

Photos Street View Map View



Weeping Paperbark Tree ID #329

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.305
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	2.01
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914682
Latitude:	-31.984431

Photos Street View Map View



Dryland Tea-tree Tree ID #330

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	14.72
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914651
Latitude:	-31.984396

Photos Street View Map View



Cook Pine Tree ID #331

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	7
DBH [cm]:	58.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.72
Tree Protection Zone (TPZ) [m]:	7.02
Structural Root Zone (SRZ) [m]:	2.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914615
Latitude:	-31.984332

Photos Street View Map View



Cook Pine Tree ID #332

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Has Failed
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	8
DBH [cm]:	38
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	1.15
Tree Protection Zone (TPZ) [m]:	4.56
Structural Root Zone (SRZ) [m]:	3.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal is recommended, as one of the main leader has failed
Foraging species:	No

Tree Location

Longitude:	115.914561
Latitude:	-31.984247

Photos Street View Map View



Broad-leaved Paperbark Tree ID #333

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Poor
Structure:	Poor
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	29
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.385
Tree Protection Zone (TPZ) [m]:	3.48
Structural Root Zone (SRZ) [m]:	2.22
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal is recommended, due to it's poor condition
Foraging species:	No

Tree Location

Longitude:	115.914492
Latitude:	-31.984173

Photos Street View Map View



Broad-leaved Paperbark Tree ID #334

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	10
DBH [cm]:	77.79
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.02
Tree Protection Zone (TPZ) [m]:	9.33
Structural Root Zone (SRZ) [m]:	3.34
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914458
Latitude:	-31.984137

Photos Street View Map View



Broad-leaved Paperbark Tree ID #335

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	9
DBH [cm]:	75
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.83
Tree Protection Zone (TPZ) [m]:	9
Structural Root Zone (SRZ) [m]:	3.06
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914409
Latitude:	-31.984073

Photos Street View Map View



Weeping Paperbark Tree ID #336

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	10
DBH [cm]:	30.56
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.425
Tree Protection Zone (TPZ) [m]:	3.67
Structural Root Zone (SRZ) [m]:	2.31
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914343
Latitude:	-31.983972

Photos Street View Map View



Weeping Paperbark Tree ID #337

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	4
DBH [cm]:	52
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.54
Tree Protection Zone (TPZ) [m]:	6.24
Structural Root Zone (SRZ) [m]:	2.55
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914312
Latitude:	-31.983933

Photos Street View Map View



Broad-leaved Paperbark Tree ID #338

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914262
Latitude:	-31.983865

Photos Street View Map View



Broad-leaved Paperbark Tree ID #339

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Poor
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	9
DBH [cm]:	56
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.652
Tree Protection Zone (TPZ) [m]:	6.72
Structural Root Zone (SRZ) [m]:	2.77
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914181
Latitude:	-31.983775

Photos Street View Map View



Broad-leaved Paperbark Tree ID #340

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Has Failed
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	6
DBH [cm]:	23.2
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.78
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	This tree has suffered the loss of half-wit main trunk removal could be considered
Foraging species:	No

Tree Location

Longitude:	115.914103
Latitude:	-31.983674

Photos Street View Map View



Broad-leaved Paperbark Tree ID #341

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	56.8
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.62
Tree Protection Zone (TPZ) [m]:	6.82
Structural Root Zone (SRZ) [m]:	2.71
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914056
Latitude:	-31.983614

Photos Street View Map View



Weeping Paperbark Tree ID #342

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	17.69
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.245
Tree Protection Zone (TPZ) [m]:	2.12
Structural Root Zone (SRZ) [m]:	1.83
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.914008
Latitude:	-31.983571

Photos Street View Map View



Weeping Paperbark Tree ID #343

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	7
DBH [cm]:	22.69
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.346
Tree Protection Zone (TPZ) [m]:	2.72
Structural Root Zone (SRZ) [m]:	2.12
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913940
Latitude:	-31.983484

Photos Street View Map View



Cook Pine Tree ID #344

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	10
DBH [cm]:	49.8
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.435
Tree Protection Zone (TPZ) [m]:	5.98
Structural Root Zone (SRZ) [m]:	2.33
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913901
Latitude:	-31.983428

Photos Street View Map View



Broad-leaved Paperbark Tree ID #345

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	36.07
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.33
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913826
Latitude:	-31.983351

Photos Street View Map View



Broad-leaved Paperbark Tree ID #346

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7.5
DBH [cm]:	53.5
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.63
Tree Protection Zone (TPZ) [m]:	6.42
Structural Root Zone (SRZ) [m]:	2.73
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913751
Latitude:	-31.983277

Photos Street View Map View



Broad-leaved Paperbark Tree ID #347

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.4
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	2.25
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913697
Latitude:	-31.983202

Photos Street View Map View



Cook Pine Tree ID #348

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	11
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.53
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.53
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting required to provide 2m clearance above ground level
Foraging species:	No

Tree Location

Longitude:	115.913616
Latitude:	-31.983132

Photos Street View Map View



Broad-leaved Paperbark Tree ID #349

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	9
DBH [cm]:	51
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.62
Tree Protection Zone (TPZ) [m]:	6.12
Structural Root Zone (SRZ) [m]:	2.71
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.913490
Latitude:	-31.982992

Photos Street View Map View



Broad-leaved Paperbark Tree ID #350

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	10
DBH [cm]:	35.71
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.72
Tree Protection Zone (TPZ) [m]:	4.29
Structural Root Zone (SRZ) [m]:	2.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.913432
Latitude:	-31.982919

Photos Street View Map View



Cook Pine Tree ID #351

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	7.5
DBH [cm]:	47
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.64
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2 Meters.
Foraging species:	No

Tree Location

Longitude:	115.913343
Latitude:	-31.982842

Photos Street View Map View



Broad-leaved Paperbark Tree ID #353

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	42.92
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.57
Tree Protection Zone (TPZ) [m]:	5.15
Structural Root Zone (SRZ) [m]:	2.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.913270
Latitude:	-31.982767

Photos Street View Map View



Weeping Paperbark Tree ID #354

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	6
DBH [cm]:	13
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.913213
Latitude:	-31.982700

Photos Street View Map View



Coastal Tea Tree Tree ID #355

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	9.27
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.913192
Latitude:	-31.982672

Photos Street View Map View



Weeping Bottlebrush Tree ID #356

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	12.61
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy
Foraging species:	No

Tree Location

Longitude:	115.913122
Latitude:	-31.982608

Photos Street View Map View



Weeping Bottlebrush Tree ID #357

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor Uplift canopy
Foraging species:	No

Tree Location

Longitude:	115.913098
Latitude:	-31.982584

Photos Street View Map View



Weeping Paperbark Tree ID #358

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.19
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.65
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy 2m
Foraging species:	No

Tree Location

Longitude:	115.913039
Latitude:	-31.982518

Photos Street View Map View



Coastal Tea Tree Tree ID #359

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.13
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.4
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.913024
Latitude:	-31.982495

Photos Street View Map View



Weeping Bottlebrush Tree ID #360

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4.5
DBH [cm]:	12.61
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy
Foraging species:	No

Tree Location

Longitude:	115.912992
Latitude:	-31.982465

Photos Street View Map View



Dryland Tea-tree Tree ID #361

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	7
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.912971
Latitude:	-31.982433

Photos Street View Map View



Broad-leaved Paperbark Tree ID #362

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	25.61
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	3.07
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.912917
Latitude:	-31.982387

Photos Street View Map View



Weeping Paperbark Tree ID #363

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	6
DBH [cm]:	25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.41
Tree Protection Zone (TPZ) [m]:	3
Structural Root Zone (SRZ) [m]:	2.28
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912899
Latitude:	-31.982376

Photos Street View Map View



Weeping Bottlebrush Tree ID #364

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	5
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912887
Latitude:	-31.982353

Photos Street View Map View



Weeping Bottlebrush Tree ID #365

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	5
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912806
Latitude:	-31.982282

Photos Street View Map View



Cook Pine Tree ID #366

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	16
Canopy Spread [m]:	7
DBH [cm]:	39
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	4.68
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	None
Foraging species:	No

Tree Location

Longitude:	115.912783
Latitude:	-31.982263

Photos Street View Map View



Broad-leaved Paperbark Tree ID #367

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5.5
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912730
Latitude:	-31.982196

Photos Street View Map View



Weeping Bottlebrush Tree ID #368

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	5.5
DBH [cm]:	8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.18
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912712
Latitude:	-31.982169

Photos Street View Map View



Weeping Bottlebrush Tree ID #369

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	6
DBH [cm]:	23.9
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2.87
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.912673
Latitude:	-31.982134

Photos Street View Map View



Weeping Paperbark Tree ID #370

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	5.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912636
Latitude:	-31.982099

Photos Street View Map View



Cook Pine Tree ID #371

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	11
DBH [cm]:	61
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.64
Tree Protection Zone (TPZ) [m]:	7.32
Structural Root Zone (SRZ) [m]:	2.74
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.912589
Latitude:	-31.982060

Photos Street View Map View



Coastal Tea Tree Tree ID #372

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5.5
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912540
Latitude:	-31.982000

Photos Street View Map View



Weeping Paperbark Tree ID #373

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	6.5
DBH [cm]:	32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	3.84
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912524
Latitude:	-31.981976

Photos Street View Map View



Weeping Bottlebrush Tree ID #374

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6.5
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912504
Latitude:	-31.981956

Photos Street View Map View



Broad-leaved Paperbark Tree ID #375

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	6.5
DBH [cm]:	63
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.71
Tree Protection Zone (TPZ) [m]:	7.56
Structural Root Zone (SRZ) [m]:	2.87
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912467
Latitude:	-31.981928

Photos Street View Map View



Weeping Paperbark Tree ID #376

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	9
DBH [cm]:	35.81
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	4.3
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912425
Latitude:	-31.981880

Photos Street View Map View



Weeping Bottlebrush Tree ID #377

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912411
Latitude:	-31.981855

Photos Street View Map View



Dryland Tea-tree Tree ID #378

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912396
Latitude:	-31.981828

Photos Street View Map View



Weeping Paperbark Tree ID #379

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	7
DBH [cm]:	39
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.48
Tree Protection Zone (TPZ) [m]:	4.68
Structural Root Zone (SRZ) [m]:	2.43
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.912361
Latitude:	-31.981806

Photos Street View Map View



Coastal Tea Tree Tree ID #380

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	8
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	37
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	15.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Removal recommended as this is an invasive species
Foraging species:	No

Tree Location

Longitude:	115.912227
Latitude:	-31.981680

Photos Street View Map View



Weeping Bottlebrush Tree ID #381

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	10.49
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift canopy
Foraging species:	No

Tree Location

Longitude:	115.912187
Latitude:	-31.981648

Photos Street View Map View



Weeping Paperbark Tree ID #382

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	8
DBH [cm]:	24
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	2.88
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912148
Latitude:	-31.981602

Photos Street View Map View



Cook Pine Tree ID #383

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	22
Canopy Spread [m]:	13
DBH [cm]:	71
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.83
Tree Protection Zone (TPZ) [m]:	8.52
Structural Root Zone (SRZ) [m]:	3.06
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No work required
Foraging species:	No

Tree Location

Longitude:	115.912099
Latitude:	-31.981565

Photos Street View Map View



Broad-leaved Paperbark Tree ID #384

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplifting.
Foraging species:	No

Tree Location

Longitude:	115.912029
Latitude:	-31.981471

Photos Street View Map View



Weeping Bottlebrush Tree ID #388

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	5.5
DBH [cm]:	9.9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.13
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.4
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplift
Foraging species:	No

Tree Location

Longitude:	115.911988
Latitude:	-31.981460

Photos Street View Map View



Weeping Paperbark Tree ID #389

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	14.87
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplift
Foraging species:	No

Tree Location

Longitude:	115.911962
Latitude:	-31.981433

Photos Street View Map View



Cook Pine Tree ID #390

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	10
DBH [cm]:	73
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.83
Tree Protection Zone (TPZ) [m]:	8.76
Structural Root Zone (SRZ) [m]:	3.06
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.911924
Latitude:	-31.981396

Photos Street View Map View



Weeping Paperbark Tree ID #391

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	8.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.13
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.4
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.911879
Latitude:	-31.981325

Photos Street View Map View



Broad-leaved Paperbark Tree ID #392

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	11.5
DBH [cm]:	60
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.64
Tree Protection Zone (TPZ) [m]:	7.2
Structural Root Zone (SRZ) [m]:	2.74
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.911826
Latitude:	-31.981285

Photos Street View Map View



Weeping Bottlebrush Tree ID #393

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.11
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.31
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.911785
Latitude:	-31.981237

Photos Street View Map View



Weeping Paperbark Tree ID #394

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	42.73
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.65
Tree Protection Zone (TPZ) [m]:	5.13
Structural Root Zone (SRZ) [m]:	2.76
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.911748
Latitude:	-31.981212

Photos Street View Map View



Weeping Bottlebrush Tree ID #395

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	23
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	2.76
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.911687
Latitude:	-31.981153

Photos Street View Map View



Cook Pine Tree ID #396

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	10
DBH [cm]:	67
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.73
Tree Protection Zone (TPZ) [m]:	8.04
Structural Root Zone (SRZ) [m]:	2.9
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.911643
Latitude:	-31.981090

Photos Street View Map View



Mugga, Red Ironbark Tree ID #397

Tree Details

Latin Name:	Eucalyptus sideroxylon
Common Name:	Mugga, Red Ironbark
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	11
DBH [cm]:	49
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.5
Tree Protection Zone (TPZ) [m]:	5.88
Structural Root Zone (SRZ) [m]:	2.47
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.911577
Latitude:	-31.981029

Photos Street View Map View



Coastal Tea Tree Tree ID #398

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	9.95
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.27
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.91
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.911521
Latitude:	-31.980986

Photos Street View Map View



Broad-leaved Paperbark Tree ID #399

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Good
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	13
DBH [cm]:	65.12
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.93
Tree Protection Zone (TPZ) [m]:	7.81
Structural Root Zone (SRZ) [m]:	3.21
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.911459
Latitude:	-31.980914

Photos Street View Map View



Mugga, Red Ironbark Tree ID #400

Tree Details

Latin Name:	Eucalyptus sideroxylon
Common Name:	Mugga, Red Ironbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	9
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.56
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	2.59
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	No works required
Foraging species:	No

Tree Location

Longitude:	115.911409
Latitude:	-31.980874

Photos Street View Map View



Weeping Bottlebrush Tree ID #401

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2.5
DBH [cm]:	10.82
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.911369
Latitude:	-31.980817

Photos Street View Map View



Cook Pine Tree ID #402

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	12
DBH [cm]:	55
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	6.6
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.911307
Latitude:	-31.980771

Photos Street View Map View



Mugga, Red Ironbark Tree ID #403

Tree Details

Latin Name:	Eucalyptus sideroxylon
Common Name:	Mugga, Red Ironbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	11
DBH [cm]:	43
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	5.16
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.911270
Latitude:	-31.980722

Photos Street View Map View



Coastal Tea Tree Tree ID #404

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	13.3
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	None
Foraging species:	No

Tree Location

Longitude:	115.911247
Latitude:	-31.980682

Photos Street View Map View



Broad-leaved Paperbark Tree ID #405

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	63
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.73
Tree Protection Zone (TPZ) [m]:	7.56
Structural Root Zone (SRZ) [m]:	2.9
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.911197
Latitude:	-31.980645

Photos Street View Map View



Weeping Bottlebrush Tree ID #406

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.911156
Latitude:	-31.980591

Photos Street View Map View



Weeping Paperbark Tree ID #407

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	7
DBH [cm]:	27.02
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.911117
Latitude:	-31.980558

Photos Street View Map View



Weeping Bottlebrush Tree ID #408

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	4
DBH [cm]:	16.28
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.23
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.79
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.911101
Latitude:	-31.980525

Photos Street View Map View



Weeping Paperbark Tree ID #409

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	33.42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	4.01
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Minor uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.911030
Latitude:	-31.980470

Photos Street View Map View



Cook Pine Tree ID #410

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	11
DBH [cm]:	56
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	6.72
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910983
Latitude:	-31.980440

Photos Street View Map View



Mugga, Red Ironbark Tree ID #411

Tree Details

Latin Name:	Eucalyptus sideroxylon
Common Name:	Mugga, Red Ironbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	68.12
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	8.17
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.910822
Latitude:	-31.980228

Photos Street View Map View



Cook Pine Tree ID #412

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	10
DBH [cm]:	58
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.67
Tree Protection Zone (TPZ) [m]:	6.96
Structural Root Zone (SRZ) [m]:	2.8
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910670
Latitude:	-31.980101

Photos Street View Map View



Broad-leaved Paperbark Tree ID #413

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	12
DBH [cm]:	51
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.62
Tree Protection Zone (TPZ) [m]:	6.12
Structural Root Zone (SRZ) [m]:	2.71
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.910548
Latitude:	-31.979983

Photos Street View Map View



Weeping Bottlebrush Tree ID #414

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	3
DBH [cm]:	15.62
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.13
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.4
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.910526
Latitude:	-31.979944

Photos Street View Map View



Cook Pine Tree ID #415

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	22
Canopy Spread [m]:	126
DBH [cm]:	54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	6.48
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.910454
Latitude:	-31.979882

Photos Street View Map View



Weeping Paperbark Tree ID #416

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	31.3
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.47
Tree Protection Zone (TPZ) [m]:	3.76
Structural Root Zone (SRZ) [m]:	2.41
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.910413
Latitude:	-31.979836

Photos Street View Map View



Weeping Bottlebrush Tree ID #417

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift 2m
Foraging species:	No

Tree Location

Longitude:	115.910340
Latitude:	-31.979788

Photos Street View Map View



Weeping Paperbark Tree ID #418

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	26.25
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.33
Tree Protection Zone (TPZ) [m]:	3.15
Structural Root Zone (SRZ) [m]:	2.08
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	None
Foraging species:	No

Tree Location

Longitude:	115.910322
Latitude:	-31.979741

Photos Street View Map View



Weeping Bottlebrush Tree ID #419

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.910281
Latitude:	-31.979730

Photos Street View Map View



Coastal Tea Tree Tree ID #420

Tree Details

Latin Name:	Leptospermum laevigatum
Common Name:	Coastal Tea Tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	6
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.910245
Latitude:	-31.979689

Photos Street View Map View



Dryland Tea-tree Tree ID #421

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	4
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.910213
Latitude:	-31.979656

Photos Street View Map View



Dryland Tea-tree Tree ID #422

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	34
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.46
Tree Protection Zone (TPZ) [m]:	4.08
Structural Root Zone (SRZ) [m]:	2.39
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.910201
Latitude:	-31.979626

Photos Street View Map View



Weeping Bottlebrush Tree ID #423

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	9
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.2
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.910190
Latitude:	-31.979613

Photos Street View Map View



Dryland Tea-tree Tree ID #424

Tree Details

Latin Name:	Melaleuca lanceolata
Common Name:	Dryland Tea-tree
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	19.42
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.33
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.910163
Latitude:	-31.979585

Photos Street View Map View



Weeping Paperbark Tree ID #425

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	20
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	2.4
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.910123
Latitude:	-31.979561

Photos Street View Map View



Weeping Bottlebrush Tree ID #426

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	5
DBH [cm]:	12
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.910095
Latitude:	-31.979533

Photos Street View Map View



Cook Pine Tree ID #427

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	12
DBH [cm]:	59
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	7.08
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.909680
Latitude:	-31.979124

Photos Street View Map View



Weeping Paperbark Tree ID #428

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	12
DBH [cm]:	23.35
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	2.8
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909668
Latitude:	-31.979076

Photos Street View Map View



Weeping Bottlebrush Tree ID #429

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.909653
Latitude:	-31.979053

Photos Street View Map View



Broad-leaved Paperbark Tree ID #430

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	11
DBH [cm]:	67
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.74
Tree Protection Zone (TPZ) [m]:	8.04
Structural Root Zone (SRZ) [m]:	2.92
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909592
Latitude:	-31.978993

Photos Street View Map View



Weeping Bottlebrush Tree ID #431

Tree Details

Latin Name:	Callistemon viminalis
Common Name:	Weeping Bottlebrush
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	4
DBH [cm]:	4
DBH Range:	0-8cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift
Foraging species:	No

Tree Location

Longitude:	115.909561
Latitude:	-31.978962

Photos Street View Map View



Norfolk Island Pine Tree ID #432

Tree Details

Latin Name:	Araucaria heterophylla
Common Name:	Norfolk Island Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	22
Canopy Spread [m]:	9
DBH [cm]:	57
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.64
Tree Protection Zone (TPZ) [m]:	6.84
Structural Root Zone (SRZ) [m]:	2.74
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909472
Latitude:	-31.978855

Photos Street View Map View



Broad-leaved Paperbark Tree ID #433

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	10
DBH [cm]:	63.19
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.14
Tree Protection Zone (TPZ) [m]:	7.58
Structural Root Zone (SRZ) [m]:	3.5
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909420
Latitude:	-31.978810

Photos Street View Map View



Broad-leaved Paperbark Tree ID #434

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	10
DBH [cm]:	56
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.68
Tree Protection Zone (TPZ) [m]:	6.72
Structural Root Zone (SRZ) [m]:	2.81
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909366
Latitude:	-31.978761

Photos Street View Map View



Broad-leaved Paperbark Tree ID #435

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	40.1
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.61
Tree Protection Zone (TPZ) [m]:	4.81
Structural Root Zone (SRZ) [m]:	2.69
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909282
Latitude:	-31.978661

Photos Street View Map View



Weeping Paperbark Tree ID #436

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	5
DBH [cm]:	11
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.14
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909255
Latitude:	-31.978624

Photos Street View Map View



Cook Pine Tree ID #437

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	9
DBH [cm]:	49
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.56
Tree Protection Zone (TPZ) [m]:	5.88
Structural Root Zone (SRZ) [m]:	2.59
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.909209
Latitude:	-31.978598

Photos Street View Map View



Broad-leaved Paperbark Tree ID #438

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	49.02
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	5.88
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909154
Latitude:	-31.978510

Photos Street View Map View



Broad-leaved Paperbark Tree ID #439

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	11
DBH [cm]:	73
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	8.76
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909077
Latitude:	-31.978442

Photos Street View Map View



Broad-leaved Paperbark Tree ID #440

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	9
DBH [cm]:	39.33
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	1.06
Tree Protection Zone (TPZ) [m]:	4.72
Structural Root Zone (SRZ) [m]:	3.39
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.909024
Latitude:	-31.978400

Photos Street View Map View



Norfolk Island Pine Tree ID #441

Tree Details

Latin Name:	Araucaria heterophylla
Common Name:	Norfolk Island Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	22
Canopy Spread [m]:	9
DBH [cm]:	64
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.75
Tree Protection Zone (TPZ) [m]:	7.68
Structural Root Zone (SRZ) [m]:	2.93
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908951
Latitude:	-31.978323

Photos Street View Map View



Broad-leaved Paperbark Tree ID #442

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	10
DBH [cm]:	34.66
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.71
Tree Protection Zone (TPZ) [m]:	4.16
Structural Root Zone (SRZ) [m]:	2.87
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908890
Latitude:	-31.978257

Photos Street View Map View



Weeping Paperbark Tree ID #443

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	3
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908866
Latitude:	-31.978238

Photos Street View Map View



Broad-leaved Paperbark Tree ID #444

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	9
DBH [cm]:	58
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	6.96
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908819
Latitude:	-31.978175

Photos Street View Map View



Broad-leaved Paperbark Tree ID #445

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	15
Canopy Spread [m]:	11
DBH [cm]:	61.15
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.46
Tree Protection Zone (TPZ) [m]:	7.34
Structural Root Zone (SRZ) [m]:	3.88
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908748
Latitude:	-31.978114

Photos Street View Map View



Cook Pine Tree ID #446

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	21
Canopy Spread [m]:	13
DBH [cm]:	57
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.63
Tree Protection Zone (TPZ) [m]:	6.84
Structural Root Zone (SRZ) [m]:	2.73
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.908645
Latitude:	-31.978026

Photos Street View Map View



Broad-leaved Paperbark Tree ID #447

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	12
DBH [cm]:	43.71
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.7
Tree Protection Zone (TPZ) [m]:	5.25
Structural Root Zone (SRZ) [m]:	2.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908609
Latitude:	-31.977956

Photos Street View Map View



Broad-leaved Paperbark Tree ID #448

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	13
DBH [cm]:	103.66
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.23
Tree Protection Zone (TPZ) [m]:	12.44
Structural Root Zone (SRZ) [m]:	3.61
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908541
Latitude:	-31.977895

Photos Street View Map View



Broad-leaved Paperbark Tree ID #449

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	13
DBH [cm]:	40.1
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	4.81
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908450
Latitude:	-31.977820

Photos Street View Map View



Cook Pine Tree ID #450

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	24
Canopy Spread [m]:	12
DBH [cm]:	61
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	7.32
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908379
Latitude:	-31.977744

Photos Street View Map View



Broad-leaved Paperbark Tree ID #451

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	17
Canopy Spread [m]:	10
DBH [cm]:	78.49
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.29
Tree Protection Zone (TPZ) [m]:	9.42
Structural Root Zone (SRZ) [m]:	3.68
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908321
Latitude:	-31.977685

Photos Street View Map View



Broad-leaved Paperbark Tree ID #452

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	6
DBH [cm]:	83
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	0.66
Tree Protection Zone (TPZ) [m]:	9.96
Structural Root Zone (SRZ) [m]:	2.78
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908231
Latitude:	-31.977617

Photos Street View Map View



Broad-leaved Paperbark Tree ID #453

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	10
DBH [cm]:	69.22
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	1.03
Tree Protection Zone (TPZ) [m]:	8.31
Structural Root Zone (SRZ) [m]:	3.35
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908206
Latitude:	-31.977557

Photos Street View Map View



Broad-leaved Paperbark Tree ID #454

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	12
DBH [cm]:	41.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.6
Tree Protection Zone (TPZ) [m]:	4.98
Structural Root Zone (SRZ) [m]:	2.67
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908161
Latitude:	-31.977497

Photos Street View Map View



Cook Pine Tree ID #455

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	20
Canopy Spread [m]:	11
DBH [cm]:	58
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.69
Tree Protection Zone (TPZ) [m]:	6.96
Structural Root Zone (SRZ) [m]:	2.83
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908067
Latitude:	-31.977440

Photos Street View Map View



Broad-leaved Paperbark Tree ID #456

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	11
DBH [cm]:	39.86
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	4.78
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.908022
Latitude:	-31.977369

Photos Street View Map View



Broad-leaved Paperbark Tree ID #457

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	11
DBH [cm]:	36.95
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.85
Tree Protection Zone (TPZ) [m]:	4.43
Structural Root Zone (SRZ) [m]:	3.09
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907967
Latitude:	-31.977303

Photos Street View Map View



Broad-leaved Paperbark Tree ID #458

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	14
Canopy Spread [m]:	12
DBH [cm]:	94
DBH Range:	>75cm
Diameter at Root Flare (DRF) [m]:	1.04
Tree Protection Zone (TPZ) [m]:	11.28
Structural Root Zone (SRZ) [m]:	3.36
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907881
Latitude:	-31.977250

Photos Street View Map View



Broad-leaved Paperbark Tree ID #459

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	33.26
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	3.99
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907819
Latitude:	-31.977188

Photos Street View Map View



Broad-leaved Paperbark Tree ID #460

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	23
Canopy Spread [m]:	11
DBH [cm]:	54
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.64
Tree Protection Zone (TPZ) [m]:	6.48
Structural Root Zone (SRZ) [m]:	2.74
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.907742
Latitude:	-31.977092

Photos Street View Map View



Broad-leaved Paperbark Tree ID #461

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	4
DBH [cm]:	30.43
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.61
Tree Protection Zone (TPZ) [m]:	3.65
Structural Root Zone (SRZ) [m]:	2.69
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.907703
Latitude:	-31.977014

Photos Street View Map View



Broad-leaved Paperbark Tree ID #462

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	13
Canopy Spread [m]:	6
DBH [cm]:	45
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.71
Tree Protection Zone (TPZ) [m]:	5.4
Structural Root Zone (SRZ) [m]:	2.87
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.907662
Latitude:	-31.976990

Photos Street View Map View



Broad-leaved Paperbark Tree ID #463

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	6
DBH [cm]:	39.99
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.91
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	3.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.907605
Latitude:	-31.976927

Photos Street View Map View



Moort Tree ID #464

Tree Details

Latin Name:	Eucalyptus platypus
Common Name:	Moort
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	18.6
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.23
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907570
Latitude:	-31.976898

Photos Street View Map View



Cook Pine Tree ID #465

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	19
Canopy Spread [m]:	12
DBH [cm]:	74
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.79
Tree Protection Zone (TPZ) [m]:	8.88
Structural Root Zone (SRZ) [m]:	3
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.907468
Latitude:	-31.976815

Photos Street View Map View



Cook Pine Tree ID #466

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	11
Canopy Spread [m]:	6
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.63
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.73
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907397
Latitude:	-31.976704

Photos Street View Map View



Cook Pine Tree ID #467

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	18
Canopy Spread [m]:	10
DBH [cm]:	74
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.77
Tree Protection Zone (TPZ) [m]:	8.88
Structural Root Zone (SRZ) [m]:	2.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907338
Latitude:	-31.976638

Photos Street View Map View



Broad-leaved Paperbark Tree ID #468

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	49
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.74
Tree Protection Zone (TPZ) [m]:	5.88
Structural Root Zone (SRZ) [m]:	2.92
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907272
Latitude:	-31.976579

Photos Street View Map View



Weeping Paperbark Tree ID #469

Tree Details

Latin Name:	Melaleuca leucadendra
Common Name:	Weeping Paperbark
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	3
DBH [cm]:	15
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.3
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907241
Latitude:	-31.976539

Photos Street View Map View



Moort Tree ID #470

Tree Details

Latin Name:	Eucalyptus platypus
Common Name:	Moort
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	10
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907211
Latitude:	-31.976521

Photos Street View Map View



Moort Tree ID #471

Tree Details

Latin Name:	Eucalyptus platypus
Common Name:	Moort
Tree Age:	Juvenile
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	11.31
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.15
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907181
Latitude:	-31.976476

Photos Street View Map View



Cook Pine Tree ID #472

Tree Details

Latin Name:	Araucaria columnaris
Common Name:	Cook Pine
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	22
Canopy Spread [m]:	10
DBH [cm]:	74
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.76
Tree Protection Zone (TPZ) [m]:	8.88
Structural Root Zone (SRZ) [m]:	2.95
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907176
Latitude:	-31.976456

Photos Street View Map View



Broad-leaved Paperbark Tree ID #473

Tree Details

Latin Name:	Melaleuca quinquenervia
Common Name:	Broad-leaved Paperbark
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	12
Canopy Spread [m]:	12
DBH [cm]:	74
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.78
Tree Protection Zone (TPZ) [m]:	8.88
Structural Root Zone (SRZ) [m]:	2.98
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Uplift to 2m
Foraging species:	No

Tree Location

Longitude:	115.907098
Latitude:	-31.976372

Photos Street View Map View



Queensland Box Tree ID #474

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	32
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.43
Tree Protection Zone (TPZ) [m]:	3.84
Structural Root Zone (SRZ) [m]:	2.32
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910567
Latitude:	-31.978857

Photos Street View Map View



Queensland Box Tree ID #475

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	8
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910639
Latitude:	-31.978785

Photos Street View Map View



Queensland Box Tree ID #476

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	70.5
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.8
Tree Protection Zone (TPZ) [m]:	8.46
Structural Root Zone (SRZ) [m]:	3.01
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910739
Latitude:	-31.978710

Photos Street View Map View



Queensland Box Tree ID #477

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	9
DBH [cm]:	44
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	5.28
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910835
Latitude:	-31.978625

Photos Street View Map View



Queensland Box Tree ID #478

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	72
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.81
Tree Protection Zone (TPZ) [m]:	8.64
Structural Root Zone (SRZ) [m]:	3.03
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910838
Latitude:	-31.978441

Photos Street View Map View



Queensland Box Tree ID #479

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	10
Canopy Spread [m]:	10
DBH [cm]:	65
DBH Range:	60-75cm
Diameter at Root Flare (DRF) [m]:	0.74
Tree Protection Zone (TPZ) [m]:	7.8
Structural Root Zone (SRZ) [m]:	2.92
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910744
Latitude:	-31.978514

Photos Street View Map View



Queensland Box Tree ID #480

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	7
DBH [cm]:	35
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.38
Tree Protection Zone (TPZ) [m]:	4.2
Structural Root Zone (SRZ) [m]:	2.2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910672
Latitude:	-31.978602

Photos Street View Map View



Queensland Box Tree ID #481

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	9
Canopy Spread [m]:	9
DBH [cm]:	42
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.52
Tree Protection Zone (TPZ) [m]:	5.04
Structural Root Zone (SRZ) [m]:	2.51
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910469
Latitude:	-31.978744

Photos Street View Map View



Queensland Box Tree ID #482

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	40
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.51
Tree Protection Zone (TPZ) [m]:	4.8
Structural Root Zone (SRZ) [m]:	2.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910382
Latitude:	-31.978819

Photos Street View Map View



Queensland Box Tree ID #483

Tree Details

Latin Name:	Lophostemon confertus
Common Name:	Queensland Box
Tree Age:	Mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	8
DBH [cm]:	35.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.49
Tree Protection Zone (TPZ) [m]:	4.26
Structural Root Zone (SRZ) [m]:	2.45
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	
Foraging species:	No

Tree Location

Longitude:	115.910274
Latitude:	-31.978909

Photos Street View Map View



Flowering Gum Tree ID #484

Tree Details

Latin Name:	Corymbia ficifolia
Common Name:	Flowering Gum
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	7
DBH [cm]:	30.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	3.66
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Treat with 1000 litres of water with 1%Bioprime and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924673
Latitude:	-31.995895

Photos Street View Map View



Illawarra Flame Tree Tree ID #485

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	3
Canopy Spread [m]:	2
DBH [cm]:	16
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924475
Latitude:	-31.995738

Photos Street View Map View



Illawarra Flame Tree Tree ID #486

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.25
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924430
Latitude:	-31.995696

Photos Street View Map View



Illawarra Flame Tree Tree ID #487

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	15.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.21
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.72
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924381
Latitude:	-31.995662

Photos Street View Map View



Illawarra Flame Tree Tree ID #488

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	15.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.213
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.73
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924335
Latitude:	-31.995624

Photos Street View Map View



Illawarra Flame Tree Tree ID #489

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	18
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2.16
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924292
Latitude:	-31.995594

Photos Street View Map View



Illawarra Flame Tree Tree ID #490

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	22.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.253
Tree Protection Zone (TPZ) [m]:	2.7
Structural Root Zone (SRZ) [m]:	1.86
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924220
Latitude:	-31.995547

Photos Street View Map View



Illawarra Flame Tree Tree ID #491

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2
DBH [cm]:	11.8
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.182
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.62
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924206
Latitude:	-31.995519

Photos Street View Map View



Illawarra Flame Tree Tree ID #492

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	24.4
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.302
Tree Protection Zone (TPZ) [m]:	2.93
Structural Root Zone (SRZ) [m]:	2
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924160
Latitude:	-31.995486

Photos Street View Map View



Illawarra Flame Tree Tree ID #493

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	26
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.31
Tree Protection Zone (TPZ) [m]:	3.12
Structural Root Zone (SRZ) [m]:	2.02
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.924020
Latitude:	-31.995371

Photos Street View Map View



Illawarra Flame Tree Tree ID #494

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	19
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.252
Tree Protection Zone (TPZ) [m]:	2.28
Structural Root Zone (SRZ) [m]:	1.85
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923962
Latitude:	-31.995336

Photos Street View Map View



Illawarra Flame Tree Tree ID #495

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.347
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2.12
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone. Remove all deadwood.
Foraging species:	No

Tree Location

Longitude:	115.923922
Latitude:	-31.995305

Photos Street View Map View



Illawarra Flame Tree Tree ID #496

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	8
Canopy Spread [m]:	5
DBH [cm]:	41
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.58
Tree Protection Zone (TPZ) [m]:	4.92
Structural Root Zone (SRZ) [m]:	2.63
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone. Minor uplifting required to provide 2m clearance above ground level.
Foraging species:	No

Tree Location

Longitude:	115.923870
Latitude:	-31.995265

Photos Street View Map View



Illawarra Flame Tree Tree ID #497

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	23.71
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.265
Tree Protection Zone (TPZ) [m]:	2.85
Structural Root Zone (SRZ) [m]:	1.89
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923780
Latitude:	-31.995193

Photos Street View Map View



Illawarra Flame Tree Tree ID #498

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	3
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.37
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	2.18
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923734
Latitude:	-31.995158

Photos Street View Map View



Illawarra Flame Tree Tree ID #499

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	43
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.51
Tree Protection Zone (TPZ) [m]:	5.16
Structural Root Zone (SRZ) [m]:	2.49
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923681
Latitude:	-31.995118

Photos Street View Map View



Illawarra Flame Tree Tree ID #500

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	30.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	3.66
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923634
Latitude:	-31.995082

Photos Street View Map View



Illawarra Flame Tree Tree ID #501

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.45
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.37
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923593
Latitude:	-31.995045

Photos Street View Map View



Illawarra Flame Tree Tree ID #502

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	27
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.34
Tree Protection Zone (TPZ) [m]:	3.24
Structural Root Zone (SRZ) [m]:	2.1
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone. Remove all deadwood
Foraging species:	No

Tree Location

Longitude:	115.923562
Latitude:	-31.995014

Photos Street View Map View



Illawarra Flame Tree Tree ID #503

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	36
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.55
Tree Protection Zone (TPZ) [m]:	4.32
Structural Root Zone (SRZ) [m]:	2.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923521
Latitude:	-31.994984

Photos Street View Map View



Illawarra Flame Tree Tree ID #504

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	7
Canopy Spread [m]:	5
DBH [cm]:	29.36
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.35
Tree Protection Zone (TPZ) [m]:	3.52
Structural Root Zone (SRZ) [m]:	2.13
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923471
Latitude:	-31.994949

Photos Street View Map View



Illawarra Flame Tree Tree ID #505

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	6
Canopy Spread [m]:	6
DBH [cm]:	48
DBH Range:	46-60cm
Diameter at Root Flare (DRF) [m]:	0.595
Tree Protection Zone (TPZ) [m]:	5.76
Structural Root Zone (SRZ) [m]:	2.66
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923379
Latitude:	-31.994876

Photos Street View Map View



Illawarra Flame Tree Tree ID #506

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	19.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.275
Tree Protection Zone (TPZ) [m]:	2.34
Structural Root Zone (SRZ) [m]:	1.92
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923339
Latitude:	-31.994849

Photos Street View Map View



Illawarra Flame Tree Tree ID #507

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4.5
DBH [cm]:	31.5
DBH Range:	30-45cm
Diameter at Root Flare (DRF) [m]:	0.395
Tree Protection Zone (TPZ) [m]:	3.78
Structural Root Zone (SRZ) [m]:	2.24
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone. Remove all deadwood
Foraging species:	No

Tree Location

Longitude:	115.923301
Latitude:	-31.994821

Photos Street View Map View



Illawarra Flame Tree Tree ID #508

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	3
DBH [cm]:	21
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.22
Tree Protection Zone (TPZ) [m]:	2.52
Structural Root Zone (SRZ) [m]:	1.75
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone. Remove all deadwood
Foraging species:	No

Tree Location

Longitude:	115.923267
Latitude:	-31.994797

Photos Street View Map View



Illawarra Flame Tree Tree ID #509

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	4
Canopy Spread [m]:	2.5
DBH [cm]:	14
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.24
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.82
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923211
Latitude:	-31.994751

Photos Street View Map View



Illawarra Flame Tree Tree ID #510

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	5
Canopy Spread [m]:	4
DBH [cm]:	23.5
DBH Range:	16-30cm
Diameter at Root Flare (DRF) [m]:	0.292
Tree Protection Zone (TPZ) [m]:	2.82
Structural Root Zone (SRZ) [m]:	1.97
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone.
Foraging species:	No

Tree Location

Longitude:	115.923170
Latitude:	-31.994715

Photos Street View Map View



Illawarra Flame Tree Tree ID #511

Tree Details

Latin Name:	Brachychiton acerifolius
Common Name:	Illawarra Flame Tree
Tree Age:	Semi mature
Health:	Fair
Structure:	Fair
Tree Height (Estimated) [m]:	2
Canopy Spread [m]:	2
DBH [cm]:	10.5
DBH Range:	8-16cm
Diameter at Root Flare (DRF) [m]:	0.17
Tree Protection Zone (TPZ) [m]:	2
Structural Root Zone (SRZ) [m]:	1.57
Useful Life Expectancy:	40+ years
Origin:	Exotic
Habitat value:	Low
QTRA Risk Category:	Broadly Acceptable
Observation Comments:	Remove grass and mulch root zone
Foraging species:	No

Tree Location

Longitude:	115.923120
Latitude:	-31.994686

Photos Street View Map View



9.0 Conclusion

510 Trees were picked up on the western side of the train tracks between Miller Street to Leach Highway, Labelled as Part C.

This section has 7 Marri, 2 Jarrah and 14 Red Cap Gums which are foraging species for Forest red-tailed black cockatoo (calyptorhynchus banksii naso); - Baudin's cockatoo (calyptorhynchus baudinii); - Carnaby's cockatoo (calyptorhynchus latirostris); - Peregrine falcon (falco peregrinus). No trees were observed to hold any Habitat value for these species of bird.

136 Grass trees are located within this section which would be suitable for transplanting, with the correct preparation and aftercare.

5 Melaleuca, labelled 449, 453 454, 455 and 456 could possibly be transplanted, as they are of a small size and have suitable space around them that would allow for appropriate root preparation to take place, without disturbing other trees.

No other trees are suitable for transplanting due to their location, proximity to other trees and/or size.

11 trees were identified as being in poor condition, Trees 1, 2, 3, 6, 8, 17, 317, 319, 331, 350, 423. Tree 4 is regarded as dead and should be removed.

14 additional trees that were picked up on the western side of the train tracks between Lacey Street to Leach Highway, Labelled as Part C as part of the report of the 6 May 2022 which totals 510

These trees are a Mix of olives, Red Cap Gums, Melaleuca and Ficus

511 Trees were picked up on the eastern side of the train tracks between Miller Street to Leach Highway, Labelled as Part D.

This section has 2 Marri, which are foraging species for Forest red-tailed black cockatoo (calyptorhynchus banksii naso); - Baudin's cockatoo (calyptorhynchus baudinii); - Carnaby's cockatoo (calyptorhynchus latirostris); - Peregrine falcon (falco peregrinus). No trees were observed to hold any Habitat value for these species of bird. It is possible that these birds can turn to E. camaldulensis, C. citriodora and other eucalyptus in the absence of their traditional foraging foods.

8 Queensland Box Trees were picked up in addition to the Trees which were originally picked up on the eastern side of the train tracks between Lacey Street to Leach Highway, Labelled as Part D as part of the report of the 6 May 2022.

No trees were observed to hold any Habitat value for these species of bird.

No trees are suitable for transplanting due to their location, proximity to other trees and/or size within this section with the exception of the 88 Grass Trees, which are mostly within the Rail Corridor.

Trees 1, 2, 3, 12, 94, 102, 145, 204, 205, 276, 280 and 333, are at the end of their useful life and are now either dead or in decline, these should also be removed. 3 Acacias were identified, these could also be considered for removal as they are a relatively short-lived species.

49 trees were picked up as part of A supplementary tree survey around Welshpool Train Station on the 7 July 2022

There are 4 WA Red Flowering Gym and 17 Jacaranda, which are in a suitable condition.

There are 28 Brachychiton that are in a suitable condition for their species. The trees are holding varying amounts of deadwood in their canopies, which is attributable to being grown in sand. Brachychiton prefer a loamy soil that has a higher moisture and nutrient content, which WA Sands do not provide, As such the trees are not in as best aesthetic quality as they could be.

The overall condition of these trees could be improved by removing the grass around them and replacing this with mulch. This will assist in improving the condition of the soil and with moisture retention. This will also remove competition from the grass that would take up any nutrients making with way through the soil before the trees have an opportunity to get it. All trees have been planted as part of landscaping around the station.

On a general level over the two verge areas, there are large amounts of Victorian Tea (*Leptospermum laevigatum*)Tree and Geraldton Wax (Chamelaucium uncinatum) which can be regarded as a weed species and over large amounts of ground, preventing other vegetation from growing. It is recommended to remove these two species, as it will open large areas of ground up, increase passive surveillance and improve the amenity of the new areas to be created.

Additionally, the majority of trees and shrubs were observed to require pruning to either begin uplifting of the canopy or full uplifting of their canopies to achieve 2m clearance above ground level. This will also increase passive surveillance into the area that is currently the rial corridor, reduce the build-up of rubbish and prevent undesirable activities, such as drug use by removing areas for people to conceal themselves.

As noted previously, there are only a small number of trees that are suitable to be transplanted, this is mostly due to the close proximity of other trees that would prevent appropriate root preparation from taking place. Should transplanting of any Tree or Gras tree be considered, it needs to be acknowledged that the appropriate root preparation time for trees can be approximately 6 months, followed by 2 years of aftercare. Grass trees can be removed without root preparation but require 6 months of appropriate aftercare when replanted. The transplanting of grass trees carries a high risk of death without the appropriate expertise applied.

Across the site referred to as “Package 1: the following trees were found to have a DBH 500mm in diameter or greater that have the potential (in the long term) to provide nesting habitat for the bird species listed above. As such, these have been noted as holding a “High” Habitat Value.

- Part C, there were 4 Marri, and 2 Jarrah (Numbered: 10, 11, 14, 66, 73, and 95)
- Part D there was on 1 Marri (Numbered: 291)

No Rare or Priority Flora was identified in the area of Package 1 (Leach Highway to Miller Street)

10.0 Glossary of Arboricultural Terminology

Abscission - The shedding of a leaf or other short-lived part of a woody plant, involving the formation of a corky layer across its base; in some tree species twigs can be shed in this way.

Abiotic - Pertaining to non-living agents, e.g., environmental factors.

Absorptive roots - non-woody, short-lived roots, generally having a diameter of less than one millimetre, the primary function of which is uptake of water and nutrients.

Adaptive growth - In tree biomechanics, the process whereby the rate of wood formation in the cambial zone, as well as wood quality, responds to gravity and other forces acting on the cambium. This helps to maintain a uniform distribution of mechanical stress.

Adaptive roots - The adaptive growth of existing roots; or the production of new roots in response to damage, decay or altered mechanical loading.

Adventitious shoots - Shoots that develop other than from apical, axillary, or dormant buds; see also 'epicormic'

Anchorage - The system whereby a tree is fixed within the soil, involving cohesion between roots and soil and the development of a branched system of roots which withstands wind and gravitational forces transmitted from the aerial parts of the tree.

Axil - The place where a bud is borne between a leaf and its parent shoot.

Bacteria - Microscopic single-celled organisms, many species of which break down dead organic matter, and some of which cause diseases in other organisms.

Bark - A term usually applied to all the tissues of a woody plant lying outside the vascular cambium, thus including the phloem, cortex, and periderm; occasionally applied only to the periderm or the phellem.

Basidiomycotina (Basidiomycetes) - One of the major taxonomic groups of fungi.

Bolling - A term sometimes used to describe pollard heads.

Bottle-butt - A broadening of the stem base and buttresses of a tree, in excess of normal and sometimes denoting a growth response to weakening in that region, especially due to decay.

Bracing - The use of rods or cables to restrain the movement between parts of a tree.

Branch:

- **Primary** - A first order branch arising from a trunk or stem
- **Lateral** - A second order branch, subordinate to a primary branch
- **Sub-lateral** - A third order branch, originating from lateral branch

Branch bark ridge - The raised arc of bark tissues that forms within the acute angle between a branch and its parent stem.

Branch-collar - A visible swelling formed at the base of a branch.

Brown-rot - A type of wood decay in which cellulose is degraded, while lignin is only modified.

Buckling - An irreversible deformation of a structure subjected to a bending load.

Buttress zone - The region at the base of a tree where the major lateral roots join the stem, with buttress-like formations on the upper side of the junctions.

Cambium - Layer of dividing cells producing xylem (woody) tissue internally and phloem (bark) tissue externally.

Canker - A persistent lesion formed by the death of bark and cambium due to colonisation by fungi or bacteria.

Canopy species - Tree species that mature to form a closed forest canopy.

Cleaning out - The removal of dead, crossing, weak, and damaged branches, where this will not damage or spoil the overall appearance of the tree.

Compartmentalisation - The chemical confinement of disease, decay, or other dysfunction within a trees tissue, due to passive and/or active defences operating at the boundaries of the affected region.

Compression fork - An acute angled fork that is mechanically optimised for the growth pressure that two or more adjacent stems exert on each other.

Compression strength - The ability of a material or structure to resist failure when subjected to compressive loading, measurable in trees with special drilling devices.

Compressive loading - Mechanical loading which exerts a positive pressure, the opposite to tensile loading.

Tree Protection Zone - Area from which access is prohibited for the duration of the project to prevent damage to a tree.

Crown/Canopy - The main foliage bearing section of the tree.

Crown lifting - The removal of limbs and small branches to a specified height above ground level.

Crown thinning - The removal of a proportion of secondary branch growth throughout the crown to produce an even density of foliage around a well-balanced branch structure.

Crown reduction/shaping - A specified reduction in crown size whilst preserving, as far as possible, the natural tree shape.

Crown reduction/thinning - Reduction of the canopy volume by thinning to remove selected branches whilst preserving the natural tree shape.

Deadwood - Branch or stem wood bearing no live tissues.

Decurrent - A system of branching in which the crown is borne on a number of major widely spreading limbs of similar size.

Defect - In relation to tree hazards, any feature of a tree which detracts from the uniform distribution of mechanical stress, or which makes the tree mechanically unsuited to its environment.

Delamination - The separation of wood layers along their length, visible as longitudinal splitting.

Dieback - The death of parts of a woody plant, starting at shoot-tips or root-tips.

Disease - A malfunction in or destruction of tissues within a living organism, usually excluding mechanical damage; in trees, usually caused pathogens.

Distal - In the direction away from the main body of a tree or subject organism (cf. proximal)

Dominance - In trees, the tendency for a leading shoot to grow faster or more vigorously than the lateral shoots; also, the tendency of a tree to maintain a taller crown than its neighbours.

Dormant bud - An axial bud which does not develop into a shoot until after the formation of two or more annual wood increments; many such buds persist through the life of a tree and develop only if stimulated to do so.

Dysfunction - In woody tissues, the loss of physiological function, especially water conduction, in sapwood.

DBH (Diameter at Breast Height) - Stem diameter measured at a height of 1.4 metres or the nearest measurable point. Where measurement at a height of 1.4 metres is not possible, another height may be specified.

Endophytes - Micro-organisms that live inside plant tissues without causing overt disease, but in some cases capable of causing disease if the tissues become physiologically stressed.

Epicormic shoot - A shoot having developed from a dormant or adventitious bud and not having developed from a first-year shoot.

Excrescence - Any abnormal outgrowth on the surface of tree or other organism.

Excurrent - In trees, a system of branching in which there is a well-defined central main stem, bearing branches which are limited in their length, diameter, and secondary branching (cf. decurrent).

Fastigiate - Having upright, often clustered branches.

Flush cut - A pruning cut which removes part of the branch bark ridge and or branch-collar.

Girdling root - A root which circles and constricts the stem or roots possibly causing death of phloem and/or cambial tissue.

Habit - The overall growth characteristics, shape of the tree and branch structure.

Haloing - Removing or pruning trees from around the crown of another (usually mature or post-mature) tree to prevent it becoming supressed.

Hazard beam - An upwardly curved part of a tree in which strong internal stresses may occur without being reduced by adaptive growth, prone to longitudinal splitting.

Heartwood/false-heartwood - The dead central wood that has become dysfunctional as part of the aging processes and being distinct from the sapwood.

Heave - The lifting of pavements and other structures by root diameter expansion; also, the lifting of one side of a wind-rocked root-plate.

High canopy tree species - Tree species having potential to contribute to the closed canopy of a mature forest.

Incipient failure - In wood tissues, a mechanical failure which results only in deformation or cracking, and not in the fall or detachment of the affected part.

Included bark (ingrown bark) - Bark of adjacent parts of a tree (usually forks, acutely joined branches or basal flutes) which is in face-to-face contact.

Infection - The establishment of a parasitic micro-organism in the tissues of a tree or other organism.

Internode - The part of a stem between two nodes; not to be confused with a length of stem which bear nodes but no branches.

Lever arm - A mechanical term denoting the length of the lever represented by a structure that is free to move at one end, such as a tree or individual branch.

Lignin - The hard, cement-like constituent of wood cells; deposition of lignin within the matrix of cellulose microfibrils in the cell wall is termed Lignification.

Lions tailing - When a branch of a tree that has few if any side branches except at its end and is thus liable to snap due to end-loading.

Loading - A mechanical term describing the force acting on a structure from a particular source, e.g., the weight of the structure itself or wind pressure.

Longitudinal - Along the length (of a stem, root, or branch).

Lopping - A term often used to describe the removal of large branches from a tree, but also used to describe other forms of cutting

Minor deadwood - Deadwood of a diameter less than 25mm and or unlikely to cause significant harm or damage upon impact with a target.

Mulch - Material laid down over the rooting area of plants to help conserve moisture; mulch may consist of organic matter, or artificial material.

Mycelium - The body of a fungus, consisting of branched filaments (hyphae).

Occlusion - The process whereby a wound is progressively closed by the formation of new wood and bark around it.

Pathogen - A micro-organism which causes disease in another organism.

Photosynthesis - The process whereby plants use light energy to split hydrogen from water molecules and combine it with carbon dioxide to form the molecular building blocks for synthesizing carbohydrates and other biochemical products.

Phytotoxic - Toxic to plants.

Pollarding - The removal of the tree canopy, back to the stem or primary branches, usually to a point just outside that of the previous cutting.

Primary branch - A major branch, generally having a basal diameter greater than 0.25 x stem diameter.

Probability - A statistical measure of the likelihood that a particular event might occur.

Pruning - The removal or cutting back tree parts to growth points.

Rams-horn - In connection with wounds on trees, a roll of occluding tissues which has a spiral structure as seen in cross section.

Reactive Growth/Reaction Wood - Production of woody tissue in response to altered mechanical or external loading.

Residual wall - The amount of non-decayed wood remaining following decay of internal wood

Rib - A ridge of wood that has usually developed because of locally increased mechanical loading. Often associated with internal cracking in the wood of the stem, branch, or root.

Ringbarking (girdling) - The removal of a ring of bark and phloem around the circumference of a stem or branch, normally resulting in an inability to transport photosynthetic assimilates above or below the area of damage.

Ripewood - The older central wood of those tree species in which sapwood gradually ages without being converted to heartwood.

Root-collar - The transitional area between the stem/s and roots.

Root zone - Area of soils containing absorptive roots of the tree/s described. The Primary root zone is that which we consider of primary importance to the physiological well-being of the tree.

Sapwood - Living xylem tissues.

Selective delignification - A kind of wood decay (white-rot) in which lignin is degraded faster than cellulose.

Shedding - In woody plants, the normal abscission, rotting off or sloughing of leaves, floral parts, twigs, fine roots, and bark scales.

Shrub species - Woody perennial species forming the lowest level of woody plants in a forest or garden and not normally considered to be trees.

Simultaneous white rot - A kind of wood decay in which lignin and cellulose are degraded at about the same rate.

Soft-rot - A kind of wood decay in which a fungus degrades cellulose within the cells,

Spores - Propagules of fungi; most spores are microscopic and dispersed in air or water.

Sporophore - The spore bearing structure of fungi.

Stem/s - Principle above-ground structural component(s) of a tree that supports its branches.

Stress - In plant physiology, a condition under which one or more physiological functions are not operating within their optimum range, for example due to lack of water, inadequate nutrition, or extremes of temperature: In mechanics, the application of an external force to an object.

Stringy white-rot - The kind of wood decay produced by selective delignification.

Structural roots - Roots, generally having a diameter greater than 50 millimetres, and contributing significantly to the structural support and stability of the tree.

Structural root zone (ZRZ) - The zone of the root plate most likely to contain roots that are critical for anchorage and the stability of the tree.

Subsidence - In relation to soil or structures resting in or on soil, a sinking due to shrinkage when certain types of clay soil dry out, sometimes due to extraction of moisture by tree roots.

Subsidence - In relation to branches of trees, a term that can be used to describe a progressive downward bending due to increasing weight.

Taper - In stems and branches, the degree of change in girth along a given length.

Targets - In tree risk assessment persons or property or other things of value which might be harmed or damaged by falling parts of a tree

Topping/ Lopping - In arboriculture, the removal of the crown of a tree, or of a major proportion of it.

Torsional stress - Mechanical stress applied by a twisting force.

Translocation - In plant physiology, the movement of water and dissolved materials through the body of the plant.

Transpiration - The evaporation of moisture from the surface of a plant, especially via the stomata of leaves; it exerts a suction which draws water up from the roots and through the intervening xylem cells.

Tree Protection Zone (TRZ) - This is an area left around a tree to ensure protection of the above and below ground parts of the tree during construction works. It will usually include the SRZ and is usually recommended to be fenced off for the period of the works.

Understorey - A layer of vegetation consisting of younger or smaller trees and shrubs which are adapted to grow under lower light conditions.

Understorey tree species - Tree species not having potential to attain a size at which they can contribute to the closed high canopy of a forest or garden.

Vascular wilt - A type of plant disease in which water-conducting cells become dysfunctional.

Vessels - Water-conducting cells in plants, usually wide and long for hydraulic efficiency; generally, not present in coniferous trees.

Vigour - The expression of carbohydrate expenditure to growth (in trees).

Vitality - A measure of physiological condition.


White-rot - A range of kinds of wood decay in which lignin, usually together with cellulose and other wood constituents, is degraded.

Wind exposure - The degree to which a tree or other object is exposed to wind, both in terms of duration and velocity.

Windthrow - The blowing over of a tree at its roots.

Woundwood - Wood with atypical anatomical features, formed in the vicinity of a wound.

11.0Appendices – QTRA Risk Thresholds



12.0 References

Mattheck, C. and Breloer, H. 1994. The body language of trees - a handbook for failure analysis. The Stationery Office, London England. p 11- 21, 22 – 27, 39, 60 – 65, 130 – 136, 171 – 172.

Harris, R, H. Clark, J, R. Matheny, N, P. 2004 Arboriculture, Integrated management of Trees, Shrubs, and vines. Pearson education, Upper Saddle River, New Jersey, USA. p 162, 351.

Lonsdale, D. 1999, 2010 Principles of Tree Hazard Assessment and Management. The Stationary Office, London England. PG: 149-150.

Shigo, A, L. 1979. Tree Decay; An expanded Concept. USDA Forest Service Agricultural Information. Bulletin No 419.

Duiker, S, W. 2002. Diagnosing Soil Compaction using a Penetrometer. Penn State College of Agricultural Science Research. Pennsylvania, USA.

Day, S.D. and Bassuk, N.L. 1994. Soil Compaction: A Review of the effects of soil compaction and amelioration treatments on landscape trees. Journal of Arboriculture. Vol 20 No 1 p 9-17.

Ganesson, S. 1995 Plant Pathology 202. Challenger Institute of Technology, Murdoch. Perth, Western Australia, Pg: 81 to 93.

Dunster, J, A, A. Smiley, T. Matheny, N. Lilly, S. (2013) Tree Risk Assessment Manual. International society of Arboriculture. Champaign Illinois, USA. p 29, 67 – 71, 74 – 84, 88 – 95.

Fay, N. 2007 Defining and Surveying Veteran and Ancient Trees, UK Biodiversity Action plan. England.

Smith, K, D. May, P, B. Moore, G, M. 2001. The Influence of Compaction and soil Strength on the Establishment of four Australian Landscape Trees, Journal of Arboriculture Vol 27 No 1.

Ellison, M. (2010). Quantified Tree Risk Assessment – Licensed User Manual, Quantified Tree Risk Assessment Ltd, Poynton, England.

Standards Australia. AS 4373 – 2007 Pruning of amenity Trees, Sydney, Australia.

Standards Australia. AS 4970 – 2009 Protection of Trees on Development Sites.

13.0 Disclaimer and Limitations

a. References in this report to the “Consultant” means the person listed on the cover page as an employee of Westworks Consultancy.
b. References in this report to Westworks Consultancy means Westworks Group Pty Ltd as trustee for Ussheridan Trust trading as Westworks Consultancy (ACN 156 131 010 ABN 46 156 131 010).
c. In this report a reference to a group of persons includes a reference to all of them collectively, any two or more collectively and each of them individually.
d. The releases and limitations in this report apply to the Arborist, Westworks Consultancy and any employees, directors, contractors, and agents of the Arborist and/or Westworks Consultancy.
e. This report only covers identifiable defects present at the time of inspection. The Arborist and Westworks Consultancy accept no responsibility and cannot be held liable for any structural defect or unforeseen event/situation that may occur after the time of inspection.
f. The Arborist and Westworks Consultancy cannot and do not guarantee trees contained within this report will be structurally sound under all circumstances and cannot and do not guarantee that the recommendations made will categorically result in the tree being made “safe.” Unless specifically mentioned this report will only be concerned with above ground inspections, that will be undertaken visually from ground level.
g. Trees are living organisms and as such cannot be classified as “safe” under any circumstances.
h. Failure events can occur for any number of reasons at any time and cannot always reasonably be foreseen, as any number of circumstances can come about at any time before or after an inspection that the Arborist and Westworks Consultancy may not be aware of.
i. All recommendations are made based on what can be reasonably identified at the time of inspection therefore the author accepts no liability for any recommendations made.
j. Care has been taken to obtain all information from reliable sources. All data has been verified or as much as possible; however, the Arborist and Westworks Consultancy can neither guarantee nor be responsible for the accuracy of information provided by others.
k. Booking of re-assessment after the prescribed period is the responsibility of the land manager/owner only. The Arborist and Westworks Consultancy are not responsible for providing reminders or notification that re assessment may be due and will not be held responsible to reinspect the listed trees until requested.
l. The Arborist and Westworks Consultancy make no express warranties under this report.
m. Except as the report specifically states, or as contained in any express warranty provided in relation to any goods or services provided or to be provided, the report does not include by implication any other term, condition, or warranty in respect of the quality, merchantability, acceptability, fitness for purpose, condition, description, assembly, manufacture, design or performance of the goods or services or any contractual remedy for their failure.
n. If the client is a consumer nothing in the Repot restricts, limits, or modifies the client's rights or remedies against Westworks Consultancy for failure of a statutory guarantee under the ACL save to the extent lawfully permissible.
o. To the greatest extent permitted under law the Arborist and Westworks Consultancy are not liable to the client or any third party in any way under or in connection with the Report or in connection with the goods or services provided by them to the client or any third party.
p. To the greatest extent permitted under law the Arborist and Westworks Consultancy are not liable for any indirect or consequential losses or expenses suffered by the client or any third party, howsoever caused, including but not limited to loss of turnover, profits, business or goodwill or any liability to any other party.
q. The client expressly acknowledges and agrees that:
    i. it has not relied upon, any service involving skill and judgement, or on any advice, recommendation, information, or assistance given by the Arborist or Westworks Consultancy, their agents, contractors, or employees in relation to any goods or services or their use or purpose.
    ii. it has not made known, whether expressly or by implication, to the Arborist and Westworks Consultancy any purpose for which it requires the goods or services and it has the sole responsibility of satisfying itself that any goods or services as suitable for the use of the client.
    iii. nothing in this Report is to be interpreted as excluding, restricting, or modifying the application of any non-excludable State or Federal legislation applicable to the sale of goods or supply of service.
    iv. Any reinspection is the responsibility of the tree owner to arrange as required.
    v.

Tree Protection Report

Location: Armadale Line Upgrade

Report Prepared for: ALUA

Date: 13/05/22

Mark Short
Grad Cert Arboriculture

Arboricultural Consultant
Westworks Consultancy
PO Box 173
Mundijong WA 6121
Mobile: 0417 011 426
mark@westworksconsultancy.com.au
www.westworksconsultancy.com.au
QTRA Licensed user 2290

Contents

1.0 Introduction 2
2.0 Location of Subject Trees – Zone A 3
2.1 Location of Subject Trees – Zone B 4
2.2 Location of Subject Trees – Zone C 5
2.3 Location of Subject Trees – Zone D 6
3.0 Discussion 7
4.0 Tree Protection and Excavation Methodology 8
5.0 Tree Protection Measures within the TPZ & SRZ 10
6.0 Conclusion 17
7.0 Recommendations 17
8.0 Glossary of Arboricultural Terminology 18
9.0 Appendices 21
9.1 QTRA Risk Thresholds 21
10.0 References 22
11.0 Disclaimer and Limitations 23

1.0 Introduction

An assessment was undertaken on a variety of trees within the ALUA project area that stretches from Lacey street in Beckenham, north, to Miller Street in East Victoria Park.

For ease of pick up and identification the area has been divided into 4 zones.

Zone A is west of the Rail tracks and runs from Lacey Street to Leach highway, 36 trees were picked up in this zone.

Zone B is east of the rail and also runs from Lacey Street to Leach highway, this zone has 42 trees.

Zone C is west of the tracks and runs from Leach Highway to Miller Street in East Victoria Park, it contains 474 trees.


Zone D, runs from Leach highway to Miller Street, and is east of the tracks with 469 trees

A Tree Survey Report have been prepared for Zone A and B and another for Zone C and D, which should be referred to whilst reading this document.

The purpose of this document is to provide tree protection advice that will be applicable for the duration of the Armadale Line upgrade project and should be referred to in the event of works of any kind being undertaken near trees and grass trees

2.0 Location of Subject Trees – Zone A

Subject tree marked with coloured dots to reference species



2.1 Location of Subject Trees – Zone B



2.2 Location of Subject Trees – Zone C



2.3 Location of Subject Trees – Zone D



3.0 Discussion

Of the 1021 trees assessed from Lacey Street to Miller Street, the main works found to be required is pruning to remove deadwood over 25mm in diameter and lifting of the canopies. The majority of these trees have been backed by a fence line and the rail corridor. They have seemingly been left with low foliage for the purpose of screening the rail corridor and reducing noise.

Uplifting of these verge trees will assist with the overall vision of the creation of new public open spaces. It will improve sightlines through the area and improve passive surveillance, whilst removal of deadwood will reduce the level of enquiry from the public about concerns over the level of risk.

The level of risk across the surveyed tree population was found to be “Bradley Acceptable” in terms of where risk from trees in imposed upon others. In this regard there was not any significant pruning found to be required in order to reduce the level of risk from the surveyed trees.

Within Zone A there are 20 Jacarandas adjacent the current Bus Interchange area that are established specimens that would compliment a future open space.

Within Zone B, and also around the Cannington Train Station are 5 *Brachychiton acerifolius* and 4 *Brachychiton populneus* that are good specimens that are recommended to be retained in situ due to their good condition and aesthetic value. Tree 1 and 3 (Marri and Maculata) are good specimens that should ideally remain in situ, whereas tree 4 and 6 (Marri’s) have been heavily pruned over a number of years to provide clearance to the OLE, with the removal of the OLE and a reduced pruning regime, they can be assisted with reforming their canopies.

Trees 8 and 11 (Flooded Gum) are large specimen that would provide food sources for birds and should remain in situ.

Zone C: At the Leach Highway end of Zone C, trees 1, 2, 3, 4, 5, 6, 8, 10, 15 and 17 are suffering from nutrient deficiencies and should be treated with 500 litres of water with Bioprime mixed at 1%, additionally the grass should be removed from around their trunks to a radius of 3m and replaced with mulch. These trees will need to be reinspected after 1 months and retreated every 6 weeks. In this section there are 5 Melaleuca that could be transplanted, the appropriate time requirements for root preparation and the cost need to be considered against the cost of buying advanced stock that can be brought to site and planted within a smaller period and with lower ongoing maintenance requirements.

Within Zone D there are 39 Cook Pines that are in good health and will continue to contribute to the amenity of the area as they are literally standout specimens due to their size, the removal of some smaller shrubs around these could be undertaken to highlight these even more. Tree 291 is a remnant Marri located adjacent to Oats Street Station, this tree will require full protection in line it the advice provided below during demolition and construction works.

4.0 Tree Protection and Excavation Methodology

The Australian standard for Protection of trees on development sites, AS 4970 – 2009, serves to set out protection measures for trees on construction sites during the period of construction and is comprised of two zones.

The first is the Tree Protection Zone (TPZ) (Diagram 1) which considers protection of the canopy and roots. In which it is ideal that no plant and equipment enter in order to prevent any damage to the canopy of the tree and damage to the roots through excavation works.

All design considerations should ideally allow for the TPZ in the first instance. Only falling to the second zone when absolutely necessary. With works taking place within the TPZ under the supervision of the Project Arborist.




Diagram 1

The second is the Structural Root Zone (SRZ) which is ultimately a no dig zone for excavation works in instances where it is found that there is an absolute need to dig within the TPZ. Please note that the TPZ is inclusive of the SRZ measurement. Even when working outside of the TPZ, it is important that any excavation works conducted around these trees is done in a radial pattern and not across the root plate of the trees (Diagram 2).

Where soil removal is required to take place from the start of the TPZ up to the edge of the SRZ, this is best undertaken using vacuum extraction as it causes less damage to roots that might be present. This process can also be used to remove soil, allowing for replacement with a structural soil mix or landscape mix with improved water and nutrient holding capacity.

Mechanical equipment should ideally not be used to dig in the TPZ, as they tend to dig across a root plate and catch any roots in their path and pull against them. This action leads to damage further along the root and fracturing at the root crown where the root joins onto the base of the tree. This can lead to death of the root and decline or even death of the tree. If mechanical equipment is used, it should ideally only be for hard digging where absolutely necessary. This will require scraping radially along the surface to gradually expose roots, allowing them to be cut cleanly (Diagram 2). This reduces the possibility of significant damage occurring and will help to maintain the good condition of the trees into the future.

All staff and contractors undertaking any form of excavation would be required to follow this process and may only cut roots smaller than 50mm in diameter that are found outside of the TPZ. Any requirement to cut roots larger than this should be deferred to the Project Arborist for advice. Where pruning of roots is undertaken, this must be done using a sharp saw or bypass secateurs that have been cleaned with Methylated spirits or a 10% bleach solution before and after pruning. Roots are not to be torn, pulled, or cut with an axe.




Diagram 2

The accompanying reports provides Tree Protection Zone (TPZ) and Structural Root Zone measurements (SRZ). Which are to be observed for all trees. With regards to grass trees a standard 2m TPZ should be implemented for all Grass trees regardless of their size.

Should any works need to be undertaken within the TPZ, it is recommended that the Project Arborist is consulted prior to works being undertaken in order to provide guidance. This is especially important for any form of soil movement and excavation.

Where any work is undertaken up to the TPZ area, it is important that this is still done in a considered manner after consultation with the Project Arborist.

5.0 Tree Protection Measures within the TPZ & SRZ

Within the Tree Protection Zones (TPZ) and Structural Root Zones (SRZ) for each tree, site workers and contractors are NOT to allow the following to occur.

- Mechanical excavation including trenching without consulting the site Arborist.
- Excavation for silt fencing.
- Cultivation.
- Storage.
- Preparation of chemicals, including preparation of cement products.
- Parking of vehicles and plant.
- Refuelling.
- Dumping of waste.
- Placement of fill.
- Lighting of fires.
- Soil level changes.
- Temporary or permanent installation of utilities and signs.
- Physical damage to the tree.

TPZ control measures

- Where practical, always trench outside the TPZ. Impacting more than 10% of the TPZ can affect the long-term health of the tree.
- Where it is not possible to work outside the TPZ and an encroachment of more than 10% is required the site Arborist must be contacted prior further works being completed.
- Within the TPZ, minimise the extent impacted and for significant encroachments, under bore/directional drill at least 600 mm beneath the ground surface, or if excavating, hand dig or use an air spade or vacuum excavation.
- Always where possible, establish and work outside the TPZ. Fence off the TPZ to avoid physical damage to trees.


6.1.1 INSTALLATION OF UNDERGROUND SERVICES WITHN THE TPZ

All services should be routed outside the TPZ. If underground services must be routed within the TPZ, they should be installed by Horizontal directional drilling, the directional should be a minimum depth of 600 mm. With start and finish holes being placed outside of the TPZ

For manual excavation of trenches, the project arborist should advise on roots to be retained and should monitor the works. Manual excavation may include the use of pneumatic and hydraulic tools.

5.1.2 TREE PROTECTION FENCING

An exclusion zone should be established along the TPZ perimeters of retained trees and cordoned off with a physical barrier of ridged chain mesh fence, 1.8m in height, which is securely anchored. The role of these fences is to prevent any damage to the complete tree including root system (SRZ & TPZ), stem and branch structure as well as the crown or canopy.





The Project Arborist must be consulted at any time entry into a TPZ of the retained trees is required. No routing of services, parking of vehicles, stacking of materials, equipment etc. is to occur within the TPZ of retained tree/s, nor disposal of fuels, paints, chemicals, or any other waste product is to occur within the protected TPZ area. Nor any other activity which could otherwise cause injury and/or adversely affect the health of a retained tree.

5.1.3 ACTIVITY OUTSIDE THE TREE PROTECTION ZONE (TPZ)

Planning of site operations should take sufficient account of wide loads, tall loads and plant with booms, jibs, and counterweights (including piling rigs), in order that they can operate without coming into contact with retained trees. Such contact can result in serious damage to the trees and might make their safe retention impossible. Consequently, any transit or traverse of plant in proximity to trees should be conducted under supervision/spotter, to ensure that adequate clearance from trees is maintained at all times.

Additional precautions outside the exclusion zone - Materials whose accidental spillage would cause damage to a tree should be stored and handled well away from the outer edge of its TPZ.

5.1.4 AVOIDING PHYSICAL DAMAGE TO ROOTS

To avoid damage to tree roots, existing ground levels should be retained within the TPZ. Intrusion into soil (other than for piling) within the TPZ is generally not acceptable, and topsoil within it should be retained in situ. However, limited manual excavation within the TPZ might be acceptable, subject to justification. Such excavation should be undertaken carefully, using hand-held tools and preferably by compressed air soil displacement or vacuum excavation.

Roots, whilst exposed, should immediately be wrapped, or covered to prevent desiccation and to protect them from rapid temperature changes. Any wrapping should be removed prior to backfilling, which should take place as soon as possible, roots should not be exposed for any more than 8hrs exposure.

Roots smaller than 5o mm diameter may be pruned back, making a clean cut with a suitable sharp tool (e.g., secateurs or handsaw), except where they occur in clumps. Roots occurring in clumps or greater than 50mm diameter over may be able to be be severed only following

consultation with the project Arborist, as these roots might be essential to the tree's health and stability.

Prior to backfilling, retained roots should be surrounded with topsoil or uncompacted sharp sand (builders' sand should not be used because of its high salt content, which is toxic to tree roots), or other loose inert granular fill, before soil or other suitable material is replaced. This material should be free of contaminants and other foreign objects potentially injurious to tree roots.

5.1.5 Soil and base materials

New soil used to raise existing soi levels should have a low clay content, the Richgro Native soil mix is recommended as it uses a large grain sand that maintains large open pore spaces, which is ideal for reduced compaction and allows air and water to enter.

Application of the new soil should be done to ensure that it covers any fibrous roots but should not be placed within 300mm of the trunk, and not be applied to a thickness greater than 100mm above the existing soil level.

Any new soil or base materials used for construction purposed, such as crushed limestone, brickies sand, or gravels, which will be placed on the site must be certified pathogen free. This is to ensure that pest, disease, or fungi are not transported to the site and infect the trees.

5.1.6 Mulch

Any mulch used should also be certified pathogen free.
A basic woodchip mulch is best over other processed mulches, however, due to the nature of the development, Pine bark is recommended for use. This is due to its aesthetic appeal, ease of maintenance and ability to remain open, uncompacted and highly porous.

It is important to avoid highly processed landscape mulches that have fine particles, as they tend to become very compacted and form a hardpan layer over the summer period, which prevents the free movement of oxygen and water infiltration come winter.

It is preferable that mulch zones be created around all trees over the placement of lawn.

Lawn competes with trees to the point that they can gather nutrients and water in the top layers of soil before it can filter to the tree's roots below. Also, lawn encourages foot traffic, which, in turn, leads to compaction over root plates. Whereas mulch discourages people from walking across an area. The SRZ measurement are a good guide for the size of the mulch zone for a tree.

5.1.7 Supplemental watering, liquid fertilising, and irrigation

For the duration of construction, where any excavation is being undertaken with in the TPZ of any tree, it should be provided with supplemental water. This can be achieved with an application by a water truck and the process can be sped up, by installing temporary poly systems, using multiple bubblers, 2 bubblers for a small tree (up to 5m) 4 for a medium size tree (5 to 15. and 6 to 10 for large trees (15m+)

The adjacent chart should be followed.

A treatment of 500 litres of water with Bioprime trace combined with Bailey's liquid Grosorb (Mix rate 10%) should be undertaken on trees 1, 2, 3, 4, 5, 6, 8, 10, 15 and 17 prior to construction beginning to help with nutrient deficiencies that have been observed. This would then need to be repeated every 6 weeks during the period of construction and for one summer after completion.

Watering Regime for Small Trees

Time period	Volume	Frequency
15 Oct to 1 May	100 L	every second day
2 May to 1 July	75 L	every second day
2 July to 15 Sept	50 L	every third day - do not water on days of heavy rain fall
16 Sept to 15 Oct	75	Every second day

Watering Regime for Medium Trees

Time period	Volume	Frequency
15 Oct to 1 May	200 L	every second day
2 May to 1 July	100 L	every second day
2 July to 15 Sept	50 L	every third day - do not water on days of heavy rain fall
16 Sept to 15 Oct	150	Every second day

Watering Regime for Large Trees

Time period	Volume	Frequency
15 Oct to 1 May	400 L	every second day
2 May to 1 July	200 L	every second day
2 July to 15 Sept	100 L	every second day - do not water on days of heavy rain fall
16 Sept to 15 Oct	250	Every second day

Permanent irrigation will be highly beneficial for the long-term health and appearance of the trees, especially new plantings, as it will assist greatly in encouraging the trees to increase density in their canopies and improve their appearance.

5.1.8 Hardstand areas

It would be advantageous for the long-term health of all trees (even those yet to be planted) if a permeable material were used for all footpaths and car parking areas. Permeable materials would allow water and oxygen to enter the soil assisting with root growth and overall tree health.

Midland Brick, for instance, produce an aesthetic, highly effective permeable range of pavers, with low maintenance requirements that suit many applications. Alternatively, there are permeable asphalts and concretes. Permeable surfaces will also assist with water capture into the ground water table.

In addition to using a permeable or semi permeable hardstand, structural soil or root cells can be installed beneath these areas to form open root zone. The following methodology, then acts as a workable base for laying paving or other surfaces.

Structural Soil

Structural soils are effectively a landscape mix that contain, binding agents and very large aggregate materials which take load and compaction, whilst maintaining large spaces between them and prevent the soil media from becoming compacted.

On top of either structural soils or strata cells. two topping layers of finer gravel are used to support the paving. The first is a 10mm washed gravel that is laid 50mm thick over the structural soil or cells. The second and final layer is a 3 to 5mm washed gravel, also 50mm deep, this layer can be compacted and screeded which allows the paving to be laid directly onto it.

It is imperative that sand is not added to any of these layers, as it will clog the open spaces between the gravel and cause compaction. This will prevent the system from working properly.

Each layer of gravel will maintain open pore spaces due to its angular nature. This will then provide uncompacted, aerated soil for root growth and reduce upward root growth by roots that are normally searching for oxygen, as they will be able to freely move downwards into the root cells or structural soil and not upwards because of the higher oxygen content lower down in the soil profile.



This photo shows the good quality of root growth in structural soils

Root/Strata Cells

Root cells are effectively open plastic cubes or rectangle boxed that are load barring and are installed below ground level to support a hard trafficable surface above. The cells are filled with a soil media that does not become compacted and conduits for services can be laid through them.




A Tree being planted with root cells around it, the pavement is then installed around the tree, over the cells

Raised walkways can also be considered, as they leave open soil that can absorb oxygen and water.

Where structural soils and or root cells are used in combination with permeable surfaces, this has been proven to provide for larger healthier trees that are longer lived with a low risk od harm, additionally, these methods lead to less root disturbance to infrastructure over the life of the tree.

All hardstand areas should have a 1% fall towards garden beds and tree pits to utilise rainwater run off to a greater extent.




A diagram with root cells, a tree and conduits installed

5.1.9 Pruning


Where the pruning of any tree is undertaken, this must be performed by an AQF level 3 Arborist. Unqualified persons must not prune any part of a tree, nor should they rip or tear any part of a tree.

The Arborist must use sharp and appropriately maintained pruning equipment that has been sterilised with either a 10% bleach solution or methylated spirits prior to starting work on any tree. This includes multiple trees, where sterilisation should take place between each tree. The sterilisation of pruning equipment is especially important to prevent the spread of diseases such as *Quambalaria coreycup* between the *Eucalyptus* and *Corymbia' s.*

All pruning must be undertaken in accordance with the Australian Standard of Amenity Pruning (AS4373 – 2007) (Branch pruning diagram exert shown to the right)



Pruning is best undertaken in the spring months, when sap flow and general tree growth is active, pruning requirements other than the uplifting and deadwood removal already specified will need to be assessed as the design progresses.



5.1.10 Tree Removal

Where any tree is removed, this should be undertaken in a manner that prevents damage occurring to adjacent trees that are to remain in situ. Additionally, is the stump of a removed tree being within the TPZ of another remaining tree, stump grinding should only be undertaken to reduce the stump to no more than 50mm below ground level, this is to prevent damage to the remaining tree's root systems.

5.1.11 Site Induction

The purpose of the Tree Protection Zone should be included in the Site Induction for all ALUA sites. This is to ensure that all staff and contractors are aware of the purpose of the zone, fencing and are aware of the rules around this zone.

5.1.12 Site Inspection (By Project Arborist)

It is most ideal that given consideration for the level of work that will be undertaken across this site, that a site inspection be undertaken at a minimum of once a month.

Consultation and additional site visits are to be scheduled where there are excavation works being undertaken within the TPZ of all tree species, but especially for the following species:

- *Araucaria columnaris*
- *Corymbia calophylla*
- *Corymbia ficifolia*
- *Eucalyptus maculata*
- *Eucalyptus camaldulensis*
- *Eucalyptus citriodora*
- *Eucalyptus marginata*
- *Eucalyptus rudis*
- *Xanthohhhoea sp*

5.1.13 Spotters for clearing

Spotters will be required when removing any of the following , low, dense, shrub species.

- *Chamelaucium uncinatum*
- *Adenanthos cygnorum*
- *Jacksonia fercillata*
- *Petrophilie linearis*
- *Leptospermum laevigatum*

A spotter will also be required when removing or transplanting any Grass Trees

A list of locations of these species is provided as a separate appendix to this report and the accompanying Tree Survey Reports, in excel format.

6.0 Conclusion

There are many well established tree specimens that will significantly contribute towards the revitalised landscape and community spaces. The observation of excavation and care methodology in this document will ensure that these trees continue to contribute to the streetscape and ecological environment for a number of years to come.

A crucial element of tree protection for this project will be minimising the extent that plant and equipment travel over the root zones of trees, where this can be minimised, or more importantly, excluded, this will prevent soil compaction over root zones. Soil compaction is a major cause in tree decline, as it excludes important oxygen from the soil that contributes to healthy tree growth. The other main issue experienced in construction project are strikes to trees from ground-based plant and strikes from lifting equipment, which often break branches.

The creation of tree protection zones is essential in preventing all of these issues that have long term impacts to tree health.

It is encouraged that all trees are maintained in situ and minimal removals are undertaken, as established trees make a considerable impact upon an area, where it takes many years to achieve a similar feel and ambience from newly planted stock. It is however recommended to remove the masses of Chamelaucium and Leptospermum (Geraldton Wax and Victorian Tea Tree) that line the rail corridor, as this is exclusive to other plant species, harbours rubbish and creates areas that enable undesirable activities.

7.0 Recommendations

- Tree Protection fencing should be erected around all trees to be retained.
- All construction work within the TPZ of any retained tree should always be authorised & supervised by the site Arborist.
- Any demolition and excavation must be undertaken in line with the methodology described in section 4.0
- Addition of new soil and replanting must be conducted with due care. There shall be no use of strip style excavation adjacent to or within the TPZ of any retained tree, e.g., for removal of topsoil, installation of boundary fencing, future foundations, installation of services, kerb/roadside guttering etc.
- It is imperative that TPZ fencing protection measures are installed for the protection of all retained trees prior to the commencement of the future construction phase, and that it remains in situ for the duration and until completion of proposed construction works.
- TPZ fencing and other measures must be fixed so that they cannot be moved either by accidental physical impact or other inadvertent means. There should be no entry within any TPZ by any construction crew or other persons during the construction phase without authorisation and/or attendance of the site Arborist.
- Watering of trees is to occur where excavation takes place within their TPZ, or immediately on the edge of the TPZ, in line with the watering table in section 5.1.7 and is to continue for at least one summer after construction is complete.

8.0 Glossary of Arboricultural Terminology

Abscission - The shedding of a leaf or other short-lived part of a woody plant, involving the formation of a corky layer across its base; in some tree species twigs can be shed in this way.

Abiotic - Pertaining to non-living agents, e.g., environmental factors.

Absorptive roots - non-woody, short-lived roots, generally having a diameter of less than one millimetre, the primary function of which is uptake of water and nutrients.

Adaptive growth - In tree biomechanics, the process whereby the rate of wood formation in the cambial zone, as well as wood quality, responds to gravity and other forces acting on the cambium. This helps to maintain a uniform distribution of mechanical stress.

Adaptive roots - The adaptive growth of existing roots; or the production of new roots in response to damage, decay or altered mechanical loading.

Adventitious shoots - Shoots that develop other than from apical, axillary, or dormant buds; see also 'epicormic'

Anchorage - The system whereby a tree is fixed within the soil, involving cohesion between roots and soil and the development of a branched system of roots which withstands wind and gravitational forces transmitted from the aerial parts of the tree.

Axil - The place where a bud is borne between a leaf and its parent shoot.

Bacteria - Microscopic single-celled organisms, many species of which break down dead organic matter, and some of which cause diseases in other organisms.

Bark - A term usually applied to all the tissues of a woody plant lying outside the vascular cambium, thus including the phloem, cortex, and periderm; occasionally applied only to the periderm or the phellem.

Basidiomycotina (Basidiomycetes) - One of the major taxonomic groups of fungi.

Bolling - A term sometimes used to describe pollard heads.

Bottle-butt - A broadening of the stem base and buttresses of a tree, in excess of normal and sometimes denoting a growth response to weakening in that region, especially due to decay.

Bracing - The use of rods or cables to restrain the movement between parts of a tree.

Branch:

- **Primary** - A first order branch arising from a trunk or stem
- **Lateral** - A second order branch, subordinate to a primary branch
- **Sub-lateral** - A third order branch, originating from lateral branch

Branch bark ridge - The raised arc of bark tissues that forms within the acute angle between a branch and its parent stem.

Branch-collar - A visible swelling formed at the base of a branch.

Brown-rot - A type of wood decay in which cellulose is degraded, while lignin is only modified.

Buckling - An irreversible deformation of a structure subjected to a bending load.

Buttress zone - The region at the base of a tree where the major lateral roots join the stem, with buttress-like formations on the upper side of the junctions.

Cambium - Layer of dividing cells producing xylem (woody) tissue internally and phloem (bark) tissue externally.

Canker - A persistent lesion formed by the death of bark and cambium due to colonisation by fungi or bacteria.

Canopy species - Tree species that mature to form a closed forest canopy.

Cleaning out - The removal of dead, crossing, weak, and damaged branches, where this will not damage or spoil the overall appearance of the tree.

Compartmentalisation - The chemical confinement of disease, decay, or other dysfunction within a trees tissue, due to passive and/or active defences operating at the boundaries of the affected region.

Compression fork - An acute angled fork that is mechanically optimised for the growth pressure that two or more adjacent stems exert on each other.

Compression strength - The ability of a material or structure to resist failure when subjected to compressive loading, measurable in trees with special drilling devices.

Compressive loading - Mechanical loading which exerts a positive pressure, the opposite to tensile loading.

Tree Protection Zone - Area from which access is prohibited for the duration of the project to prevent damage to a tree.

Crown/Canopy - The main foliage bearing section of the tree.

Crown lifting - The removal of limbs and small branches to a specified height above ground level.

Crown thinning - The removal of a proportion of secondary branch growth throughout the crown to produce an even density of foliage around a well-balanced branch structure.

Crown reduction/shaping - A specified reduction in crown size whilst preserving, as far as possible, the natural tree shape.

Crown reduction/thinning - Reduction of the canopy volume by thinning to remove selected branches whilst preserving the natural tree shape.

Deadwood - Branch or stem wood bearing no live tissues.

Decurrent - A system of branching in which the crown is borne on a number of major widely spreading limbs of similar size.

Defect - In relation to tree hazards, any feature of a tree which detracts from the uniform distribution of mechanical stress, or which makes the tree mechanically unsuited to its environment.

Delamination - The separation of wood layers along their length, visible as longitudinal splitting.

Dieback - The death of parts of a woody plant, starting at shoot-tips or root-tips.

Disease - A malfunction in or destruction of tissues within a living organism, usually excluding mechanical damage; in trees, usually caused pathogens.

Distal - In the direction away from the main body of a tree or subject organism (cf. proximal)

Dominance - In trees, the tendency for a leading shoot to grow faster or more vigorously than the lateral shoots; also, the tendency of a tree to maintain a taller crown than its neighbours.

Dormant bud - An axial bud which does not develop into a shoot until after the formation of two or more annual wood increments; many such buds persist through the life of a tree and develop only if stimulated to do so.

Dysfunction - In woody tissues, the loss of physiological function, especially water conduction, in sapwood.

DBH (Diameter at Breast Height) - Stem diameter measured at a height of 1.4 metres or the nearest measurable point. Where measurement at a height of 1.4 metres is not possible, another height may be specified.

Endophytes - Micro-organisms that live inside plant tissues without causing overt disease, but in some cases capable of causing disease if the tissues become physiologically stressed.

Epicormic shoot - A shoot having developed from a dormant or adventitious bud and not having developed from a first-year shoot.

Excrescence - Any abnormal outgrowth on the surface of tree or other organism.

Excurrent - In trees, a system of branching in which there is a well-defined central main stem, bearing branches which are limited in their length, diameter, and secondary branching (cf. decurrent).

Fastigiate - Having upright, often clustered branches.

Flush cut - A pruning cut which removes part of the branch bark ridge and or branch-collar.

Girdling root - A root which circles and constricts the stem or roots possibly causing death of phloem and/or cambial tissue.

Habit - The overall growth characteristics, shape of the tree and branch structure.

Haloing - Removing or pruning trees from around the crown of another (usually mature or post-mature) tree to prevent it becoming supressed.

Hazard beam - An upwardly curved part of a tree in which strong internal stresses may occur without being reduced by adaptive growth, prone to longitudinal splitting.

Heartwood/false-heartwood - The dead central wood that has become dysfunctional as part of the aging processes and being distinct from the sapwood.

Heave - The lifting of pavements and other structures by root diameter expansion; also, the lifting of one side of a wind-rocked root-plate.

High canopy tree species - Tree species having potential to contribute to the closed canopy of a mature forest.

Incipient failure - In wood tissues, a mechanical failure which results only in deformation or cracking, and not in the fall or detachment of the affected part.

Included bark (ingrown bark) - Bark of adjacent parts of a tree (usually forks, acutely joined branches or basal flutes) which is in face-to-face contact.

Infection - The establishment of a parasitic micro-organism in the tissues of a tree or other organism.

Internode - The part of a stem between two nodes; not to be confused with a length of stem which bear nodes but no branches.

Lever arm - A mechanical term denoting the length of the lever represented by a structure that is free to move at one end, such as a tree or individual branch.

Lignin - The hard, cement-like constituent of wood cells; deposition of lignin within the matrix of cellulose microfibrils in the cell wall is termed Lignification.

Lions tailing - When a branch of a tree that has few if any side branches except at its end and is thus liable to snap due to end-loading.

Loading - A mechanical term describing the force acting on a structure from a particular source, e.g., the weight of the structure itself or wind pressure.

Longitudinal - Along the length (of a stem, root, or branch).

Lopping - A term often used to describe the removal of large branches from a tree, but also used to describe other forms of cutting

Minor deadwood - Deadwood of a diameter less than 25mm and or unlikely to cause significant harm or damage upon impact with a target.

Mulch - Material laid down over the rooting area of plants to help conserve moisture; mulch may consist of organic matter, or artificial material.

Mycelium - The body of a fungus, consisting of branched filaments (hyphae).

Occlusion - The process whereby a wound is progressively closed by the formation of new wood and bark around it.

Pathogen - A micro-organism which causes disease in another organism.

Photosynthesis - The process whereby plants use light energy to split hydrogen from water molecules and combine it with carbon dioxide to form the molecular building blocks for synthesizing carbohydrates and other biochemical products.

Phytotoxic - Toxic to plants.

Pollarding - The removal of the tree canopy, back to the stem or primary branches, usually to a point just outside that of the previous cutting.

Primary branch - A major branch, generally having a basal diameter greater than 0.25 x stem diameter.

Probability - A statistical measure of the likelihood that a particular event might occur.

Pruning - The removal or cutting back tree parts to growth points.

Rams-horn - In connection with wounds on trees, a roll of occluding tissues which has a spiral structure as seen in cross section.

Reactive Growth/Reaction Wood - Production of woody tissue in response to altered mechanical or external loading.

Residual wall - The amount of non-decayed wood remaining following decay of internal wood

Rib - A ridge of wood that has usually developed because of locally increased mechanical loading. Often associated with internal cracking in the wood of the stem, branch, or root.

Ringbarking (girdling) - The removal of a ring of bark and phloem around the circumference of a stem or branch, normally resulting in an inability to transport photosynthetic assimilates above or below the area of damage.

Ripewood - The older central wood of those tree species in which sapwood gradually ages without being converted to heartwood.

Root-collar - The transitional area between the stem/s and roots.

Root zone - Area of soils containing absorptive roots of the tree/s described. The Primary root zone is that which we consider of primary importance to the physiological well-being of the tree.

Sapwood - Living xylem tissues.

Selective delignification - A kind of wood decay (white-rot) in which lignin is degraded faster than cellulose.

Shedding - In woody plants, the normal abscission, rotting off or sloughing of leaves, floral parts, twigs, fine roots, and bark scales.

Shrub species - Woody perennial species forming the lowest level of woody plants in a forest or garden and not normally considered to be trees.

Simultaneous white rot - A kind of wood decay in which lignin and cellulose are degraded at about the same rate.

Soft-rot - A kind of wood decay in which a fungus degrades cellulose within the cells,

Spores - Propagules of fungi; most spores are microscopic and dispersed in air or water.

Sporophore - The spore bearing structure of fungi.

Stem/s - Principle above-ground structural component(s) of a tree that supports its branches.

Stress - In plant physiology, a condition under which one or more physiological functions are not operating within their optimum range, for example due to lack of water, inadequate nutrition, or extremes of temperature: In mechanics, the application of an external force to an object.

Stringy white-rot - The kind of wood decay produced by selective delignification.

Structural roots - Roots, generally having a diameter greater than 50 millimetres, and contributing significantly to the structural support and stability of the tree.

Structural root zone (ZRZ) - The zone of the root plate most likely to contain roots that are critical for anchorage and the stability of the tree.

Subsidence - In relation to soil or structures resting in or on soil, a sinking due to shrinkage when certain types of clay soil dry out, sometimes due to extraction of moisture by tree roots.

Subsidence - In relation to branches of trees, a term that can be used to describe a progressive downward bending due to increasing weight.

Taper - In stems and branches, the degree of change in girth along a given length.

Targets - In tree risk assessment persons or property or other things of value which might be harmed or damaged by falling parts of a tree

Topping/ Lopping - In arboriculture, the removal of the crown of a tree, or of a major proportion of it.

Torsional stress - Mechanical stress applied by a twisting force.

Translocation - Plant physiology, the movement of water and dissolved materials through the body of the plant.

Transpiration - The evaporation of moisture from the surface of a plant, especially via the stomata of leaves; it exerts a suction which draws water up from the roots and through the intervening xylem cells.

Tree Protection Zone (TRZ) - This is an area left around a tree to ensure protection of the above and below ground parts of the tree during construction works. It will usually include the SRZ and is usually recommended to be fenced off for the period of the works.

Understorey - This layer consists of younger individuals of the dominant trees, together with smaller trees and shrubs which are adapted to grow under lower light conditions.

Understorey tree species - Tree species not having potential to attain a size at which they can contribute to the closed high canopy of a forest or garden.

Vascular wilt - A type of plant disease in which water-conducting cells become dysfunctional.

Vessels - Water-conducting cells in plants, usually wide and long for hydraulic efficiency; generally, not present in coniferous trees.

Vigour - The expression of carbohydrate expenditure to growth (in trees).

Vitality - A measure of physiological condition.

White-rot - A range of kinds of wood decay in which lignin, usually together with cellulose and other wood constituents, is degraded.


Wind exposure - The degree to which a tree or other object is exposed to wind, both in terms of duration and velocity.

Windthrow - The blowing over of a tree at its roots.

Woundwood - Wood with atypical anatomical features, formed in the vicinity of a wound.

9.0 Appendices

9.1 QTRA Risk Thresholds



10.0 References

Mattheck, C. and Breloer, H. 1994. The body language of trees - a handbook for failure analysis. The Stationery Office, London England. p 11- 21, 22 – 27, 39, 60 – 65, 130 – 136, 171 – 172.

Harris, R, H. Clark, J, R. Matheny, N, P. 2004 Arboriculture, Integrated management of Trees, Shrubs, and vines. Pearson education, Upper Saddle River, New Jersey, USA. p 162, 351.

Lonsdale, D. 1999, 2010 Principles of Tree Hazard Assessment and Management. The Stationary Office, London England. PG: 149-150.

Shigo, A, L. 1979. Tree Decay; An expanded Concept. USDA Forest Service Agricultural Information. Bulletin No 419.

Duiker, S, W. 2002. Diagnosing Soil Compaction using a Penetrometer. Penn State College of Agricultural Science Research. Pennsylvania, USA.

Day, S.D. and Bassuk, N.L. 1994. Soil Compaction: A Review of the effects of soil compaction and amelioration treatments on landscape trees. Journal of Arboriculture. Vol 20 No 1 p 9-17.

Ganesson, S. 1995 Plant Pathology 202. Challenger Institute of Technology, Murdoch. Perth, Western Australia, Pg: 81 to 93.

Dunster, J, A, A. Smiley, T. Matheny, N. Lilly, S. (2013) Tree Risk Assessment Manual. International society of Arboriculture. Champaign Illinois, USA. p 29, 67 – 71, 74 – 84, 88 – 95.

Fay, N. 2007 Defining and Surveying Veteran and Ancient Trees, UK Biodiversity Action plan. England.

Smith, K, D. May, P, B. Moore, G, M. 2001. The Influence of Compaction and soil Strength on the Establishment of four Australian Landscape Trees, Journal of Arboriculture Vol 27 No 1.

Ellison, M. (2010). Quantified Tree Risk Assessment – Licensed User Manual, Quantified Tree Risk Assessment Ltd, Poynton, England.

Standards Australia. AS 4373 – 2007 Pruning of amenity Trees, Sydney, Australia.

Standards Australia. AS 4970 – 2009 Protection of Trees on Development Sites.

11.0 Disclaimer and Limitations

a. References in this report to the "Consultant" means listed on the cover page as an employee of Westworks Consultancy. References in this report to Westworks Consultancy means Westworks Group Pty Ltd as trustee for Ussheridan Trust trading as Westworks Consultancy (ACN 156 131 010 ABN 46 156 131 010).

b. In this report a reference to a group of persons includes a reference to all of them collectively, any two or more collectively and each of them individually.

c. The releases and limitations in this report apply to the Arborist, Westworks Consultancy and any employees, directors, contractors, and agents of the Arborist and/or Westworks Consultancy.

d. This report only covers identifiable defects present at the time of inspection. The Arborist and Westworks Consultancy accept no responsibility and cannot be held liable for any structural defect or unforeseen event/situation that may occur after the time of inspection.

e. The Arborist and Westworks Consultancy cannot and do not guarantee trees contained within this report will be structurally sound under all circumstances and cannot and do not guarantee that the recommendations made will categorically result in the tree being made "safe." Unless specifically mentioned this report will only be concerned with above ground inspections, that will be undertaken visually from ground level.

f. Trees are living organisms and as such cannot be classified as "safe" under any circumstances.

g. Failure events can occur for any number of reasons at any time and cannot always reasonably be foreseen, as any number of circumstances can come about at any time before or after an inspection that the Arborist and Westworks Consultancy may not be aware of.

h. All recommendations are made based on what can be reasonably identified at the time of inspection therefore the author accepts no liability for any recommendations made.

i. Care has been taken to obtain all information from reliable sources. All data has been verified or as much as possible; however, the Arborist and Westworks Consultancy can neither guarantee nor be responsible for the accuracy of information provided by others.

j. Booking of re-assessment after the prescribed period is the responsibility of the land manager/owner only. The Arborist and Westworks Consultancy are not responsible for providing reminders or notification that re assessment may be due and will not be held responsible to reinspect the listed trees until requested.

k. The Arborist and Westworks Consultancy make no express warranties under this report.

l. Except as the report specifically states, or as contained in any express warranty provided in relation to any goods or services provided or to be provided, the report does not include by implication any other term, condition, or warranty in respect of the quality, merchantability, acceptability, fitness for purpose, condition, description, assembly, manufacture, design or performance of the goods or services or any contractual remedy for their failure.

m. If the client is a consumer nothing in the Repot restricts, limits, or modifies the client's rights or remedies against Westworks Consultancy for failure of a statutory guarantee under the ACL save to the extent lawfully permissible.

n. To the greatest extent permitted under law the Arborist and Westworks Consultancy are not liable to the client or any third party in any way under or in connection with the Report or in connection with the goods or services provided by them to the client or any third party.

o. To the greatest extent permitted under law the Arborist and Westworks Consultancy are not liable for any indirect or consequential losses or expenses suffered by the client or any third party, howsoever caused, including but not limited to loss of turnover, profits, business or goodwill or any liability to any other party.

p. The client expressly acknowledges and agrees that:

   i. it has not relied upon, any service involving skill and judgement, or on any advice, recommendation, information, or assistance given by the Arborist or Westworks Consultancy, their agents, contractors, or employees in relation to any goods or services or their use or purpose.

   ii. it has not made known, whether expressly or by implication, to the Arborist and Westworks Consultancy any purpose for which it requires the goods or services and it has the sole responsibility of satisfying itself that any goods or services as suitable for the use of the client.

   iii. nothing in this Report is to be interpreted as excluding, restricting, or modifying the application of any non-excludable State or Federal legislation applicable to the sale of goods or supply of service.

   iv. Any reinspection is the responsibility of the tree owner to arrange as required.